U. S. DEPARTMENT OF COMMERCE

NATIONAL BUREAU OF STANDARDS

RESEARCH PAPER RP1534

Part of Journal of Research of the National Bureau of Standards, Volume 30, April 1943

SOME PROPERTIES OF HEAT-SETTING REFRACTORY MORTARS

By Raymond A. Heindl and William L. Pendergast

ABSTRACT

Twelve brands of the heat-setting type of refractory mortar were studied with respect to sieve analysis, pyrometric cone equivalent, amount of mixing water required, troweling and drying properties, and strengths after heating at various temperatures. The tendency of the mortars to shrink, crack, and adhere when exposed to high temperatures, both in fusion blocks and in units of three bricks each, was also investigated.

CONTENTS

		1 480
I.	Introduction	303
II.	Materials	303
III.	Preparation of specimens and methods of testing	304
	1. Mortars	304
	2. Mortar and brick	304
IV.	Results and discussion	305
	1. Mortars	305
	(a) Sieve analysis	305
	(b) Pyrometric cone equivalent	305
	(c) Mixing water and flow-table test	305
	(d) Troweling	307
	2. Mortar and brick	307
V.	Summary	310

I. INTRODUCTION

There are four materials ordinarily used for bonding fire-clay bricks or refractory shapes. Ground plastic fire clay was the generally accepted medium for many years, but with the improvement in refractories, the heat-setting mortar and the wet and dry types of airsetting mortars were developed and marketed. Federal specifications based on the results of investigations made at the National Bureau of Standards have already been prepared for fire clay and the two types of air-setting mortars. It is planned that the data reported in the present paper will be used for a similar purpose in the case of the heat-setting type of mortar.

II. MATERIALS

Twelve refractory mortars of the heat-setting type were supplied by eight manufacturers. One of these mortars was originally submitted as an air-setting mortar of the dry type, but because it had very little strength after air-setting, it was considered a heat-setting mortar.

514400-43-4

303

III. PREPARATION OF SPECIMENS AND METHODS OF TESTING

1. MORTARS

Each mortar was mechanically mixed with water for 1 hour, during which period the water content was adjusted to obtain the proper consistency for troweling as judged by "feel." After soaking the mortars overnight they were mixed for an additional 4 hours before testing them. All the tests were made on mortars so treated except the sieve analysis test,¹ which was made after the 1-hour mixing. The amount of mixing water was determined by drying samples of approximately 200 g to a constant weight at about 105° C. The pyrometric cone equivalents were determined according to the ASTM standard method.² The flow-table test was made as described in Federal Specification SS-C-158,3 and also in the ASTM standard specifications.⁴

The troweling tests were made with the machine described by Heindl and Pendergast.⁵ A ¹/₄-in. layer of mortar was spread evenly by hand-troweling on the upper 9- by $4\frac{1}{2}$ -in. face of a brick by means of a template. Using such specimens, two tests of troweling properties were made by reducing this ¼-in. layer to ½ in. in 1 stroke, and to ½ in. in 25 strokes (0.005 in. per stroke), respectively. The mortar caps were examined before drying for uniformity of thickness and adherence to the brick and, after drying, for cracks.

The modulus of rupture (transverse strength) was determined on mortar bars 6 by 1 by ¼ in. after drying for 27 hours at approximately 105° C. The bars were placed on supports 5 in. apart and loaded midspan. For convenience in reporting the results of the breaking tests, reference hereafter to the "original" position indicates that the surfaces of the bar in the test machine were in the same position as they were when made, that is, the same surface was uppermost on both occasions. Conversely, reference to "inverted" position indicates the surfaces were in reverse position during the tests. Half of the 10 mortar bars were tested in the original position in the cross-breaking machine and the other half in the inverted position.

The linear shrinkage determinations were made on three bar specimens of each mortar after each of three heat treatments, namely at 105°, 1,350°, and 1,500° C, respectively.

Tests of the mortars for adherence and also observations for shrinkage were made by heating each mortar in a fusion block having a compartment $\frac{1}{2}$ in. deep. The heat treatments were identical with those used for the bar specimens.

2. MORTAR AND BRICK

Assemblies of two half-brick and mortar were used for determining the strength of brick-to-mortar bond. The brick were cut parallel to the $2\frac{1}{2}$ - by $4\frac{1}{2}$ -in. faces into two equal parts. A laboratory screw

 ¹ In general, the test was similar to that described in Standard Method of Test for Particle Size of Ground Refractory Materials, ASTM Designation C 92-36, Am. Soc. Testing Materials Standards, pt. 2, Nonmetallic Materials—Constructional, p. 195 (1939).
 ³ Pyrometric Cone Equivalents of Refractory Materials, ASTM Designation C 24-35, Am. Soc. Testing Materials Standards, pt. 2, Nonmetallic Materials—Constructional, p. 214 (1939).
 ³ Cements, Hydraulic, General Specification.
 ⁴ Standard Specifications for Masonry Cement, ASTM Designation C 91-40, Am. Soc. Testing Materials Standards, Supplement, pt. 2, p. 1-7 (1940).
 ⁴ J. Research NBS 23, 7 (1939) RP1219.

press ⁶ was used in bonding the two half-brick with mortar. Sections of $\frac{1}{2}$ -in. drill rod were used as temporary spacers to obtain uniform thickness of mortar joints. The modulus of rupture of the mortar joint was determined after drying the specimen for 27 hours at about 105° C. The specimens were placed on supports 8 in. apart and loaded midspan.

A second type of brick-and-mortar assembly was made, consisting of a pier of two standard-sized brick and two half-brick laid flat to give one vertical joint between the two horizontal joints. Three of these piers were laid up with a troweled joint $\frac{1}{6}$ in. thick. The piers dried at 105° C and also heated at 1,350° and 1,500° C, were examined, when cool, for defects of the mortar cap and mortar joints.

The bonding ability of a mortar may be judged by grasping the top brick in a pier made of three brick as described above, and lifting it. If the mortar and brick pier remains intact, it can be assumed that the mortar has reasonably good bonding properties. This simple test was made on piers heated for 1 hour at 1,350° and at 1,500° C and cooled.

IV. RESULTS AND DISCUSSION

1. MORTARS

(a) SIEVE ANALYSIS

The results of the sieve analysis are given in table 1, columns 2 to 7. Less than 1 percent was retained on the No. 20 sieve for 8 of the 12 mortars. In the case of five of the mortars, over 60 percent passed the No. 200 sieve. Mortars P1 and Y1, on the other hand, had the largest percentage of coarse fractions, only 35 percent having passed the No. 200 sieve.

(b) PYROMETRIC CONE EQUIVALENT

The pyrometric cone equivalent of the mortars, listed in table 1, column 8, ranged from 27–28 to 35–36. The refractoriness of the mortars was fairly high, since the pyrometric cone equivalent was above 30 in all but one instance.

(c) MIXING WATER AND FLOW-TABLE TEST

The amounts of water, in terms of percentage of the dry weight of the mortar, used for bringing the mixtures to the proper consistencies for troweling are given in table 1, column 9. The amount of water ranged from 21.2 to 41.5 percent. In general, the mortars which contained greater proportions of coarse particles, as indicated by the total percentage retained on the No. 200 sieve, required the least amounts of water for tempering. The two exceptions to this relation are mortars N1 and O1, which contained the lesser proportions of coarse particles. Both of these mortars showed definite alkaline reaction when tested with 0.2 N hydrochloric acid and the deflocculation resulting from this alkalinity no doubt accounted for the low percentages of water required. The other two mortars which gave indications of alkalinity were P1 and R1. Both contained high percentages of coarse-grained material, in fact, P1 led all others in that respect, and hence any deflocculating action which could have been caused by the alkalies present may have been largely nullified.

⁶ J. Research NBS 23, 7 (1939) RP1219.

Sieve analysis ¹							Pyro-	Watan		Troweling Spreading and	Drying properties of troweled caps		
Mortar	Retained on No. 20	Passed No. 20. Retained on No. 40	Passed No. 40. Retained on No. 60	Passed No. 60. Retained on No. 100	Passed No. 100. Retained on No. 200	Cumula- tive total not passing No. 200	metric cone equiva- lent	water content of neat mortar	Flow- table readings	From ½ in. to ½ in. in 1 stroke	From ¼ in. to ¼ in. in 25 strokes	Adhered	Cracked
1	2	3	4	5	6	7	8	9	10	11	12	13	14
J 1 K 1 N 1 O 1 P 1 Q 1	Percent 0.0 .2 .0 .0 .0 .0 .2	Percent 1.7 1.8 0.2 .1 12.2 0.9	Percent 16. 2 9. 3 4. 4 3. 3 20. 2 17. 2	Percent 21.0 12.9 9.9 10.6 16.3 20.1	Percent 17.2 14.0 14.5 15.2 15.7 19.1	Percent 56. 1 37. 2 29. 0 29. 2 64. 6 57. 4	Cone 31 30-31 32-33 31-32 31 31-32	Percent 25.6 36.0 22.8 25.7 26.4 32.0	Percent 72 76 82 70 75 65	Gooddo do do do Fair Good	Gooddo Poor Fair Good	Percent 100 0 95 35 100 100	No. Do. Do. Do. Do.
Ř 1 S 1	1.9 0.1	$12.7 \\ 6.5$	21.4 20.9	12.1 16.1	11.2 12.9	59.3 56.5	35–36 35	24.6 22.2	77 74	do	do	95 100	Do. Do.
T 1 U 1 V 1 Y 1	$ \begin{array}{c c} 1.2\\ 1.5\\ 0.1\\ 2.7 \end{array} $	$ \begin{array}{r} 8.7\\ 11.5\\ 2.0\\ 32.1 \end{array} $	9.0 9.8 16.5 19.2	9.5 7.7 20.7 5.2	9.67.715.16.5	38.0 38.2 54.4 65.7	$\begin{array}{c c} & 32 \\ 31 - 32 \\ & 32 \\ 27 - 28 \end{array}$	$\begin{array}{c} 41.5\\ 39.0\\ 32.2\\ 21.2 \end{array}$	79 57 66 82	do do do do	Fair Good do do	0 0 95 95	Moderately. Do. No. Do.

TABLE 1.—Some properties of heat-setting refractory mortars

¹U. S. Standard Sieve Series.

306 Journal of Research of the National Bureau of Standards

Heat-setting Refractory Mortars

The results of the flow-table test of the mortars in a troweling consistency are given in table 1, column 10. The values range from 57 to 82, all but three being between 70 and 82, indicating that the initial consistency of most of the mortars was very nearly the same.

(d) TROWELING

The results of the mechanical-troweling tests are given in table 1, columns 11 and 12. These tests gave an indication of the workability of the mortars. In the one-stroke test all mortars except P1, which lacked sufficient plasticity, proved satisfactory, but in the 25-stroke test mortars O1, P1, and T1 were the exceptions. Mortar O1 was rated "poor" because of excessive stickiness, resulting in its adhering to the trowel and being partially pulled from the brick.

The condition of the mortar caps on the brick, after troweling and drying, are given in table 1, columns 13 and 14. Mortars K1, T1, and U1 showed no indication of adherence to the brick, and mortar O1 adhered only about one-third. The remainder had good adherence. The degree of adherence of the mortar cap, however, was no indication of the bonding property of the mortar when used in joints. The caps were remarkably free from drying cracks; only 2 (T1 and U1) of the 12 showed any development of cracks and these were not serious.

In table 2 are given the average transverse strengths of the neatmortar bars after heating them at 105° , $1,350^{\circ}$, and $1,500^{\circ}$ C. In each case three values are given: (1) the average for not less than five bars broken in the inverted position, (2) a similar average for bars broken in the original position, and (3) the averages for both positions. The results obtained after heating the bars at 105° C indicate no significant difference in strength with position of specimen during loading. However, the specimens, after heating at $1,350^{\circ}$ and $1,500^{\circ}$ C, showed strengths averaging about 18 percent greater when tested in the inverted position than when tested in the original position. This relation is the reverse of the findings in tests of air-setting mortars ⁷ of the wet and dry types.

The average transverse strength of the neat mortars dried at 105° C ranged from 0 to 290 lb/in², those heated at $1,350^{\circ}$ C from 350 to 4,720 lb/in², and those heated at $1,500^{\circ}$ C from 1,705 to 5,550 lb/in², all the specimens being cooled to room temperature before testing.

The linear shrinkages of neat mortars resulting from heating at 105° , $1,350^{\circ}$, and $1,500^{\circ}$ C and cooling are given in table 2. The two mortars, T1 and U1, which show the highest shrinkages after heating at 105° C, were the only ones which cracked on drying after the troweling tests.

2. MORTAR AND BRICK

The results of the transverse-strength tests made on assemblies of the two half-brick bonded with mortar are given in table 2. After heating at 1,350° C, eight of the 12 mortars indicated no significant bonding of the end faces of half-brick, as indicated by lack of crossbreaking strength of the brick-and-mortar units. After heating at 1,500° C, however, all but four of the mortars had good adherence or bonding properties, the strengths of the assemblies ranging as

⁷ R. A. Hein II and W. L. Pendergast, Properties of air-setting refractory bonding mortars of the wet type, J. Research NBS 23, 7 (1939) RP1219; Some properties of dry air-setting type of refractory bonding mortar, 28, 401 (1942) RP1461.

Journal of Research of the National Bureau of Standards 308

Mortar	Transve lus of mortar at—	rse strength rupture) bars afte	1 (modu- of neat- r heating	Linear mortar b	shrinkage ^s ars after he	Transverse strength (modulus of rup- ture) of two-half- brick-and-mortar assemblage after heating at—		
	105° C	1,350° C	1,500 C°	105° C	1,350° C	1,500° C	1,350° C	1,500° C
	<i>lb/in.</i> ²	<i>lb/in.</i> ²	<i>lb/in.</i> ² 2.765	Percent	Percent	Percent	lb/in.2	lb/in.2
J1	$\begin{cases} 240 \\ 235 \\ 210 \end{cases}$	1,570 1,580 5,200	2, 365 2, 565 3, 010	2.4	1.7	3.0	90	520
<i>K</i> 1	$\begin{cases} 200\\ 205\\ 125 \end{cases}$	4,235 4,720 3,885	2,950 2,980 6,020	6.9	5.9	4.4	0	0
N1	$\left\{\begin{array}{c} 125\\ 135\\ 130\\ 160\end{array}\right.$	2,625 3,220	5, 090 5, 550 4, 750	4.8	3. 5	6.3	0	0
01	$\begin{cases} 150 \\ 155 \\ 165 \end{cases}$	3, 400 3, 785 2, 120	4, 330 4, 540 3, 040	6.3	4.1	6.4	0	0
P1	$\begin{cases} 100 \\ 175 \\ 170 \\ 160 \end{cases}$	2, 035 2, 080 2, 680	2,480 2,760 4 120	2.5	2. 9	5.3	25	300
Q1	$\left\{\begin{array}{c} 100 \\ 150 \\ 155 \end{array}\right.$	2, 355 2, 515 (1 205	2, 680 3, 400 2, 315	6.2	3. 1	5.6	0	365
R1	0	$\left\{\begin{array}{c} 1,200\\ 895\\ 1,050\\ 1.635\end{array}\right.$	2, 180 2, 150 2, 000	0.9	0.8	1.5	180	665
S1	$\begin{cases} 180 \\ 180 \\ 185 \\ 170 \end{cases}$	1,780 1,710 2,405	2,500 2,175 2,580 3,115	2.5	1.4	3.1	0	³ 260
T1	{ 180 175 200	2,405 2,405 2,405	2, 730 2, 920 2, 955	9.2	3.7	5. 1	0	0
U1	$\begin{cases} 290\\ 290\\ 110 \end{cases}$	2, 920 3, 160	2,750 3,005	7.7	6.4	7.4	0	145
V1	$\begin{cases} 110 \\ 95 \\ 105 \\ 100 \end{cases}$	2,075 2,060 2,070 250	4, 530 3, 835	6.5	3. 2	4.8	0	3 85
Y1	$ \begin{cases} 190 \\ 205 \\ 195 195 $	345 350	1, 755 1, 655 1, 705	4.0	1.0	3.9	-95	460

TABLE 2.-Strength and shrinkage of heat-setting mortars after heating at several temperatures

¹ The 3 values determined for each mortar after having been heated at each of 3 temperatures represent, in the order given, the averages for: (1) 5 specimens broken with the surface that was originally at the top during drying in tension ("inverted position"), (2) 5 specimens with the surface that was originally on the bottom in tension ("original position"), (3) all specimens. ² Values tabulated in columns for 1,350° and 1,500° C are burning shrinkages.

³ Average of 2 specimens.

high as 665 lb/in^2 . In all cases the lack of strength in the assembly was due to failure of bonding of the mortar and brick and not due to weakness of the mortar.

The results of the visual examination of the mortars in the joints of the three-brick piers and in the fusion blocks after heating at 105°, $1,350^{\circ}$, and $1,500^{\circ}$ C are given in table 3. Only those cracks described as "bad" would be considered as affecting the quality of the mortar. Almost without exception the information relative to the shrinkage and cracking of a mortar, whether obtained from examination of a fusion block or of a cap, correlated with that obtained on the joints. The following exceptions may be cited. (1) The shrinkage of K1 was less in the joints than in the fusion block or in the cap, (2) the shrinkage of O1 in the joints and in the fusion block was less than in the cap with comparable heat treatment and, (3) the appearance of mortar Q1 in the joints of the pier and that in the fusion block heated at 1,500° C did not correlate.

Mortar	Appearan I	ce of mortar pier after hea	in ¼-in. joints ¹ of ting at—	Appearance of	mortar in fusion block	after heating at—	Condition ² of ^{1/8} after her	Bond in pier satis- factory after heat- ing for 1 hour at—		
	105° C	1,350° C	1,500° C	105° C	1,350° C	1,500° C	105° C	1,350° C	1,350° C	1,500° C
J1 K1	Good ⊥ and ∥ cracks.	L and cracks. Moderate	Good Moderate _ and	Slight shrinkage Moderate shrink- age.	Slight to moderate shrinkage. High shrinkage. No adherence.	Slight shrinkage. No adherence. High shrinkage. No adherence.	Good Badly cracked. 75% not bond-	Good Badly cracked. 80% not bond-	Yes No	Yes. Do.
N1 01	do Moderate ⊥ and ∥	cracks.	Bad ⊥ and mod- erate cracks.	Slight shrinkage dodo	Moderate shrinkage do	Moderate shrinkagedo	ed. Slightly cracked_ Badly cracked	ed. Slightly cracked. Badly cracked. 25% not bond-	do Yes	No. Yes.
P1 Q1	Good	Good	Good Bad ⊥ and slight ∥ cracks.	Good Slight shrinkage	Good Slight shrinkage	Good Slight to moderate shrinkage.	Gooddo	Good Slightly cracked. 10% not bond-	do do	Do. Do.
R1	do	1 and	Thermal cracks.	do	do	do	do	Slightly cracked	do	Do.
S1	do	Good	Good	do	Slight to moderate	Slight to moderate	do	Good	do	Do.
<i>T</i> 1	Moderate	Bad L and I	Bad ⊥ and mod- erate ∥ cracks.	Moderate shrink- age.	shrinkage. High shrinkage. No adherence.	shrinkage. High shrinkage. No adherence.	Badly cracked. 50% not bond-	Badly cracked. 80% not bond-	do	Do.
U1 V1	Good	do and	do and cracks	do Slight shrinkage	Moderate shrinkage	do Moderate shrinkage	dodo	Slightly cracked	do	Do. Do.
¥1	do	Good	Good	do	Good	Slight shrinkage	do	Slightly cracked. 50% not bond- ed.	do	Do.

TABLE 3.—Appearance of mortar in fusion block, cap and in joints of three-brick-and mortar assemblage

¹ Cracks occurring in the horizontal joints are designated ∥; those in the vertical joints ⊥. ² No reference to "adherence" indicates that bonding had taken place between mortar and fusion block.

309

In general, the cracking which occurred in the mortar joints and caps could have been predicted on the basis of selecting from the mortars listed in table 2, those having the highest shrinkage values after drying at 105° C.

The results of the test for judging the bonding ability of the mortars by grasping the top brick of a pier of three bricks bonded with mortar are listed in the last two columns of table 3. All the mortars proved satisfactory in the tests except K1 and N1. Mortar K1 failed in this test after having been heated at 1,350° C, and mortar N1 failed both after heating at 1,350° and at 1,500° C.

V. SUMMARY

Twelve refractory mortars of the heat-setting type supplied by eight manufacturers were investigated.

The mortars were finely ground, as supplied, only one contained as much as 2 percent of material that would not pass a United States Standard Sieve No. 20. The refractoriness of the mortars, as indicated by the pyrometric cone equivalent, was high, all but one being above cone 30. The amount of mixing water ranged from 21.2 to 41.5 percent. The consistencies of the mortars, however, as indicated by the flow-table test, were, with three exceptions, within a narrow range. The ease of troweling on brick, determined mechanically, was considered satisfactory except for one mortar. After troweling and drying, three mortars failed to adhere to the brick, but cracking was absent in all but two cases and these were not serious. These two mortars also had the greatest drying shrinkages.

The average modulus of rupture of the neat mortars dried at 105° C ranged from 0 to 290 lb/in.²; of those heated at $1,350^{\circ}$ C, from 350 to 4,720 lb/in.²; and of those heated at $1,500^{\circ}$ C, from 1,705 to 5,550 lb/in². In the transverse tests the bonding strength of the mortars in assemblies of two half-brick and mortar, heated at $1,350^{\circ}$ C and cooled, was poor, as indicated by the lack of any significant strength of 8 of the 12 mortars. Satisfactory bonding strength was shown, however, by 8 of the 12 mortars after the heat treatment at $1,500^{\circ}$ C. On the other hand, when the mortars were tested for their bonding property by grasping the upper brick in a pier made up of three brick and motar and lifting it, the results were very different. In these tests only two mortars were observed to fail when heated at $1,350^{\circ}$ C, and but one when heated at $1,500^{\circ}$ C and cooled.

The majority of mortars included in this study would be considered of satisfactory quality with respect to the technical requirements in a Federal specification based on the results of this investigation.

WASHINGTON, January 11, 1943.