

U. S. DEPARTMENT OF COMMERCE


BUILDING
MATERIALS
AND
STRUCTURES

REPORT BMS76

Effect of Outdoor Exposure,
on the Water Permeability
of Masonry Walls

by CYRUS C. FISHBURN,
DOUGLAS E. PARSONS,
and PERRY H. PETERSEN

NATIONAL
BUREAU OF STANDARDS



The program of research on building materials and structures carried on by the National Bureau of Standards was undertaken with the assistance of the Central Housing Committee, an informal organization of governmental agencies concerned with housing construction and finance, which is cooperating in the investigations through a committee of principal technicians.

CENTRAL HOUSING COMMITTEE ON RESEARCH, DESIGN, AND CONSTRUCTION

HUGH L. DRYDEN, *Chairman*.
National Bureau of Standards.

HOWARD P. VERMILYA, *Vice Chairman*.
Federal Housing Administration.

STERLING R. MARCH, *Secretary*.
MARY F. TAYLOR, *Assistant Secretary*.

PIERRE BLOUKE,
Federal Home Loan Bank Board.

JOHN F. DONOVAN,
Farm Security Administration.

A. C. SHIRE,
United States Housing Authority.

GEORGE W. TRAYER,
Forest Service (F. P. Laboratory).

WARREN G. NOLL,
Public Buildings Administration.

ROLLO H. BRITTEN,
Public Health Service.

LUTHER M. LEISENRING,
Construction Division (War).

GEORGE E. KNOX,
Yards and Docks (Navy).

EDWARD A. POYNTON,
Office of Indian Affairs.

WILLIAM R. TALBOTT,
Veterans' Administration.

WALLACE ASHBY,
Bureau of Agricultural Chemistry and Engineering.

NATIONAL BUREAU OF STANDARDS STAFF COMMITTEE ON ADMINISTRATION AND COORDINATION

HUGH L. DRYDEN, *Chairman*.
Mechanics and Sound.

PHAON H. BATES,
Clay and Silicate Products.

GUSTAV E. F. LUNDELL,
Chemistry.

HOBART C. DICKINSON,
Heat and Power.

ADDAMS S. MCALLISTER,
Codes and Specifications.

WARREN E. EMLEY,
Organic and Fibrous Materials.

HENRY S. RAWDON,
Metallurgy.

The Forest Products Laboratory of the Forest Service is cooperating with both committees on investigations of wood constructions.

BUILDING MATERIALS *and* STRUCTURES

REPORT BMS76

Effect of Outdoor Exposure on the
Water Permeability of Masonry Walls

by CYRUS C. FISHBURN, DOUGLAS E. PARSONS,
and PERRY H. PETERSEN



ISSUED AUGUST 15, 1941

The National Bureau of Standards is a fact-finding organization; it does not "approve" any particular material or method of construction. The technical findings in this series of reports are to be construed accordingly.

Foreword

Previous reports describe investigations of the factors affecting the water permeability of small masonry walls when first constructed and the effects of exposures in a dry condition to extremes of temperature and to wetting and drying at temperatures above freezing. This report gives data on the permeability of walls both before and after their exposure outdoors for three years at Washington, D. C. The weathering exposure was found to have had no great effect on the permeability of masonry walls of adequate thickness built of durable materials. The permeability of a few specimens, visibly damaged by the exposure, was found to have increased.

LYMAN J. BRIGGS, *Director.*

Effect of Outdoor Exposure on the Water Permeability of Masonry Walls

BY CYRUS C. FISHBURN, DOUGLAS E. PARSONS, AND PERRY H. PETERSEN

CONTENTS

	Page		Page
Forward.....	ii	IV. Effects of the Outdoor Exposure—Con.	
I. Introduction.....	1	2. Permeability of the plain, not water-	
II. The Wall Specimens.....	2	proofed, walls.....	18
1. Materials used in the walls.....	2	(a) All-brick and brick-faced walls	
2. Workmanship used in the walls.....	3	8 or more inches in thickness....	18
3. Walls with waterproofed faces.....	3	(b) Four-inch brick walls with	
4. Walls without waterproofings.....	3	parged backings.....	19
III. Method of Test.....	4	(c) Stucco-faced walls.....	19
1. Outdoor exposure.....	4	3. Permeability of the waterproofed	
2. Permeability tests.....	5	walls.....	19
3. Observations.....	5	(a) Walls treated with paraffin and	
4. The data.....	5	tung-oil solutions and waxes....	20
5. Performance ratings.....	11	(b) Walls with repointed face	
IV. Effects of the Outdoor Exposure.....	12	joints.....	20
1. Structural condition of the walls after		(c) Walls with grouted face joints..	20
exposure.....	12	(d) Walls painted with oil or	
(a) All-brick masonry walls, not		cement-water paints.....	20
waterproofed.....	12	(e) Proprietary waterproofing ma-	
(b) Other masonry walls, not		terials.....	20
waterproofed.....	14	V. Summary.....	21
(c) Waterproofed masonry walls..	16		

ABSTRACT

The water permeabilities of about 100 small masonry-wall specimens were measured before and after exposing them to the weather at Washington, D. C., for a maximum period of 3 years. Some of the more permeable walls had been waterproofed before exposure, and the durability of the waterproofing treatments, as well as the structural appearance or condition of the walls, was also determined.

The exposure did not have an important effect on the permeability of all-brick or brick-faced walls 8 in. or more in thickness. The permeability of stucco-faced walls was slightly increased. Repointing of the face joints was the most effective and durable of the waterproofing treatments.

I. INTRODUCTION

Although masonry building walls afford excellent protection from the weather and serve well

the purpose for which they were built, they may occasionally be penetrated by wind-driven rains. In such cases it is sometimes difficult, by examination of the structure or of the walls, to determine whether the leakage of water is through openings originally present at the time of construction or through cracks developed during the life of the structure. It has been thought that differential movements between the masonry units and the mortar, caused by temperature fluctuations, changes of moisture content, or by freezing of contained water, may produce cracks and subsequent leakage. The effects of such weathering agents may be determined by measuring the change in the permeability of masonry-wall specimens that have been subjected to exposure.

Previous investigations were made on small masonry-wall specimens at the National Bureau

of Standards to determine the effects on permeability of bathing dry walls in alternately hot and cold air,¹ and of alternately wetting and drying walls at temperatures above freezing.² This paper reports the effects of outdoor exposure on the water permeability of small masonry walls. Some of the specimens were waterproofed before the outdoor exposure, and the effects of weathering on the durability of these waterproofing treatments were determined.

II. THE WALL SPECIMENS

The 101 masonry walls were about 40 in. long and 50 in. high, and they included the 19 specimens described in BMS41 and BMS55. The walls were faced at the ends and top with a mortar parging $\frac{3}{8}$ to $\frac{1}{2}$ in. thick, which was applied to seal these areas so that a pressure gradient could be maintained within the masonry when pressure was applied to one face. A description of the materials and of the method or types of workmanship used in the construction of the walls is given in a previous publication³ of the National Bureau of Standards. That report also contains data obtained from permeability tests made before the walls were placed outdoors. In this report only a brief description is given of the materials and methods of constructing the walls.

¹ C. C. Fishburn and P. Petersen, Effect of Heating and Cooling on the Permeability of Masonry Walls, Building Materials and Structures Report BMS41.

² C. C. Fishburn, Effect of Wetting and Drying on the Permeability of Masonry Walls, Building Materials and Structures Report BMS55.

³ C. C. Fishburn, D. Watstein, D. E. Parsons, Water Permeability of Masonry Walls, Building Materials and Structures Report BMS7.

1. MATERIALS USED IN THE WALLS

The letters and numbers assigned the different masonry materials are given in the second columns of tables 3 and 4 and are the same as those assigned in BMS7.

Brick.—Brick *a* was a low-absorptive, side-cut, fire-clay brick having an average absorption during a 24-hour cold-water immersion of 0.4 percent by weight. Brick *b* was a side-cut shale brick having an absorption of about 8 percent. Brick *c* was a dry-press brick with an absorption of about 17 percent. The brick *c* were selected as underburned and contained a large percentage of salmon brick.

Stucco.—The stucco facings were mixed in the weight proportions of 1 part of portland cement to 3 parts of building sand. The stucco applied to the facings of four of the eight walls contained ammonium stearate in amount equal to 0.1 percent of the cement.

Hollow Units.—Structural clay tile *d*, double-shell, 8 by 12 by 10½ in., was a 6-cell end-bearing stretcher with bonding units. Tile *f*, Speed-a-backer, 8 by 8 by 12 in., was a side-construction stretcher or bonding unit. Tile *g*, Raritle, 8 by 12 by 8 in., was a 4-cell end-bearing stretcher with bonding units. Tile *h*, Techwood, 8 by 12 by 10 in., was a 6-cell end-bearing stretcher with bonding units.

Block *m*, 8 by 12 by 8 in., was a 2-cell stone-concrete block. Block *n* was a similar unit made with cinder concrete.

Mortars.—The proportions and the physical properties of the mortars are given in table 1.

TABLE 1.—Physical properties of the mortars

Properties of the mortars	Mortar numbers and proportions				
	1	2	3	4 ^a	5 ^b
Proportions of cement, lime, and sand—					
by volume ^c	1:0.25:3	1:1:6	1:2:9	1:1:6	1:1:6
by dry weight	1:0.11:2.6	1:0.42:5.1	1:0.85:7.7	1:0.42:5.1	1:0.42:5.1
Average water content, percentage by weight of dry materials	19.3	22.6	23.7	22.7	19.8
Water retentivity. ^d Initial flow 110 percent	77	86	88	86	30
Compressive strength in 28 days, lb/in. ² ^e	2,850	640	250	530	950
Tensile strength in 28 days, lb/in. ² ^f	310	130	50		155

^a Mortar 4 contained 0.2 percent of ammonium stearate by weight of cement plus dry hydrated lime in the putty.

^b Mortar 5 contained a hydrated lime of low plasticity, which was added to the mortar in the dry state; all other mortars contained a highly plastic lime putty prepared from pulverized quicklime.

^c Proportioning was by weight assuming portland cement weighs 94 lb/ft³, dry hydrated lime 40 lb/ft³, and that 1 ft³ of loose damp sand contains 80 lb. of dry sand.

^d Percentage of flow after suction to that of initial flow of 110 percent. Federal Specification SS-C-181a.

^e Cured according to Federal Specification SS-C-181.

^f Cured in damp air at 70° F.

Mortar *1w*, not listed in table 1, was used only in wall A16, and it was similar to mortar 1 except that it contained 0.2 percent of ammonium stearate by weight of portland cement plus lime.

2. WORKMANSHIP USED IN THE WALLS

The wall constructions differed in the method of applying mortar to the units, in the amount of mortar placed in the interior of the wall joints, and in the treatment of the face joints. Nearly all of the walls were built of either workmanship *A* or *B*. In class *A* workmanship, all of the joints were solidly filled with mortar. The face joints were tooled. Workmanship *B* was similar to much commercial workmanship in that the collar joints and the interior of the head joints were not filled. The face joints were cut flush with the faces of the brick. Workmanship *C* was similar to workmanship *A* except that the facing joints were cut without subsequent tooling. Workmanship *D* was the same as class *B* except that the joints in the exposed face were tooled to form a concave surface, as in class *A* workmanship.

Most of the walls contained copper flashings so placed as to collect leakage passing through the wall or dropping between the wythes. During the tests on walls without flashings, it could not be determined if moisture appearing on the supporting channels at the back of the walls had penetrated the wall facing or had leaked through the bed joints between the walls and the supporting channels.

3. WALLS WITH WATERPROOFED FACES

Thirty-three wall specimens, listed in table 4, were waterproofed on the exposed faces and tested for permeability before being placed outdoors. The waterproofing treatments and their immediate effects on the permeability of the walls are described in report BMS7.

Ten walls were treated with a solution containing 10 percent of paraffin and 5 percent of tung oil, by weight, in mineral spirits. The joints of six of these walls were then coated with a wax containing equal parts, by weight, of paraffin and tung oil. One wall, No. 37,

was treated with a paraffin and tung-oil solution applied after the face joints were repointed. This solution contained 10 percent of paraffin and 10 percent of tung oil in mineral spirits. The total amount applied on this wall in two treatments was equivalent to about 22 sq. ft. of wall per gallon of solution.

The face joints of 12 walls were repointed with the same kind of mortar which was used in the original construction. The repointed joints were tooled with a rounded bar. The faces of 10 of these walls were treated with additional waterproofing materials, applied after the repointing operation. These additional waterproofings included aluminum-stearate solutions, a linseed-oil solution, melted paraffin, and both oil and cement-water paints.

The joints in the faces of four walls were treated with portland cement grouts applied with a brush.

One wall was painted with an oil paint mixed at the Bureau and designed for use on masonry walls (see p. 30 of BMS7). Three walls were painted with cement-water paints, and five were waterproofed with proprietary compounds. The treatments with proprietary materials are described in BMS7, with the exception of those applied to walls 88 and 34. Wall 88 was treated by grouting the face joints with a mixture of 60 percent by weight of Rocktite, 10 percent of sand passing No. 30 sieve, and 30 percent of water. This grout was applied in two treatments, the total amount of dry materials used being equivalent to 8.7 lb per 100 sq ft of wall area. The face of wall 34 was brushed with two applications of a grout mixture consisting of 50 percent by weight of Rocktite color coating (white), 8 percent of sand passing No. 30 sieve, and 44 percent of water. The total amount of dry materials used was about 30 lb per 100 sq ft of wall area. The face of this wall crazed within 1 day after making a permeability test of the waterproofing.

4. WALLS WITHOUT WATERPROOFINGS

The plain walls (without waterproofings) included the least permeable of the specimens described in BMS7. This group of walls,




FIGURE 1.—Temperature record.

listed in table 3, contained 48 all-brick walls 8 or 12 in. thick, 9 walls faced with brick and backed with hollow units, 8 walls faced with stucco on hollow-unit backings, and 3 brick walls 4 in. thick with a backing of mortar parging.

III. METHOD OF TEST

1. OUTDOOR EXPOSURE

The walls were stored outdoors at Washington, D. C., during the time interval between January 1936 and May 1940. They were tested for permeability after being exposed outdoors for intervals of 1 to 3 years. During the storage periods they were placed end to end in parallel rows spaced 50 in. apart and facing

east. The waterproofed walls that gave good performances after being treated, were partially protected from the weather by sheet-metal coverings on the tops, backs, and ends, so that only the treated faces were exposed to wind and rain. The top coverings were adjusted so that rain and snow water dripping from them would run down the exposed, waterproofed faces of the walls. All of the plain walls, without waterproofings, as well as those specimens in which the waterproofing treatments were ineffective, were placed outdoors without coverings.

The maximum and the minimum monthly air temperature and the mean for each month of the daily maximum and of the daily minimum air temperatures are shown in figure 1, for the

period between January 1936 and May 1940.⁴ It can be seen from figure 1 that the maximum annual air temperature approached or exceeded 100° F and that the minimum annual air temperature averaged about 12° F. The greatest monthly fluctuation in air temperature (about 60° F), occurred during the winter months and the least, during the summer months. The number of times each month that the air temperature fell below and then rose to above freezing is also shown in figure 1. The meteorological data indicated that the air temperature did not rise above freezing more than once in any one day. The monthly precipitation at Washington, D. C., for the period of outdoor exposure of the walls is given in table 2.

TABLE 2.—Monthly precipitation at Washington, D. C.

Month	Year					
	1936	1937	1938	1939	1940	Normal
	<i>in.</i>	<i>in.</i>	<i>in.</i>	<i>in.</i>	<i>in.</i>	<i>in.</i>
January	5.9	7.8	2.6	3.4	2.1	3.6
February	3.8	3.3	2.4	5.7	2.8	3.4
March	4.5	1.5	2.2	2.9	3.4	3.8
April	2.0	6.9	1.7	3.8	6.2	3.3
May	5.3	4.0	3.5	.4	3.1	3.7
June	2.3	5.2	2.3	4.6	.9	4.1
July	4.1	3.7	5.0	2.0	-----	4.7
August	3.6	6.7	4.6	3.2	-----	4.0
September	2.0	1.8	4.3	6.9	-----	3.2
October	1.7	8.8	1.2	4.1	-----	2.8
November	.8	3.9	2.6	1.4	-----	2.4
December	5.2	.7	2.7	2.2	-----	3.3
Total	41.2	54.3	35.1	40.6	-----	42.3

2. PERMEABILITY TESTS

A full description of the permeability testing apparatus and of the method of test is given in BMS7 (heavy-rain test). The walls were dried to nearly constant weight before the tests were made. Each wall was supported on metal skids and clamped into position so that the exposed face formed one side of a pressure chamber. An air pressure of 10 lb/ft² above atmospheric pressure was maintained within the chamber, and water from a perforated tube was applied to the upper portion of the exposed face at the rate of about 40 gal/hr. This air pressure, equivalent to that produced by a head of 2 in. of water, is about the maximum produced by a wind velocity of 50 mph. Permeability

tests were made on the wall specimens at the ends of outdoor-exposure periods, and the tests extended for a period having a minimum of 1 to a maximum of 5 days.

The temperature of the water applied to the walls in the earlier tests was not observed, and although the water was warmed in a heater during the winter months, the water temperature may have been below the dew-point temperature of the testing room during some of these tests. Similarly, during some of the earlier tests, the rate of water application was adjusted by eye and may have sometimes exceeded 40 gal (152 liters) per hour, especially for tests made on walls faced with the high-absorptive brick *c*. However, during the later tests, the rate of water application was regulated by means of orifice meters, and the water temperature was maintained above the dew-point temperature of the testing room. During all tests the relative humidity in the testing room was usually between 80 and 90 percent.

3. OBSERVATIONS

The following observations were made during the permeability test:

Time for the appearance of moisture (dampness) on the backs of the walls.

Time for the appearance of visible water on the back of the walls.

Time for leakage to flow from the flashings. Maximum rate of leakage, if any.

Extent of damp area on the back of the wall after an exposure of 1 day and at the end of the test.

Observations were made at frequent intervals daily. The backs of the walls had been painted with white-wash, and the appearance of moisture (dampness) on the back could be easily detected.

4. THE DATA

Data obtained from the permeability tests are given in tables 3 and 4. Column 2 in these tables designates the kind of masonry units used in the wall facing and backing, the wall thickness, the type of workmanship, and the kind of mortar. Column 3 indicates the kind of test or kind of waterproofing treatment given

⁴Data obtained from the meteorological summary, Weather Bureau, U. S. Department of Agriculture.

each wall before it was placed outdoors. Beneath these are shown the periods of outdoor exposure that preceded the permeability tests.

Data obtained from the permeability tests and an arbitrary rating of wall performance are given in columns 4 to 9.

TABLE 3.—Permeability of masonry walls exposed outdoors

[The data in columns 4 to 9 are from permeability tests made before the walls were stored outdoors and after the outdoor exposure periods indicated in column 3]

[E, excellent; G, good; F, fair; P, poor; VP, very poor]

Wall No.	Designation ^a	Period of outdoor exposure, inclusive	Time to failure as indicated by—			Maximum rate of leakage	Area damp in 1 day	Rating
			Damp on back	Visible water	Leak			
1	2	3	4	5	6	7	8	9
12-INCH BRICK WALLS OF COMMON AMERICAN BOND								
			hr	hr	hr	Liters/hr	%	
15	aa12A1	Before exposure				0	0	E
		Jan. 1936 to Feb. 1937				0	0	E
		Apr. 1937 to Apr. 1939				0	0	E
77	aa12A1	Before exposure ^b				0	0	E
		Sept. 1937 to Sept. 1939				0	0	E
65	aa12A2	Before exposure				0	0	E
		May 1936 to May 1937	161			0	0	E
		July 1937 to July 1939				0	0	E
84	aa12A2	Before exposure	26			0	0	G
		July 1936 to Aug. 1937	15 ± 6			0	1	G
		Sept. 1937 to Sept. 1939	66 ± 3			0	0	E
56	aa12A3	Before exposure	85 ± 8			0	0	G
		May 1936 to May 1937	60 ± 6			0	0	G
		July 1937 to July 1939	83 ± 3			0	0	G
74	aa12A3	Before exposure ^b	39 ± 6			0	0	G
		Aug. 1937 to Aug. 1939	66 ± 3			0	0	G
42	aa12A4	Before exposure				0	0	E
		May 1936 to May 1937				0	0	E
		Aug. 1937 to Aug. 1939	10 ± 2			0	0	E
68	aa12C2	Before exposure	42 ± 3			0	0	E
		June 1936 to May 1937	38 ± 5			0	0	E
		July 1937 to July 1939				0	0	F
69	aa12D2	Before exposure	4		0.5	2.5	25	P
		June 1936 to May 1937	15 ± 5		2.5	1.0	8	P
		July 1937 to July 1939	19 ± 3		1.7	0.6	1	F
18	bb12A1	Before exposure	4 ± 1		0	0	15	G
		July 1936 to July 1937	0.6	13 ± 7	0	0	45	F
		Aug. 1937 to Aug. 1939	10 ± 3	10 ± 3	0	0	30	F
A1	bb12A1	Before exposure ^b	33 ± 2		12	.01	0	F
		Sept. 1937 to Sept. 1939	22 ± 3			0	1	E
27	bb12A2	Before exposure	1	2	1	(°)	7	P
		Apr. 1936 to Apr. 1937	0.2	1.5		0	45	P
		Aug. 1937 to Aug. 1939	2	15 ± 6		0	15	F
85	bb12A2	Before exposure	9 ± 2			0	10	G
		July 1936 to Aug. 1937	9 ± 2		1.5	.07	20	F
		Sept. 1937 to Sept. 1939	0.6	14 ± 6		0	30	F
A4	bb12A2	Before exposure ^b	31 ± 4	42 ± 3		0	0	G
		Nov. 1937 to Nov. 1939	18 ± 3			0	3	G
73	bb12A3	Before exposure	12 1			0	15	G
		Sept. 1936 to Sept. 1937	17 ± 4			0	4	G
		Oct. 1937 to Oct. 1939	18 ± 3			0	3	G
A2	bb12A3	Before exposure ^b	28			0	1	G
		Nov. 1937 to Nov. 1939	39 ± 6			0	2	G
45	bb12A4	Before exposure	0.6	0.6		0	21	P
		July 1936 to July 1937	2.3	15 ± 6		0	33	F
		Oct. 1937 to Oct. 1939	2.5	18 ± 3		0	23	F
19	bb12B3	Before exposure	0.03	0.03	0.03	23	90	VP
		Mar. 1936 to Aug. 1936	.1	.13	.22	17	93	VP
		Sept. 1937 to Sept. 1939						
28	cc12A1	Before exposure	6.5			0	6	G
		Aug. 1936 to Aug. 1937	5			0	8	G
		Oct. 1937 to Oct. 1939	10 ± 2			0	3	G
76	cc12A1	Before exposure	1.1	9 ± 1		0	95	F
		Aug. 1936 to Aug. 1937	1.9		(°)	0	45	(°)
		Oct. 1937 to Oct. 1939	3.7	15 ± 6		0	40	F
94	cc12A1	Before exposure ^b	14.5			0	1	G
		Sept. 1937 to Sept. 1939	10 ± 2			0	5	G
35	cc12A2	Before exposure	7 ± 1			0	20	G
		June 1936 to Aug. 1936	9 ± 2			0	18	G
		Oct. 1937 to Oct. 1939	10 ± 2			0	8	F
66	cc12A2	Before exposure	0.4	1.3	2.3	(°)	100	P
		July 1936 to Aug. 1937	.7	15 ± 6	15 ± 6	.4	100	F
		Oct. 1937 to Oct. 1939	.8	15 ± 6	15 ± 6	.1	85	F
33	cc12A3	Before exposure	8 ± 1			0	16	G
		June 1936 to June 1937	0.07	0.07	15 ± 6	.1	80	P
		Sept. 1937 to Sept. 1939	.3	.7	6.4	10.0	90	VP
75	cc12A3	Before exposure ^b	18 ± 3			0	10	G
		Dec. 1937 to Dec. 1939	10 ± 2	26		0	15	G

See footnote at end of table.

TABLE 3.—Permeability of masonry walls exposed outdoors—Continued

Wall No.	Designation	Period of outdoor exposure, inclusive	Time to failure as indicated by—			Maximum rate of leakage	Area damp in 1 day	Rating
			Damp on back	Visible water	Leak			
1	2	3	4	5	6	7	8	9
12-INCH BRICK WALLS OF COMMON AMERICAN BOND								
43	cc12A4	Before exposure June 1936 to July 1937 Oct. 1937 to Oct. 1939	hr. 1 2 2.5	hr. (c) 2.8 4.1	hr. 3 ±1 15 ±6	Liters/hr. (c) 0.6 0	% d 60 90 75	(c) P F
A17	cc12A5	Before exposure Sept. 1936 to Sept. 1937 Oct. 1937 to Oct. 1939	0.2 .6 .9	(c) 15 ±6 2.5		0 0 0	80 55 40	(c) F P
A19	cc12A5	Before exposure Sept. 1936 to Sept. 1937 Oct. 1937 to Oct. 1939	.1 .35 .5	0.7 15 ±6 2.7	15 ±6 14 ±6 6 ±2	.6 .6 .3	95 95 85	P F P
67	cc12B2	Before exposure Aug. 1936 to Aug. 1937 Oct. 1937 to Oct. 1939	.25 .35 .8	0.5 2 1.5	0.07 2 .4	130 63 28	75 VP 75	VP VP VP
21	cc12B3	Before exposure Apr. 1936 to Apr. 1937 Aug. 1937 to Aug. 1939	.1 .4 .1	1.8 1.2 0.9	.6 .8 2.3	41 80 0.4	d 80 100 80	VP VP P
A18	cc12B5	Before exposure Sept. 1936 to Sept. 1937 Oct. 1937 to Oct. 1939	.08 .07 .25	.12 .1 .5	0.08 .07 .5	248 234 73	95 95 85	VP VP VP
A20	cc12B5	Before exposure Aug. 1936 to Aug. 1937 Before exposure	.05 .05 .4	.1 .05 (c)	.1 .09 .6	249 283 0.4	100 94 50	VP VP FP
71	cc12C2	Before exposure Sept. 1936 to Sept. 1937 Oct. 1937 to Oct. 1939	.5 1 0.25	15 ±6 2.6 14 ±6	(c) — .13	(c) 0 67	d 25 60 804	FP P VP
70	cc12D2	Before exposure Aug. 1936 to Aug. 1937 Oct. 1937 to Oct. 1939	1.1 1.9 1.9	15 ±6 13 ±6 13 ±6	.55 .8 .8	18 12 12	70 65 65	VP VP VP
8-INCH BRICK WALLS OF COMMON AMERICAN BOND								
14	aa8A1	Before exposure* Aug. 1937 to Aug. 1939	111 ±6 114 ±3			0 0	0 0	G E
89	aa8A2	Before exposure July 1936 to July 1937 Aug. 1937 to Aug. 1939	44 ±3 39 ±6 75 ±1			0 0 0	4 0 2	G G G
58	aa8A3	Before exposure* Oct. 1937 to Oct. 1939	18 ±4 24 ±1 3			0 0 0	48 3 12	G G G
51	aa8A4	Before exposure* Aug. 1937 to Aug. 1939	10 ±3 12 ±2			0 0	2 60	G F
92	aa8A5	Before exposure July 1936 to Aug. 1937 Oct. 1937 to Oct. 1939	18 ±3 18 ±3 0.03			0 0 0.03	17 10 d 9	G G VP
47	aa8B4	Before exposure Apr. 1936 to Apr. 1937 May 1937 to Apr. 1939	4.5 0.30 0.03	0.03 — (c)	0.03 .02 .13	25 19 3.2	9 20 9	VP VP P
90	bb8A2	Before exposure Aug. 1936 to Aug. 1937 Oct. 1937 to Oct. 1939	.03 .05 .05	14 ±6 0.3 5		0 0 .08	90 80 60	FP F P
36	cc8A2	Before exposure July 1937 to Sept. 1939	.2 .3 .25	.4 .4 .4	2.2 2.5 1.5	1.7 1.3 3.2	100 100 100	P P P
38	cc8A2	Before exposure June 1936 to July 1937 Aug. 1937 to Aug. 1939	.3 .3 .3	.5 .7 .5	1.8 1.4 (c)	6.6 4.0 (c)	100 96 d 70	VP P P
20	cc8A3	Before exposure May 1936 to May 1937 July 1937 to July 1939	.2 .3 .75	.3 .3 (c)	2.0 0.8 14 ±7	1.8 0.7 (c)	100 96 100	P P P
40	cc8A4	Before exposure June 1936 to July 1937 Aug. 1937 to Aug. 1939	.6 .7 .05	(c) 1.9 0.1	4 ±2 15 ±5 0.1	2.2 1.3 146	100 100 100	P P VP
41	cc8B4	Before exposure June 1936 to June 1937 July 1937 to July 1939	.03 .15 .15	.03 .2 .2	.05 .2 .2	157 41 41	100 100 100	VP VP VP
8-INCH BRICK WALLS OF COMMON AMERICAN BOND								
86	ac8A2	Before exposure July 1936 to Aug. 1937 Sept. 1937 to Sept. 1939	hr 85 ±6 111 ±6 114 ±4	hr	hr	Liters/hr 0 0 0	% 0 0 0	E G E
87	ac8B2	Before exposure Aug. 1936 to Aug. 1937 Oct. 1937 to Oct. 1939	0.05 .1 .1	0.8 16 ±4 0.6	0.3 1 1	20 16 10	100 92 85	VP VP VP

See footnote at end of table.

TABLE 3.—Permeability of masonry walls exposed outdoors—Continued

Wall No.	Designation	Period of outdoor exposure, inclusive	Time to failure as indicated by—			Maximum rate of leakage	Area damp in 1 day	Rating
			Damp on back	Visible water	Leak			
1	2	3	4	5	6	7	8	9
12-INCH BRICK WALLS WITH HOLLOW UNIT BACKINGS								
82	bg12A2	Before exposure July 1936 to Aug. 1937 Oct. 1937 to Oct. 1939	0.5 1.5 2.8		4 ±2 5.3	(c) 0.01 0	47 45 11	G G G
80	bm12A2	Before exposure June 1936 to July 1937 Oct. 1937 to Oct. 1939	0.2 .7 .08	(c) 15 ±6 0.2	0.6 5 ±1 2.8	6 0.8 2.5	100 80 95	VP F P
A3	bm12A2	Before exposure b (Sept. 1937 to Sept. 1939)	3 1.8	15 ±6	15 ±6	0.1 0	29 15	F G
A5	bm12A2	Before exposure c (Dec. 1937 to Dec. 1939)	18 ±4 18 ±4			0 0	1 1	E G
78	bn12A2	Before exposure June 1936 to July 1937 Sept. 1937 to Sept. 1939	0.1 .1 .6	(c) 0.75 15 ±6	0.6 5.7	(c) .3 0	50 75 15	PF P F
93	bn12A2	Before exposure Aug. 1936 to Aug. 1937 Nov. 1937 to Nov. 1939	50 ±2 17 ±3 43 ±3			0 0 0	1 1 0	G G E
83	bg12B2	Before exposure July 1936 to July 1937 Oct. 1937 to Oct. 1939	0.2 .7 .2		0.03 15 ±6 14 ±6	93 .03 .1	85 80 70	VP VP VP
81	bn12B2	Before exposure July 1936 to July 1937 Sept. 1937 to Sept. 1939	.07 .1 .16		.03 0.13 .4	93 .3 .2	85 71 36	VP VP VP
79	bn12B2	Before exposure June 1936 to July 1937 Sept. 1937 to Sept. 1939	.08 .05 .07	.08 .1 .1	.03 .09 .08	159 101 36	60 40 30	VP VP VP
4-INCH BRICK WALLS WITH PARGED BACKING								
A13	ap4A1	Before exposure July 1936 to Aug. 1937 Oct. 1937 to Oct. 1939	0.9 5.7 0.2			0 0 0	25 15 25	G G P
A14	ep4A1	Before exposure July 1936 to Aug. 1937 Sept. 1937 to Sept. 1939	.2 .3 .5	1.1		0 0 0	35 25 70	G F F
A16	ep4A1w	Before exposure July 1936 to Aug. 1937 Oct. 1937 to Oct. 1939	.4 .3 .2		1.2 15 ±6 0.7	.07 0 .1 .9	25 70 15 90 85	F G F P
WALLS WITH STUCCO FACINGS †								
1	sj9A2 (Eps) a	Before exposure Jan. 1936 to Feb. 1937 Mar. 1937 to Mar. 1939	87 ±6 23 ±1 19 ±3				0 4 4	G E G
2	sj9A2 (Epr) a	Before exposure Before exposure b Nov. 1937 to Nov. 1939	41 ±3 15 ±6 9 ±2			0 0 0	0 8 15	G G G
3	sj9A2 (Ews) a	Before exposure Before exposure b (Sept. 1937 to Sept. 1939)	207 ±6 25 18 ±3			0 0 0	0 10 20	E G G
4	sj9A2 (Ewr) a	Before exposure Jan. 1936 to Feb. 1937 Apr. 1937 to Apr. 1939	60 ±8 15 ±3 2.7				15 10 30	G G G
WALLS WITH STUCCO FACINGS †								
5	sj9A2 (Sps) a	Before exposure Jan. 1936 to Feb. 1937 Mar. 1937 to Mar. 1939	108 ±7 64 ±6 4.4			0 0 (c)	0 0 8	E E F
6	sj9A2 (Spr) a	Before exposure Apr. 1936 to Apr. 1937 May 1937 to May 1939	132 ±7 10 ±3 2.5	10 ±3			0 5 25	E G G
7	sj9A2 (Sws) a	Before exposure Before exposure c Oct. 1937 to Oct. 1939	132 111 ±6 58 ±2				0 3 0	E G E
8	sj9A2 (Swr) a	Before exposure May 1936 to May 1937 Aug. 1937 to Aug. 1939	2 0.5	0.5			5 10 33	E G P

^a Lower-case letters denote kind of masonry units in facing and backing. First numeral denotes nominal wall thickness in inches. Capital letters denote type of workmanship. Final number denotes kind of mortar.

^b Tested after having been subjected to heating and cooling, see BMS41.

^c Not determined.

^d Duration of test exposure less than 24 hours.

^e Tested after having been subjected to wetting and drying, see BMS55.

[†] Wall not flashed at bottom.

^a For stucco-faced walls:

E, end-bearing tile backing.

S, side-bearing tile backing.

p, plain stucco.

w, waterproofed stucco.

s, smooth finish stucco.

r, rough finish stucco.

TABLE 4.—Permeability of waterproofed masonry walls exposed outdoors

The data in columns 4 to 9 are from permeability tests made before the walls were waterproofed, after they were waterproofed, and after being stored outdoors, as is indicated in column 3]

[E, excellent; G, good; F, Fair; P, poor; VP, very poor]

Wall No.	Designation *	Waterproofing treatment or period of outdoor exposure ^b	Time to failure as indicated by—			Maximum rate of leakage	Area damp in 1 day	Rating
			Damp on back	Visible water	Leak			
1	2	3	4	5	6	7	8	9
WALLS TREATED WITH PARAFFIN (PAR.) AND TUNG OIL SOLUTIONS AND WAXES								
A7.....	bb12A1.....	Before waterproofing	hr 43 ±3	hr	hr	liters/hr 0	% 0	E
		Paraffin and tung oil	-----	-----	-----	0	0	E
		Dec. 1936 to Dec. 1937	83 ±6	-----	-----	0	0	G
		Jan. 1938 to Mar. 1940	-----	-----	-----	0	0	E
A8.....	cc12A1.....	Before waterproofing	9 ±2	-----	-----	0	16	G
		Paraffin and tung oil	19 ±4	-----	-----	0	11	G
		*Oct. 1936 to Nov. 1937	16 ±3	-----	-----	-----	1	G
		*Dec. 1937 to Apr. 1940	38 ±6	-----	-----	-----	0	G
31.....	cc8A1.....	Before waterproofing	0.5	()	()	()	100	PF
		Paraffin and tung oil	3.5	4.1	15 ±6	0.3	80	F
		Nov. 1936 to Dec. 1937	1.3	5 ±1	-----	0	55	F
		Dec. 1937 to Dec. 1939	1.3	4.4	-----	-----	55	F
16.....	aa12B1.....	Before waterproofing	0.1	0.1	0.1	21	70	VP
		Paraffin and tung oil	.35	1	1	14	55	VP
		Waxed joints	4.4	4.4	7.5	1.5	35	P
		Dec. 1936 to Dec. 1937	.03	0.03	.7	4	55	P
29.....	cc12B1.....	Jan. 1938 to Mar. 1940	0.3	.3	.7	3	50	P
		Before waterproofing	.03	.04	.02	158	70	VP
		Paraffin and tung oil	.5	4 ±1	1	46	50	VP
		Waxed joints	7	-----	15.0	0.4	18	F
72.....	bb12B1.....	Before waterproofing	0.1	15 ±6	.3	11	85	VP
		*Jan. 1937 to Jan. 1938	.1	0.3	.2	34	85	VP
		Mar. 1938 to Mar. 1940	.2	.3	.2	40	100	VP
		Before waterproofing	1.3	15 ±6	.7	43	75	VP
17.....	aa8B1.....	Paraffin and tung oil	0.7	0.8	.6	18	65	VP
		Sept. 1937 to Sept. 1939	.03	.03	.05	17	75	VP
		Before waterproofing	.13	.13	.12	15	55	VP
		Paraffin and tung oil	24	-----	-----	0	0	G
62.....	bb8A1.....	Waxed joints	1.6	1.6	2	3	35	P
		*Dec. 1936 to Dec. 1937	0.5	0.8	0.8	3	30	P
		Dec. 1937 to Dec. 1939	.01	.01	.3	16	100	VP
		Before waterproofing	.05	.08	.4	4	100	P
63.....	bb8B1.....	Paraffin and tung oil	3	-----	-----	0	55	F
		Waxed joints	12 ±1	-----	-----	0	10	G
		Paraffin and tung oil	0.3	.3	10 ±3	.9	75	P
		*Jan. 1937 to Jan. 1938	.05	.08	0.4	3	95	P
30.....	cc8B1.....	Mar. 1938 to Mar. 1940	.02	.04	.03	120	100	VP
		Before waterproofing	.03	.13	.05	80	100	VP
		Paraffin and tung oil	3.4	15 ±6	2.2	0.6	80	F
		Waxed joints	0.4	1.6	0.15	9	100	VP
48.....	aa12B4.....	Jan. 1937 to Jan. 1938	.4	0.7	.25	13	95	VP
		Feb. 1938 to Mar. 1940	.1	.1	.1	88	100	VP
		Before waterproofing	.3	.4	.5	50	100	VP
		Paraffin and tung oil	2.1	17 ±3	11 ±2	1.4	70	P
46.....	bb12B4.....	Waxed joints	0.05	0.05	0.07	25	95	VP
		Jan. 1937 to Jan. 1938	.3	.5	.3	23	95	VP
		Mar. 1938 to Mar. 1940	-----	-----	-----	-----	-----	-----
		Before waterproofing	0.1	0.13	.05	36	100	VP
64.....	aa12B2.....	Repointed	1.2	-----	0.2	14	25	VP
		Before waterproofing	19 ±3	-----	8 ±2	0.3	8	F
		*Sept. 1936 to Sept. 1937	63 ±6	-----	-----	0	0	E
		*Oct. 1937 to Oct. 1939	-----	-----	-----	0	0	E
50.....	bb12B2.....	Before waterproofing	0.6	-----	0.05	15	15	VP
		Repointed	32 ±2	-----	-----	0	0	G
		*Aug. 1936 to Oct. 1937	65 ±3	-----	-----	0	0	E
		*Nov. 1937 to Nov. 1939	-----	-----	-----	0	0	E
46.....	bb12B4.....	Before waterproofing	0.1	0.13	.05	36	100	VP
		Repointed	1.4	15 ±6	.7	1.7	42	P
		Linseed oil solution	13	-----	19 ±3	0.1	10	F
		*Jan. 1937 to Jan. 1938	12 ±1	-----	20	.1	12	F
46.....	bb12B4.....	*Mar. 1938 to Mar. 1940	17 ±3	-----	17 ±3	.2	1	F
		Before waterproofing	10 ±2	-----	10 ±2	.2	15	F
		Aluminum stearate solution	0.12	0.12	0.03	38	100	VP
		Repointed	2.4	15 ±6	.5	2	55	P
46.....	bb12B4.....	Aluminum stearate solution	17 ±1	-----	9 ±1	0.1	1	F
		*Feb. 1937 to Feb. 1938	159 ±6	-----	-----	0	0	E
		*Mar. 1938 to Apr. 1940	78 ±1	-----	18 ±3	.1	0	F
		Before waterproofing	9 ±2	99 ±2	18 ±4	.1	2	F

See footnote at end of table.

TABLE 4.—Permeability of waterproofed masonry walls exposed outdoors—Continued

Wall No.	Designation	Waterproofing treatment or period of outdoor exposure	Time to failure as indicated by—			Maximum rate of leakage	Area damp in 1 day	Rating
			Damp on back	Visible water	Leak			
1	2	3	4	5	6	7	8	9
WALLS WITH REPOINTED FACE JOINTS—Continued								
37	cc12B2	Before waterproofing	hr 0.2	hr 0.8	hr 0.1	Liters/hr 101	% 80	VP
		Repointed	8 ±1		2.6	2.7	40	P
		1st, paraffin and tung oil	51 ±1		38 ±6	0	0	G
		2nd, paraffin and tung oil	15 ±6			0	4	G
		*Aug. 1937 to Oct. 1938	106 ±3		67 ±3	0	0	G
22	bb8B2	*Jan. 1939 to Apr. 1940	17 ±3	38 ±6	9 ±2	1.7	10	P
		Before waterproofing	0.05	0.05	0.13	50	100	VP
		Repointed paraffin solution	4.8	15 ±6		0	55	F
		*Oct. 1936 to Oct. 1937	1.5	15 ±6		0	70	F
		Nov. 1937 to Nov. 1939	1.4	15 ±6	15 ±6	.3	85	F
91	bb8B2	Before waterproofing	0.03	0.03	0.03	69	100	VP
		Repointed; aluminum stearate 10 solution	10 ±2		18 ±4	0.06	9	F
		*Oct. 1936 to Oct. 1937	8 ±1			0	1	E
		*Nov. 1937 to Nov. 1939	25 ±1			0	1	E
A9	bb8B2	Before waterproofing	0.02	.02	0.02	56	100	VP
		Repointed-linseed-oil solution	9 ±1			0	10	G
		*Nov. 1936 to Nov. 1937	39 ±6			0	1	E
		*Dec. 1937 to Dec. 1939	18 ±4			0	1	E
54	bb8B3	Before waterproofing	0.02	.07	.07	79	100	VP
		Repointed; aluminum stearate solution	2 ±1	19 ±4		0	20	F
		*Oct. 1936 to Sept. 1937	3.8			0	10	G
		*Nov. 1937 to Nov. 1939	15 ±5		51 ±14	0	10	G
52	bb8B4	Before waterproofing	0.01	0.01	0.02	59	100	VP
		Repointed	.5	9 ±2	9 ±2	0.8	75	F
		Molten paraffin	5			0	10	G
		*Dec. 1936 to Dec. 1937	38 ±6			0	0	E
		*Jan. 1938 to Mar. 1940	57 ±2			0	0	E
WALLS WITH GROUTED FACE JOINTS								
55	aa12B3	Before waterproofing	1	15 ±6	0.08	14	65	VP
		Grouted joints	90 ±4			0	0	E
		*Dec. 1936 to Dec. 1937	106 ±2			0	0	E
		*Jan. 1938 to Mar. 1940	91 ±3			0	0	G
57	aa8B3	Before waterproofing	0.1	0.1	.03	19	90	VP
		Grouted joints	41 ±7			0	0	G
		*Dec. 1936 to Jan. 1938	39 ±3			0	0	G
		*Jan. 1938 to Mar. 1940	9 ±2			0	7	G
53	bb8A2	Before waterproofing	0.03	.08	.4	.9	100	P
		Grouted joints	2.4		0	0	52	F
		Dec. 1936 to Dec. 1937	0.2	15 ±6		0	90	F
		Jan. 1938 to Mar. 1940	.8	18 ±4		0	75	F
59	bb8A3	Before waterproofing	.02	0.05	.2	.7	100	P
		Grouted joints	3.5			0	35	G
		*Dec. 1936 to Dec. 1937	3			0	30	G
		*Jan. 1938 to Mar. 1940	3.7	18 ±4		0	35	F
WALLS PAINTED WITH OIL OR CEMENT-WATER PAINTS								
44	cc12B4	Before waterproofing	0.3	0.35	.03	70	80	VP
		Repointed	2.6	15 ±6	1.4	3	35	P
		Cement-water paint				0	0	E
		*Feb. 1937 to Feb. 1938	67 ±4			0	0	E
A10	bb8B2	Before waterproofing	0.02	0.02	0.02	49	100	VP
		Repointed—oil paint	7.8			0	22	G
		*Feb. 1937 to Feb. 1938				0	0	E
		*Mar. 1938 to Mar. 1940	106 ±3			0	0	E
A12	m8A2e	Before waterproofing	0.02	.02	(c)	(c)	100	(c)
		Cement-water paint	161 ±10			0	0	E
		*Jan. 1937 to Jan. 1938	114 ±3			(c)	1	(c)
		*Jan. 1938 to Mar. 1940	91 ±4			(c)	6	(c)
A11	n8A2e	Before waterproofing	0.05	.05	(c)	(c)	70	(c)
		Cement-water paint	2.8		(c)	(c)	16	(c)
		Repeated test	0.7		(c)	(c)	30	(c)
		*Feb. 1937 to Feb. 1938	1.8		(c)	(c)	15	(c)
		*Mar. 1938 to Apr. 1940	1.8	39 ±6	(c)	(c)	15	(c)

See footnote at end of table.

TABLE 4.—Permeability of waterproofed masonry walls exposed outdoors—Continued

Wall No.	Designation	Waterproofing treatment or period of outdoor exposure	Time to failure as indicated by—			Maximum rate of leakage	Area damp in 1 day	Rating
			Damp on back	Visible water	Leak			
1	2	3	4	5	6	7	8	9
WALLS WATERPROOFED WITH PROPRIETARY MATERIAL								
61	aa8B2	Before waterproofing	hr 0.05	hr 0.3	hr 0.01	Liters/hr 20	% 80	VP
		Grouted joints (Capsis)	25 ±2			0	1	G
		*Sept. 1936 to Sept. 1937	40 ±5			0	0	G
		*Nov. 1937 to Nov. 1939	34 ±2		0	0	0	G
88	aa8B2	Before waterproofing	0.02	.02	.03	10	d 50	VP
		June 1936 to June 1937	.03	.07	.4	4	85	P
		Rocktite grout joints.	.3	6	.7	0.7	50	F
		Rocktite grout joints.	.3	15 ±6		0	45	F
34	ee8B2	July 1937 to July 1938	.7	11 ±3		0	40	F
		Sept. 1938 to Apr. 1940	.1	0.1	18 ±4	0.08	35	P
		Before waterproofing	.03	.05	0.08	51	100	VP
		June 1936 to June 1937	.07	.1	.2	45	100	VP
39	ee8B2	Rocktite color coat.	2.1			0	35	G
		July 1937 to July 1938	29 ±1			0	0	E
		Sept. 1938 to Apr. 1940	9 ±2			0	3	G
		Before waterproofing	0.08	.2	.4	67	100	VP
49	bb8A4	Bldg. Chem. Corp. No. 1	9 ±1			0	12	G
		*Sept. 1936 to Sept. 1937	5.5	15 ±6		0	4	F
		*Nov. 1937 to Nov. 1939	5.1			0	8	G
		Before waterproofing	0.05	0.05	.1	2	100	P
		Bldg. Chem. Corp. No. 2	.7	16 ±5		0	35	F
		*Sept. 1936 to Sept. 1937	4 ±1	15 ±6		0	60	F
		*Nov. 1937 to Nov. 1939	0.07	0.07	.07		85	P

* Lower case letters denote kind of masonry units in facing and backing.

First numeral denotes nominal wall thickness in inches.

Capital letters denote type of workmanship.

Final number denotes kind of mortar.

^b Weathering exposure periods preceded by an asterisk indicate that wall was metal covered on back, top and sides during exposure.

* Data not determined.

^d Duration of test exposure less than 24 hours.

* Wall not flashed at bottom.

5. PERFORMANCE RATINGS

The permeability test is a more severe exposure than the natural wind and rain storms to which most building walls may be subjected. Nearly all information of a practical value on the permeability of masonry test walls may therefore be obtained during an exposure period of 1 day in the test chamber. However, to determine possible slight changes in permeability, produced by outdoor exposure, the tests on some of the less permeable specimens have been continued for 5 days. The arbitrary ratings of wall performance given below are similar, except for some slight revision, to those given in report BMS7, page 12, and are based on the assumption that visible water, extensive damp areas on the back, or leakage through a wall would damage plaster applied directly to the back of a wall or would injure the finished interior of a building.

WALL PERFORMANCE RATINGS

Excellent (E):

No visible water on back of wall in 1 day.
Not more than 25 percent of wall area damp in 5 days. No leaks ⁵ through either the wall or the facing wythe in 5 days.

Good (G):

No visible water in 1 day. Less than 50 percent of the wall area damp in 1 day. No leaks ⁶ through either the wall or the facing wythe in 1 day.

Fair (F):

Visible water on back of wall in not less than 3 or more than 24 hours. Total leakage rate (both flashings) less than 1 liter/hr in 1 day.

⁵ Leaks are defined as follows: A leak is a flow of water from either flashing having a rate of flow equal to or greater than 0.05 liter/hr. Water ponded on a flashing having no flow is not considered a leak.

⁶ See footnote 5.

Poor (P):

Visible water on back of wall in 3 hr or less. Total leakage rate not more than 5 liters/hr in 1 day.

Very Poor (VP):

Total leakage rate greater than 5 liters/hr in 1 day.

IV. EFFECTS OF THE OUTDOOR EXPOSURE

1. STRUCTURAL CONDITION OF THE WALLS AFTER EXPOSURE

(a) All-Brick Masonry Walls, Not Waterproofed

The walls were inspected when they were brought indoors to be tested, and the effects of weathering were noted. Although all of the mortar pargings were crazed, the effects of weathering were most apparent in the top pargings and in the top courses of the walls. It was observed that face joints that had been tooled were eroded sufficiently to remove the film of cement and fines brought to the surface by the tooling iron, so that the joint surface was roughened, exposing particles of the sand contained in the mortar. The joint structure of very few walls was damaged or cracked, but the top pargings on many were so badly cracked as to become loose or spalled. Structural damage to the walls or pargings probably resulted from the freezing of water absorbed by the brick or accumulated in the joints between the pargings and the masonry. The most severe structural failures in the masonry were characterized by an upward heaving of the top courses of brick with extensive horizontal cracking in the bed joints, and, in some cases, by spalling of the faces of the brick and their adjacent mortar joints.

A measure of the resistance to damage by weathering of a group of 48 all-brick walls is given in table 5. The data show the general structural condition of the walls before the final permeability test and also give a measure of the

relative resistances of the different kinds of brick and of mortars to weathering. Neither the thickness of the walls (8 or 12 in.) or the kind of workmanship used appeared to have a significant effect on their structural condition. The arbitrary ratings of structural condition are given in table 5.

TABLE 5.—*Structural condition, after outdoor exposure, of 48 all-brick walls 8 or 12 inches thick*

Kind of brick in facing	Rating of structural condition ¹	Number of walls of—					Total number of walls, all mortars
		Mortar 1	Mortar 2	Mortar 3	Mortar 4	Mortar 5	
a.....	A.....	2	6	1	2	0	11
	B.....	1	1	2	1	1	6
	C.....	0	0	0	0	0	0
b.....	A.....	2	3	1	1	0	7
	B.....	0	1	2	0	0	3
	C.....	0	0	0	0	0	0
c.....	A.....	2	5	0	1	3	11
	B.....	0	2	1	0	1	4
	C.....	1	0	3	2	0	6

¹ The ratings of structural condition are arbitrary and are defined as follows:

Rating A: Pargings crazed only, none loose. No cracks in mortar joints.

Rating B: Portions of pargings are loose or spalled. No cracks in mortar joints.

Rating C: Mortar joints in masonry cracked, loose or spalled.

The joint structure of the masonry in all walls containing the low- or medium-absorptive bricks (bricks *a* and *b*, table 5) was undamaged. The mortar joints in only 3 of 17 walls built of brick *c* with mortars 1, 2, 4, or 5 were cracked or spalled, whereas the joints in 3 of 4 walls built of these brick with mortar 3 were damaged.

The pargings applied to the ends and tops of 16 of 21 of the walls built of brick *a* or *b* and mortars 1, 2, 4, or 5 were crazed, but not badly damaged, whereas those in 4 of 6 walls built of these brick with mortar 3 were loose or spalled. Although the condition of the pargings had little or no effect on the permeability of the walls, it is indicated (table 5) from the appearance of the walls and pargings that mortars containing not more than an equal proportion of lime hydrate to portland cement were more resistant to weathering than was the low-cement mortar 3.



FIGURE 2.—Top portion of wall 33-cc12A3 after 3 years' outdoor exposure.

The walls rated *C* in table 5 are listed below, those sustaining the greatest damage being given first:

Wall No.	Designation
33	cc12A3
21	cc12B3
20	cc8A3
40	cc8A4
43	cc12A4
94	cc12A1

The upper facing portion of wall 33 (worse damaged) is shown in figure 2. The bed joints in both faces of the top three courses of this wall were badly cracked, and there were several spalled brick and head joints in the rear facing. The bed joint under the top course of wall 21 was severely cracked and spalled in both faces. Damage sustained by walls 20, 40, 43, and 94 was comparatively small. In walls 20 and 40 a few isolated brick were spalled with cracking or spalling in the adjacent mortar joints and in

the pargings. The top parging on wall 43 was loose, and there were about 6 small vertical cracks in the upper two bed joints. Damage to the face of wall 94 was limited to about 10 small vertical cracks in the bed joints of the upper 3 courses. These cracks usually occurred near the end of a stretcher brick. There were no spalled brick or horizontal cracks in the bed joints, and the head joints appeared to be undamaged.

Since the interior of the joints in five of the six walls rated *C* in table 5 were solidly filled with mortar (workmanship *A*) and since the brick were more absorptive than the mortars, it is probable that the primary cause of damage to the joints was the expansion of the brick produced by the freezing of absorbed water.

The bricks for the walls were selected to provide a wide range in absorptive properties without regard to their probable resistance to weathering. Brick *c* was chosen as one type because of the high rate of absorption and relatively high total absorption, and was sold by



FIGURE 3.—Stucco-faced wall 3-sj9A2, with tile on end, after 2 years' outdoor exposure.

the manufacturer with the understanding that they were not suitable for exposed masonry. Moreover, investigations ⁷ indicate that a poor resistance to frost action would be expected for brick *c* because of the high saturation coefficient (C/B ratio 0.89—table 1, BMS7) and the low compressive strength (2,370 lb/in.²). Conversely, from the data in table 1 of BMS7, bricks *a* and *b* can be classified as frost resistant.

Although there is no definite explanation for the damage to the parings and mortar joints in walls containing the high-lime mortar 3, the comparatively low tensile and compressive strength of mortar 3, as compared to mortars

1, 2, 4, and 5 (see table 1), may have been the reason for the relatively low resistance of this mortar to damage from the weathering exposure. The absorptive properties of the mortars may also have had some effect on relative durabilities.

With the exception of one or two of the walls built with brick *c*, there was no important structural damage sustained by the walls listed in table 5.

(b) Other Masonry Walls, Not Waterproofed


All nine of the brick-faced walls with hollow-unit backings were built with brick *b* and mortar 2. The parings in only one or two of these

⁷ J. W. McBurney, Proc. Am. Soc. Testing Materials 35, pt. 1, p. 247 (1935).

3

FIGURE 4.—Upper portion of wall 3 after 2 years' outdoor exposure.

Cracks about one-fourth actual size.



walls were loose or spalled, and the mortar joints in all of them were intact. The cinder-concrete block used in the backing of some of these walls were somewhat damaged by popping over small isolated areas.

The 4-in. brick walls with parged backings built of brick *c* were damaged by horizontal cracks in the top bed joints. These cracks were extensive and usually extended completely through the pargings and the bed joints. It is probable that the thin section of these walls was vulnerable to sudden changes in temperature

which produced a quick freezing of the absorbed or trapped water with consequent cracking of the bed joints and pargings.

The stucco facings in all of the tile-backed stucco-faced walls were crazed and the facings in some of them were badly cracked, as can be seen from figures 3, 4, and 5. It was not determined if large cracks in the stucco facings coincided, in location, with mortar joints in the tile backing or if they were caused by possible differential movements in the backing. The tile appeared to be in good condition after exposure,



FIGURE 5.—*Upper portion of wall 8-sj9A2 after 3 years' outdoor exposure.*

Stucco-faced wall with tile on side. Cracks about one-fourth actual size.

and there was no loose or spalled stucco in the facings.

(c) *Waterproofed Masonry Walls*

Since the waterproofing gave some protection to the faces of the treated walls and since most of these walls were also protected with metal coverings, the weathering exposure produced very little structural damage to either the parings or the masonry. The discussion of the structural effects of weathering on the treated walls will therefore be confined to a few state-

ments on the general condition or appearance of the waterproofed surfaces.

The color of walls treated with waxes or solutions containing paraffin and tung oil was darkened, but it is significant that none of the high-absorptive brick *c* in these walls were spalled or damaged.

Mortar joints treated with grouting materials or joints that had been repointed appeared to be in good structural condition, except that one proprietary material, Rocktite, applied as a relatively thick grout coating to the face joints



FIGURE 6.—Oil paint film on wall A10-bb8B2, after 3 years' outdoor exposure.

Wall was reported before painting.

of wall 88, was badly eroded, exposing the original mortar surface.

The oil paint applied to wall A10-bb8B2 was in fair condition after 3 years' outdoor exposure. This wall had been repointed before painting, and the paint film over the joints was crazed and slightly peeled, as is shown in figure 6. This wall was tested once for permeability between the repointing and the painting treatments, and it is possible that the alkalinity of the repointed joints was not sufficiently neutralized before painting. There was considerable dusting in the paint film over the brick.

Walls 44-cc12B4, A12-m8A2, and A11-n8A2 were painted with a cement-water paint. After an exposure outdoors for 1 year, the paint film on wall 44 was badly crazed and was cracked away at 30 or 40 points along the upper and

lower edges of the stretcher brick. Two brick were badly spalled to a depth of one-half inch. After 3 years' outdoor exposure, the paint films on the concrete-block walls were crazed and dusting. There was no scaling of the paint film except in wall A11 where the cinder block had popped or spalled (see fig. 7).

After 3 years' outdoor exposure, the Rocktite grout coating over the brick facing of wall 34-cc8B2 was badly crazed and two brick were spalled, one to a depth of five-eighths inch. These brick were covered with mortar and a cement-water paint before the final test was made on the wall. Neither the cement-water paint or the Rocktite grout coating prevented severe spalling of some of the brick in walls containing the high-absorptive brick c.



FIGURE 7.—Cement-water paint film on cinder block wall A11-n8B2 after 3 years' outdoor exposure.

Note crazing of paint film. Dark vertical stains are from dirt washed off metal covering at top of wall.

2. PERMEABILITY OF THE PLAIN, NOT WATER-PROOFED WALLS

(a) *All-Brick and Brick-Faced Walls 8 or More Inches in Thickness*

The data (see table 3) showing the effects of outdoor exposure on the water permeability of all-brick walls 8 or 12 in. thick, and of brick-faced walls with hollow-unit backings, indicate no great change in the permeability of about two-thirds of them, a considerable decrease in the permeability of nearly one-quarter, and an increase in less than one-tenth. Only one wall that was visibly damaged (wall 33) showed a large increase in permeability. There was no significant change in the relative permeability, before and after outdoor exposure, resulting from differences in wall thickness, kind of

mortar, or in the kind of backing. The average permeability of walls containing frost-resistant bricks was slightly reduced. The rate of leakage through all of the highly permeable specimens was greatly reduced, and as a result the performance ratings of 3 in 13 of the Very Poor walls were bettered. The general effects of weathering on permeability are given in table 6, which contains the total number of walls faced with each kind of brick and the number of walls showing changes in permeability sufficient to raise or lower their performance ratings. The changes in permeability so indicated were considerable and are highly significant except where permeabilities of the walls were near the borderline between two performance classifications. Even so, the ratings of 13 walls were increased and those of only 5 were decreased.

TABLE 6.—*Effects of outdoor exposure on the permeability of 57 all-brick or brick-faced walls, 8 or 12 in. thick*

Kind of brick in facing	Number of walls			Total number of walls
	Performance rating unchanged	Performance rating increased (less permeable)	Performance rating decreased (more permeable)	
<i>a</i>	12	5	0	17
<i>b</i>	10	6	3	19
<i>c</i>	17	2	2	21
Total	39	13	5	57

Most of the walls faced with the low-absorptive brick *a* were less permeable after outdoor exposure than before. The performance ratings of none of these walls was reduced, whereas those of nearly 30 percent were raised. Previous observations on the effects of repeated permeability tests have indicated a slight but definite decrease in permeability, and it appears from the data (table 6) that the effects of weathering exposure did not prevent these walls from also becoming more resistant to penetration.

The relative performances, before and after outdoor exposure, of the walls faced with the medium-absorptive brick *b* were about the same as those of walls faced with brick *a*, except that the permeability ratings of two specimens were reduced from Good to Fair.

Although nearly 30 percent of the walls built with brick *c* had sustained some damage to the joint structure, the permeability of only 10 percent of the total number was greatly increased while that of another 10 percent showed a considerable decrease. The average permeability of this group of walls was practically unchanged.

(b) Four-Inch Brick Walls With Parged Backings

The permeability of all of the 4-in. brick walls with parged backings was greatly increased by the weathering exposure (table 3). Failure through these walls appeared much higher on the back than was the case for the Heavy Rain tests made before outdoor exposure, thus indicating a penetration through new cracks or openings at the top of the walls.

(c) Stucco-Faced Walls

The weathering exposure greatly reduced the time required for the penetration of moisture through the stucco-faced walls. The penetration of water in quantity sufficient to become visible on the backs of walls 6 and 8 reduced their performance ratings from Excellent to Fair or Poor. These walls were not flashed at the bottoms, and the bond between the supporting channel and the wall was broken in all except wall 2, so that no measurements could be made of the relative amounts of leakage through the faces occurring before and after exposure. The walls with tile backings laid on the side (walls 5, 6, 7, and 8) appeared to be affected more by the exposure than did the walls in which the tile cells were placed vertically, but this observation may have been influenced by the tendency for water entering hollow units with vertical cells to drop or run down the interior of the wall. There was no apparent advantage in favor of either the plain or water-proofed stucco facings, but walls with the smooth-finished facings (walls 1, 3, 5, and 7) appeared to be slightly less permeable after exposure than did the walls with rough surface textures, wood floated. This difference, however, was very small and may not be significant. In general, although the permeability of the stucco-faced walls was noticeably increased, the performance of these walls after exposure was about the same as that of 8-in. all-brick walls of workmanship A built of medium or low-absorptive bricks.

3. PERMEABILITY OF THE WATERPROOFED WALLS

The effectiveness of the waterproofings applied to the walls before they were exposed outdoors is discussed in section IX of BMS7. A measure of the durability, or effectiveness, of the waterproofing treatments, after weathering exposure, is obtained by comparing the permeabilities of the specimens before and after outdoor storage. Only brief references are made to the original effectiveness of the treatments, but in table 4 there is given complete data obtained from all the permeability tests that have been made before and after the treatments were

applied. In reviewing the data given in table 4, it should be remembered that the exposure periods preceded in the table with an asterisk indicate that the top, back, and sides of the walls were protected with sheet metal during the outdoor storage, thereby exposing only the treated faces to the weather.

(a) Walls Treated With Paraffin and Tung-Oil Solutions and Waxes

Paraffin and tung oil in a solution of mineral spirits was applied to both the brick and the mortar joints in the wall face, whereas a paraffin and tung-oil wax was usually applied only to the joints. Although the permeability of walls of workmanship *B* was greatly reduced by buttering the joints with wax, the effect was only temporary and the specimens were found to be highly permeable after an exposure outdoors of only 1 year (see table 4). Similarly, two or three applications of a paraffin and tung oil, applied to the high-absorptive brick facing of a wall of workmanship *B* with repointed joints, wall 37-cc12B2, was effective for at least 1 year, but some leakage through the wall was observed after an exposure of 3 years. The treatments reduced the rate of absorption and the amount of water absorbed by walls of low permeability, but they were either ineffective or of poor durability when used where they were most needed, on walls that leaked badly.

(b) Walls With Repointed Face Joints

Repointing and tooling of the face joints was found to be the most effective and durable method of sealing the joints in walls of workmanship *B*. Although the treatment stopped leaks through the joints, it was not successful on walls built with the high-absorptive bricks *c*, unless the brick were also treated. The permeability of most of the repointed walls, either with or without additional treatments, was found to have become progressively lower after successive periods of outdoor exposure, and the final test performance on half of them was rated Excellent.

(c) Walls With Grouted Face Joints

Grouting or filling interstices in the face joints with cementitious materials greatly re-

duced the permeability of walls of workmanship *B* built of the low- or the medium-absorptive bricks. Although most of the grouted walls were more permeable when tested after 3 years' outdoor exposure than they were before, the treatment was still highly effective and may be expected to have a satisfactory durability and to be economical, especially since the probable cost of grouting is considerably lower than that of repointing.

(d) Walls Painted With Oil or Cement-Water Paints

Both oil and cement-water paints were found to be highly effective waterproofings after 3 years of outdoor exposure, even though there was evidence of dusting and peeling or crazing of the paint films. Large openings in the facing joints of the brick walls 44 and A10 were filled by repointing before these walls were painted. The performance of wall 44, built of high-absorptive brick and painted with a cement-water paint, was rated Excellent. Although the paint film showed considerable deterioration, the waterproofing effect was not changed after an exposure period of 1 year. Since the concrete block walls (A11 and A12) were not flashed, it was not possible to measure the rate of leakage, if any, through the walls and thereby determine their performance ratings, but the available data indicate that the cement-water paints were still effective as waterproofings after 3 years of exposure. The back of wall A12, at the supporting channel, was dry or merely damp during the latter tests.

(e) Proprietary Waterproofing Materials

The grouting treatment of CAP 515, applied to the joints of wall 61-aa8B2 by the Building Chemicals Corporation, was still highly effective after 3 years' outdoor exposure, and there was no significant change in the permeability of the wall during that period. A grouting treatment of Roectite grout was applied thickly to the face joints of wall 88-aa8B2 by representatives of a waterproofing company. This grout was fairly effective but, after 3 years, the permeability of the wall was greatly increased. It would appear, therefore, that cementitious grouts applied as a

thick coating to the joints may be neither as effective nor as durable as relatively thin coatings whose primary purpose is to fill interstices between the mortar joints and the building units.

Wall 34-cc8B2 brushed with a grout containing Rocktite color coating was rated Excellent after an exposure of 1 year and was rated Good after an exposure of 3 years. There was no leakage through the wall, but two spalled brick were covered with a cement mortar and paint before the final test.

Walls 39 and 49 were also treated by the Building Chemicals Corporation (see pages 28 and 29 of BMS7). The permeability of wall 49-bb8A4, treated with paraffin and tung-oil solution and wax, was greatly increased after 3 years' exposure. The joints of wall 39-cc8B2 were filled with CAP 515 in addition to the paraffin and tung-oil treatments and the performance of this wall was rated Good after more than 3 years of outdoor exposure.

V. SUMMARY

These conclusions pertain to the effects of a 3-year period of outdoor exposure at Washington, D. C., on the structural appearance and the water permeability of a group of small masonry wall specimens.

The exposure did not have much effect on the permeability of all-brick or brick-faced walls 8 or 12 in. in thickness. The average permeability of walls built with the low- or with the medium-absorptive bricks was slightly but significantly reduced. This was true irrespective of the kind of mortar used. With the exception of one or two specimens (badly damaged by weathering), the average permeability of walls containing salmon brick was not greatly changed.

The joint structure or masonry in all-brick and in brick-faced walls, 8 or 12 in. thick, built of frost-resistant bricks, was not damaged by the exposure. The masonry in 30 percent of the walls containing salmon brick was damaged, and the damage was most severe in those walls which contained the lowest proportion of cement in the mortar.

The upper bed joints in brick walls, 4 in.

thick, with mortar pargings on the backs, were badly cracked. The cracks extended through the pargings, and the permeability of the walls was greatly increased.

The weathering exposure damaged the mortar pargings applied to the tops and ends of brick walls. Both end and top pargings were more or less crazed, and about 30 percent of the top pargings were cracked loose or spalled. Pargings that were made of mortar containing the lowest proportion of portland cement to lime (1:2:9 parts by volume of cement, hydrated lime, and loose damp sand) were more severely damaged than were those of the 1:1:6 or the 1:1/4:3 mortars.

Portland cement stucco, used as a facing on a structural clay tile backing, was cracked or badly crazed, but not loose or spalled from the backing. Although the permeability of the stucco-faced walls was significantly increased, the average performance, after exposure, was nearly the same as that of 8 in. brick walls built of low-absorptive brick with the joints filled with mortar.

Repointing of the face joints was both an effective and durable method of waterproofing when applied to brick walls of medium- or of low-absorptive brick. Nearly all of the repointed walls were less permeable after exposure than before.

Grouts containing portland cement and fine sand, thinly applied to the face joints of brick walls built of low- or of medium-absorptive brick, were effective as waterproofings after 3 years of exposure. The average permeability of the grouted walls was increased but their performances were still satisfactory.

A paraffin and tung-oil wax, applied to the face joints of brick walls that leaked badly, was ineffective as a waterproofing after an exposure of 1 year, at which time the specimens were highly permeable.

Although the paint films were visibly damaged, both oil and cement-water paints were still highly effective as waterproofings after exposure.

WASHINGTON, March 28, 1941.

○

BUILDING MATERIALS AND STRUCTURES REPORTS

On request, the Superintendent of Documents, U. S. Government Printing Office, Washington, D. C., will place your name on a special mailing list to receive notices of new reports in this series as soon as they are issued. There will be no charge for receiving such notices.

An alternative method is to deposit with the Superintendent of Documents the sum of \$5, with the request that the reports be sent to you as soon as issued, and that the cost thereof be charged against your deposit. This will provide for the mailing of the publications without delay. You will be notified when the amount of your deposit has become exhausted.

If 100 copies or more of any paper are ordered at one time, a discount of 25 percent is allowed.

Send all orders and remittances to the *Superintendent of Documents, U. S. Government Printing Office, Washington, D. C.*

The following publications in this series are available by purchase from the Superintendent of Documents at the prices indicated:

BMS1	Research on Building Materials and Structures for Use in Low-Cost Housing-----	10¢
BMS2	Methods of Determining the Structural Properties of Low-Cost House Constructions---	10¢
BMS3	Suitability of Fiber Insulating Lath as a Plaster Base-----	10¢
BMS4	Accelerated Aging of Fiber Building Boards-----	10¢
BMS5	Structural Properties of Six Masonry Wall Constructions-----	15¢
BMS6	Survey of Roofing Materials in the Southeastern States-----	15¢
BMS7	Water Permeability of Masonry Walls-----	10¢
BMS8	Methods of Investigation of Surface Treatment for Corrosion Protection of Steel-----	10¢
BMS9	Structural Properties of the Insulated Steel Construction Co.'s "Frameless-Steel" Constructions for Walls, Partitions, Floors, and Roofs-----	10¢
BMS10	Structural Properties of One of the "Keystone Beam Steel Floor" Constructions Spon- sored by the H. H. Robertson Co.-----	10¢
BMS11	Structural Properties of the Curren Fabrihome Corporation's "Fabrihome" Construc- tions for Walls and Partitions-----	10¢
BMS12	Structural Properties of "Steelox" Constructions for Walls, Partitions, Floors, and Roofs Sponsored by Steel Buildings, Inc.-----	15¢
BMS13	Properties of Some Fiber Building Boards of Current Manufacture-----	10¢
BMS14	Indentation and Recovery of Low-Cost Floor Coverings-----	10¢
BMS15	Structural Properties of "Wheeling Long-Span Steel Floor" Construction Sponsored by the Wheeling Corrugating Co.-----	10¢
BMS16	Structural Properties of a "Tilecrete" Floor Construction Sponsored by Tilecrete Floors, Inc.-----	10¢
BMS17	Sound Insulation of Wall and Floor Constructions-----	10¢
	Sound Insulation of Wall and Floor Constructions (Supplement to Report BMS17)---	5¢
BMS18	Structural Properties of "Pre-Fab" Constructions for Walls, Partitions, and Floors Sponsored by the Harnischfeger Corporation-----	10¢
BMS19	Preparation and Revision of Building Codes-----	15¢
BMS20	Structural Properties of "Twachtman" Constructions for Walls and Floors Sponsored by Connecticut Pre-Cast Buildings Corporation-----	10¢
BMS21	Structural Properties of a Concrete-Block Cavity-Wall Construction Sponsored by the National Concrete Masonry Association-----	10¢
BMS22	Structural Properties of "Dun-Ti-Stone" Wall Construction Sponsored by the W. E. Dunn Manufacturing Co.-----	10¢
BMS23	Structural Properties of a Brick, Cavity-Wall Construction Sponsored by the Brick Manufacturers Association of New York, Inc.-----	10¢
BMS24	Structural Properties of a Reinforced-Brick Wall Construction and a Brick-Tile Cavity- Wall Construction Sponsored by the Structural Clay Products Institute-----	10¢
BMS25	Structural Properties of Conventional Wood-Frame Constructions for Walls, Partitions, Floors, and Roofs-----	15¢
BMS26	Structural Properties of "Nelson Pre-Cast Concrete Foundation" Wall Construction Sponsored by the Nelson Cement Stone Co., Inc.-----	10¢
BMS27	Structural Properties of "Bender Steel Home" Wall Construction Sponsored by The Bender Body Co.-----	10¢
BMS28	Backflow Prevention in Over-Rim Water Supplies-----	10¢
BMS29	Survey of Roofing Materials in the Northeastern States-----	10¢

[List continued on cover page iv]

BUILDING MATERIALS AND STRUCTURES REPORTS

[Continued from cover page III]

BMS30	Structural Properties of a Wood-Frame Wall Construction Sponsored by the Douglas Fir Plywood Association.....	10¢
BMS31	Structural Properties of "Insulite" Wall and "Insulite" Partition Constructions Sponsored by The Insulite Co.....	15¢
BMS32	Structural Properties of Two Brick-Concrete-Block Wall Constructions and a Concrete-Block Wall Construction Sponsored by the National Concrete Masonry Association.....	10¢
BMS33	Plastic Calking Materials.....	10¢
BMS34	Performance Test of Floor Coverings for Use in Low-Cost Housing: Part 1.....	10¢
BMS35	Stability of Sheathing Papers as Determined by Accelerated Aging.....	10¢
BMS36	Structural Properties of Wood-Frame Wall, Partition, Floor, and Roof Constructions with "Red Stripe" Lath Sponsored by the Western Paper and Manufacturing Co.....	10¢
BMS37	Structural Properties of "Palisade Homes" Constructions for Walls, Partitions, and Floors, Sponsored by Palisade Homes.....	10¢
BMS38	Structural Properties of Two "Dunstone" Wall Constructions Sponsored by the W. E. Dunn Manufacturing Co.....	10¢
BMS39	Structural Properties of a Wall Construction of "Pfeifer Units" Sponsored by the Wisconsin Units Co.....	10¢
BMS40	Structural Properties of a Wall Construction of "Knap Concrete Wall Units" Sponsored by Knap America, Inc.....	10¢
BMS41	Effect of Heating and Cooling on the Permeability of Masonry Walls.....	10¢
BMS42	Structural Properties of Wood-Frame Wall and Partition Constructions With "Celotex" Insulating Boards Sponsored by the Celotex Corporation.....	10¢
BMS43	Performance Test of Floor Coverings for Use in Low-Cost Housing: Part 2.....	10¢
BMS44	Surface Treatment of Steel Prior to Painting.....	10¢
BMS45	Air Infiltration Through Windows.....	10¢
BMS46	Structural Properties of "Scot-Bilt" Prefabricated Sheet-Steel Constructions for Walls, Floors, and Roofs Sponsored by The Globe-Wernicke Co.....	10¢
BMS47	Structural Properties of Prefabricated Wood-Frame Constructions for Walls, Partitions, and Floors Sponsored by American Houses, Inc.....	10¢
BMS48	Structural Properties of "Precision-Built" Frame Wall and Partition Constructions Sponsored by the Homasote Co.....	10¢
BMS49	Metallic Roofing for Low-Cost House Construction.....	10¢
BMS50	Stability of Fiber Building Boards as Determined by Accelerated Aging.....	10¢
BMS51	Structural Properties of "Tilecrete Type A" Floor Construction Sponsored by the Tilecrete Corporation.....	10¢
BMS52	Effect of Ceiling Insulation Upon Summer Comfort.....	10¢
BMS53	Structural Properties of a Masonry Wall Construction of "Munlock Dry Wall Brick," Sponsored by the Munlock Engineering Co.....	10¢
BMS54	Effect of Soot on the Rating of an Oil-Fired Heating Boiler.....	10¢
BMS55	Effects of Wetting and Drying on the Permeability of Masonry Walls.....	10¢
BMS56	A Survey of Humidities in Residences.....	10¢
BMS57	Roofing in the United States—Results of a Questionnaire.....	10¢
BMS58	Strength of Soft-Soldered Joints in Copper Tubing.....	10¢
BMS59	Properties of Adhesives for Floor Coverings.....	10¢
BMS60	Strength, Absorption, and Resistance to Laboratory Freezing and Thawing of Building Bricks Produced in the United States.....	15¢
BMS61	Structural Properties of Two Nonreinforced Monolithic Concrete Wall Constructions.....	10¢
BMS62	Structural Properties of a Precast Joist Concrete Floor Construction Sponsored by the Portland Cement Association.....	10¢
BMS63	Moisture Condensation in Building Walls.....	10¢
BMS64	Solar Heating of Various Surfaces.....	10¢
BMS65	Methods of Estimating Loads in Plumbing Systems.....	10¢
BMS66	Plumbing Manual.....	20¢
BMS67	Structural Properties of "Mu-Steel" Prefabricated Sheet-Steel Constructions for Walls, Partitions, Floors, and Roofs Sponsored by Herman A. Mugler.....	15¢
BMS68	Performance Test of Floor Coverings for Use in Low-Cost Housing: Part 3.....	15¢
BMS69	Stability of Fiber Sheathing Boards as Determined by Accelerated Aging.....	10¢
BMS70	Asphalt-Prepared Roll Roofings and Shingles.....	15¢
BMS71	Fire Tests of Wood- and Metal-Framed Partitions.....	20¢
BMS72	"Precision-Built Jr." Prefabricated Wood-Frame Wall Construction Sponsored by the Homasote Co.....	10¢
BMS73	Indentation Characteristics of Floor Coverings.....	10¢
BMS74	Structural and Heat-Transfer Properties of "U. S. S. Panelbilt" Prefabricated Sheet-Steel Constructions for Walls, Partitions, and Roofs Sponsored by the Tennessee Coal, Iron & Railroad Co.....	15¢
BMS75	Survey of Roofing Materials in the North Central States.....	15¢
BMS76	Effect of Outdoor Exposure on the Water Permeability of Masonry Walls.....	15¢