



A11104 190297

NIST
PUBLICATIONS



United States Department of Commerce
Technology Administration
National Institute of Standards and Technology

NISTIR 5016

NIST MODEL PM2 POWER MEASUREMENT SYSTEM FOR 1 mW AT 1 GHz

F.R. Clague

~~QC~~

100

.U56

#5016

1993



NISTIR 5016

NIST MODEL PM2 POWER MEASUREMENT SYSTEM FOR 1 mW AT 1 GHz


F.R. Clague

Electromagnetic Fields Division
Electronics and Electrical Engineering Laboratory
National Institute of Standards and Technology
Boulder, Colorado 80303-3328

December 1993



U.S. DEPARTMENT OF COMMERCE, Ronald H. Brown, Secretary
TECHNOLOGY ADMINISTRATION, Mary L. Good, Under Secretary for Technology
NATIONAL INSTITUTE OF STANDARDS AND TECHNOLOGY, Arati Prabhakar, Director



CONTENTS

1. INTRODUCTION	1
2. OPERATION	2
2.1 Initial Steps, Hardware	2
2.2 Software Installation	3
2.3 Measurement Software and Procedure	4
2.3.1 Select Measurement Mount	6
2.3.2 Input Wavetek Serial Number	10
2.3.3 Change Number of Measurement Points	11
2.3.4 Wavetek Operating Instructions	11
2.3.5 Begin Measurement	12
3. SYSTEM DESCRIPTION	17
3.1 Theory of Operation	17
3.2 Hardware	18
3.3 Software	22
4. UNCERTAINTY ANALYSIS	23
4.1 Voltmeter Uncertainty	23
4.2 Uncertainty in Thermistor Mount Effective Efficiency	25
4.3 Mismatch Uncertainty	25
4.4 Dual-Element Error	26
4.5 Random Effects	26
4.6 Expanded Uncertainty	26
5. REFERENCES	27
APPENDIX A. Software Menu Tree	28
APPENDIX B. Instrument Specifications	29
APPENDIX C. Software Listing	30

TRADE NAME DISCLAIMER

Certain commercial components used in the measurement system are identified in this document in order clearly to instruct the operator in the use of the system. The instructions refer to specific models of specific instruments, and to their controls to ensure that there are no ambiguities. Such use and identification does not imply recommendation or endorsement by NIST, nor does it imply that the identified items are necessarily the best available for the purpose.

NIST MODEL PM2 POWER MEASUREMENT SYSTEM FOR 1 mW AT 1 GHz

Fred R. Clague

National Institute of Standards and Technology
Boulder, Colorado 80303

The design and operation of an automated measurement system designed to measure power accurately at the level of 1 mW and at the frequency of 1 GHz are described. The system consists of commercial IEEE Std-488 bus-controlled instruments, a computer controller, and software. The results of a series of measurements are output to the computer display and, optionally, to a printer. The results are the mean of the measurement series and an estimate of the Type A (here random) and Type B (here systematic) uncertainty. The estimated total expanded uncertainty for the average of six consecutive measurements of a nominal 1 mW, 1 GHz source is typically less than 1 percent. The system can measure any power from 0.1 to 10 mW at any microwave frequency by making appropriate changes to the software and, possibly, the hardware.

Key words: automated measurement; microwave; microwave power measurement; power; power measurement; power measurement system.

1. INTRODUCTION

This system is designed to accurately measure microwave power at the level of 1 mW and the frequency of 1 GHz. Specifically, it supports the calibration of the Wavetek 8502A pulse power meter, which has a 1 mW, 1 GHz calibrator output port. The manufacturer's specification on the power output accuracy is ± 1.5 percent. Use of the system is not restricted to this specific application; relatively simple modifications to the software would make it possible to measure other power levels and frequencies.

The microwave power measurement method is based on the dc substitution technique. The system is implemented using a commercial version of the NIST-developed Type IV microwave power meter, a commercial coaxial thermistor mount, a digital voltmeter (DVM), and a dedicated computer controller. The Type IV power meter is not direct reading; the substituted dc power is calculated using readings obtained from the DVM. The computer controls the measurement process, calculates the results, and prints them out. Measurement results include an estimate of uncertainty for each data set. Automation also allows use of a procedure that adequately corrects for drift of the thermistor mount caused by external temperature changes. The system is packaged in a single operating case with a storage drawer containing all necessary cables, two thermistor mounts, system software, and the operating manuals.

2. OPERATION

2.1 Initial Steps, Hardware

1. Connect the supplied ac power cables to the DVM and power meter.
2. Connect the supplied IEEE 488 bus cable to the power measurement system and the IEEE 488 bus card in the PC.
3. Connect the thermistor mount to the Type IV power meter. The end of the cable with the single connector goes to the thermistor mount, while the connector marked with an "A" goes to "Channel A" on the power meter and the unmarked connector goes to "Channel B."
4. Depress the input selector switch on the DVM to connect the rear panel input.
5. Turn on all the instruments. The output of the Wavetek 8502A calibrator is more stable after a 2-h warmup, rather than the 30 min specified by the manual. The 2-h warmup period is recommended for both the 8502A and the power measurement system. Also, the thermistor mount should be attached to the calibrator output for at least 30 min before making the measurement. This will reduce the temperature drift of the mount, improving the measurement accuracy. Be sure to note the serial number of the mount selected.

2.2 Software Installation

The software includes an installation program that will create a directory and copy all needed files to the hard drive. The drive must have at least 1 MB of free space and TransEra HTBasic 3.0 or higher already installed.

1. Turn on the power to the computer and allow DOS to load. At the DOS prompt, type `CD\HTB386` (or other directory where the BASIC system is located) and press ENTER. Then type `HTB386C` and again press ENTER. At this point HTBasic should be loaded as indicated by the BASIC soft keys appearing at the bottom of the screen.
2. Insert the disk labeled PM2 MEASUREMENT SYSTEM in the 3.5-in drive and type `LOAD "drive:INSTALL",1` where `drive` is the name of the drive where the PM2 MEASUREMENT SYSTEM disk is located; for example, `LOAD "B:INSTALL",1` and press ENTER. Be sure to type the quotation marks as shown.
3. The first screen lists the software and computer requirements and asks if you want to continue. Type `Y` and press ENTER to continue or `N` and press ENTER to terminate the installation.
4. The name of the source drive (drive from which the files are copied) is requested; press ENTER to accept the default (`B:`) or type another drive letter and press ENTER.
5. The destination drive (drive to which the files are copied) is requested; press ENTER to accept the default (`C:\`) or enter another drive. Note: the installation program will create its own directory named `NIST_PM2` on the destination drive.
6. The location of the BASIC system files is requested: press ENTER to accept the default (`C:\HTB386`) or enter another drive and directory. Then the directory `NIST_PM2` is created, and the program and support files copied.
7. The program asks if you want to use the supplied AUTOST program. It will activate the IEEE 488 bus card and the system printer, and then load and run the measurement program. The AUTOST program includes code lines as described below. Type `Y` and press ENTER to use the supplied AUTOST.

8. Finally you will be asked if the PC has the Morse KP 800/16 VGA graphics adapter, and the if the 800x600 display mode is desired. Type `Y` and press `ENTER` to use the 800x600 display mode.
9. This completes the software installation. Type `QUIT` and press `ENTER` to leave HTBasic and then, if you have HTBasic version 3.0, reboot the computer (this is necessary to avoid an out-of-memory error that may occur when you try to run the program).

The supplied AUTOST program is a modified version of the example supplied with HTBasic. The following lines in the example program have been changed:

```
310 !LOAD BIN "GPIBN;BOARD AT-GPIB" ! NATIONAL INST
```

is un-commented (! removed) to read:

```
310 LOAD BIN "GPIBN;BOARD AT-GPIB" ! NATIONAL INST
```

```
730 LOAD "DEMO",1
```

is commented out (! added) to read:

```
730 !LOAD "DEMO",1
```

If the your PC is configured differently than the one on which the prototype system was tested, additional or different changes may be required.

2.3 Measurement Software and Procedure

To run the program follow the directions for starting HTBasic under item 1 in the previous section. If the supplied AUTOST has been installed, the measurement program will load and run automatically. Otherwise, type `LOAD "PWR_MTR2", 1` and press `ENTER` to load and start the program. If the power meter or the DVM is not turned on, the program will report it can not find the power meter at address 713 or the DVM at address 722. Pressing `ENTER` after each statement will let the program run, but measurements can not be made.

The remainder of this section describes the various software options that are available. The screens and menus as seen on the CRT are shown in figures 2.1 through 2.9. Numbered soft keys, corresponding to the keyboard function keys, are along the bottom of the menus. For quick reference, a menu tree is shown in appendix A.

The first screen displayed by the program is shown in figure 2.1. Additional detail on each item is in later sections of this chapter.

Press F1 to change the thermistor mount to be used in the measurement, or the stored data (such as after a thermistor mount recalibration). The serial number of the selected mount is shown.

Press F2 to enter the serial number of the Wavetek 8502A being measured. The serial number is then displayed and printed with the measurement result.

Press F3 to change the number of repeated measurements to be averaged in a set (at least 6 to 10 is recommended). The present setting is shown.

Press F4 to see instructions on how to operate the Wavetek 8502A (turn the calibrator output on and off).

Press F5 to begin the measurement set.

Press F10 to exit the program.




Figure 2.1. Screen display of the measurement menu.

2.3.1 Select Measurement Mount

Figure 2.2 shows the screen after selecting option 1 from the previous menu. Two bolometer mounts are supplied with each system. The calibration data (as listed in the NIST report of calibration) for both mounts is stored in a file called "CALDATA" that is read when the program is started.

Press F1 or F2 to select the active mount.




Figure 2.2. Screen display of the mount selection menu.

Press F3 in the Mount Selection Menu (figure 2.2) to change any entries in the CALDATA file (for a new mount or for the existing mounts if they have been recalibrated).

Figure 2.3 shows the screen that appears after pressing F3. You can change any of the four data entries (mount serial number, calibration factor, calibration uncertainty, or the mount reflection coefficient) in sequence. If there is no change for a particular entry, just press ENTER, and the original data will be retained. At each request for input you can abort the process and return to the mount selection menu. When all the changes have been entered, you are asked if you want to permanently save them to the CALDATA file and if the data is for mount 1 or mount 2.




Figure 2.3. Screen display for changing stored calibration data.

Figure 2.4 is the last of the series of screens that appear after pressing F3 in the Mount Selection Menu. It asks for a path and file name for saving the mount data. Note: the name must be "CALDATA" for the file to load automatically when the program is started.




Figure 2.4. Screen display for saving the CALDATA file.

Press F4 in the Mount Selection Menu (figure 2.2) to load or save a CALDATA file.

The menu changes as seen in figure 2.5. If "S" is entered, the data presently in memory for the two mounts will be stored in CALDATA. Again, there is an opportunity to change the path or file name before it is saved, as the screen shown in figure 2.4 is repeated.




Figure 2.5. Mount selections screen after choosing the fourth item.

If for some reason it is necessary to restore the original calibration data, the initial calibration reports are included with the system, and the data could be re-entered. As an added precaution, a backup version of the original CALDATA file, called "CALDATA.ORG", is on the distribution disk. It can be loaded by pressing F4 in the Mount Selection Menu (figure 2.2), entering the "L" for load, and then the file name as shown in figure 2.6.




Figure 2.6. Mount selection screen when loading a CALDATA file.

2.3.2 Input Wavetek Serial Number

Pressing F2 in the Measurement Menu (figure 2.1) will let you input the serial number of the Wavetek power meter being calibrated. The serial number will then be printed on the measurement report as part of the permanent record.

2.3.3 Change Number of Measurement Points

Pressing F3 in the Measurement Menu (figure 2.1) will let you change the number of repeated measurements made during the calibration. No less than the default six measurements should be made; more than six will slightly reduce the total uncertainty because of a smaller standard uncertainty with additional repeat measurements.

2.3.4 Wavetek Operating Instructions

Pressing F4 in the Measurement Menu (figure 2.1) results in the screen that appears in figure 2.7. It gives brief instructions for manually controlling the 8502A calibrator output based on information given in the instrument's operating manual. The four numbered steps shown on the screen should be carried out before proceeding with the measurement. Press F10 to return to the main menu.




Figure 2.7. Screen display of operating instructions for the calibrator output.

2.3.5 Begin Measurement

Pressing F5 in the Measurement Menu (figure 2.1) leads to the screen that appears in figure 2.8. (Before starting the measurement, check the mount serial number to be sure the mount in use is the one shown on the screen.) Just before the message TURN RF ON (PRESS 8502A KEY '7') is displayed, the computer will beep once. At that point press key 7 on the 8502A to turn the rf on and wait for a pair of beeps from the computer. The message will change to TURN RF OFF (PRESS 8502A 'CLEAR'). After pressing the CLEAR key on the 8502A, wait until a single beep sounds again before pressing key 7 to begin the next measurement in the set. This sequence will be automatically repeated until all the measurements making up the set have been completed. As indicated, the measurement series can be aborted by pressing the ESCAPE key.




Figure 2.8. Screen display at the start of the measurement.

When the desired number of measurements is complete, the screen shown in figure 2.9 is displayed. The upper half of the screen shows a summary of each measurement in the set as explained in table 2.1 below. The final results are displayed on the lower half of the screen below the horizontal dashed line. The explanation of each column is given in table 2.2.

Press F1 to dump this screen to the system printer. A more detailed report is also available and can be printed or sent to a file, as explained in the paragraph following table 2.2.

PWR_MTR 2.0		MEASUREMENT COMPLETE				
MOUNT: Hp 8478B, S/N 2106A 24522				11:49:16 18 Nov 1993		
POWER METER: WAUETEK MODEL 8502A, S/N PM20PGU						
No.	Power (mW)	Pwr-1 mW (%)	U1 (U)	Delta U (mU)	U1 Drift (uU/s)	Ref. Offset (mU)
1	0.99390	-0.610	2.249627	44.290	1.4	-2.429
2	0.99474	-0.526	2.249636	44.328	0.7	-2.429
3	0.99459	-0.541	2.249644	44.320	0.3	-2.428
4	0.99427	-0.573	2.249646	44.306	0.1	-2.428
5	0.99461	-0.539	2.249649	44.321	0.5	-2.427
6	0.99424	-0.576	2.249650	44.304	0.3	-2.425

RESULTS:						
	AUG PWR (mW)	AUG-1 mW (%)	MAX DEV (%)	STD DEV (%)	W/C UNC (%)	EXP UNC (%)
	0.99439	-0.561	+0.036, -0.049	0.013	0.835	0.558

1	DUMP SCREEN	2	PRINT REPORT	3	REPORT TO FILE	4
6		7		8		9
					0	MAIN MENU

Figure 2.9. Screen display of the measurement results.

Table 2.1. Explanation of the upper part of the measurement screen	
Column Heading	Explanation
No.	Number of the power measurement.
Power	Result of the individual power measurement in mW.
Pwr - 1 mW	Normalized deviation of the measured power from 1 mW, percent.
V1	Power meter voltage with the rf off (see section 3.1).
Delta V	Change that occurs in the power meter voltage when the rf is turned on.
V1 Drift	Drift of V_1 in $\mu\text{V/s}$ that occurred from the beginning of the measurement until it was complete. Note that if the drift is greater than 10 $\mu\text{V/s}$ the measurement should be repeated after waiting a period of time for the mount temperature to further stabilize.
Ref. Offset	The compensation element channel is used as the voltage reference; this column shows the voltage difference between the measurement thermistor channel and the compensation thermistor channel when the rf is off.

Table 2.2. Explanation of the results section of the measurement screen	
Column Heading	Explanation
AVG PWR	Average power in mW, computed from the measured data set.
AVG - 1mW	Percent deviation of the average power level from 1 mW.
MAX DEV	The maximum positive and negative deviations from the average.
STD DEV	The standard deviation of the mean.
W/C UNC	Worst-case uncertainty; the total uncertainty in the measurement when all components are simply added.
EXP UNC	Expanded uncertainty; the RSS combination of all uncertainty components multiplied by a coverage factor (k) of two. For a discussion of standard and expanded uncertainty see section 4 and reference [1].

Press F3 in the measurement results screen (figure 2.9) to print a copy of the detailed measurement report which can be used as a permanent record. Press F4 to save the report to a DOS text file that can be imported into a word processor. This report, which is not displayed on the CRT, shows the individual measurements, summarizes the results, and lists the uncertainty components. Figure 2.10 is an example of the report.

The top section of the report essentially duplicates what was shown in the results screen of figure 2.9.

The lower section of the report contains a table listing the uncertainties in the measurement. Each uncertainty component discussed in section 4 is shown, followed by a pair of values. The uncertainty limits column contains values which can be considered the traditional systematic and random components that are added to give the worst case sum. The standard uncertainty column contains the values needed for the method of expressing uncertainty in measurement recommended by the CIPM (International Committee for Weights and Measures) and required by NIST [1]. The final expanded uncertainty is twice the square root of the sum of the squares (RSS) of the standard uncertainties. Section 4 and reference [1] (also listed in the report) give more detail. The two columns make available a choice of uncertainty expression and uncertainty components to meet the user's requirement.

MEASUREMENT DATA

FOR POWER METER: WAVETEK MODEL 8502A, S/N PM20PGV

USING MOUNT: Hp 8478B, S/N 2106A 24522

11:49:16 18 Nov 1993

	Power (mW)	Pwr-1 mW (%)	V1 (V)	Delta V (mV)	V1 Drift (μ V/s)	Ref. Offset (mV)
1	0.99390	-0.610	2.249627	44.848	1.4	-2.429
2	0.99474	-0.526	2.249636	44.328	0.7	-2.429
3	0.99459	-0.541	2.249644	44.320	0.3	-2.428
4	0.99427	-0.573	2.249646	44.306	0.1	-2.428
5	0.99461	-0.539	2.249649	44.321	0.5	-2.427
6	0.99424	-0.576	2.249650	44.304	0.3	-2.425

MEASUREMENT RESULTS

The mean of the 6 measurements is 0.99439 mW with 0.008 percent standard deviation of the mean. The maximum deviation from the mean is +0.036 and -0.049 percent. The mean is 0.561 percent less than 1 mW.

The table below shows the values of the major uncertainty components. The total uncertainty is expressed as both the worst case sum and the expanded uncertainty. For a discussion of standard and expanded uncertainty see NIST Technical Note 1297, "Guidelines for Evaluating and Expressing the Uncertainty of NIST Measurement Results."

Value of uncertainty components in percent at 1 GHz.		
Uncertainty factor	Uncertainty limits	Standard uncertainty
DVM	0.033	0.080
Mount calibration factor	0.350	0.202
Mismatch (mount reflection coefficient = 0.0101)	0.113	0.080
Dual element	0.300	0.173
Random effects (standard deviation of the mean)	0.039	0.080
Worst case sum	0.835	
Combined standard uncertainty (RSS)		0.279
Expanded uncertainty (coverage factor = 2)		0.558

Figure 2.10. Sample of the hardcopy output.

3. SYSTEM DESCRIPTION

3.1 Theory of Operation

The NIST Type IV power meter is not a direct reading instrument. An external precision dc voltmeter must be connected to the power meter, and the power calculated from the voltmeter readings. For this system, the microwave power P is given by

$$P = \frac{1}{K_b R_0} (V_1^2 - V_2^2), \quad (3.1)$$

where V_1 is the output voltage without rf power, V_2 is the voltage with rf power, R_0 is the operating resistance of the mount, and K_b is the mount calibration factor. Note that the power is proportional to the "bolometric power," which is simply the change of the mount dc bias power as rf power is applied and removed.

Equation (3.1) shows that, as the rf power becomes small, V_2 approaches V_1 . Because of the uncertainty "magnification" that occurs in the computed difference of two nearly equal numbers, the power measurement uncertainty becomes very large as the power decreases. The solution to this problem is to measure the difference between V_1 and V_2 directly. This requires a reference voltage generator (RVG) which is set nominally equal to V_1 and, in effect, stores V_1 .

When an RVG is used, the expression for calculating power from measured voltages becomes

$$P = \frac{1}{K_b R_0} (2V_1 - \Delta V) \Delta V, \quad (3.2)$$

where V_1 , R_0 , and K_b were previously defined, and ΔV is the change in the power meter voltage when rf is applied; that is, $V_1 - V_2$. In providing for a first-order correction of mount drift, the value of V_1 and ΔV are estimated by assuming linear drift and taking several other readings while the rf is off, as shown in figure 3.1.

The diagram in figure 3.1 depicts the outputs of the power meter and RVG as a function of time while the rf is cycled on and off. The measurement sequence of five voltage and time readings used to calculate the power and correct for the mount drift is also shown. Note that the reference voltage generator is not set equal to V_1 , nor is it constant with time. This is because it is convenient to use the compensation element of the mount, biased by the second power meter channel, as the reference voltage generator. Thus the RVG does drift




Figure 3.1. Measured power meter voltages vs time.

during the measurement, but this change is also corrected, to first order, by the measurement series.

In terms of the measured voltages, the values to be used in eq (3.2) are given by

$$V_1 = V_{1i} + \left(\frac{t_3 - t_1}{t_5 - t_1} \right) (V_{1f} - V_{1i}) \quad (3.3)$$

and

$$\Delta V = V_{2X} - \left[V_{1Xi} + \left(\frac{t_3 - t_2}{t_4 - t_2} \right) (V_{1Xf} - V_{1Xi}) \right]. \quad (3.4)$$

3.2 Hardware

The system block diagram is shown in figure 3.2. The input switching to the digital voltmeter (DVM) is done with the multiplexer internal to the DVM. The controller is user supplied. The generic specifications for the instruments are given in appendix B.




Figure 3.2. System block diagram.

The internal wiring of the thermistor mount as received from the factory is shown in figure 3.3.




Figure 3.3. Original mount wiring.

Figure 3.4 shows the internal wiring diagram of the thermistor mount as modified for this application. The mount bias connector is replaced and internal wiring changes are made. These changes provide four-wire connections to the measurement and compensation thermistors, which eliminate lead and connector contact resistance errors. Only the modified mounts can be used with the system.




Figure 3.4. Modified mount wiring.

Figure 3.5 is a diagram showing the physical layout of the pc board in the mount with the attachment points for the wires leading to the connector and the thermistor elements.




Figure 3.5. HP 8478B thermistor mount pc board layout with modified wiring.

Figure 3.6 is the wiring diagram for the cable that connects the mount to the power meter.




Figure 3.6. Thermistor mount connecting cable wiring diagram.

Figure 3.7 is a view of the cable end of the connector showing the pin-out. The specific connectors used are listed in Table 3.1.




Figure 3.7. Connector pin-out (Male cable connector as seen from cable end).

Table 3.1. Connectors		
Connector designation	Connector model NO.	Manufacturer
Connectors A, B, C	FGG.2B.310.CNAD72Z	Lemo USA INC P.O. Box 11488 Santa Rosa, CA 95406
Connector D	EHG.2B.310.CNL	

3.3 Software

A software listing is included as appendix C. Comments at the beginning of the code define the variables (and their location) that one might want to change for other applications such as a different power level. However, if changes are made, the user is responsible for the results. NIST cannot support modified code.

4. UNCERTAINTY ANALYSIS

The uncertainties associated with the measurement are grouped in two categories according to the method used to estimate their numerical values [1]. The Type A evaluations of standard uncertainty are based on statistical analysis of measurement results. The Type B evaluations of standard uncertainty are based on other methods, such as manufacturer's instrument specifications, measurement results, and scientific judgement. The standard uncertainties obtained by either the Type A or the Type B evaluations are the equivalent of a standard deviation.

The factors listed below contribute to the total measurement uncertainty and are included in the analysis. The standard uncertainty for each component is determined by either a Type A or a Type B evaluation as appropriate.

1. Uncertainty in the dc voltage measurements.
2. Uncertainty in the thermistor mount effective efficiency calibration.
3. Mismatch uncertainty due to the source (8502A calibrator output) reflection coefficient and the thermistor mount reflection coefficient.
4. The "dual element substitution error" associated with the coaxial thermistor mount.
5. Random effects.
6. Type IV power meter uncertainty. There are four sources of possible error internal to the power meter. They are the reference resistors, the operational amplifier open loop gain, input offset voltages, and input bias currents. The Type IV error analysis [2] indicates that all of them are negligible compared to the four factors listed above.

The first five of these items are considered individually in the following sections. An example of the results is summarized in a concluding table.

4.1 Voltmeter Uncertainty

The effect of uncertainty in the individual voltmeter readings can be determined by taking the total differential of the expression for power, eq (3.2),

$$dP = \frac{2}{K_b R_0} [\Delta V dV_1 + (V_1 - \Delta V) d\Delta V]. \quad (4.1)$$

Let

$$T_{1f} \equiv \frac{t_3 - t_1}{t_5 - t_1} \quad (4.2)$$

and

$$T_{2f} \equiv \frac{t_3 - t_2}{t_4 - t_2}. \quad (4.3)$$

Thus, in terms of the measured parameters,

$$dV_1 = (1 - T_{1f}) \delta V_{1i} + T_{1f} \delta V_{1f} \quad (4.4)$$

and

$$d\Delta V = \delta V_{2X} + (1 - T_{2f}) \delta V_{1Xi} - T_{2f} \delta V_{1Xf}. \quad (4.5)$$

The quantities δV_{1i} , δV_{1f} , δV_{1Xi} , δV_{1Xf} , and δV_{2X} , are the uncertainties in the measured values of V_{1i} , V_{1f} , V_{1Xi} , V_{1Xf} , and V_{2X} . These uncertainties in the measured voltages are based on the voltmeter specifications, which are usually given in two parts as a fraction of reading term, α , and a fraction of full scale term β . The general expression for the voltmeter uncertainty is given by

$$\delta V = \alpha V_{reading} + \beta V_{fullscale}. \quad (4.6)$$

Figure 4.1 shows the uncertainty in power measurement as a function of power level near 1 mW, as calculated using the above procedure for the voltmeter, power meter, and measurement configuration used in this system. In the calculations, the signs of the independent terms are chosen to give the maximum contribution to the total uncertainty. This uncertainty is obtained from a Type B evaluation and has a rectangular distribution.




Figure 4.1. Power measurement uncertainty from the DVM.

4.2 Uncertainty in Thermistor Mount Effective Efficiency

This is the uncertainty of the NIST thermistor mount calibration. The NIST calibration also gives a value for the mount calibration factor C_f , which is the factor used in this measurement rather than effective efficiency alone. It is defined in the next section. The values listed on the report of calibration will, of course, be constant for any given mount, until the unit is periodically recalibrated. This uncertainty is based on a Type B evaluation and has a rectangular distribution.

4.3 Mismatch Uncertainty

The net power delivered to a termination by a source is given by

$$P_t = P_0 \frac{1 - |\Gamma_t|^2}{|1 - \Gamma_g \Gamma_t|^2}, \quad (4.7)$$

where P_0 is the power the source would deliver to a nonreflecting termination, Γ_g is the generator reflection coefficient, and Γ_t is the termination reflection coefficient. Ideally, the calibrator should deliver a net power of 1 mW to the power detector being calibrated, but that can be accomplished only if the complex reflection coefficients of the power detector, generator, and calibrating thermistor mount are known, which is generally not the case. Assuming, then, that the calibrator output specification is the power delivered to a nonreflecting load P_0 , the measured output is given by

$$P_0 = \frac{P_m}{\eta_m} \frac{|1 - \Gamma_g \Gamma_m|^2}{1 - |\Gamma_m|^2}, \quad (4.8)$$

where P_m is the bolometrically measured power, η_m is the effective efficiency of the thermistor mount, Γ_g is the generator reflection coefficient, and Γ_m is the thermistor mount reflection coefficient. The denominator of eq (4.8) is the mount calibration factor

$$C_f = \eta_m (1 - |\Gamma_m|^2), \quad (4.9)$$

so eq (4.8) becomes

$$P_0 = \frac{P_m}{C_f} |1 - \Gamma_g \Gamma_m|^2. \quad (4.10)$$

The value of Γ_m has been measured during the NIST calibration, but only an upper limit to the magnitude of Γ_g is known (from the source return loss specification). Only the limits to the term involving the reflection coefficients are known. Thus,

$$(1 - |\Gamma_g||\Gamma_m|)^2 \leq |1 - \Gamma_g \Gamma_m|^2 \leq (1 + |\Gamma_g||\Gamma_m|)^2, \quad (4.11)$$

so P_0 is also only known within the limits

$$\frac{P_m}{C_f} (1 - |\Gamma_g||\Gamma_m|)^2 \leq P_0 \leq \frac{P_m}{C_f} (1 + |\Gamma_g||\Gamma_m|)^2. \quad (4.12)$$

This uncertainty in P_o is the mismatch uncertainty and its relative value is given to first order by

$$\pm 2 |\Gamma_g| |\Gamma_m|. \quad (4.13)$$

The return loss specification on the calibrator output is greater than 25 dB, which results in a value for $|\Gamma_g|$ of ≤ 0.056 . Since value of $|\Gamma_m|$ is different for each thermistor mount, the mismatch uncertainty is calculated for each. This uncertainty is based on a Type B evaluation and has a U-shaped distribution [3].

4.4 Dual-Element Error

The power detector is a dual-element coaxial thermistor mount. Dual-element bolometer units are nonlinear with power level as a result of a dc-rf substitution error that arises because the two elements are not identical [4]. The magnitude of the error is different for each mount. The error is of concern because the measurement is being made at 1 mW, while the NIST calibration of mount efficiency is done at 10 mW. The only way to determine the error magnitude is by direct measurement, which is difficult at best.

Several methods were tried, but all had one or more deficiencies in giving a completely accurate, self-consistent determination. The problem is the effect is comparable to the noise, especially at 1 mW. However, the different methods did give results in general, if not exact agreement. The results reported here are from measurements on 20 mounts using a six-port reflectometer calibrated at 10 mW. The effective efficiency of each mount was measured at 10 mW and again at 1 mW without disconnecting the mount.

The differences between the effective efficiencies at the two powers for the sample of 20 mounts is used to make inferences about the differences of the entire population (80 mounts). A normal probability plot indicated the data can be considered normal. The two-sided tolerance interval [5] for the differences is [-0.00269, 0.00305]. This interval should include 99 percent of the population with 95 percent confidence. Making the interval symmetric about 0 [-0.003, 0.003] will still include at least 99 percent of the population with 95 percent confidence. This uncertainty is based on a Type B evaluation and is assumed to have a rectangular distribution.

4.5 Random Effects

The measurement is repeated a minimum of six times. The standard deviation of the mean of the measurement set is the uncertainty component. This uncertainty is based on a Type A evaluation and has a normal distribution.

4.6 Expanded Uncertainty

Table 4.1 shows how the contribution of each uncertainty component is converted to a standard uncertainty. Again, definitions for the variables and terms used are found in reference [1]. The numbers in the table come from the sample measurement detailed in section 2. The components

used in the worst case total shown in figure 2.10 are the values from the half-width interval column except for the random effects. The value of the random component for the worst case total is three times the standard deviation of the mean.


Table 4.1. Value of uncertainty components in percent					
Uncertainty factor	Evaluation type	Half-width interval (<i>a</i>)	Distribution	Conversion formula	Standard uncertainty
DVM and power meter	B	0.034	Rectangular	$u_j = a/\sqrt{3}$	0.020
Mount calibration	B	0.380	Rectangular	$u_j = a/\sqrt{3}$	0.219
Mismatch	B	0.195	U-shaped	$u_j = a/\sqrt{2}$	0.138
Dual-element	B	0.300	Rectangular	$u_j = a/\sqrt{3}$	0.173
Random effects	B	-	Normal	-	0.008
Combined standard uncertainty (RSS)					0.312
Expanded uncertainty ($k = 2$)					0.626

5. REFERENCES

- [1] Taylor, B.N.; Kuyatt, C.E. Guidelines for evaluating and expressing the uncertainty of NIST measurement results. Natl. Inst. Stand. Technol. Tech. Note 1297; 1993 January. 15 p.
- [2] Larsen, N.T. A new self-balancing dc-substitution rf power meter. IEEE Trans. Instrum. Meas. IM-25: 343-347; 1976 December.
- [3] Harris, I. A.; Warner, F.L. Re-examination of mismatch uncertainty when measuring microwave power and attenuation. IEE Proc. 128, Pt. H, No.1: 35-41; 1981 February.
- [4] Engen, G.F. A dc-rf substitution error in dual-element bolometer mounts. IEEE Trans. Instrum. Meas. IM-13: 58-64; 1964 June-September
- [5] Hahn, G.S.; Meeker, W.Q. Statistical intervals: a guide for practitioners. New York, NY: John Wiley & Sons; 1991, 58-59.

APPENDIX A. Software Menu Tree

The numbered entries are menu soft-key labels where the numbers correspond to function keys, except for 0 which is function key 10 (F10).



APPENDIX B. Instrument Specifications

1. Digital voltmeter: 5½ digit resolution; 3 V dc range with 0.007 percent of reading and 0.0007 percent of full scale accuracy; 300 mV dc range with 0.012 percent of reading and 0.001 percent of full scale accuracy; IEEE Std-488 bus; optional integrated reed relay multiplexer.
2. Multiplexer: integrated with the DVM (or separate unit); minimum six single-pole, single-throw contacts; maximum thermal offset of 3 μ V; IEEE Std-488 bus.
3. Dual NIST Type IV power meter (or two single units).
4. Coaxial thermistor mount: type N male connector; temperature compensation thermistors; dc bias power \approx 30 mW; maximum $|\Gamma| < 0.025$; NIST calibration at 1 GHz; modified for a 4-wire connection to both the measurement thermistors and the compensation thermistors.
5. Computer controller: programmable in Hewlett Packard Work Station Basic version 5.13 ("Rocky Mountain Basic"), or TransEra "HTBasic" with IEEE Std-488 capability; IEEE Std-488 bus.

APPENDIX C. Software Listing

```

100 ! NIST-PM2 Power Measurement System Version 2.0
110 File$="PWR_MTR2" ! Started:9001111632/FRC
120 Rev$="9312171312" ! NTL/FRC/PGV
130 !
140 RE-STORE "PWR_MTR2"
150 !!!
160 ! US DEPARTMENT OF COMMERCE
170 ! NATIONAL INSTITUTE OF STANDARDS AND TECHNOLOGY
180 ! MICROWAVE METROLOGY GROUP
190 ! 325 BROADWAY
200 ! BOULDER, CO 80303-3328
210 !!!
220 ! NOTES:
230 ! 9311151100 - Added Escape key support (setup, update). PGV
240 ! 9311110930 - Added keyboard & knob(mouse) trapping in RF and MEAS sub's
250 ! 9310251015 - Added error trapping for PM & DVM now works under HTB 3.2
260 ! 9310220905 - Load or Save 'CALDATA' file under setup menu
270 ! 9310220825 - Automatic backup of CALDATA file.
280 ! - Loads new CALDATA file (must be bdat).
290 ! 9310211400 - Now fully functional under HTBasic 4.0
300 ! 9310201740 - Added print report to DOS ASCII file (hardcopy)
310 ! 9309301445 - Now supports bdat file CALDATA. This file stores the
320 ! calibration data for the two measurement mounts used with this system
330 ! (PM2). This file must be in the current directory during program.
340 ! execution.
350 ! 9308260845 - Cleaned up code and squashed bugs.
360 ! 9308201530 - Print measurement results in text/table format to PRT on
370 ! parallel port (#10).
380 ! 9308170735 - Modified for use with Epson FX-86e/FX-800 compatible
390 ! printer (e. g., Panasonic KX-P1180 9-pin printer). May work with an
400 ! Epson LQ printer (untested). Screen resolutions of 640x480 or
410 ! 800x600 are sensed automatically. PGV
420 ! Written with HTBasic 3.2 ;PGV
430 !
440 ! This program attempts to load the following data file upon execution:
450 ! CALDATA
460 !
470 ! Errors, Select_v, Dvm_init, Pm_init, Ke_199 defined for use with:
480 ! Keithley 199 DMM/Scanner
490 ! Arbiter 1096A Dual Type IV Power Meter
500 !
510 ! This program measures the 1 mW calibrator output of the Wavetek
520 ! model 8501A peak power meter.
530 !
540 ! This version measures V1 and delta V with the compensation element
550 ! used as a voltage source (RVG) to offset the DVM. It also calculates
560 ! the measurement uncertainty.
570 !
580 ! Total measurement uncertainty components include:
590 ! Mount calibration factor,
600 ! Calculated mismatch uncertainty for the source ( $|\Gamma| \leq 0.056$ )
610 ! and the mount,
620 ! Dual element uncertainty,
630 ! The DVM and Type IV error contributions.
640 !
650 ! INSTRUMENTS CONTROLLED: ADDRESS
660 ! 1. Keithley 199 DMM/Scanner 722
670 ! 2. Epson FX compatible printer 10 (PRT)
680 ! 3. Arbiter 1096A Type IV PM 713
690 !
700 ! DESCRIPTION OF PRINCIPAL VARIABLES IN LABELED COMMON:
710 !
720 ! - - - - -
730 ! The following are in the COMMON labeled "/Dvm/":
740 !
750 ! ** "Dvm_name$" - The DVM identifier (ie, K199)
760 !
770 ! * "P0" - Power level in milliwatts. The measurement results are
780 ! compared with this value. Default setting is 1 mW.
790 !
800 ! * "R0" - Mount operating resistance in ohms. It is normally 200
810 ! ohms for a coax mount and may be either 100 or 200 ohms
820 ! for a waveguide mount. Default setting is 200 ohms.
830 !
840 ! * "A1-A5" - Fraction of reading error, for each DVM range
850 !
860 ! * "B1-B5" - Fraction of full scale error, for each DVM range
870 !
880 ! * "R1-R5" - Full scale DVM ranges available
890 !
900 ! - - - - -
910 ! The following are in the COMMON labeled "/Mount/":
920 !
930 ! ++ "Mount$" -.Bolometer mount identifier for active mount
940 ! (manufacturer, model, and serial number).
950 !
960 ! ++ "Cf" - Mount calibration factor as measured by NIST. This value
970 ! must be changed after mount replacement or recalibration.
980 !
990 ! - - - - -
1000 ! The following are in the COMMON labeled "/Errs/":
1010 !
1020 ! ++ "Cfu" - Total quoted uncertainty of the NIST mount calibration
1030 ! factor.
1040 !
1050 ! * "Mmu" - Calculated mismatch uncertainty.
1060 !
1070 ! * "Deu" - Added uncertainty for dual-element error.
1080 !
1090 ! * "Dp" - Power uncertainty due to DVM.
1100 !
1110 ! ++ "Gm" - Mount reflection coefficient magnitude.
1120 !
1130 ! - - - - -
1140 ! The following is in the COMMON labeled "/Wavetek/":
1150 !

```

```

1160 ! "Sn$" - records the serial number of the Wavetek meter
1170 ! being measured. It can be input before the measure-
1180 ! ment from an item on the initial menu.
1190 !
1200 ! -----
1210 !
1220 ! CHANGING INITIAL VALUE OF VARIABLES
1230 !
1240 ! * These variables are initially defined in the subprogram "Set_up".
1250 ! To change them, move to the subprogram by executing "EDIT
1260 ! Set_up". Change the values as needed and "Re-store" the program
1270 ! if the changes are to be permanent.
1280 !
1290 ! ++ These variables are stored in the bdat file CALDATA and are
1300 ! called from the subprogram "Set_up". To change them from the
1310 ! main menu, choose option 1 (Select measurement mount). From
1320 ! the setup menu choose option 3 (Change attributes) and follow
1330 ! the prompts to change and save the data to the file CALDATA.
1340 !
1350 ! ** Dvm_name$ is defined in the subprogram "Ke_199". If a different
1360 ! DVM is used, the subprogram Ke_199 must be replaced by a similar
1370 ! module for the new DVM. Follow the pattern of SUB Ke_199. The
1380 ! corresponding CALL statement must also be changed. The SUB
1390 ! Dvm_init contains the DVM driver, which must be changed.
1400 ! program. Use the manufacturer's specifications for the new DVM.
1410 !
1420 ! ----- MAIN PROGRAM -----
1430 !
1440 Main: !
1450 OPTION BASE 1
1460 COM /Dvm/P0,R0,A1,A2,A3,A4,A5,B1,B2,B3,B4,B5,R1,R2,R3,R4,R5
1470 COM /Dvm/Dvm_name${40} ! DVM ID
1480 COM /Errs/Dp,V1c,V1i,V1f,V1xi,V1xf,V1x,V2x,T1fac,T2fac,Cfu,Mmu,Deu,Dpu
1490 COM /Errs/Gm,Scfu,Smmu,Sdeu,Sdpu,Wc_unc,Cs_unc,Ex_unc
1500 COM /Mount/Mount${40},Cf,Defm ! Mount ID
1510 COM /Wavetek/Sn${7} ! Wavetek serial number
1520 COM /Hardcopy/Tdate${40} ! Time and date of measurement
1530 COM /Harddata/Pdata(100,7),Pres(7,1) ! Measurement data and results
1540 COM /Caldata/Mount1${40},Mount2${40},Cf1,Cf1,Gm1,Cf2,Cfu2,Gm2
1550 COM /Init/Pm_avail,Dvm_avail ! Power Meter/DVM availability
1560 REAL P(100,1) ! Power measurement data
1570 Num_meas=6 ! Default no. of measurements (<=100)
1580 Pm_avail=1 ! Power meter available if =1, else, 0
1590 Dvm_avail=1 ! DVM available if =1, else, 0
1600 RESET 7 ! Reset GPIB
1610 CONTROL 2,1;0 ! Turn PRT ALL off
1620 KBD CMODE ON ! Turn on Nimitz style softkeys
1630 Sys_prt=VAL(SYSTEM$( "SYSTEM PRIORITY" )) ! Determine system priority
1640 Lcl_prt=Sys_prt+1 ! Set local priority higher for ON KEY
1650 ON INTR 7,Lcl_prt CALL Pm_init ! If power meter error (for SRQ)
1660 GINIT
1670 PLOTTER IS CRT,"INTERNAL";COLOR MAP
1680 PRINTER IS CRT ! Make CRT output device
1690 Crt_id$=SYSTEM$( "CRT ID" ) ! Determine the no. of CRT columns
1700 KEY LABELS PEN 5 ! Cyan
1710 KBD LINE PEN 4 ! Yellow
1720 CALL Set_up(0) ! For mount & measurement parameters
1730 CALL Pm_init ! Arbiter 1096A initialization
1740 CALL Ke_199 ! Get DVM parameters
1750 CALL Dvm_init ! Keithly 199 initialization
1760 Top: LOOP
1770 CALL Menu1(Num_meas,Quit,Rev$) ! First user menu
1780 IF Quit THEN GOTO Quit ! Terminate
1790 REDIM P(Num_meas,1) ! Redimension
1800 CALL Hdr ! Screen header
1810 CALL Measloop(Num_meas,P(*),Esc) ! Start Measurement loop
1820 IF Esc=1 THEN Top
1830 CALL Errors ! Calculate errors
1840 CALL Stats(P(*)) ! Calculate the statistics of the run
1850 CALL Menu2(Num_meas,P0) ! Post print options
1860 END LOOP
1870 Quit: CLEAR SCREEN ! Have a nice day! :- )
1880 KEY LABELS ON
1890 END
1900 !
1910 ! ----- S U B P R O G R A M S -----
1920 !
1930 Set_up: SUB Set_up(Cp) ! Initialize mount parameters.
1940 ! Cp=0 Load default mount spec's
1950 ! Cp=1 User Select mount spec's
1960 OPTION BASE 1
1970 COM /Dvm/P0,R0,A1,A2,A3,A4,A5,B1,B2,B3,B4,B5,R1,R2,R3,R4,R5
1980 COM /Dvm/Dvm_name${40} ! DVM ID
1990 COM /Errs/Dp,V1c,V1i,V1f,V1xi,V1xf,V1x,V2x,T1fac,T2fac,Cfu,Mmu,Deu,Dpu
2000 COM /Errs/Gm,Scfu,Smmu,Sdeu,Sdpu,Wc_unc,Cs_unc,Ex_unc
2010 COM /Caldata/Mount1${40},Mount2${40},Cf1,Cf1,Gm1,Cf2,Cfu2,Gm2
2020 COM /Mount/Mount${40},Cf,Defm ! Mount ID
2030 Execution: IF Cp=0 THEN
2040 CALL Mount_data(1,"CALDATA") ! Read mount data from file CALDATA
2050 IF Defm=0 THEN GOSUB Mount1 ! Make mount one the default mount
2060 IF Defm=1 THEN GOSUB Mount2 ! Make mount two the default mount
2070 Deu=.30 ! Uncertainty for dual element error
2080 R0=200 ! Mount operating resistance in ohms
2090 P0=1.0 ! Comparison power in mW. Note that
2100 ! the following line limits this set-
2110 ! ting to a 0.1 mW resolution.
2120 P0=DROUND(P0,2) ! Limit P0 to 1 place beyond decimal
2130 END IF
2140 User: IF Cp=1 THEN ! User enters mount data
2150 Sys_prt=VAL(SYSTEM$( "SYSTEM PRIORITY" )) ! Determine system priority
2160 Lcl_prt=Sys_prt+1 ! Set local priority higher for ON KEY
2170 M_flag=1 ! To write menu
2180 USER 1 KEYS ! 1st set of soft keys
2190 FOR N=0 TO 19 ! Clear keys
2200 ON KEY N LABEL "" GOTO Top ! Default destination
2210 NEXT N
2220 ON KEY 0 LABEL " MOUNT ONE ",Lcl_prt GOSUB Mount1
2230 ON KEY 1 LABEL " MOUNT TWO ",Lcl_prt GOSUB Mount2
2240 ON KEY 2 LABEL " CUSTOM MOUNT ",Lcl_prt GOSUB Custom

```

```

2250 ON KEY 3 LABEL " LOAD or SAVE ",Lcl_prty GOSUB Caldata_io
2260 ON KEY 9 LABEL " MAIN MENU ",Lcl_prty GOSUB Nochange
2270 Top: LOOP ! Wait for input
2280 IF M_flag=1 THEN GOSUB Menu
2290 END LOOP
2300 Menu: CLEAR SCREEN
2310 STATUS 1,13;Rows ! Get CRT height
2320 KEY LABELS ON
2330 PEN 6
2340 IF Rows>31 THEN CLIP 15,85,35,87 ! 800x600 displays
2350 IF Rows<31 THEN CLIP 20,102,22,80 ! 640x480 displays
2360 FRAME
2370 PRINT TABXY(21,8),CHR$(136)&"- - MOUNT SELECTION MENU - -"&CHR$(138)
2380 PRINT TABXY(20,10),CHR$(129)&" 1 "&CHR$(128)&" "&Mount1$
2390 PRINT TABXY(20,12),CHR$(129)&" 2 "&CHR$(128)&" "&Mount2$
2400 PRINT TABXY(20,14),CHR$(129)&" 3 "&CHR$(128)&" Custom Mount or Change Attributes"
2410 PRINT TABXY(20,16),CHR$(129)&" 4 "&CHR$(128)&" Load/Save CALDATA File"
2420 PRINT TABXY(20,18),CHR$(129)&" 0 "&CHR$(128)&" Main Menu"
2430 PRINT TABXY(15,20),CHR$(137)&"Current Selection is "&Mount$
2440 PRINT TABXY(15,21),"Calibration Factor = ";Cf
2450 PRINT TABXY(15,22),"Calibration Uncertainty = ";Cfu
2460 PRINT TABXY(15,23),"Reflection Coefficient = ";Gm;CHR$(138)
2470 M_flag=0
2480 RETURN
2490 Mount1: Mount$=Mount1$ ! Mount 1
2500 Cf=Cf1 ! Mount calibration factor
2510 Cfu=Cfu1 ! Mount calibration uncertainty in %
2520 Gm=Gm1 ! Mount reflection coefficient
2530 Mmu=200*.056*Gm ! Mismatch factor uncertainty in %
2540 ! Generator refl. coeff. <=0.056
2550 Defm=0 ! Remember mount selection
2560 M_flag=1
2570 RETURN
2580 Mount2: Mount$=Mount2$ ! Mount 2
2590 Cf=Cf2 ! Mount calibration factor
2600 Cfu=Cfu2 ! Mount calibration uncertainty in %
2610 Gm=Gm2 ! Mount reflection coefficient
2620 Mmu=200*.056*Gm ! Mismatch factor uncertainty in %
2630 ! Generator refl. coeff. <=0.056
2640 Defm=1 ! Remember mount selection
2650 M_flag=1
2660 RETURN
2670 Custom: KEY LABELS OFF ! Custom mount data or change value
2680 CLEAR SCREEN
2690 PRINT TABXY(10,10),"CURRENT MOUNT"
2700 PRINT TABXY(10,12),"Model/Serial Number: ",Mount$
2710 PRINT TABXY(10,14),"Calibration Factor = ";Cf
2720 PRINT TABXY(10,16),"Calibration Uncertainty in Percent = ";Cfu
2730 PRINT TABXY(10,18),"Reflection Coefficient = ";Gm
2740 OUTPUT 2;Mount$;CHR$(255)&"H";
2750 LINPUT "Enter Mount Model/Serial Number",Mount$
2760 PRINT TABXY(10,12),"Model/Serial Number: ";Mount$, "
2770 OUTPUT 2 USING "#,Z.DDDD";Cf
2780 INPUT "Enter Mount Calibration Factor",Cf
2790 PRINT TABXY(10,14),"Calibration Factor = ";Cf,CHR$(128)
2800 OUTPUT 2 USING "#,Z.DD";Cfu
2810 INPUT "Enter Calibration Uncertainty in Percent",Cfu
2820 PRINT TABXY(10,16),"Calibration Uncertainty in Percent = ";Cfu,CHR$(128)
2830 OUTPUT 2 USING "#,Z.DDDD";Gm
2840 INPUT "Enter Mount Reflection Coefficient = ",Gm
2850 Mmu=200*.056*Gm ! Recalculate mismatch factor uncert.
2860 PRINT TABXY(10,18),"Reflection Coefficient = ";Gm,CHR$(128)
2870 BEEP
2880 ON KNOB 1 GOSUB Mouse
2890 ON KBD GOSUB Keytest
2900 DISP CHR$(136)&"Permanently save these changes to BDAT file CALDATA? ("&CHR$(138)&"Y"&CHR$(136)&")es or
("&CHR$(138)&"N"&CHR$(136)&")o"
2910 LOOP
2920 Ans$=KBD$
2930 EXIT IF UPC$(Ans$)="Y" ! Yes
2940 EXIT IF UPC$(Ans$)="N" ! No
2950 EXIT IF Ans$=CHR$(27) ! Escape
2960 END LOOP
2970 OFF KBD
2980 OFF KNOB
2990 IF UPC$(Ans$)="Y" THEN CALL Update(0)
3000 M_flag=1 ! Reset menu flag
3010 RETURN
3020 Caldata_io: KEY LABELS OFF ! Load/Save CALDATA file
3030 DISP CHR$(136)&"("&CHR$(138)&"L"&CHR$(136)&")oad or ("&CHR$(138)&"S"&CHR$(136)&")ave 'CALDATA'. Press
"&CHR$(138)&"ESC"&CHR$(136)&" to abort."! Load or save data
3040 ON KNOB 1 GOSUB Mouse ! Mouse trap
3050 ON KBD GOSUB Keytest ! Trap keyboard
3060 LOOP
3070 K$=KBD$ ! Read KBD$ buffer
3080 EXIT IF UPC$(K$)="L" ! Load file
3090 EXIT IF UPC$(K$)="S" ! Save file
3100 EXIT IF K$=CHR$(27) ! Exit
3110 END LOOP
3120 Action: OFF KBD !
3130 OFF KNOB !
3140 IF K$=CHR$(27) THEN End action ! Exit
3150 IF UPC$(K$[1,1])="L" THEN ! Load
3160 CALL Update(1)
3170 IF Defm=0 THEN GOSUB Mount1! Make mount one the default mount
3180 IF Defm=1 THEN GOSUB Mount2! Make mount two the default mount
3190 END IF
3200 IF UPC$(K$[1,1])="S" THEN CALL Update(2) ! Save data
3210 End_action: KEY LABELS OFF ! Return to menu
3220 M_flag=1
3230 RETURN
3240 Mouse: RETURN ! Trap mouse [NO RODENTS]
3250 Keytest: RETURN ! Trap unused keys [DEAD KEYS]
3260 END IF
3270 Nochange: SUBEND ! Exit back to main menu
3280 !
3290 ! -----
3300 !
3310 Mount_data: SUB Mount_data(A,F$) ! Writes or reads mount cal data from

```

```

3320                                     ! file CALDATA or special filename
3330 OPTION BASE 1
3340 COM /Caldata/Mount1$(40),Mount2$(40),Cf1,Cfu1,Gm1,Cf2,Cfu2,Gm2
3350 DIM Cat$(40) (80)
3360 F$=UPCS(F$) ! Make string all uppercase
3370 IF A=0 THEN GOSUB Write_data
3380 IF A=1 THEN GOSUB Read_data
3390 SUBEXIT
3400 Write_data:
3410 IF F$="CALDATA" THEN ! Backup CALDATA only
3420 A=2
3430 ASSIGN @Path_1 TO F$&".BAK";RETURN Uncreated! Open file CALDATA.BAK
3440 ASSIGN @Path_1 TO * ! Close path
3450 IF NOT Uncreated THEN PURGE F$&".BAK" ! Purge file if found
3460 END IF
3470 ASSIGN @Path_1 TO F$;RETURN Uncreated ! Open file CALDATA
3480 ASSIGN @Path_1 TO * ! Close path
3490 IF A=2 AND NOT Uncreated THEN COPY F$ TO F$&".BAK" ! Backup CALDATA only
3500 IF NOT Uncreated THEN PURGE F$ ! Purge file if found
3510 IF F$<>"CALDATA" THEN A=3
3520 ON ERROR GOTO Cant_make
3530 CREATE BDAT F$,1 ! Create file CALDATA
3540 OFF ERROR
3550 ASSIGN @Path_1 TO F$ ! Open file CALDATA
3560 OUTPUT @Path_1;Mount1$ ! Mount one S/N
3570 OUTPUT @Path_1;Cf1 ! Mount calibration factor
3580 OUTPUT @Path_1;Gm1 ! Reflection coefficient magnitude
3590 OUTPUT @Path_1;Cfu1 ! Cal factor uncertainty in percentage
3600 OUTPUT @Path_1;Mount2$ ! Mount two serial number
3610 OUTPUT @Path_1;Cf2 ! Mount calibration factor
3620 OUTPUT @Path_1;Gm2 ! Reflection coefficient magnitude
3630 OUTPUT @Path_1;Cfu2 ! Cal factor uncertainty in percentage
3640 ASSIGN @Path_1 TO * ! Close path
3650 RETURN
3660 Read_data: ! Open file & read data
3670 IF F$<>"CALDATA" THEN A=3
3680 ASSIGN @F TO F$;RETURN Uncreated ! Open file CALDATA or user filename
3690 IF Uncreated THEN GOSUB No_file! If not found warn
3700 ENTER @F;Mount1$ ! Mount one serial number
3710 ENTER @F;Cf1 ! Mount calibration factor
3720 ENTER @F;Gm1 ! Reflection coefficient magnitude
3730 ENTER @F;Cfu1 ! Cal factor uncertainty in percentage
3740 ENTER @F;Mount2$ ! Mount two serial number
3750 ENTER @F;Cf2 ! Mount calibration factor
3760 ENTER @F;Gm2 ! Reflection coefficient magnitude
3770 ENTER @F;Cfu2 ! Cal factor uncertainty in percentage
3780 ASSIGN @F TO * ! Close file
3790 RETURN
3800 No_file: ! No file CALDATA found; warn user
3810 IF A=3 THEN Cant_make
3820 CLEAR SCREEN
3830 BEEP ! Beep Beep
3840 BEEP
3850 BEEP
3860 PRINT PEN 2
3870 PRINT TABXY(5,10),"Can not find BDAT file "&F$&".
3880 PRINT PEN 3
3890 PRINT TABXY(5,12),"The file 'CALDATA' is used to store the calibration data"
3900 PRINT TABXY(5,13),"for the measurement mounts and should be located in the same"
3910 PRINT TABXY(5,14),"directory as this program."
3920 ASSIGN @F TO * ! Close path
3930 LINPUT "Press ENTER to continue.",Fake$
3940 CLEAR SCREEN
3950 SUBEXIT
3960 RETURN
3970 Cant_make: ! Can not make file
3980 OFF ERROR
3990 BEEP
4000 LINPUT "ERROR - Filename or Directory not found. Press enter.",Fake$
4010 A=-1
4020 SUBEXIT
4030 SUBEND
4040 !
4050 ! -----
4060 !
4070 Update: SUB Update(Pv) ! Displays and updates bdatt file CALDATA
4080 OPTION BASE 1 ! with new info entered by user
4090 COM /Errs/Dp,V1c,V1i,V1f,V1xi,V1xf,V1x,V2x,T1fac,T2fac,Cfu,Mmu,Deu,Dpu
4100 COM /Errs/Gm,Scfu,Smmu,Sdeu,Sdpu,Wc_unc,Cs_unc,Ex_unc
4110 COM /Mount/Mount$(40),Cf,Defm ! Mount ID
4120 COM /Caldata/Mount1$(40),Mount2$(40),Cf1,Cfu1,Gm1,Cf2,Cfu2,Gm2
4130 STATUS 1,13;Rows ! Get screen rows
4140 CLEAR SCREEN
4150 IF Pv=0 THEN GOSUB Mount_1
4160 IF Pv=1 OR Pv=2 THEN
4170 A=1
4180 GOSUB Caldata_mem
4190 END IF
4200 SUBEXIT
4210 Mount 1: ! Display data for mount one
4220 PRINT PEN 1
4230 IF Jump=0 THEN PRINT TABXY(41,4),"Current data in file CALDATA"
4240 IF Jump=1 THEN PRINT TABXY(41,4)," Current/New data in memory "
4250 PRINT PEN 3
4260 IF A=1 AND Pv=0 THEN PRINT PEN 5
4270 PRINT TABXY(40,6),"MOUNT ONE" !
4280 PRINT TABXY(40,8),"S/N ";Mount1$ ! Serial number
4290 PRINT TABXY(40,9),"Cf=" ;Cf1 ! Calibration factor
4300 PRINT TABXY(40,10),"Cfu=" ;Cfu1 ! Calibration factor uncertainty in %
4310 PRINT TABXY(40,11),"Gm=" ;Gm1 ! Reflection coefficient
4320 PEN 6
4330 IF Rows>31 THEN CLIP 50,95,69,88 ! For 800x600 screen
4340 IF Rows<31 THEN CLIP 62,118,62,85 ! For 640x480 screen
4350 FRAME
4360 Mount 2: ! Display data for mount two
4370 PRINT PEN 3
4380 IF A=2 AND Pv=0 THEN PRINT PEN 5
4390 PRINT TABXY(40,15),"MOUNT TWO"
4400 PRINT TABXY(40,17),"S/N ";Mount2$ ! Serial number

```

```

4410 PRINT TABXY(40,18),"Cf= ";Cf2 ! Calibration factor
4420 PRINT TABXY(40,19),"Cfu= ";Cfu2 ! Calibration factor uncertainty in %
4430 PRINT TABXY(40,20),"Gm= ";Gm2 ! Reflection coefficient
4440 IF Rows>31 THEN CLIP 50,95,45,64 ! 800x600
4450 IF Rows<31 THEN CLIP 62,118,32,55 ! 640x480
4460 FRAME
4470 PEN 2
4480 IF Rows>31 THEN CLIP 49,96,44,89 ! 800x600
4490 IF Rows<31 THEN CLIP 61,119,31,86 ! 640x480
4500 FRAME
4510 IF Jump=1 THEN RETURN
4520 New_data: ! Display new mount data
4530 PRINT PEN 5
4540 PRINT TABXY(5,10),"NEW DATA"
4550 PRINT TABXY(5,12),"S/N ";Mount$ ! Serial number
4560 PRINT TABXY(5,13),"Cf= ";Cf ! Calibration factor
4570 PRINT TABXY(5,14),"Cfu= ";Cfu ! Calibration factor uncertainty in %
4580 PRINT TABXY(5,15),"Gm= ";Gm ! Reflection coefficient
4590 PRINT PEN 3
4600 Update_caldata: ! Update date for mount one or two
4610 ON KNOB 1 GOSUB Mouse_trap
4620 ON KBD GOSUB Keytest
4630 DISP CHR$(136)&"Enter "&CHR$(138)&"1"&CHR$(136)&" to save as mount one, "&CHR$(138)&"2"&CHR$(136)&" to save as mount two,
or '&CHR$(138)&"ESC"&CHR$(136)&"' to abort."
4640 LOOP
4650 AS=KBD$
4660 EXIT IF AS="1"
4670 EXIT IF AS="2"
4680 EXIT IF AS=CHR$(27)
4690 END LOOP
4700 Action: !
4710 OFF KNOB
4720 OFF KBD
4730 IF AS=CHR$(27) THEN End_action
4740 A=VAL(AS)
4750 IF A=1 THEN ! Update mount ONE data
4760 Mount1$=Mount$ ! Model/serial number
4770 Cf1=Cf ! Calibration factor
4780 Cfu1=Cfu ! Calibration factor uncertainty in percent
4790 Gm1=Gm ! Reflection coefficient
4800 END IF
4810 IF A=2 THEN ! Update mount TWO data
4820 Mount2$=Mount$ ! Model/serial number
4830 Cf2=Cf ! Calibration factor
4840 Cfu2=Cfu ! Calibration factor uncertainty in percent
4850 Gm2=Gm ! Reflection coefficient
4860 END IF
4870 Caldata mem: ! Display Caldata in memory
4880 IF A=1 OR A=2 THEN ! Redisplay data with new changes
4890 Jump=1
4900 CLEAR SCREEN
4910 GOSUB Mount_1
4920 PRINT PEN 3
4930 BEEP
4940 ALLOCATE Y$(255)
4950 Y$="C:\NIST_PM2\CALDATA"
4960 IF Pv=1 THEN Y$="C:\NIST_PM2\CALDATA.ORG" ! Default Path
4970 User_input: !
4980 IF Pv=1 THEN A=1
4990 IF Pv=0 OR Pv=2 THEN A=0
5000 OUTPUT 2,Y$,CHR$(255)&"H"; ! Output default filename
5010 IF Pv=1 THEN LINPUT "Enter path and name of file to LOAD. Enter a blank line to Exit.",Y$
5020 IF Pv=2 OR Pv=0 THEN LINPUT "Enter path and name of file to SAVE. Enter a blank line to Exit.",Y$
5030 Y$=TRIM(Y$) ! Remove trailing and leading spaces
5040 IF Y$="" THEN SUBEXIT ! If string is empty then exit
5050 CALL Mount_data(A,Y$) ! Save data as bdat file CALDATA or User filename
5060 IF A=-1 THEN GOTO User_input
5070 END IF
5080 End_action: RETURN !
5090 KeyTest: RETURN ! Dead Keys
5100 Mouse_trap: Return ! No Rodents
5110 SUBEND
5120 !
5130 ! -----
5140 !
5150 Pm_init: SUB Pm_init ! Initialize Arbiter 1096A Power Meter
5160 OPTION BASE 1
5170 COM /Init/Pm_avail,Dvm_avail
5180 ON TIMBOUT 7,2 GOTO Pm_e
5190 CLEAR 713
5200 OUTPUT 713;"RA2,RB2,MA2,DB0,E1a" ! Initialize power meter
5210 ! RA2 = Set mount A for 200 ohm
5220 ! RB2 = Set mount B for 200 ohm
5230 ! MA2 = Activate front panel meter
5240 ! DB0 = Turn DVM bus off
5250 ! E1a = SRQ interrupt mask byte=11
5260 Stat=SPOLL(713) ! Poll for power meter status
5270 IF Stat=0 THEN CALL Pm_error ! If error warn user
5280 Pm_avail=1 ! PM ready
5290 OFF TIMBOUT 7
5300 SUBEXIT
5310 Pm_e: ! PM, where are you?
5320 OFF TIMBOUT 7
5330 BEEP
5340 Pm_avail=0 ! PM not available
5350 OUTPUT 1;" ! Warn user
5360 OUTPUT 1;" Arbiter 1096A dual type IV power meter not found at address 713."
5370 LINPUT "Press 'ENTER' to Continue",Fakes$
5380 SUBEND
5390 !
5400 ! -----
5410 !
5420 Pm_error: SUB Pm_error ! Service 1096A PM error interrupt
5430 CLEAR SCREEN ! Danger! Danger! - Will Robinson!
5440 PRINT TABXY(25,10),CHR$(137)&"HARDWARE ERROR - PROGRAM HALTED"&CHR$(136)
5450 PRINT TABXY(21,12),"Arbiter 1096A Type IV power meter error."&CHR$(138)
5460 PRINT TABXY(19,28),"Check Power Meter and Press RUN To Restart"
5470 DISP " "
5480 KEY LABELS ON

```

```

5490 BEEP 400,.3
5500 STOP
5510 SUBEND
5520 !
5530 !
5540 !
5550 Ke_199: SUB Ke_199 ! DVM ranges and uncertainty
5560 OPTION BASE 1 ! (Keithly 199, 1 yr, 5-1/2 dig)
5570 Dvm_name$="Keithly 199"
5580 ! FOR DVM: VALUE QUANTITY
5590 COM /Dvm/P0,R0,A1,A2,A3,A4,A5,B1,B2,B3,B4,B5,R1,R2,R3,R4,R5
5600 COM /Dvm/Dvm_name${40} !DVM ID
5610 Nc: DATA 3.02999E5 ! number of counts, full scale
5620 A1: DATA 1.2E-4 ! fraction-of-rdg error, range R1, 1 yr
5630 A2: DATA 7.0E-5 ! fraction-of-rdg error, range R2, etc.
5640 A3: DATA 9.0E-5 ! fraction-of-rdg error, range R3
5650 A4: DATA 9.0E-5 ! fraction-of-rdg error, range R4
5660 B1: DATA 3. ! fraction-of-PS error, counts, range R1
5670 B2: DATA 2. ! fraction-of-PS error, counts, range R2
5680 B3: DATA 2. ! fraction-of-PS error, counts, range R3
5690 B4: DATA 2. ! fraction-of-PS error, counts, range R4
5700 R1: DATA 0.302999 ! lowest range (including overrange), volts
5710 R2: DATA 3.02999 ! next range up
5720 R3: DATA 30.2999 ! next range up
5730 R4: DATA 302.999 ! next range up
5740 READ Nc,A1,A2,A3,A4,B1,B2,B3,B4,R1,R2,R3,R4
5750 Convert_fs_errs: ! Normalize FS count errors to fractional errors
5760 B1=B1/Nc
5770 B2=B2/Nc
5780 B3=B3/Nc
5790 B4=B4/Nc
5800 SUBEND
5810 !
5820 !
5830 !
5840 Dvm_init: SUB Dvm_init ! Initialize Ke199 DVM/Scanner
5850 OPTION BASE 1
5860 COM /Init/Pm_avail,Dvm_avail
5870 ABORT 7 ! Stop all HP-IB activity (HTB 3.0)
5880 ON TIMEOUT 7,.5 GOTO Dvm_e !
5890 CLEAR 722 ! Clear the DVM
5900 OUTPUT 722;"FOROT4P1S1NLX" ! Initialize Keithly 199 DVM/Scanner
5910 CALL Dvm(V,T) ! Get DVM reading if ready (HTB 3.0)
5920 ! P0 = DC Volts
5930 ! R0 = Auto Range
5940 ! T4 = Trigger Continuous on X
5950 ! P1 = Internal Filter Enabled
5960 ! S1 = 5 1/2-digit resolution
5970 ! N1 = Channel one
5980 Dvm_avail=1 ! DVM ready to go
5990 OFF TIMEOUT 7
6000 SUBEXIT
6010 Dvm_e: ! DVM not found
6020 OFF TIMEOUT 7
6030 BEEP
6040 Dvm_avail=0 ! No DVM available
6050 OUTPUT 1;" ! Warn user
6060 OUTPUT 1;" Keithly 199 System DMM/Scanner not found at address 722."
6070 LINPUT "Press 'ENTER' to continue",Fake$
6080 SUBEND
6090 !
6100 !
6110 !
6120 Menu1: SUB Menu1(Num_meas,Quit,Rev$) ! Premeasurement set up & soft keys
6130 OPTION BASE 1
6140 COM /Wavetek/Sn${7} ! For the serial number
6150 COM /Mount/Mount${40},Cf,Defm ! Mount ID
6160 COM /Init/Pm_avail,Dvm_avail
6170 STATUS 1,13;Rows !
6180 Sys_prt=VAL(SYSTEM$( "SYSTEM PRIORITY" )) ! Determine system priority
6190 Lcl_prt=Sys_prt+1 ! Set local priority 1 higher for ON KEY
6200 M_flag=1 ! To write menu
6210 USER 1 KEYS ! 1st set of soft keys
6220 KEY LABELS ON ! Turn on soft keys
6230 FOR N=0 TO 19 ! Clear keys
6240 ON KEY N LABEL "" GOTO Top ! Default destination
6250 NEXT N
6260 ON KEY 0 LABEL " MOUNT ",Lcl_prt GOSUB Change_setup
6270 ON KEY 1 LABEL " SERIAL NO. ",Lcl_prt GOSUB Sn
6280 ON KEY 2 LABEL " NO. POINTS ",Lcl_prt GOSUB Change
6290 ON KEY 3 LABEL " HELP ",Lcl_prt GOSUB Help
6300 ON KEY 4 LABEL " MEASURE ",Lcl_prt GOSUB Exit_to_meas
6310 ON KEY 9 LABEL " EXIT ",Lcl_prt GOTO Quit
6320 Top: LOOP ! Wait for input
6330 IF M_flag=1 THEN GOSUB Menu
6340 IF Pm_avail=1 THEN Errorloop=1+Errorloop! Check PM every 3000 counts
6350 IF Errorloop=3000 THEN GOSUB Error_pm
6360 END LOOP
6370 Menu: CLEAR SCREEN ! Main menu
6380 PEN 6
6390 IF Rows>31 THEN CLIP 15,85,30,87 ! 800x600 display
6400 IF Rows>31 THEN A=0
6410 IF Rows<31 THEN CLIP 23,97,28,88 ! 640x480 display
6420 IF Rows<31 THEN A=3
6430 FRAME
6440 PRINT TABXY(5,4-(A/2)),CHR$(137);" P W R _ M T R 2 . 0 ";CHR$(138)
6450 PRINT TABXY(24,8-A)," - - MEASUREMENT MENU - - "
6460 PRINT TABXY(20,11-A),CHR$(129);" 1 ";CHR$(128);" SELECT MEASUREMENT MOUNT"
6470 PRINT TABXY(25,12-A),CHR$(136)&"(";Mount$;")"&CHR$(138)
6480 PRINT TABXY(20,14-A),CHR$(129);" 2 ";CHR$(128);" INPUT WAVETEK SERIAL NUMBER"
6490 IF LEN(TRIM$(Sn$))<1 THEN PRINT TABXY(25,15-A),CHR$(137)&"(No S/N in memory)"&CHR$(138)
6500 IF LEN(TRIM$(Sn$))>0 THEN PRINT TABXY(25,15-A),CHR$(136)&"(S/N ";Sn$;" in memory)"&CHR$(138)
6510 PRINT TABXY(20,17-A),CHR$(129);" 3 ";CHR$(128);" CHANGE # OF MEASUREMENT POINTS"
6520 PRINT TABXY(25,18-A),CHR$(136)&"(Present setting =";Num_meas;") "&CHR$(138)
6530 PRINT TABXY(20,20-A),CHR$(129);" 4 ";CHR$(128);" WAVETEK OPERATING INSTRUCTIONS"
6540 PRINT TABXY(20,22-A),CHR$(129);" 5 ";CHR$(128);" BEGIN MEASUREMENT"
6550 PRINT TABXY(20,24-A),CHR$(129);" 0 ";CHR$(128);" EXIT PROGRAM"
6560 PRINT TABXY(48-A,28-A),CHR$(139);"rev ";Rev$
6570 M_flag=0

```

```

6580 RETURN
6590 Sn: ! Input the WAVETEK serial number
6600 KEY LABELS OFF ! Turn off soft keys
6610 OUTPUT 2;Sn$;
6620 LINPUT "WAVETEK SERIAL NUMBER ?",Sn$[1,7]
6630 Sn$=TRIM$(Sn$)
6640 KEY LABELS ON ! Turn keys back on
6650 M_flag=1
6660 RETURN
6670 Change: ! Change # of meas points
6680 KEY LABELS OFF ! Turn off soft keys
6690 INPUT "NUMBER OF MEASUREMENT POINTS ?",Num_meas
6700 Num_meas=MIN(Num_meas,100)
6710 Num_meas=MAX(Num_meas,1)
6720 KEY LABELS ON ! Turn keys back on
6730 M_flag=1
6740 RETURN
6750 Help: ! With operation of Wavetek
6760 CALL Help
6770 M_flag=1
6780 RETURN
6790 Change setup: ! Change default mount settings
6800 CALL Set_up(1)
6810 KEY LABELS ON
6820 M_flag=1
6830 RETURN
6840 Error_pm: ! Poll power meter for error
6850 ON TIMEOUT 7,.2 GOTO Pm_e
6860 Stat=SPOLL(713)
6870 IF Stat>0 THEN CALL Pm_init
6880 Errorloop=0
6890 OFF TIMEOUT 7
6900 RETURN
6910 Pm_e: ! Power meter error
6920 OFF TIMEOUT 7
6930 Errorloop=0
6940 Pm_avail=0
6950 RETURN
6960 Exit to meas: ! Exit to begin measurement
6970 IF Pm_avail=0 OR Dvm_avail=0 THEN ! PM or DVM have not been init.
6980 CALL Pm_init
6990 CALL Dvm_init
7000 END IF
7010 M_flag=1
7020 IF Pm_avail=0 OR Dvm_avail=0 THEN RETURN ! No PM, no DVM, no measure
7030 SUBEXIT
7040 Quit: ! Terminate program
7050 Quit=1 ! User goes home
7060 KEY LABELS OFF
7070 SUBEND
7080 !
7090 !-----
7100 !
7110 Help: SUB Help ! Wavetek user information
7120 OPTION BASE 1
7130 Sys_prt=VAL(SYSTEMS("SYSTEM PRIORITY")) ! Determine system priority
7140 Lcl_prt=Sys_prt+1 ! Set local priority 1 higher for ON KEY
7150 USER 1 KEYS ! 1st set of soft keys
7160 KEY LABELS ON ! Turn on soft keys
7170 FOR N=0 TO 19 ! Clear keys
7180 ON KEY N LABEL "" GOTO Top ! Default destination
7190 NEXT N
7200 ON KEY 9 LABEL " MAIN MENU ",Lcl_prt GOTO Exit
7210 GOSUB Text ! Print info
7220 Top: LOOP ! Wait for input
7230 END LOOP
7240 Text: ! Here be info
7250 CLEAR SCREEN
7260 PRINT PEN 1
7270 PRINT TABXY(22,2),"CONTROLLING 8502A CALIBRATOR OUTPUT"
7280 PRINT TABXY(12,4),"Press the following 8502A front panel control keys in the"
7290 PRINT TABXY(12,5),"sequence indicated:"
7300 PRINT TABXY(14,7),"(1)-'CW',"
7310 PRINT TABXY(25,7),"(2)-'Menu',"
7320 PRINT TABXY(38,7),"(3)-'F3',"
7330 PRINT TABXY(49,7),"(4)-'F1',"
7340 PRINT TABXY(12,9),"Then, pressing the 8502A key '7' will turn the calibrator"
7350 PRINT TABXY(12,10),"output ON, and pressing the 8502A key 'CLEAR' will turn the"
7360 PRINT TABXY(12,11),"calibrator output OFF."
7370 PRINT TABXY(12,13),"For more detail see 'Calibrator Output Level Test' on page 6-2"
7380 PRINT TABXY(12,14),"of the 8502A manual."
7390 PRINT TABXY(12,17),"CAUTION: Do not press any UNITS key when the mount is"
7400 PRINT TABXY(12,18),"connected to the calibrator. This will cause the"
7410 PRINT TABXY(12,19),"calibrator to output 100 mW which might damage the mount."
7420 RETURN
7430 Exit: ! Helped
7440 SUBEND
7450 !
7460 !-----
7470 !
7480 Hdr: SUB Hdr ! Header text for measurement and screen
7490 OPTION BASE 1
7500 COM /Dvm/P0,R0,A1,A2,A3,A4,A5,B1,B2,B3,B4,B5,R1,R2,R3,R4,R5
7510 COM /Dvm/Dvm_name${40} ! DVM ID
7520 COM /Mount/Mount${40},Cf,Defm ! Mount ID
7530 COM /Wavetek/Sn${7} ! For the serial number
7540 COM /Hardcopy/Tdate${40}
7550 CLEAR SCREEN
7560 PRINT TABXY(1,2),CHR$(137)&"PWR MTR 2.0"&CHR$(136)
7570 PRINT TABXY(30,2),CHR$(136);CHR$(179);" MEASUREMENT IN PROGRESS ";CHR$(128)
7580 PRINT TABXY(1,4),CHR$(140);"MOUNT: ";Mount$;CHR$(136)
7590 PRINT TABXY(59,4),CHR$(140);"TIMES(TIMEDATE)";" ";DATE$(TIMEDATE);CHR$(136)
7600 Tdate$=TIMES(TIMEDATE)&" "&DATE$(TIMEDATE) !Sore time and data of measurement
7610 PRINT TABXY(1,5),CHR$(140);"POWER METER: WAVETEK MODEL 8502A, S/N ";Sn$;CHR$(136)
7620 PRINT ""
7630 OUTPUT B$ USING "#,K";P0 ! Format power string
7640 PRINT " No. Power Pwr-";B$;" mW V1 Delta V V1 Drift Ref. Offset"
7650 IMAGE "a C",4X,"a (mW) C",4X,"a (µ) C",7X,"a (V) C",3X,"a (mV) C",3X,"a (uV/s) C",3X,"a (mV) C"
7660 PRINT USING 7650

```

```

7670 SUBEND ! Hdr
7680 !
7690 ! -----
7700 !
7710 Measloop: SUB Measloop(Num_meas,P(*),Esc) ! Measurement loop
7720 KEY LABELS OFF
7730 FOR N=1 TO Num_meas ! Num_meas= no. of measurements(1-100)
7740 DISP N
7750 Esc=0 ! Reset bailout flag
7760 CALL Meas(N,P1,Esc) ! Do the measurement
7770 IF Esc=1 THEN SUBEXIT ! bailout
7780 P(N,1)=P1 ! Fill array for statistics
7790 ! WAIT 1 ! Wait before measuring again
7800 NEXT N
7810 OUTPUT 722;"T4X" ! Let DVM continue reading
7820 KEY LABELS ON
7830 SUBEND
7840 !
7850 ! -----
7860 !
7870 Meas: SUB Meas(N,P1,Esc) ! Performs measurement, calculates
7880 OPTION BASE 1 ! and prints results.
7890 COM /Dvm/P0,R0,A1,A2,A3,A4,A5,B1,B2,B3,B4,B5,R1,R2,R3,R4,R5
7900 COM /Dvm/Dvm_name$(40) ! DVM ID
7910 COM /Errs/Dp,Vic,V1f,V1f,V1xi,V1xf,V1x,V2x,T1fac,T2fac,Cfu,Mmu,Deu,Dpu
7920 COM /Errs/Gm,Scfu,Smmu,Sdeu,Sdpu,Wc_unc,Cs_unc,Ex_unc
7930 COM /Mount/Mount$(40),Cf,Defm ! Mount ID
7940 COM /Harddata/Pdata(100,7),Pres(7,1)
7950 DIM Esc$(255)
7960 ON KBD GOSUB Bail_out ! Escape if user hits ESC key
7970 CALL Dvm(V1,T1i) ! V1 before rf turn_on
7980 OUTPUT 722;"N2R1TOX" ! Connect for delta V/Trig on talk
7990 WAIT .2 !
8000 CALL Dvm(V1xi,T1xi) ! Initial delta V1 (V1xi) with rf off
8010 Vt=V1xi+V1i-SQR(V1i^2-9.E-4*R0) ! Calculate threshold for Rf sub
8020 CALL Rf(1,Vt,Lcl_prty,Esc) ! Calls for rf ON and determines when
8030 IF Esc THEN Bail_out
8040 WAIT 1 ! For source to settle
8050 CALL Dvm(V2x,T2x) ! Read delta V2 (V2x) with rf on
8060 CALL Rf(0,Vt,Lcl_prty,Esc) ! Calls for rf OFF and determines when
8070 IF Esc THEN Bail_out
8080 WAIT 1 ! Wait again
8090 CALL Dvm(V1xf,T1xf) ! Final delta V1 (V1xi) with rf off
8100 OUTPUT 722;"N1R2X" ! Reconnect for V1
8110 WAIT .2 !
8120 CALL Dvm(V1f,T1f) ! Final V1 with rf off
8130 T1fac=(T2x-T1i)/(T1f-T1i) ! First timing factor
8140 Vic=V1i+T1fac*(V1f-V1i) ! V1 corrections
8150 T2fac=(T2x-T1xi)/(T1xf-T1xi) ! Second timing factor
8160 V1x=V1xi+T2fac*(V1xf-V1xi) ! Delta V corrections
8170 Dv1=(V1f-V1i)*1.E+6 ! Change in V1
8180 Dv1_dt=Dv1/(T1f-T1i) ! Drift rate of V1 in mV/sec
8190 Dv2=V2x-V1x ! Change in V2 - (delta V)
8200 P1=(2*Vic-(Dv2))*(Dv2)*1000/R0 ! Power in mW
8210 P1=P1/Cf ! Cal factor correction
8220 Printout: ! Realtime
8230 IMAG 3D,5X,Z.5D,6X,MZ.3D,9X,Z.6D,2X,3D.3D,6X,M2D.D,5X,M2D.3D
8240 PRINT USING 8230;N,P1,100*(P1-P0)/P0,V1c,Dv2*1.E+3,Dv1_dt,V1x*1.E+3
8250 Save_results: !
8260 Pdata(N,1)=N ! Store data into array for future use
8270 Pdata(N,2)=P1
8280 Pdata(N,3)=100*(P1-P0)/P0
8290 Pdata(N,4)=V1c
8300 Pdata(N,5)=Dv2*1.E+3
8310 Pdata(N,6)=Dv1_dt
8320 Pdata(N,7)=V1x*1.E+3
8330 SUBEXIT !
8340 Bail_out: ! User interrupt
8350 IF Esc$(27) THEN Esc=1 ! If ESC key
8360 IF Esc=1 THEN
8370 OFF KBD ! Turn off trapping
8380 OFF KNOB !
8390 BEEP ! Beep Beep
8400 BEEP !
8410 BEEP !
8420 PRINT TABXY(30,2),CHR$(128);CHR$(136);" M E A S U R E M E N T S T O P P E D "
8430 LINPUT "ESC Key Pressed; Measurement ABORTED, Press ENTER to Exit.",Fake$
8440 CALL Dvm_init ! Reset DVM
8450 SUBEXIT ! Leave
8460 END IF
8470 RETURN
8480 Exit: ! Measurement complete
8490 SUBEND ! SUB Meas
8500 !
8510 ! -----
8520 !
8530 Rf: SUB Rf(On,Vt,Lcl_prty,Esc) ! Turn rf ON/OFF
8540 DIM Esc$(255) ! Long string to handle key bangers
8550 Esc$=""
8560 ON KNOB 1 GOSUB Knob_service ! Trap mouse
8570 ON KBD GOSUB Bail ! Bailout to keyboard
8580 IF On THEN
8590 DISP CHR$(139)&CHR$(129);" TURN RF ON (PRESS 8502A KEY '7') "&CHR$(143)&" "&CHR$(137)&" Press 'ESC' to ABORT ";
8600 CHR$(128)&CHR$(138) ! Tell operator
8610 BEEP ! Attention
8620 LOOP ! Wait for rf to be turned on/off
8630 CALL Dvm(V,T) ! Read DVM
8640 WAIT 1 !
8650 EXIT IF V>Vt ! If rf is turned ON
8660 END LOOP
8670 ELSE
8680 DISP CHR$(136)&CHR$(129);" TURN RF OFF (PRESS 8502A KEY '7') "&CHR$(143)&" "&CHR$(137)&" Press 'ESC' to ABORT ";
8690 CHR$(128)&CHR$(138) ! Tell operator
8700 BEEP ! Attention
8710 WAIT .2 !
8720 BEEP !
8730 LOOP ! Wait for rf to be turned on/off
8740 CALL Dvm(V,T) ! Read DVM
8750 WAIT 1 !

```

```

8740      EXIT IF V<Vt          ! If rf is turned OFF
8750      END LOOP
8760      END IF
8770      DISP ""
8780      SUBEXIT
8790 Knob_service:             ! Mouse trap
8800      | NO RODENTS
8810      RETURN
8820 Bail: !
8830      Esc$=KBD$             ! Trap keyboard
8840      IF Esc$=CHR$(27) THEN ! If ESC key
8850          Esc=1             ! Set bail flag
8860      SUBEXIT             ! Leave
8870      END IF
8880      RETURN               ! Else continue
8890      SUBEND
8900      !
8910      !-----
8920      !
8930 Dvm: SUB Dvm(V,T)         ! DVM reading
8940      SEND 7;UNL LISTEN 22 ! Get dvm's attention
8950      TRIGGER 7            ! Trigger to read
8960      ENTER 722;V          ! Read DVM
8970      T=TIMEDATE           ! Get the time
8980      SUBEND
8990      !
9000      !-----
9010      !
9020 Errors: SUB Errors       ! Calculates uncertainty in power due to DVM
9030      OPTION BASE 1
9040      COM /Dvm/P0,R0,A1,A2,A3,A4,A5,B1,B2,B3,B4,B5,R1,R2,R3,R4,R5
9050      COM /Dvm/Dvm_name$(40) ! DVM ID
9060      COM /Errs/Dp,V1c,V1i,V1f,V1xi,V1xf,V1x,V2x,T1fac,T2fac,Cfu,Mmu,Deu,Dpu
9070      COM /Errs/Gm,Scfu,Smmu,Sdeu,Sdpu,Wc_unc,Cs_unc,Ex_unc
9080      CALL Select_v(V1i,Aa1i,Bb1i,Ss1i) ! Aa_ - fract. of reading error
9090      CALL Select_v(V1f,Aa1f,Bb1f,Ss1f) !
9100      CALL Select_v(V1xi,Aa1xi,Bb1xi,Ss1xi) !
9110      CALL Select_v(V1xf,Aa1xf,Bb1xf,Ss1xf) ! Bb_ - fract. of FS error
9120      CALL Select_v(V2x,Aa2x,Bb2x,Ss2x) ! Ss_ - fullscale reading
9130 With_rvg:
9140      Dv1i=Aa1i*V1i+Bb1i*Ss1i ! Eq's derived 900111/FRC
9150      Dv1f=Aa1f*V1f+Bb1f*Ss1f ! Delta-V due to initial V1 measmnt
9160      Dv1xi=ABS(Aa1xi*V1xi)+Bb1xi*Ss1xi ! Delta due to initial V1x measmnt
9170      Dv1xf=ABS(Aa1xf*V1xf)+Bb1xf*Ss1xf ! Delta-V due to final V1x measmnt
9180      Dv2x=ABS(Aa2x*V2x)+Bb2x*Ss2x ! Delta-V due to V2x measmnt
9190      Dv1c=(1-T1fac)*Dv1i+T1fac*Dv1f ! Error in corrected V1
9200      Dv1x=(1-T2fac)*Dv1xi+T2fac*Dv1xf ! Error in delta V correction
9210      Dpv1=ABS((V2x-V1x)*Dv1c) ! Delta-power due to V1 measmnt errors
9220      Dpv1x=ABS((V1c-V2x+V1x)*Dv1x) ! Delta-power due to V1x " "
9230      Dpv2x=ABS((V1c-V2x+V1x)*Dv2x) ! Delta-power due to V2x " "
9240      Dp=2*(Dpv1+Dpv1x+Dpv2x)/R0 ! Sum (2 & R0 left out above)
9250      Dp=Dp*1.E+3 ! Dp in mW
9260      SUBEND
9270      !
9280      !-----
9290      !
9300 Select_v: SUB Select_v(V,Aa,Bb,Ss) ! Returns range with fraction of full
9310      OPTION BASE 1 ! scale & fraction of reading error
9320      COM /Dvm/P0,R0,A1,A2,A3,A4,A5,B1,B2,B3,B4,B5,R1,R2,R3,R4,R5
9330      COM /Dvm/Dvm_name$(40) ! DVM ID
9340      SELECT ABS(V) ! V may be of either polarity
9350      CASE <=R1 ! Start at lowest range
9360          Aa=A1 ! Fraction of rdg error for V on range R1
9370          Bb=B1 ! Fraction of FS error for V on range R1
9380          Ss=R1 ! Fullscale reading for V, range R1
9390          Range=1 ! Range_no number for plot
9400      CASE <=R2 ! Uprange if necessary
9410          Aa=A2
9420          Bb=B2
9430          Ss=R2 ! Etc. for range R2
9440          Range=2
9450      CASE <=R3 ! And again
9460          Aa=A3
9470          Bb=B3
9480          Ss=R3
9490          Range=3
9500      CASE <=R4
9510          Aa=A4
9520          Bb=B4
9530          Ss=R4
9540          Range=4
9550      CASE <=R5
9560          Aa=A5
9570          Bb=B5
9580          Ss=R5
9590          Range=5
9600      CASE ELSE
9610          BEEP
9620          PRINT "Voltage Error"
9630      END SELECT
9640      SUBEND
9650      !
9660      !-----
9670      !
9680 Stats: SUB Stats(REAL P(*) ! Calculates standard deviation and
9690      ! final uncertainty, prints results to
9700      ! screen & stores results for hard copy
9710      OPTION BASE 1
9720      COM /Dvm/P0,R0,A1,A2,A3,A4,A5,B1,B2,B3,B4,B5,R1,R2,R3,R4,R5
9730      COM /Dvm/Dvm_name$(40) ! DVM ID
9740      COM /Errs/Dp,V1c,V1i,V1f,V1xi,V1xf,V1x,V2x,T1fac,T2fac,Cfu,Mmu,Deu,Dpu
9750      COM /Errs/Gm,Scfu,Smmu,Sdeu,Sdpu,Wc_unc,Cs_unc,Ex_unc
9760      COM /Harddata/Pdata(100,7),Pres(7,1)
9770      Sz=SIZE(P,1)
9780      MAT Pres=(0) ! Zero out array
9790      ALLOCATE Dum(Sz,1) ! Use Dum(*) to preserve P(*)
9800      Sd: !
9810      MAT Dum=P
9820      Sum=SUM(Dum) ! Sum of the elements in P(*)

```

```

9830 Mean=Sum/Sz ! Mean of P(*)
9840 MAT Dum=P-(Mean) ! Dum(*) contains deviations from mean
9850 Maxpdv=MAX(Dum(*)) ! Largest positive deviation
9860 Maxndv=MIN(Dum(*)) ! Largest negative deviation
9870 Maxdv=MAX(ABS(Maxpdv),ABS(Maxndv)) ! Largest largest deviation
9880 MAT Dum=Dum . Dum ! Dum holds squares of deviations
9890 IF Sz>1 THEN Var=SUM(Dum)/(Sz-1) ! Variance
9900 Sd=SQR(Var) ! Standard deviation
9910 Dpu=(Dp/Mean)*100 ! % uncertainty due to DVM
9920 Sdpu=Dpu/SQR(3) ! DVM and Type IV
9930 Sdm=Sd/SQR(Sz) ! Standard Deviation of the mean
9940 Sdmu=100*Sdm/Mean ! % of standard deviation of the mean
9950 Scfu=Cfu/SQR(3) ! Calibration factor std uncertainty
9960 ! rectangular distribution
9970 Smmu=Mmu/SQR(2) ! Mismatch std. unc U-shaped dist.
9980 Sdeu=Deu/SQR(3) ! Dual element std. unc. rec. dist.
9990 Wc_unc=(Sdmu*3)+Cfu+Mmu+Deu+Dpu ! Worst case sum
10000 Cs_unc=SQR(Scfu^2+Smmu^2+Sdeu^2+Sdpu^2+Sdmu^2) ! Combined standard
10010 Ex_unc=Cs_unc*2 ! Expanded uncertainty
10020 Prt:
10030 PRINT "-----"
10040 PRINT "RESULTS:"
10050 IF Sz=1 THEN
10060 PRINT
10070 OUTPUT Scr$ USING "#,Z.5D",P(1,1)
10080 PRINT " The single power measurement resulted in a value of "&Scr$&" mW."
10090 PRINT
10100 PRINT " The table of uncertainties is not displayed for a single measurement."
10110 ELSE
10120 OUTPUT B$ USING "#,K",P0
10130 PRINT " AVG PWR AVG-" ;B$; " mW MAX DEV STD DEV W/C UNC EXP UNC"
10140 IMAGE 8X,"A (mw) C",4X,"A (%)" C",7X,"A (%)" C",3X,"A (%)" C",3X,"A (%)" C",3X,"A (%)" C"
10150 PRINT USING 10140
10160 IMAGE 8X,Z.5D,6X,SZ.3D,8X,SZ.3D,K,SZ.3D,5X,Z.3D,5X,Z.3D,5X,Z.3D
10170 PRINT USING 10160;Mean,100*(Mean-P0)/P0,100*Maxpdv/Mean,"",100*Maxndv/Mean,Sdmu,Wc_unc,Ex_unc
10180 END IF
10190 PRINT TABXY(30,2),CHR$(128),CHR$(136);" M E A S U R E M E N T C O M P L E T E "
10200 Save stats: ! Store data into array for future use
10210 Pres(1,1)=Mean ! Mean power in mW
10220 Pres(2,1)=100*(Mean-P0)/P0 ! Mean percent offset from P0
10230 Pres(3,1)=100*Maxpdv/Mean ! Max % dev from the mean(+)
10240 Pres(4,1)=100*Maxndv/Mean ! Max % dev from the mean(-)
10250 Pres(5,1)=Sdmu ! Standard deviation of the mean
10260 DEALLOCATE Dum(*) ! Free memory
10270 SUBEND
10280 !
10290 ! -----
10300 !
10310 Menu2: SUB Menu2(Num_meas,P0) ! Post measurement soft keys
10320 OPTION BASE 1
10330 Sys_prt=VAL(SYSTEM$( "SYSTEM PRIORITY" )) ! Determine system priority
10340 Lcl_prt=Sys_prt+1 ! Set local priority 1 higher for ON KEY
10350 USER 1 KEYS ! 1st set of soft keys
10360 KEY LABELS ON ! Turn on soft keys
10370 FOR N=0 TO 19 ! Clear keys
10380 ON KEY N LABEL "" GOTO Top ! Default destination
10390 NEXT N
10400 ON KEY 0 LABEL " DUMP SCREEN ",Lcl_prt GOSUB Dump
10410 ON KEY 1 LABEL " PRINT REPORT ",Lcl_prt GOSUB Print
10420 ON KEY 2 LABEL "REPORT TO FILE",Lcl_prt GOSUB Text_file
10430 ON KEY 9 LABEL " MAIN MENU ",Lcl_prt GOSUB Exit
10440 Top: LOOP ! Wait for input
10450 END LOOP
10460 Dump: ! Alpha dump to printer at 10
10470 CALL Kx_init ! Init Panasonic KX-F1180 Printer
10480 KEY LABELS OFF ! Turn off soft keys
10490 KBD LINE PEN 0 ! Line pen black
10500 DUMP ALPHA #10 ! Alpha dump to printer
10510 KBD LINE PEN 4 ! Line pen green
10520 KEY LABELS ON ! Turn keys back on
10530 PRINTER IS CRT
10540 RETURN
10550 Print: ! Print report to printer
10560 CALL Hardcopy(Num_meas,P0,"H")
10570 RETURN
10580 Text_file: ! Print report to text file
10590 CALL Hardcopy(Num_meas,P0,"S")
10600 RETURN
10610 Exit: !
10620 KEY LABELS OFF
10630 ON KNOB 1 GOSUB Mousetrap
10640 ON KBD GOSUB Keytrap
10650 DISP CHR$(136)&"All data will be lost. EXIT ("&CHR$(138)&"Y"&CHR$(136)&)"es or ("&CHR$(138)&"N"&CHR$(136)&)"o."
10660 LOOP
10670 M$=KBDS
10680 EXIT IF UPC$(M$)="Y" ! Exit on YES
10690 EXIT IF UPC$(M$)="N" ! Exit on NO
10700 END LOOP
10710 M$=TRIM$(M$) ! Remove leading and trailing spaces
10720 OFF KNOB
10730 OFF KBD
10740 DISP "" ! Clear display line
10750 IF UPC$(M$)="Y" THEN SUBEXIT ! Lost the data
10760 KEY LABELS ON
10770 RETURN
10780 Mousetrap: ! Trap mouse
10790 ! No Rodents
10800 RETURN
10810 Keytrap: ! Trap unused keys
10820 ! Dead Keys
10830 RETURN
10840 SUBEND
10850 !
10860 ! -----
10870 !
10880 Hardcopy: SUB Hardcopy(Num_meas,P0,O$) ! Hardcopy report
10890 OPTION BASE 1 ! O$="H" use Printer
10900 COM /Hardcopy/Tdate$[40] ! O$="S" use DOS ASCII file
10910 COM /Harddata/Pdata(100,7),Pres(7,1)

```

```

10920 COM /Mount/Mount${40},Cf,Defm
10930 COM /Wavetek/Sn${7}
10940 DIM Tfile$(80)
10950 IF OS="H" THEN ! Output to printer
10960 CALL Kx_init ! Init Panasonic KX-F1180 Printer
10970 ASSIGN @P1 TO 10 ! Assign path to printer
10980 ELSE ! Output to DOS ASCII file
10990 KEY LABELS OFF
11000 Tfile$="C:\NIST_PM2\&Sn${&}.RPT" ! Build filename
11010 Enter_name: !
11020 OUTPUT 2;Tfile$; ! Output to CRT
11030 LINPUT "CHR$(136)Enter path and name of output file. ",Tfile$
11040 Tfile$=TRIM$(Tfile$) ! Remove leading & trailing spaces
11050 IF LEN(Tfile$)<1 THEN SUBEXIT ! If no path/file then exit
11060 ASSIGN @P1 TO Tfile$;RETURN Uncreated ! Open file TFile$
11070 ASSIGN @Path_1 TO * ! Close path
11080 IF NOT Uncreated THEN ! Duplicate file name
11090 BEEP
11100 ON KNOB 1 GOSUB Mousetrap ! Disable mouse movement
11110 ON KBD GOSUB Keytrap ! Trap input
11120 DISP "CHR$(138)Duplicate file name found. Delete file? (CHR$(136)YCHR$(138))es or (CHR$(136)NCHR$(138))o."
11130 LOOP
11140 DS=KBD$
11150 EXIT IF UPC$(DS)="Y" ! Yes
11160 EXIT IF UPC$(DS)="N" ! No
11170 END LOOP
11180 OFF KNOB
11190 OFF KBD
11200 DISP ""
11210 IF UPC$(DS)="Y" THEN PURGE Tfile$ ! Purge file
11220 IF UPC$(DS)="N" THEN Enter_name ! Enter new path/file
11230 END IF
11240 ON ERROR GOTO Error_handler ! On file error
11250 CREATE Tfile$,1 ! Create file
11260 OFF ERROR ! Turn off error branching
11270 ASSIGN @P1 TO Tfile$;FORMAT ON ! Open path & format output
11280 KEY LABELS ON
11290 END IF
11300 OUTPUT P$ USING "#,K";P0 ! Compact field - Power in mW
11310 OUTPUT @P1;" MEASUREMENT DATA"
11320 OUTPUT @P1;"
11330 OUTPUT @P1;"FOR POWER METER: WAVETEK MODEL 8502A. S/N ";Sn$
11340 OUTPUT @P1;"
11350 OUTPUT @P1;"USING MOUNT: ";Mount$;" ";Tdate$;"
11360 OUTPUT @P1;"
11370 OUTPUT @P1;" Power Pwr-";P$;" mW V1 Delta V V1 Drift Ref. Offset"
11380 OUTPUT @P1;" (mW) (%) (V) (mV) ("&CHR$(230)&*V/s) (mV)"
11390 OUTPUT @P1;"
11400 IMAGE 3D,4X,Z.5D,4X,SZ.3D,4X,Z.6D,2X,3D.3D,4X,S2D.D,6X,S2D.3D
11410 FOR N=1 TO Num_meas
11420 OUTPUT @P1 USING 11400;Pdata(N,1),Pdata(N,2),Pdata(N,3),Pdata(N,4),Pdata(N,5),Pdata(N,6),Pdata(N,7)
11430 IF N=48 AND OS="H" THEN OUTPUT @P1;CHR$(12) ! Send form feed (page is 57 lines)
11440 IF N=48 AND OS="H" THEN ! Set new line and set page to two
11450 Lines=0
11460 Page=2
11470 END IF
11480 Lines=Lines+1 ! Line count
11490 NEXT N
11500 OUTPUT @P1;"
11510
11520 OUTPUT Num_meas$ USING "#,K";Num_meas ! Make strings for text output
11530 OUTPUT M$ USING "#,Z.DDDD";Pres(1,1) ! Number of measurements
11540 OUTPUT Sd$ USING "#,Z.DDD";Pres(5,1) ! Mean power in mW
11550 OUTPUT Md1$ USING "#,SZ.DDD";Pres(3,1) ! Sdm - Percent standard deviation
11560 OUTPUT Md2$ USING "#,SZ.DDD";Pres(4,1) ! Max % dev from the mean(+)
11570 OUTPUT Av$ USING "#,Z.DDD";ABS(Pres(2,1)) ! Max % dev from the mean(-)
11580 OUTPUT Av$ USING "#,Z.DDD";ABS(Pres(2,1)) ! Mean % from P0
11590 IF Page=2 AND OS="H" AND Lines>20 THEN OUTPUT @P1;CHR$(12) ! Send form feed to printer
11600 IF Page=0 AND OS="H" AND Num_meas>12 THEN OUTPUT @P1;CHR$(12) ! Send FF
11610 OUTPUT @P1;"
11620 OUTPUT @P1;" MEASUREMENT RESULTS"
11630 OUTPUT @P1;"
11640 IF Num_meas>1 THEN
11650 OUTPUT @P1;"The mean of the ";Num_meas$;" measurements is ";M$;" mW with ";Sd$;" percent standard deviation"
11660 OUTPUT @P1;"of the mean. The maximum deviation from the mean is ";Md1$;" and ";Md2$;" percent."
11670 IF Pres(2,1)<0 THEN
11680 OUTPUT @P1;"The mean is ";Av$;" percent less than ";P$;" mW."
11690 ELSE
11700 OUTPUT @P1;"The mean is ";Av$;" percent greater than ";P$;" mW."
11710 END IF
11720 OUTPUT @P1;"
11730 OUTPUT @P1;"The table below shows the values of the major uncertainty components. The total"
11740 OUTPUT @P1;"uncertainty is expressed as both the worst case sum and the expanded uncertainty."
11750 OUTPUT @P1;"For a discussion of standard and expanded uncertainty see NIST Technical Note 1297,"
11760 OUTPUT @P1;CHR$(34);"Guidelines for Evaluating and Expressing the Uncertainty of NIST Measurement"
11770 OUTPUT @P1;"Results.";CHR$(34)
11780 ELSE
11790 OUTPUT @P1;"The table of uncertainties is not computed for single measurements."
11800 END IF
11810 OUTPUT @P1;"
11820 IF Num_meas>1 THEN CALL Table(@P1) ! Print table of results
11830 IF OS="H" THEN OUTPUT @P1;CHR$(12) ! Send form feed to printer
11840 ASSIGN @P1 TO * ! Close path
11850 PRINTER IS 1 ! CRT
11860 SUBEXIT ! Back to sub Menu2
11870 Error_handler: ! Error Branch
11880 BEEP
11890 BEEP
11900 LINPUT "ERROR - Filename or Directory not found. Press enter.",Fake$
11910 Enter_name ! Back to enter path/filename
11920 RETURN
11930 Mousetrap: !
11940 !NO RODENTS
11950 RETURN
11960 Keytrap: !
11970 !DEAD KEYS
11980 RETURN
11990 SUBEND
12000 ! -----

```

```

12010 !
12020 Table: SUB Table(@P1)           ! Table of results
12030 OPTION BASE 1
12040 COM /Errs/Dp,V1c,V1i,V1f,V1xi,V1xf,V1x,V2x,T1fac,T2fac,Cfu,Mmu,Deu,Dpu
12050 COM /Errs/Gm,Scfu,Smmu,Sdeu,Sdpu,Wc_unc,Cs_unc,Ex_unc
12060 COM /Harddata/Pdata(100,7),Pres(7,1)
12070 ! Make Strings
12080 OUTPUT Cfu$ USING "#,Z.DDD";Cfu           ! Mount calibration factor
12090 OUTPUT Scfu$ USING "#,Z.DDD";Scfu         ! Std mount calibration factor
12100 OUTPUT Mmu$ USING "#,Z.DDD";Mmu         ! Mismatch uncertainty
12110 OUTPUT Smmu$ USING "#,Z.DDD";Smmu       ! Std mismatch uncertainty
12120 OUTPUT Deu$ USING "#,Z.DDD";Deu         ! Dual element uncertainty
12130 OUTPUT Sdeu$ USING "#,Z.DDD";Sdeu       ! Std dual element uncertainty
12140 OUTPUT Dpu$ USING "#,Z.DDD";Dpu         ! DVM uncertainty
12150 OUTPUT Sdpu$ USING "#,Z.DDD";Sdpu       ! Std DVM uncertainty
12160 OUTPUT Sd$ USING "#,Z.DDD";Pres(5,1)    ! Sdmu - Percent of std dev
12170 OUTPUT Sdu$ USING "#,Z.DDD";Pres(5,1)*3 ! Percent of std dev
12180 OUTPUT Wc$ USING "#,Z.DDD";Wc_unc       ! Worst case sum
12190 OUTPUT Cs$ USING "#,Z.DDD";Cs_unc       ! Combined std uncertainty
12200 OUTPUT Ex$ USING "#,Z.DDD";Ex_unc       ! Expanded uncertainty
12210 OUTPUT Gm$ USING "#,Z.DDDD";Gm         ! Mount reflection coefficient
12220 ! Print Table
12230 OUTPUT @P1;"
12240 OUTPUT @P1;"
12250 OUTPUT @P1;"
12260 OUTPUT @P1;"
12270 OUTPUT @P1;"
12280 OUTPUT @P1;"
12290 OUTPUT @P1;"
12300 OUTPUT @P1;"
12310 OUTPUT @P1;"
12320 OUTPUT @P1;"
12330 OUTPUT @P1;"
12340 OUTPUT @P1;"
12350 OUTPUT @P1;"
12360 OUTPUT @P1;"
12370 OUTPUT @P1;"
12380 OUTPUT @P1;"
12390 OUTPUT @P1;"
12400 OUTPUT @P1;"
12410 OUTPUT @P1;"
12420 OUTPUT @P1;"
12430 OUTPUT @P1;"
12440 OUTPUT @P1;"
12450 OUTPUT @P1;"
12460 SUBEND
12470 !
12480 ! -----
12490 !
12500 Kx_init: SUB Kx_init           ! Init Panasonic KX-P1180 Printer
12510 ! or any Epson FX-86e/FX-800 compatible.
12520 ! Printer must be in PGM mode.
12530 ! (Epson LQ untested)
12540 PRINTER IS 10;WIDTH 96         ! Output to printer
12550 PRINT CHR$(27)&"@";           ! Reset printer
12560 PRINT CHR$(27)&"k3";           ! 0=Courier, 1=Sans Serif, 3=Prestige
12570 PRINT CHR$(27)&"x1";           ! NLQ font
12580 PRINT CHR$(27)&"M";           ! P=10 cpi M=12 cpi
12590 PRINT CHR$(27)&"c1";           ! Selects standard graphic character set
12600 PRINT CHR$(27)&"7";           ! Selects IBM mode (character set 1)
12610 PRINT CHR$(27)&"2";           ! 6 lpi
12620 PRINT CHR$(27)&"1"&CHR$(12); ! Set left Margin to 12 chr's (1")
12630 SUBEND
12640 !
12650 ! -----
12660 !

```

Value of uncertainty components in percent at 1 GHz.		
Uncertainty factor	Uncertainty limits	Standard uncertainty
DVM	" ;Dpu\$; "	" ;Sdpu\$; "
Mount calibration factor	" ;Cfu\$; "	" ;Scfu\$; "
Mismatch (mount reflection coefficient = " ;Gm\$; ")	" ;Mmu\$; "	" ;Smmu\$; "
Dual element	" ;Deu\$; "	" ;Sdeu\$; "
Random effects (standard deviation of the mean)	" ;Sdu\$; "	" ;Sd\$; "
Worst case sum	" ;Wc\$; "	
Combined standard uncertainty (RSS)		" ;Cs\$; "
Expanded uncertainty (coverage factor = 2)		" ;Ex\$; "

