

SEP 28 1966

NATIONAL BUREAU OF STANDARDS REPORT

9417

EXAMINATION OF TYPE 431 STAINLESS STEEL
ALLOY T-BOLTS USED IN MARMAN V-BAND
COUPLINGS

By
W. F. Gerhold

To
Materials Division
Air Systems Command
Department of the Navy
Project Number RRMA 2122



U. S. DEPARTMENT OF COMMERCE
NATIONAL BUREAU OF STANDARDS

THE NATIONAL BUREAU OF STANDARDS

The National Bureau of Standards is a principal focal point in the Federal Government for assuring maximum application of the physical and engineering sciences to the advancement of technology in industry and commerce. Its responsibilities include development and maintenance of the national standards of measurement, and the provisions of means for making measurements consistent with those standards; determination of physical constants and properties of materials; development of methods for testing materials, mechanisms, and structures, and making such tests as may be necessary, particularly for government agencies; cooperation in the establishment of standard practices for incorporation in codes and specifications; advisory service to government agencies on scientific and technical problems; invention and development of devices to serve special needs of the Government; assistance to industry, business, and consumers in the development and acceptance of commercial standards and simplified trade practice recommendations; administration of programs in cooperation with United States business groups and standards organizations for the development of international standards of practice; and maintenance of a clearinghouse for the collection and dissemination of scientific, technical, and engineering information. The scope of the Bureau's activities is suggested in the following listing of its three Institutes and their organizational units.

Institute for Basic Standards. Applied Mathematics. Electricity. Metrology. Mechanics. Heat. Atomic Physics. Physical Chemistry. Laboratory Astrophysics.* Radiation Physics. Radio Standards Laboratory.* Radio Standards Physics; Radio Standards Engineering. Office of Standard Reference Data.

Institute for Materials Research. Analytical Chemistry. Polymers. Metallurgy. Inorganic Materials. Reactor Radiations. Cryogenics.* Materials Evaluation Laboratory. Office of Standard Reference Materials.

Institute for Applied Technology. Building Research. Information Technology. Performance Test Development. Electronic Instrumentation. Textile and Apparel Technology Center. Technical Analysis. Office of Weights and Measures. Office of Engineering Standards. Office of Invention and Innovation. Office of Technical Resources. Clearinghouse for Federal Scientific and Technical Information.**

*Located at Boulder, Colorado, 80301.

**Located at 5285 Port Royal Road, Springfield, Virginia, 22171.

NATIONAL BUREAU OF STANDARDS REPORT

NBS PROJECT

3120410

BU WEPS RRMA 2122

SEP 28 1966

NBS REPORT

9417

EXAMINATION OF TYPE 431 STAINLESS STEEL ALLOY T-BOLTS USED IN MARMAN V-BAND COUPLINGS

by
W. F. Gerhold

Sponsor

Materials Division
Air Systems Command
Department of the Navy

IMPORTANT NOTICE

NATIONAL BUREAU OF STANDARDS
for use within the Government. E
and review. For this reason, the
whole or in part, is not authorized
Bureau of Standards, Washington
the Report has been specifically p

Approved for public release by the
director of the National Institute of
Standards and Technology (NIST)
on October 9, 2015

; accounting documents intended
subjected to additional evaluation
listing of this Report, either in
Office of the Director, National
the Government agency for which
copies for its own use.



U. S. DEPARTMENT OF COMMERCE
NATIONAL BUREAU OF STANDARDS

Examination of Type 431 Stainless Steel
Alloy T-Bolts Used In Marman V-Band
Couplings

- References: (a) NBS Report No. 8361, "Failed Marman Type Clamps From A Model J79 Engine S/N 62-12184 and S/N 62-12189", dated June 8, 1964.
- (b) NBS Report No. 9077, "The Examination of a Failed 431 Stainless Steel alloy T-Bolt (Marman Clamps)", dated April 1, 1966
- (c) Bureau of Naval Weapons letter RRMA-223: GMY/58, dated 10 June 1964.

Introduction: Numerous failures in service of type 431 stainless steel alloy T-bolts used in Marman V-band couplings have prompted the comprehensive examination reported herein. Of the three failures examined at NBS, two were attributed to stress corrosion, Reference (a) and one to stress corrosion and fatigue, Reference (b). In each instance, well defined carbide layers were noted at the peripheral areas and at areas in and adjacent to secondary cracks in the bolts examined. These bolts were identified as having been manufactured prior to November 1962.

Subsequent to examination of the aforementioned bolts, the Naval Air Station at North Island found an unsatisfactory bolt lot. Reference (c) requested that bolts in this lot be examined to determine whether they were unsuitable as a result of marginal heat treating practice or other material conditions.

Material: Two Marman couplings, each with a type 431 stainless steel alloy T-bolt from the lot of unsatisfactory bolts were submitted for examination. The bolts were labeled North Island, lot 1, items a and b for identification purposes in this report.

Prior to completing the examination of the North Island, lot 1 items, additional materials were submitted for examination. These included the following:

1. Bolts from various stages of manufacture.
2. Bolts removed, under AFC(change) 200, from aircraft that had never flown.
3. Bolts from production lots.

4. Experimental bolts.

To facilitate examination, the material was sorted into groups identified by modification (Mod) numbers. The Mod numbers assigned are related to various head stamp markings, slotted grooves and dimples on the thread end and thread dye markings. The markings originally established the approximate date of manufacture and processing procedures employed.

Table 1 lists all of the known dates of manufacture, identifications, processing variables and heat treatment for each Mod. Mods 1 through 8 include production bolts still in use. Mods 9X through 17X are experimental materials. Mod 13X, 14X and 15X were subjected to the first stages of processing given Mod 7 bolts. No materials were submitted from the Mod 4 category.

Each of the bolts submitted was labeled by lot and item number for additional identification purposes. Table 2 includes a summarization of the materials by lot, item, number of pieces and appropriate Mod number.

Bend Tests: Guided bend test were performed on representative bolts from each lot with the exception of lot 1, 5, (item c) and 6. The results obtained from these tests are given in Table 3. The bend tests performed on bolts from lot 2 were of an unrestrained nature, while tests on bolts from all of the other lots tested were performed with the bolts held rigid at the "T" head and at the threaded end. The specimens were bent until failure occurred and the maximum bend angle obtained was recorded. All bend test specimens failed at the last thread of the bolt shank.

There did not appear to be any significant trend in bend angles other than that obtained for the $\frac{1}{4}$ inch-28 bolts from Mods 7 and 8. For these bolts the bend angles were 10 degrees and 15 degrees, respectively. The bend angle for 10-32 bolts from Mod 7 was higher (17 degrees). For materials from lots 4 and 5, processed in accordance with conditions specified for Mods 1, 2 or 3 and 5 or 6, the bend angles varied between 10 degrees and 30 degrees.

The lower structural yield load values obtained for some of the bolts may be attributed to a notch effect at the last thread on the shank.

Bolts taken from any of the Mods, when clamped at the shank end in a bench vise, were capable of being bent through an angle of 180 degrees at the unthreaded shank, without failure. Marman Process Bulletin MPB 200.030 C specifies that the bolts shall be capable of being bent without failure to an angle of 90 degrees over a mandrel having a diameter twice that of the bolt shank.

Tensile Tests: Tensile tests were performed on bolts from each lot, with the exception of those from lots 1 and 2. The tensile tests were conducted in accordance with ASTM specification A-370-64, Supplement III, Steel Fasteners. The maximum load to produce failure and the total elongation of each bolt tested are given in Table 3.

Marman MPB 200.030 C specifies, for 180 Ksi bolts, minimum tensile values of 3600 lbs and 6552 lbs, respectively, for 10-32 and $\frac{1}{4}$ -28 bolts. The total elongations specified are 0.058 inch minimum for a 10-32 bolt and 0.077 inch minimum for a $\frac{1}{4}$ "-28 bolt.

The results of the tensile tests show that 2 bolts from lot 4 and 3 bolts from lot 5 failed to meet the minimum tensile requirement for $\frac{1}{4}$ -28 bolts. These bolts were from lots that had been removed from F-4 aircraft (under AFC (change) 200). These bolts were processed in accordance with the procedures specified for Mods 1, 2 or 3 and had been manufactured prior to May 31, 1962.

All of the other bolts tested had tensile properties within specification limits.

There was no significant improvement in the tensile properties of bolts that had been shot peened or Harperized (Lot 7, items 2, 3 and 4).

Lot 8 bolts showed a decrease in breaking load and an increase in elongation over that obtained in testing bolts of the same Mod number from lot 3, item a; lot 4, item c; and lot 5, item c.

Hardness: Knoop hardness (500g load) determinations were made on transverse sections cut from the unthreaded shank areas of representative bolts from each lot. These determinations converted to Rockwell C, are given in Table 3. The first value was obtained at areas adjacent to the specimen edge and the second value was obtained from an area adjacent to the center of the specimen.

A hardness of 45 Rc maximum and an ultimate tensile strength of 180,000 psi minimum are specified for 431 stainless steel alloy T bolts in Marman Process Bulletin MPB 200.030c. The hardness for a tensile value of 180,000 psi is approximately Rc 39.

Using hardness values as criteria for acceptance in procurement, a hardness, Rc 37, for one bolt from lot 3, item b and a high hardness, Rc 47, for one bolt from lot 7, item 1, may or may not be cause for rejection, inasmuch as these values were obtained from areas adjacent to the surface only. The extremely low hardness values obtained for the two bolts from lot 4 and the three bolts from lot 5 that failed to meet the minimum tensile requirements would definitely be cause for rejection. By comparing the hardness obtained for lot 6, items 1 and 2 (annealed material) with the hardness of two bolts from lots 4 and 5 it appears that the latter were still in the annealed condition. The higher hardness, Rc 22-29, obtained for the other bolt from lot 5 indicates that this bolt had received insufficient heat treatment or had been tempered in the temperature range of 1040° to 1125°F. This is a higher tempering temperature than that specified for a 180 ksi bolt, but, may be normal for a 125 ksi bolt, (hardness Rc 26-34). The hardness of all of the other bolts examined was within the limits specified for a 180 ksi bolt.

Metallographic Examination: Sections were cut from bolts from each lot for metallographic examination.

Examination of transverse sections, obtained from unthreaded shank areas of bolts from lot 1, items a and b, revealed that the microstructure was tempered martensite with no evidence of delta ferrite, Figure 1. After repolishing and etching of the same sections, carbides were found randomly distributed throughout the sections. However, the carbides were more abundant at the bolt periphery than at the bolt center, Figures 2a and 2b. The carbide distribution in these bolts was similar to that noted and previously discussed for the failed bolts. As noted in Table 2, these bolts were identified as having been manufactured prior to May 31, 1962.

In the case of the bolts from lots 2 and 3 the carbide distribution was random and there was no evidence of a carbide layer at the surface, Figures 3a and 3b. The microstructure was tempered martensite with delta ferrite, Figure 4. These bolts were manufactured between November 1962 and February 1965 by Standard Pressed Steel under more rigid heat treatment controls.

Examination of transverse sections cut from lot 4 and 5 bolts that failed to meet the tensile and hardness requirements revealed the following:

- (1) Four tensile test specimens, 2 from each lot still in the annealed condition, Figure 5. Figure 6 shows, for purpose of comparison, the annealed microstructure of material as received from the mill (example is from lot 6, item 1).
- (2) One tensile test specimen from lot 5 (hardness Rc 22-29) had been heat treated. The microstructure in this specimen was martensitic with no metallographic evidence of delta ferrite, Figure 7. The evidence of a heat treated structure here would tend to substantiate that there was an improper heat treatment or that a higher tempering temperature than that in the previous cases was employed.

The microstructure of bolts from lot 6, items 3 and 4 were similar to that shown for the lot 2 and 3 bolts. In the case of item 5 and 6 bolts, it was observed that the abundance of carbides was considerably reduced, Figures 8a and 8b. The microstructure of the item 5 and 6 bolts was tempered martensite with delta ferrite and there was some grain growth, Figure 9.

The reduction in the amount of carbides and the grain growth may be related to the heat treatment accorded the item 5 and 6 bolts. Table 1 shows an increase in time at the austenitizing temperature for item 5 and the inclusion of a refrigeration treatment before double tempering at 550 degrees F for item 6. As noted in Table 1, the increase in time at the austenitizing temperature and the double temper at 550 degrees F are now recommended for 431 stainless steel T-bolts for use in Marman V-band couplings.

The microstructure of bolts from lot 7, items 1, 2, 3, 4 and A-2 was essentially the same as that shown in Figure 9 and the carbide distribution was similar to that shown in Figures 8a and 8b. These bolts were drawn from lots representative of the latest heat treatment. The microstructure for the bolts from item A-1 was similar to that shown in Figure 4 and the distribution of carbides was similar to that shown in Figures 3a and 3b for the lot 2 and 3 bolts.

Examination of the bolts from lot 8 revealed that the microstructure was tempered martensite with delta ferrite. However, it was noted that there was a considerable increase in the amount of delta ferrite over that previously observed in all of the other specimens examined, Figure 10. The distribution of carbides was similar to that shown in Figure 3a and 3b.

Conclusions: Type 431 stainless steel alloy T-bolts examined included the following materials:

- (1) Material from various stages of manufacture.
- (2) Bolts from production lots.
- (3) Bolts that had been removed from aircraft that had never flown.
- (4) Experimental bolts that had been subjected to various heat treatments and / or surface cold working.

The results obtained from hardness and tensile test revealed that 4 bolts removed from aircraft that had never flown were still in the annealed condition and that one bolt may have been tempered at a temperature higher than that recommended for a 180 ksi bolt. These conditions were confirmed by metallographic examination. Bolts in this category were identified as having been manufactured prior to May 31, 1962. Metallographic examination revealed undesirable carbide layers adjacent to the periphery in other bolts manufactured during this period. The microstructures observed were tempered martensite with no metallographic evidence of delta ferrite. The failures of type 431 stainless steel alloy T-bolts, previously reported in references (a) and (b) were attributed to stress corrosion and to stress corrosion and fatigue respectively. In each instance failure was linked to the presence of excessive carbides, particularly at surface areas. In addition, the failed bolts were identified as belonging to the same period of manufacture (pre May 31, 1962).

The results obtained from tensile and hardness tests showed that variations in heat treatment (time at austenitizing temperature and tempering alterations) did not significantly alter tensile and hardness properties. However, austenitizing for 1 hour and double tempering at 550 degrees F improved the solution of carbides. It was found that surface cold working, shot peening and Harperizing, did not alter the tensile or hardness properties.

The results obtained from guided bend tests did not reveal any significant correlation. The structural yield load varied within each lot tested. The variation is believed to be due to a notch effect at the last thread on the shank. Specimens from any period of manufacture were when clamped in a vise capable of being bent through an angle of 180 degrees without failure.

It is evident from the large number of modifications and identifications that a "store" problem has been created in supplying acceptable T-bolts from new installations and replacement. As the first step in alleviating this situation, it is recommended that all bolts identified as having been manufactured prior to May 31, 1962 be removed from supply bins or other access because of the unreliability of manufacturing procedures during this period.

Table 1. Bolt identification, processing variables and heat treatment for various modifications (Mod No's).

Mod. No.	Period of Manufacture	Identification	Processing Variable	Heat Treatment
1	11-19-54 to 11-1-61	Complete "T" bolt dye blue (a)	Bolts processed using normal heat treatment and military type of receiving and inspection.	Anneal at 1400°F and within 1½ hrs austenitize at 1890°F ±100 for 20 min. Oil quench within 30 sec in 75-140°F oil. Degrease. Temper at 600°F for 2 hrs and air cool. Furnace atmosphere-dry N2 or Ar2. Dew point of gas: -40 max.
2	11-1-61 to 5-31-62	¼ inch of thread end dyed blue (a)	Bolts were processed using Marman improved heat treatment with tightened requirements for heat treatment and receiving inspection tests (embrittlement, static load and metallurgical examination).	In accordance with MIL-H-6875 for 180 ksi min. tensile strength.
3	5-31-62 to 10-12-62	Same as for Mod 2 plus dimple punch on thread end (a)	Requirements of Mod 2 plus additional requirement of shaved wire stock (improved surface finish).	Same as for Mod 2.
4	10-12-62 to 11-2-62	"T" head dyed blue. Dimple punch on thread end to indicate shaved wire. (a)	Requirements of Mods 2 or 3 except heat treated by SPS to their published test procedure.	In accordance with MIL-11-6875 and to develop mechanical properties specified in Marman MPB 200.030 (b)

Table 1. (cont.)

Mod. No.	Period of Manufacture	Identification	Processing Variable	Heat Treatment
5	10-12-62 to 11-2-62	"T" head dyed blue head stamp plus dot. (c)	Complete processing by SPS to Marman MPB 200.021.	Same as Mod 4.
6	11-2-62 to 4-14-64	One inch of thread end dyed blue, head stamp plus dot.	Threads rolled after treatment. Complete processing by SPS.	Same as Mods 4 and 5 except tightened heat treating requirements -- details not available.
7	4-14-64 to 2-16-65	One inch of thread end dyed blue, head stamp plus dot plus dash. Also grooved slot in thread end for visual examination.	Same as Mod 6.	Same as Mod 6.
8	2-16-65 on.	Head stamp plus dot plus dash. Also grooved slot in thread end for visual examination.	Same as Mod 6.	Improved heat treatment which includes increase in austenitizing time to 1 hr and a double temper at 550°F.
9X	Experimental Material	Same as Mod 8.	Threads rolled after heat treatment plus shot peened on head and unthreaded shank.	Same as Mod 8.
10X	Same as Mod 9X.	Same as Mod 8.	Threads rolled after heat treatment, except Harperized before roll threading	Same as Mod 8.

Table 1. (cont.)

Mod. No.	Period of Manufacture	Identification	Processing Variable	Heat Treatment
11X	Same as Mod 9X	Same as Mod 8.	Threads rolled after heat treatment plus Harperized	Same as Mod 8.
12X	Same as Mod 9X	Head stamp plus dot.	Material high in free ferrite.	Unknown
13X	Stage material from lot 6 (Table 2).	NONE	Shaved wire stock to meet chemical requirements of MIL-S-18732-C.	Annealed as received from the mill.
14X	Same as Mod 13X	Head stamp plus dot plus dash.	Same as Mod 13X except cold headed.	Same as Mod 13X
15X	Same as Mod 13X	Same as Mod 8.	Same as Mod 14X	Same as Mod 8.
16X	Experimental Material	One inch of thread end dyed blue, head stamp plus dot plus dash.	Roll threaded after head treatment.	Same as Mod 6 except austenitizing time is 1 hr.
17X	Same as Mod 16X	Same as Mod 14X	Same as Mod 16X	In accordance with par. 3, 4, 1 (Ht 200 condition) of MIL-S-18732C.

(a) Bolts from Mods 1 through 4 may or may not have had the head stamp identification.

(b) Mechanical properties specified in Marman MPB 200.030 C for 180,000 psi bolts:

Bolt Size	Min. Tensile Value, lbs.	Min. Hardness R _c
10-32	3,600	0.058
¼-28	6,552	0.077

(c) Identification used in error.

Table 2. Additional Identification of Materials submitted for identification.

Mod. No.	Lot No.	Item No.	No. of Pieces	Head Stamp	Bolt Size
1 or 2	1	a	1	NONE	1/4" - 28
1 or 2	1	b	1	NONE	1/4" - 28
6	2	a	5	flying A.	1/4" - 28
6	2	b	5	flying A.	10 - 32
7	2	c	1	flying A.	1/4" - 28
7	3	a	10	flying A.	1/4" - 28
7	3	b	10	flying A.	10 - 32
1 or 2(3)	4(1)	a	1	NONE	1/4" - 28
1 or 2(3)	4(1)	b	6	flying A.	1/4" - 28
5 or 6(3)	4(1)	c	6	flying A.	1/4" - 28
1 or 2(3)	5(2)	a	32	NONE	1/4" - 28
1 or 2(3)	5(2)	b	7	flying A.	1/4" - 28
5 or 6(3)	5(2)	c	1	flying A.	1/4" - 28
13 X	6	1	2	(4)	1/4" dia
14 X	6	2	10	flying A.	1/4" - 28
15 X	6	3	10	flying A.	1/4" - 28
8	6	4	10	flying A.	1/4" - 28
16 X	6	5	10	flying A.	1/4" - 28
17 X	6	6	10	flying A.	1/4" - 28
8	7	1	10	flying A.	1/4" - 28
9 X	7	2	10	flying A.	1/4" - 28
10 X	7	3	10	flying A.	1/4" - 28
11 X	7	4	10	flying A.	1/4" - 28
3	7	A-1	10	flying A.	1/4" - 28
8	7	A-2	10	flying A.	1/4" - 28
12 X	8	1	10	flying A.	1/4" - 28

- (1) Bolts submitted by McDonnell Aircraft, St. Louis, Mo.; removed, under AFC (change) 200, from aircraft that had never flown.
- (2) From F-4B-150493 Oceana aircraft; removed under AFC (change) 200.
- (3) Dye markings were indeterminate or suspect due to adherent grease or dirt.
- (4) Bar stock, annealed material.

Table 3. Mechanical properties of representative T-bolts submitted for examination.

Lot No.	Item	Hardness Rockwell C (1)	Tensile Properties		Bend Properties	
			Breaking load, lbs.	Total Elongation Inches	Structural yield, load, lbs.	Bend Angle degrees
1	a	42-43				
2	b	43-42			2030	40
	a	42-44			2035	40
	b	41-41			1025	17
		46-44			800	10
3	c	42-40			1825	10
	a	46-43			1755	10
					1760	10
					2240	10
		46-44	8100	0.16		
		46-47	8025	0.20		
	b	46-45	8125	0.17		
					1750	17
					1875	17
					1810	17
4		42-45	4230	0.12		
		44-42	4270	0.12		
		37-41	4240	0.12		
	a	-----	7400	-----		
	b				2170	10
					1500	10
					3140	25
		97-100 RB	4225			
	c	95-97 RB	4100		3410	25
					2130	15
			7975		1960	10
			8925			
			8575			

Table 3. (cont.)

Lot No.	Item	Hardness Rockwell C (1)	Tensile Properties		Bend Properties	
			Breaking load, lbs.	Total Elongation Inches	Structural yield, load, lbs.	Bend Angle degrees
5	a	22-29	7325		3160	30
			7250		3200	30
			7600		3450	30
			5000			
			7000			
6	b		7375			
			7050			
					2260	20
					1590	10
	c	95-96 RB 96-97 RB 95-97 RB (2) 100-99 RB (2) 43-45 46-46	7225			
			7150			
			4375			
			4175			
			7425			
	1	45-43	8500			
	2					
	3					
	4					
	5					
	6	40-40				

Table 3. (cont.)

Lot No.	Item	Hardness Rockwell C (1)	Tensile Properties		Bend Properties	
			Breaking load, lbs.	Total Elongation Inches	Structural yield, load, lbs.	Bend Angle degrees
7	1	47-46	8075	0.091	2180	15
			7975	0.097		15
						17
	2		8125	0.093	1730	15
			7775	0.094		15
			7850	0.087		15
	3		8025	0.090	2780	15
			7825	0.088		15
			7975	0.090		15
4	7925	0.096	2150	15		
	7975	0.094		15		
	7900	0.090		15		
A-1	46-43	7975	0.084	2260	15	
		8025	0.089		15	
		7975	0.096			
	44-43	7750	0.080	3180	20	
		7675	0.074		20	
		7850	0.091		20	

Table 3. (cont.)

Lot No.	Item	Hardness Rockwell C (1)	Tensile Properties		Bend Properties	
			Breaking load, lbs.	Total Elongation Inches	Structural yield, load, lbs	Bend Angle degrees
8	1	43-40	7115	0.116	2280	25
			7215	0.121	2070	25
			7175	0.110	2415	25

(1) Hardness values are converted from Knoop (500g) determinations. First value was obtained at area adjacent to the edge; second value was obtained at area adjacent to the center. All determinations were made on transverse bolt sections.

(2) Annealed material.






Figure 1. Typical microstructure for bolts from lot 1.
Microstructure is tempered martensite with no
metallographic evidence of delta ferrite.
Etched with Kalling's reagent. X500.



a



b

Figure 2. Typical Carbide distribution in T-bolts from Lot 1. Etched, electrolytically in 10% NaCN. X500.

- a. Note abundance of carbides adjacent to bolt periphery. Concentration appears to diminish toward center.
- b. Carbide concentration at center of T-bolt.




a



b

Figure 3. Typical Carbide distribution in bolts from lots 2 and 3. Etched electrolytically in 10% NaCN. X500.
a. Concentration adjacent to bolt periphery.
b. Concentration at center.






Figure 4. Typical Microstructure in bolts from lots 2 and 3. Microstructure is tempered martensite with delta ferrite. Etched, with Kalling's reagent. X500.




Figure 5. Microstructure of lot 4 T-bolt that failed to meet the minimum tensile and hardness requirements. Microstructure is similar to that of annealed material. Etched with Kalling's reagent. X500.





Figure 6. Photomicrograph of annealed material from lot 6, item 1, presented here for comparison with the annealed microstructure shown in Figure 5. Etched with Kalling's reagent. X500.



Figure 7. Photomicrograph of a portion of the section of a lot 5 bolt that failed to meet the minimum tensile and hardness requirements for a 180 ksi bolt. Microstructure is tempered martensite with no metallographic evidence of delta ferrite. Etched with Kalling's reagent. X500.



a



b

Figure 8. Typical carbide distribution in lot 6, items 5 and 6 bolts. Etched electrolytically in 10% NaCN. X500.
a. Concentration adjacent to the periphery.
b. Concentration at the center.



Figure 9. Photomicrograph of typical structure in bolts from lot 6, item 5 and 6. Microstructure is tempered martensite with delta ferrite. Note that some grain growth occurred. Etched with Kalling's reagent. X500.



Figure 10. Microstructure in a bolt from lot 8. Note the presence of an abundance of free ferrite in the tempered martensite matrix. Etched with Vilella's reagent. X500.

