



NIST
PUBLICATIONS

NIST Special Publication 1000-5

June 2004
Progress Report on the
Federal Building and Fire Safety
Investigation of the
World Trade Center Disaster

Volume 4
Contains Appendices G, H, and I



National Institute of Standards and Technology • Technology Administration • U.S. Department of Commerce

QC
100
.457
#1000-5
v. 4
2004
c. 2

NIST Special Publication 1000-5

June 2004
Progress Report on the
Federal Building and Fire Safety
Investigation of the
World Trade Center Disaster

Volume 4
Contains Appendices G, H, and I

June 2004



U.S. Department of Commerce
Donald L. Evans, Secretary

Technology Administration
Phillip J. Bond, Under Secretary for Technology

National Institute of Standards and Technology
Arden L. Bement, Jr., Director

Disclaimer

Certain commercial entities, equipment, products, or materials are identified in this document in order to describe a procedure or concept adequately or to trace the history of the procedures and practices used. Such identification is not intended to imply recommendation, endorsement, or implication that the entities, products, materials, or equipment are necessarily the best available for the purpose. Nor does such identification imply a finding of fault or negligence by the National Institute of Standards and Technology.

Disclaimer

The policy of NIST is to use the International System of Units (metric units) in all publications. In this document, however, units are presented in metric units or the inch-pound system, whichever is prevalent in the discipline.

Use in Legal Proceedings

No part of any report resulting from a NIST investigation into a structural failure or from an investigation under the National Construction Safety Team Act may be used in any suit or action for damages arising out of any matter mentioned in such report (15 USC 281a; as amended by P.L. 107-231).

National Institute of Standards and Technology Special Publication 1000-5
Natl. Inst. Stand. Technol. Spec. Publ. 1000-5, 1,054 pages (June 2004)
CODEN: NSPUE2

U.S. GOVERNMENT PRINTING OFFICE
WASHINGTON: 2004

For sale by the Superintendent of Documents, U.S. Government Printing Office
Internet: bookstore.gpo.gov — Phone: (202) 512-1800 — Fax: (202) 512-2250
Mail: Stop SSOP, Washington, DC 20402-0001

MASTER TABLE OF CONTENTS

Volume 1

Table of Contents

List of Acronyms and Abbreviations

Metric Conversion Table

Preface

Executive Summary

Chapter 1
Interim Findings and Accomplishments

Chapter 2
Progress on the World Trade Center Investigation

Chapter 3
Update on Safety of Threatened Buildings (WTC R&D) Program

Chapter 4
Update on WTC Dissemination and Technical Assistance Program

Volume 2

Table of Contents

List of Acronyms and Abbreviations

Metric Conversion Table

Appendix A
Interim Report on the Analysis of Building and Fire Codes and Practices

Appendix B
Interim Report on Development of Structural Databases and Reference Models
for the WTC Towers

Appendix C
Interim Report on Analysis of Aircraft Impact into the WTC Towers

Volume 3

Table of Contents

List of Acronyms and Abbreviations

Metric Conversion Table

Appendix D
Interim Report on Preliminary Stability Analysis of the WTC Towers

Appendix E
Interim Report on Contemporaneous Structural Steel Specifications

Appendix F
Interim Report on Inventory and Identification of Steels Recovered from the WTC Buildings

Volume 4

Table of Contents

List of Acronyms and Abbreviations

Metric Conversion Table

Appendix G
Interim Report on Significant Fires in WTC 1, 2, and 7 Prior to September 11, 2001

Appendix H
Interim Report on Evolution of WTC Fires, Smoke, and Damage based on Image Analysis

Appendix I
Interim Report on Assessment of Sprayed Fireproofing in the WTC Towers—Methodology

Volume 5

Table of Contents

List of Acronyms and Abbreviations

Metric Conversion Table

Appendix J

Interim Report on Experiments to Support Fire Dynamics and Thermal Response Modeling

Appendix K

Interim Report on Subsystem Structural Analysis of the WTC Towers

Appendix L

Interim Report on WTC 7

Appendix M

Interim Report on 2-D Analysis of the WTC Towers Under Gravity Load and Fire

Volume 6

Table of Contents

List of Acronyms and Abbreviations

Metric Conversion Table

Appendix N

Interim Report on Analysis of First-Person Accounts from Survivors of the WTC Evacuation on September 11, 2001

Appendix O

Interim Report on Telephone Interviews

Appendix P

Interim Report on Emergency Communications

Appendix Q

NIST's Working Hypothesis for Collapse of the WTC Towers

This page intentionally left blank.

LIST OF ACRONYMS AND ABBREVIATIONS

AAPOR	American Association of Public Opinion Research
ABC	American Broadcasting Company
ACI	American Concrete Institute
AISC	American Institute of Steel Construction
AISI	American Iron and Steel Institute
ALE	Arbitrary-Lagrangian-Eulerian
AMCBO	Association of Major City/County Building Officials
ANSI	American National Standards Institute
ANSYS	finite element model
ARA	Applied Research Associates, Inc.
ASCE	American Society of Civil Engineers
ASHRAE	American Society of Heating, Refrigerating and Air-Conditioning Engineers, Inc.
ASME	American Society of Mechanical Engineers
ASTM	ASTM International
AWS	American Welding Society
BOCA	Building Officials and Code Administrators
BOCA/BBC	BOCA Basic Building Code
BPAT	Building Performance Assessment Team
BPS	Building Performance Study
BSI	British Standards Institution
C/F	cancer free
CATI	computer-assisted telephone interviews
CBR	chemical, biological, and radiological
CBS	Columbia Broadcasting System
CERF	Civil Engineering Research Foundation
CFD	computational fluid dynamics
CIB	International Council for Research and Innovation in Building and Construction
CII	Construction Industry Institute
CNN	Cable News Network

CPP	Cermak Peterka Peterson, Inc.
CPU	central processing unit
CRT	cathode-ray tube
CTB&UH	Council on Tall Buildings and Urban Habitat
CTE	coefficients of thermal expansion
DC/F	BlazeShield DC/F fire protective insulation
DL	dead load
DTAP	dissemination and technical assistance program
EMS	Emergency Medical Service
EMT	Emergency Medical Team
ER&S	Emory Roth & Sons
FBI	Federal Bureau of Investigation
FCA	Flux cored arc
FDNY	New York City Fire Department
FDS	Fire Dynamics Simulator
FE	finite element
FEA	finite element analysis
FEM	finite element model
FEMA	Federal Emergency Management Agency
FMRC	Factory Mutual Research Corp.
FSI	Fire-Structure Interface
FVM	Finite Volume Method
GFI	Government Furnished Information
GG	glass over glass
GHz	gigahertz
GMS, LLP	Gilsanz Murray Steficek, LLP
HAZ	heat affected zone
HNSE	Hugo Nue Schnutzer East
HRR	heat release rate
HVAC	heating, ventilating, and air conditioning
IAQ	indoor air quality
IBC	International Building Code

ICBO	International Conference of Building Officials
ICC	International Code Council
IMTI	Integrated Manufacturing Technology
JFK	John F. Kennedy International Airport
JIS	Japan Industrial Standard
LERA	Leslie E. Robertson Associates
LES	Large Eddy Simulation
LL	live load
LSTC	Livermore Software Technology Corporation
MBC	BOCA National Building Code
MCC	Municipal Code of Chicago
MPI	Message Passing Interface
NBC	National Broadcasting Company
NBFU	National Board of Fire Underwriters
NCSBCS	National Conference of States on Building Codes & Standards, Inc.
NCST	National Construction Safety Team
NEMA	National Electrical Manufacturers Association
NFPA	National Fire Protection Association
NIBS	National Institute of Building Sciences
NIST	National Institute of Standards and Technology
NYC	New York City
NYCBC	New York City Building Code
NYCDOB	New York City Department of Buildings
NYPD	New York City Police Department
NYSBC	New York State Building Construction Code
P.L.	Public Law
PANYNJ	Port Authority of New York and New Jersey
PAPD	Port Authority Police Department
PC&F	Pacific Car and Foundry
PDM	Pittsburg-Des Moines
PONYA	Port of New York Authority
R&D	research and development

RWDI	Rowan Williams Davis and Irwin, Inc.
SBCCI	Southern Standard Building Code
SDL	superimposed dead load
SDO	standards development organization
SEAO NY	Structural Engineers Association of New York
SFPE	Society of Fire Protection Engineering
SFRM	spray-on fire resistant material or sprayed fire resistive materials
SHCR	Skilling, Helle, Christiansen, & Robertson
SI	metric
SLB	short legs back-to-back
SMA	Shielded Metal Arc
SOD	Special Operations Division
SOM	Skidmore, Owings & Merrill
SPH	Smoothed Particle Hydrodynamics
SQL	Structured Query Language
SWMB	Skilling, Ward, Magnussen, and Barkshire
TL	Truss Lower Chord
TM	Truss Middle Chord
TU	Truss Upper Chord
UBC	Uniform Building Code
UL	Underwriters' Laboratories, Inc.
USC	United States Code
USM	United States Mineral Products Co.
VCBT	Virtual Cybernetic Building Testbed
WABC	WABC-TV New York
WCBS	WCBS-TV New York
WF	wide flange (a type of structural steel shape now usually called a W-shape). ASTM A 6 defines them as "doubly-symmetric, wide-flange shapes with inside flange surfaces that are substantially parallel."
WNBC	NBC4 New York
WNYW	FOX5 New York
WPIX	WPIX-TV New York
WTC	World Trade Center

WTC 1	World Trade Center Tower 1
WTC 2	World Trade Center Tower 2
WTC 7	World Trade Center Building 7

Abbreviations

×	by
±	plus or minus
°C	degrees Celsius
°F	degrees Fahrenheit
μm	micrometer
2D	two dimensional
3D	three dimensional
cm	centimeter
ft	foot
ft ²	square foot
F_y	yield strength (AISC usage)
g	acceleration (gravity)
g	gram
gal	gallon
h	hour
in.	inch
kg	kilogram
kip	a stress unit equal to 1,000 pounds
kJ	kilojoule
kN	kilonewton
kPa	kilopascal
klb	1,000 pounds
ksi	1,000 pounds per square inch
kW	kilowatt
kW/m ²	kilowatts per square meter
L	liter
lb	pound
m	meter
m ²	square meter
mm	millimeter
m/s	meters per second

min	minute
MJ	megajoule
MPa	megapascal
mph	miles per hour
ms	microsecond
Msi	millions pounds per square inch
MW	megawatt
N	newton
Pa	pascal
pcf	pounds per cubic foot
plf	pounds per linear foot
psf	pounds per square foot
psi	pounds per square inch
s	second

This page intentionally left blank.

METRIC CONVERSION TABLE

To convert from	to	Multiply by
-----------------	----	-------------

AREA AND SECOND MOMENT OF AREA

square foot (ft ²)	square meter (m ²)	9.290 304 E-02
square inch (in ²)	square meter (m ²)	6.4516 E-04
square inch (in ²)	square centimeter (cm ²)	6.4516 E+00
square yard (yd ²)	square meter (m ²)	8.361 274 E-01

ENERGY (includes WORK)

kilowatt hour (kW * h)	joule (J)	3.6 E+06
quad (1015 BtuIT)	joule (J)	1.055 056 E+18
therm (U.S.)	joule (J)	1.054 804 E+08
ton of TNT (energy equivalent)	joule (J)	4.184 E+09
watt hour (W * h)	joule (J)	3.6 E+03
watt second (W * s)	joule (J)	1.0 E+00

FORCE

dyne (dyn)	newton (N)	1.0 E-05
kilogram-force (kgf)	newton (N)	9.806 65 E+00
kilopond (kilogram-force) (kp)	newton (N)	9.806 65 E+00
kip (1 kip=1000 lbf)	newton (N)	4.448 222 E+03
kip (1 kip=1000 lbf)	kilonewton (kN)	4.448 222 E+00
pound-force (lbf)	newton (N)	4.448 222 E+00

FORCE DIVIDED BY LENGTH

pound-force per foot (lbf/ft)	newton per meter (N/m)	1.459 390 E+01
pound-force per inch (lbf/in)	newton per meter (N/m)	1.751 268 E+02

HEAT FLOW RATE

calorieth per minute (calth/min)	watt (W)	6.973 333 E-02
calorieth per second (calth/s)	watt (W)	4.184 E+00
kilocalorieth per minute (kcalth/min)	watt (W)	6.973 333 E+01
kilocalorieth per second (kcalth/s)	watt (W)	4.184 E+03

To convert from	to	Multiply by
-----------------	----	-------------

LENGTH

foot (ft)	meter (m)	3.048 E-01
inch (in)	meter (m)	2.54 E-02
inch (in)	centimeter (cm)	2.54 E+00
micron (m)	meter (m)	1.0 E-06
yard (yd)	meter (m)	9.144 E-01

MASS and MOMENT OF INERTIA

kilogram-force second squared per meter ($\text{kgf} \cdot \text{s}^2/\text{m}$)	kilogram (kg)	9.806 65 E+00
pound foot squared ($\text{lb} \cdot \text{ft}^2$)	kilogram meter squared ($\text{kg} \cdot \text{m}^2$)	4.214 011 E-02
pound inch squared ($\text{lb} \cdot \text{in}^2$)	kilogram meter squared ($\text{kg} \cdot \text{m}^2$)	2.926 397 E-04
ton, metric (t)	kilogram (kg)	1.0 E+03
ton, short (2000 lb)	kilogram (kg)	9.071 847 E+02

MASS DIVIDED BY AREA

pound per square foot (lb/ft^2)	kilogram per square meter (kg/m^2)	4.882 428 E+00
pound per square inch (not pound force) (lb/in^2)	kilogram per square meter (kg/m^2)	7.030 696 E+02

MASS DIVIDED BY LENGTH

pound per foot (lb/ft)	kilogram per meter (kg/m)	1.488 164 E+00
pound per inch (lb/in)	kilogram per meter (kg/m)	1.785 797 E+01
pound per yard (lb/yd)	kilogram per meter (kg/m)	4.960 546 E-01

PRESSURE or STRESS (FORCE DIVIDED BY AREA)

kilogram-force per square centimeter (kgf/cm^2)	pascal (Pa)	9.806 65 E+04
kilogram-force per square meter (kgf/m^2)	pascal (Pa)	9.806 65 E+00
kilogram-force per square millimeter (kgf/mm^2)	pascal (Pa)	9.806 65 E+06
kip per square inch (ksi) (kip/in^2)	pascal (Pa)	6.894 757 E+06
kip per square inch (ksi) (kip/in^2)	kilopascal (kPa)	6.894 757 E+03
pound-force per square foot (lbf/ft^2)	pascal (Pa)	4.788 026 E+01
pound-force per square inch (psi) (lbf/in^2)	pascal (Pa)	6.894 757 E+03
pound-force per square inch (psi) (lbf/in^2)	kilopascal (kPa)	6.894 757 E+00
psi (pound-force per square inch) (lbf/in^2)	pascal (Pa)	6.894 757 E+03
psi (pound-force per square inch) (lbf/in^2)	kilopascal (kPa)	6.894 757 E+00

To convert from	to	Multiply by
TEMPERATURE		
degree Celsius (°C)	kelvin (K)	$T/K = t/^{\circ}\text{C} + 273.15$
degree centigrade	degree Celsius (°C)	$t/^{\circ}\text{C} \approx t/\text{deg. cent.}$
degree Fahrenheit (°F)	degree Celsius (°C)	$t/^{\circ}\text{C} = (t/^{\circ}\text{F} - 32)/1.8$
degree Fahrenheit (°F)	kelvin (K)	$T/K = (t/^{\circ}\text{F} + 459.67)/1.8$
kelvin (K)	degree Celsius (°C)	$t/^{\circ}\text{C} = T/K - 273.15$
TEMPERATURE INTERVAL		
degree Celsius (°C)	kelvin (K)	1.0 E+00
degree centigrade	degree Celsius (°C)	1.0 E+00
degree Fahrenheit (°F)	degree Celsius (°C)	5.555 556 E-01
degree Fahrenheit (°F)	kelvin (K)	5.555 556 E-01
degree Rankine (°R)	kelvin (K)	5.555 556 E-01
VELOCITY (includes SPEED)		
foot per second (ft/s)	meter per second (m/s)	3.048 E-01
inch per second (in/s)	meter per second (m/s)	2.54 E-02
kilometer per hour (km/h)	meter per second (m/s)	2.777 778 E-01
mile per hour (mi/h)	kilometer per hour (km/h)	1.609 344 E+00
mile per minute (mi/min)	meter per second (m/s)	2.682 24 E+01
VOLUME (includes CAPACITY)		
cubic foot (ft ³)	cubic meter (m ³)	2.831 685 E-02
cubic inch (in ³)	cubic meter (m ³)	1.638 706 E-05
cubic yard (yd ³)	cubic meter (m ³)	7.645 549 E-01
gallon (U.S.) (gal)	cubic meter (m ³)	3.785 412 E-03
gallon (U.S.) (gal)	liter (L)	3.785 412 E+00
liter (L)	cubic meter (m ³)	1.0 E-03
ounce (U.S. fluid) (fl oz)	cubic meter (m ³)	2.957 353 E-05
ounce (U.S. fluid) (fl oz)	milliliter (mL)	2.957 353 E+01

This page intentionally left blank.

TABLE OF CONTENTS

List of Tables	G-ii
----------------------	------

Appendix G

Interim Report on Significant Fires in WTC 1, 2, and 7 Prior to September 11, 2001 G-1

G.1 Background.....	G-1
G.2 FDNY Fire Reports and Fire Investigation Reports	G-1
G.2.1 Fire Record Forms	G-2
G.2.2 Overview of Fire Incidents 1970-2001 from FDNY Records	G-3
G.2.3 Fire Incidents Occurring in WTC 1	G-5
G.2.4 Fire Incidents Occurring in WTC 2	G-8
G.2.5 Additional Fires Involving the Deployment of Standpipe Lines in WTC 1 and 2	G-9
G.2.6 Fire Incidents Occurring in WTC 7	G-10
G.3 Summary	G-10
G.4 Attachments to This Fire History	G-11
G.5 Conclusions	G-11
G.6 References	G-12

Attachments G-A.1 through G-A.3

Numeric Codes Used in the Fire Reports G-13

Attachments G-A.4 through G-A.7

Fire Reports Produced by the FDNY G-29

LIST OF TABLES

Table G-1. Categorization of WTC 1, 2, and 7 fires from FDNY records.....	G-3
Table G-2. Significant fires in WTC 1 extinguished by sprinklers and/or multiple standpipe lines.....	G-5
Table G-3. Significant fires in WTC 2 extinguished by sprinklers and/or multiple standpipe lines.....	G-8
Table G-4. Significant fires in WTC 7 extinguished by sprinklers and/or multiple standpipe lines....	G-10

Appendix G

INTERIM REPORT ON SIGNIFICANT FIRES IN WTC 1, 2, AND 7 PRIOR TO SEPTEMBER 11, 2001

Fires occurred in World Trade Center (WTC) 1, 2, and 7 prior to September 11, 2001. This appendix documents the facts of significant fires in the building after first occupancy as they relate to the performance of the automatic sprinkler, manual suppression, fire detection, and smoke purge systems. The ultimate goal of this review was to identify from New York City Fire Department (FDNY) records significant but not well known fires for further study.

G.1 BACKGROUND

The fire protection engineering department of the Port Authority of New York and New Jersey (PANYNJ) maintained records of all significant fire events in the WTC buildings. These records were lost in the collapse of the towers.

Two significant fire events involving WTC 1 are well known. On February 14, 1975, a fire started on the 11th floor of WTC 1. Workers reported the fire to WTC police headquarters. When police reached the fire floor, they reported a serious fire and ordered the heating, ventilating, and air conditioning (HVAC) system be placed into the smoke purge mode. Fire spread through unprotected floor openings in utility closets. Fire damage occurred on floor 10 through floor 19. Approximately 800 m² (9,000 ft²) of the floor 11 contents were destroyed or damaged. At that time, sprinklers had not been installed in the office spaces. However, fire barriers divided the floor into quadrants. The fire on floor 11 was confined to the southeast quadrant. Fire damage on other floors was confined to the utility closets. The fire was extinguished by FDNY. More details about this fire incident can be found in Powers (1975), Lathrop (1975), and a report that is being prepared for the National Institute of Standards and Technology (NIST) by Hughes Associates.

At 12:18 PM on February 26, 1993, a bomb exploded in an underground parking garage of the WTC complex. The explosion occurred on the B2 level in the area of the garage under WTC 3 and adjacent to WTC 1. The explosion resulted in a loss of normal electric power in WTC 1 and WTC 2. HVAC systems shut down. Smoke spread throughout WTC 1 and to a lesser extent in WTC 2. More details about this fire can be found in Isner and Klein (1993a, 1993b). The only historic record of smaller fire incidents in WTC 1, 2, and 7 known to this investigation are the fire reports and fire investigation reports prepared by the FDNY. These reports were provided to NIST by FDNY for use in this investigation.

G.2 FDNY FIRE REPORTS AND FIRE INVESTIGATION REPORTS

The FDNY released 397 Bureau of Operations Fire Reports and 112 Bureau of Fire Investigation Records (Fire Marshals' Reports) which served as the basis for a summary of the fire history in the WTC 1, 2, and 7. NIST obtained reports of fires for the period of 1970–2001 and fire investigation records between 1977 and 2001 for WTC 1, 2, and 7, which in total, consisted of over 500 documents on which to report.

These records included all responses to fires in buildings 1, 2, and 7 by the FDNY. All of these records consist of standardized forms that may be supplemented with other materials. Many were for minor fire events, such as fires that were extinguished by occupants before FDNY arrival. These were not of interest for this investigation. The records of significant fires were identified.

Significant fire incidents were those that exercised the fire suppression systems, specifically multiple sprinklers or multiple standpipes (with or without the activation of at least one sprinkler). These fires will be discussed individually, organized by the building in which they occurred. In addition to these fires, generalized facts relating to those fires involving the use of one standpipe line and one sprinkler and the use of one standpipe line will be provided throughout this report. As an aside, the majority of fire records for significant fires documented the performance of the detectors and sprinkler systems, but almost all reports lacked information about the performance of the smoke purge system.

G.2.1 Fire Record Forms

Depending upon the type and date of the incident, a specific fire report form was used by the FDNY to document the incident. For each type of emergency responded to by the FDNY, responders either completed a form that would describe a structural fire (BF-24) or a form that would describe any other type of emergency (BF-25), such as a nonstructural fire, transportation fire, and/or any other non-fire emergency. For this historical summary, only those events logged and organized under the structural fire form, 345 documents total, were of interest and used. A structural fire form is a one-page document (unless additional information is recorded on separate sheets) that gives valuable information about the fire event on various subjects, including:

- Alarm—the date and time of the received alarm
- Injuries and casualties—the numbers of each for the incident
- Extinguishment—details of the sprinkler and standpipe performance
- Ignition—information on the equipment involved in ignition, the form of the ignition source, the material type and form that was ignited, and the ignition factor (cause)
- Structure—information on the class of construction, the use of the building, and its status (vacant, occupied, under construction, etc.)
- Fire origin—the fire location and classification
- Fire extension—the means of fire extension and number of buildings/vehicles involved
- Damage—information on the damage done by flame, smoke, and water
- Detectors—the type, power source and performance of the detectors in the fire area

Each subject of the incident is given a set of codes or numbers that correspond to any incident, and in order to read the fire records successfully, an understanding of the codes is necessary (see

Attachments G-A.1, G-A.2 and G-A.3). For the nonstructural B-25 record forms, the only fire related subjects included are the injury and casualty numbers, ignition, and structure information.

Depending upon the date of the fire incident, certain information is lacking from the structural fire form. Before 1980, a different record form for structural fire incidents was used which left out the following subjects: fire extension, damage, detectors, and portions of the ignition data. Because of this, detection data are not available for the majority of the fires occurring before 1980.

G.2.2 Overview of Fire Incidents 1970–2001 from FDNY Records

Table G–1 contains the categorization of all structural fire incidents contained in the FDNY records for WTC buildings 1, 2, and 7 available to this investigation. The table contains information on the category of fire incident (whether or not the detection and/or sprinkler systems activated), the time period over which the fires occurred, the numbers of records in that category, and a descriptive statement about the category.

Table G–1. Categorization of WTC 1, 2, and 7 fires from FDNY records.

<i>WTC 1</i>			
Category	Dates	Number	Generalization of Incidents
No detection, no sprinkler	1980–2001	66	Unattended food/appliances, overheated elevator equipment, discarded material, welding operations, electrical failure and suspicious fires
No detection information and no sprinklers	1970–1979	79	Trash can fires, discarded material, food on stove, electrical failure, overheated equipment
Detection, no sprinklers	1980–2000	57	Unattended food/appliances, overheated elevator equipment, discarded material, welding operations, electrical failure
[Detection] and sprinklers	1977–1999	18	Suspicious, electrical failure, discarded material
<i>WTC 2</i>			
Category	Dates	Number	Generalization of Incidents
No detection, no sprinkler	1980–1999	37	Discarded material, welding too close, overheated equipment, suspicious, elevator motor
No detection information and no sprinklers	1975–1979	40	Discarded material, fire in office furniture, trash can fires
Detection, no sprinklers	1981–1999	40	Food on stove, small elevator fire, electrical failure, suspicious, overheated equipment
[Detection] and sprinklers	1977–2000	5	Mechanical failure, suspicious
<i>WTC 7</i>			
Category	Dates	Number	Generalization of Incidents
No detection, no sprinkler	2000	1	Trash can fire/discarded material
Detection, no sprinklers	1990	1	Electrical switch on floor – explosion
[Detection] and sprinklers	1988	1	Suspicious

All FDNY records provided to NIST, unless the records were not readable, contained relevant information about the type and performance of the suppression system. Because of this, reports of incidents in which the sprinkler system activated can range from 1970 to 2001. When the table lists “[detection]” in brackets, this is meant to symbolize that either detection was present or no information on detector performance was included on the form (as is the case with the older records). An attempt was made to compare all investigation records with the fire reports, especially those which activated the suppression system. Looking at the records in Table G-1, it is clear that only 24 fires activated the sprinkler system from 1970–2001 from all three buildings. Many of the other structural fires without sprinkler activation were labeled as suspicious, trash can fires, electrical failures, unattended food/appliances, or overheated equipment.

In order to report on significant structural fires occurring in WTC 1, 2, and 7, the FDNY records had to be reviewed for those incidents that activated sprinklers, detectors, or were extinguished by hose line and those smaller fires that self-extinguished or could be extinguished using a fire extinguisher. The structural fire incidents without detection information (before 1980), had to be reviewed to locate any fires that activated the sprinkler system.

The retrofit installation of sprinklers into WTC buildings 1 and 2 was accomplished in two phases. During the first phase in 1976, sprinkler risers/mains were installed throughout WTC 1 and WTC 2. Sprinklers were installed to protect corridors, storage rooms, lobbies, and certain tenant/PANYNJ spaces. In the second phase of the retrofit from 1983 to 2001, sprinklers were installed in all remaining places in the complex (PACO 2002; shown in Attachment G-B). Prior to the retrofit only the sub-grade areas and selected hazard areas were protected by automatic sprinklers. This retrofit proceeded throughout the buildings as much as practical when other renovations of the office spaces were underway, such as when change of tenants occurred.

After the installation of the sprinkler risers in 1976, tenants had the option of providing sprinklers or compartmentation for fire protection in compliance with Local Law 5. It was therefore possible that during the period of time when retrofit installation of sprinklers was under way, a fire that occurred may or may not have been in an area protected by automatic sprinklers.

The forms used by the FDNY after 1987 give a detailed description of the event and whether or not a system was present at the time of the fire; however, a fire recorded before 1987 will give data only on the number of sprinklers opened. Because of this, an effort was made to look through all reports, especially those that mentioned detection performance, in order to identify fires involving the use of standpipe lines by the FDNY as an alternate indication of a significant fire.

The next section of the report will highlight significant fires occurring in WTC 1, 2, and 7. The significant fires will be described individually by WTC building, and organized by the date on which they occurred in the building. In addition to these significant fires, (1) the fires that activated one sprinkler head and involved the use of one standpipe and (2) the fires that involved the use of only one standpipe, due to the number of incidents, will be generalized as to the nature of the incidents and the procedures followed by the FDNY.

G.2.3 Fire Incidents Occurring in WTC 1

After reviewing all the FDNY records of fire incidents in WTC building 1 since 1970, the significant fires were selected. There were 12 significant fires found for WTC 1, and the fire reports are included in Attachment G-A.4. Table G-2 provides a summary of the fire incident information from FDNY records, which is followed by individual paragraphs about each incident.

Table G-2. Significant fires in WTC 1 extinguished by sprinklers and/or multiple standpipe lines.

Significant Fire	Incident Date	Fire Location	# Sprinklers Activated	# Standpipes Used	Cause of Fire	Material Ignited
1	9/9/77	B-6 level storage room	2	0	None listed	Not listed
2	9/23/77	Dumpster on B-4 level	2	0	Not classified	Trash/waste
3	10/16/81	19th floor office area	-	2	Discarded material	Furniture
4	12/23/83	2 dumpsters on B-4 level	2	1	Suspicious	Trash/waste
5	1/27/85	Office space on mezzanine level (Floor 2)	2	1	Incendiary	Trash/waste
6	9/10/85	Garbage dumpster in service elevator lobby on floor 43	2	1	Suspicious	Trash/waste
7	11/1/85	Storage closet on B-4 level	3	1	Suspicious	Supplies/stock
8	6/7/86	Dumpster fire on floor 106, compactor room on floor 107	2	1	None listed	Trash/waste
9	9/30/91	Office on B-4 level	≥1	2	Discarded material	Trash/waste
10	11/19/91	Electrical closet on floor 93	0	2	Short circuit	Electrical wire or cable insulation
11	7/23/92	Level B-5 at the power distribution panel	0	2	Electrical failure	Electrical wire or cable insulation
12	11/10/99	Computer room on floor 104	3	≥1	None listed	Plastics, electronic equip

Key: ≥ symbol denotes that at least one of the units of the suppression system was used (and not specifically identified by the fire report); - indicates that the report acknowledges 0 sprinklers open; however, due to the date of the fire, the space may not have had a sprinkler system installed.

Significant Fire #1

On September 9, 1977, at 11:04 p.m., the FDNY received an alarm for a fire in the B-6 level storage room at the address of WTC 1. The fire activated two sprinklers, and was noted to be extinguished before the FDNY's arrival.

Significant Fire #2

Another fire occurred on September 23, 1977, at 11:48 p.m., in a dumpster on the B-4 level of WTC 1. This fire also activated two sprinklers, and the FDNY noted that the fire had been extinguished prior to their arrival.

In both cases, no injuries or casualties resulted from these fires, and the damage was confined to the area of origin.

Significant Fire #3

Six years later, on October 16, 1981, at 7:12 p.m., a fire occurred on floor 19 of WTC 1. The FDNY noted that they used two standpipe lines to extinguish the fire and that one person was evacuated from the scene. Again, the fire report notes that no sprinklers opened, but does not note whether or not sprinklers were present at the time of the fire. Given the date of the incident, sprinklers are not expected to be located on floor 19. The fire was caused by discarded material and involved furniture in an office area of the floor.

Significant Fire #4

Six years later on December 23, 1983, at 2:50 a.m., the FDNY responded to an alarm of fire and heavy smoke conditions on the B-4 level of WTC 1. The FDNY found two dumpsters fully involved in separate locations on the same floor and noted that the two activated sprinklers extinguished a major portion of the fire. The FDNY extinguished the rest of the flames by stretching hose from the standpipe system. Again, no injuries or casualties resulted from this fire. The cause noted on the report was suspicious and the damage was confined to the origin of the fire.

Significant Fire #5

On January 27, 1985, at 8:53 p.m., the FDNY was called for a fire located in an unoccupied office on the mezzanine level of WTC 1. Two sprinklers contained the incendiary (involving arson) fire consuming trash paper/waste. When the FDNY arrived, they extinguished the remaining fire with one standpipe line. Building and content damage was confined to less than 15 percent of the space. Also, no injuries or casualties were reported.

Significant Fire #6

Eight months later on September 10, 1985, at 4:05 p.m., the Port Authority Police informed the FDNY on arrival of a sprinkler flow and smoke condition on floor 43. A medium smoke condition was report by the FDNY on floor 43, where a fire was extinguished by two sprinklers. The fire report notes the use of one standpipe line; however, this was used during the overhaul process. This fire originated suspiciously

in a garbage dumpster in a service elevator lobby. There was no building or content damage as well as no injuries or casualties reported.

Significant Fire #7

On November 1, 1985, at 4:05 a.m., the FDNY was called for another suspicious fire producing heavy smoke on the B-4 level under WTC 1 and WTC 2. This fire occurred in a storage closet of the men's bathroom, and the FDNY noted that three sprinklers activated to keep the fire under control until their arrival. Upon arrival, the FDNY extinguished the remaining fire in the closet area with one standpipe line. Again, the damage was noted to be confined to the area of origin.

Significant Fire #8

Less than a year later, on June 7, 1986, at 9:49 a.m., the FDNY received an alarm for a heavy smoke condition on floor 110. For this call, fires were burning in two separate places; a garbage dumpster on floor 106 and the compactor room on floor 107. Sprinklers were noted in operation in both locations and seemed to control the fires, until the FDNY could complete extinguishment with one standpipe line on floor 106. There was no report of injuries or casualties for the previous two fires.

Significant Fire #9

An additional fire occurred in WTC 1 where multiple standpipe lines were used along with the activation of the sprinkler system. This fire occurred on September 30, 1991, at 6:32 p.m., in an office on the B4 level. The fire report noted that the sprinkler system operated; however, there is no mention of how many sprinklers or even their activation in the Operations/Comments section of the report. Two 1 3/4 in. or larger hose lines were used by the FDNY to extinguish this fire. The cause of the fire was abandoned material (cigarette) igniting boxes/carton material in an office. The fire damage was confined to the area of origin and smoke damage was confined to the floor. There was one uniformed officer injured and no civilian injuries or casualties.

Significant Fire #10

A fire occurred on November 19, 1991, at 6:27 pm., and two 2 1/2 in. standpipe hose lines were used by the FDNY. The FDNY responded to WTC 1 for this fire due to a report of fire and smoke condition in electrical closets on possibly four floors (floors 93-96) and an alarm transmitted from floors 93-98. According to the fire report, the sprinklers were in service, but did not operate for this fire. The noted cause of this fire was a short circuit and the material that was ignited was electrical wire or cable insulation. The fire and smoke damage was confined to its area of origin (electrical closet). Two occupants were removed from stalled elevators during this incident, and occupants were evacuated from the scene, although an exact number is not given. Also, two occupants were injured and required first aid.

Significant Fire #11

The FDNY responded to WTC 1 on July 23, 1992, at 10:02 p.m., due to a transformer fire on the 5th sub basement level. Firefighters found a fire situation in a large power distribution panel, where a firefighter was knocked unconscious by a shock blast from the panel. Similar to the fire in November of 1991, two 2-1/2 in. standpipe hose lines were used by the FDNY on this fire. The cause of the fire was an electrical

failure and the material ignited was electrical wire or cable insulation. No appreciable damage is noted. As mentioned earlier, one firefighter was injured as well as three civilians.

Significant Fire #12

The final fire associated with WTC 1 was one that occurred on November 10, 1999, at 11:01 p.m., in a computer room on floor 104. The FDNY noted that the fire was “knocked down” by three sprinklers when they arrived and they completed extinguishment with a line extended from the standpipe. The flame damage was confined to the area of origin and computer equipment was involved in fueling the fire. There was one injury and no casualties reported in the FDNY record for this fire.

Table G-2 presents the 12 significant fires in WTC 1. Five of the 12 fires occurred on the basement levels and two occurred on the upper levels (above floor 100). The causes of these significant fires include suspicious, discarded materials, and electrical failures.

G.2.4 Fire Incidents Occurring in WTC 2

Table G-3 presents the significant fire occurring in WTC 2. There were three significant fires found for WTC 2, and the fire reports are included in Attachment G-A.5. Table G-3 provides a summary of the fire incident information from FDNY records, which is followed by individual paragraphs about each incident.

Table G-3. Significant fires in WTC 2 extinguished by sprinklers and/or multiple standpipe lines.

Significant Fire	Incident Date	Fire Location	# Sprinklers Activated	# Standpipes Used	Cause of Fire	Material Ignited
1	5/19/75	Floor 32	-	3	Incendiary	Trash/waste
2	4/12/77	Duct work over grill in restaurant on floor 107	2	0	None listed	Duct work
3	3/22/93	Fan motor room on floor 108	2	0	Mechanical failure	Not classified

- Indicates that the report acknowledges 0 sprinklers open, however due the date of the fire, the space may not have had a sprinkler system installed.

Significant Fire #1

A fire occurred on May 19, 1975, at 9:38 p.m., on floor 32 of WTC 2. The FDNY noted that they used three standpipe lines to extinguish the fire and that the Port Authority reported occupants trapped on floors 31 and 32. The fire report notes that no sprinklers opened, but does not note whether or not sprinklers were present at the time of the fire. Given the date of the incident, sprinklers are not expected to be located on floors 31 and 32. The fire was labeled as incendiary and involved trash/waste. The FDNY stated that the fire involved the core area of the floor and was confined to that area. Over 20 people (civilians and uniformed personnel) were injured by this incident.

Significant Fire #2

On April 4, 1977, at 1:15 p.m., the FDNY was called to WTC 2 for a fire in the duct work over the grills in a restaurant on floor 107. The FDNY record on this fire noted that the fire was extinguished prior to its arrival. The damage was confined to the area of origin, and the fire caused no injuries or casualties.

Significant Fire #3

The second fire occurred on March 22, 1993, at 8:39 a.m., and caused a smoke condition on floor 108. The fire activated two sprinklers due to an overheated bearing in a fan motor room on floor 108. The damage to the area did not exceed 15 percent of the space, and there were no injuries or casualties reported.

Table G-3 presents the three significant fires in WTC 2. No fires were discovered in WTC 2 where multiple sprinklers or standpipes were used with another suppression system. Two of the three fires occurred on the upper levels (above floor 100) and the other occurred on floor 32. The causes of these significant fires included incendiary and mechanical failures.

G.2.5 Additional Fires Involving the Deployment of Standpipe Lines in WTC 1 and 2

The fires described in this section (31 in total) involve the use of one standpipe, with and without the activation of one sprinkler for WTC 1 and WTC 2. Four of the 31 reports describe fires that were extinguished with one sprinkler and one standpipe line (see Attachment G-A.6.1). Three of these fires were located in WTC 1 between the years of 1986-1991 and the other in WTC 2 in 1981. Two of these fires occurred in basement levels, one occurred on floor 106 of WTC 1, and the last on floor 5 in WTC 1. In some of the fire reports, the FDNY noted that the sprinkler controlled the fire, and the standpipe was used to actually extinguish the remaining fire. Half of the fires were labeled as incendiary/suspicious, one was an electrical failure, and the last was unknown.

In addition, 27 of the 31 fire reports describe fires that were extinguished using one standpipe line (see Attachment G-A.6.2). Twenty of these fires occurred in WTC 1 and the other seven occurred in WTC 2. A majority of these fires (19) are labeled as incendiary/suspicious or unknown, while the other causes of the fires are attributed to short circuits, abandoned material/cigarette, welding close to combustibles, and a mechanical failure. The dates of occurrence for these fires range from 1973-1999, with a majority (23) occurring between the years of 1973-1985. These fire incidents did not result in any casualties, but five civilians and one uniformed officer were injured.

Two of the 27 fires involved a 300 person (April 19, 1980) and a 1,500 person (April 17, 1981) evacuation. These will be described in further detail. On April 19, 1980, at 2:06 p.m., the FDNY received reports of an activated smoke detector in the return air duct on floor 106 of WTC 1. The FDNY also received reports of heavy smoke on floor 106, light smoke on floor 109, and heavy odor of smoke in stairways A and B. The report notes that while only one standpipe was used, approximately 300 people were evacuated from the Windows on the World restaurant on floor 107 via stairway C (which was clear of smoke). The fire cause was labeled as abandoned or discarded material and involved plastic material. This fire did not cause any injuries or casualties.

On April 17, 1981, at 9:18 a.m., the FDNY was informed of a fire on floor 7 and a smoke condition on floors 7 through 11 of WTC 1. The FDNY hooked up one standpipe and extinguished the fire located in an air conditioning unit in the "MER" room on floor 7. The cause of this fire was labeled as a mechanical failure. The fire report notes that the Port Authority personnel reported an evacuation of approximately 1,500 people from floors 9 through 23. However, no injuries or casualties were reported from this fire.

G.2.6 Fire Incidents Occurring in WTC 7.

Table G-4 presents the significant fire occurring in WTC 7. There was one significant fire found for WTC 7, and the fire report is included in attachment G-A.7. Table 4 provides a summary of the fire incident information from FDNY records, which is followed by an individual paragraph on the incident.

Table G-4. Significant fires in WTC 7 extinguished by sprinklers and/or multiple standpipe lines.

Significant Fire	Incident Date	Fire Location	# Sprinklers Activated	# Standpipes Used	Cause of Fire	Material Ignited
1	5/20/88	Construction shanties on floor 3	Multiple, # not listed	1	Suspicious	Shanties

Significant Fire #1

In WTC 7, a fire occurred on May 20, 1988, at 12:38 a.m., in the construction shanties on floor 3. Although the fire report does not specifically note the number of sprinklers that activated, the operations notes state that Ladder Truck 10 found the sprinklers (noting more than one) in operation and shut them down. The FDNY had to complete the extinguishment by stretching a line from the standpipe to the fire source. This fire is noted by the report as being suspicious in nature and the flame damage was confined to the area of origin.

It is possible that the fire incidents that were not specifically highlighted, especially those in the areas without sprinklers, involved other methods of extinguishment before FDNY arrival, such as a WTC houseline (pre-connected standpipe hose), hand extinguisher, or bucket of water, as noted on some of the FDNY reports. All other fires, the majority, included in other categories were either self-extinguished, extinguished prior to FDNY arrival (by staff, etc.), or a hand extinguisher was used by the FDNY.

G.3 SUMMARY

In summary, 16 significant fires occurred in WTC 1, 2, and 7, with 12 occurring in WTC 1, three in WTC 2, and one in WTC 7. In addition to these, 31 fires occurred in WTC 1 and WTC 2, which involved the use of one standpipe (with or without the activation of one sprinkler). Of these additional 31 fires, 23 occurred in WTC 1 and eight occurred in WTC 2. The following paragraphs will summarize findings from the 16 significant fires that occurred in all three buildings.

After reviewing the 16 significant fires, trends developed relating to the time of day that the fires occurred. Overall, 12 of the 16 fires occurred between the hours of 6 p.m. and 4 a.m. The fires that occurred during office hours (between 7 a.m. and 6 p.m.) included a dumpster fire in the floor 43 elevator lobby (WTC 1), a dumpster fire on floor 106 (WTC 1), a kitchen fire on floor 107 (WTC 2), and a bearing overheating in the fan motor room on floor 108 (WTC 2). Almost all of the incendiary (arson) and

suspicious fires (5 out of 6 fires) and unclassified or unlisted fires (4 out of 5 fires) occurred after business hours (before 7 a.m. and after 6 p.m.).

In addition to the time of day of the fire, trends in the cause of the fire and the materials involved in the fire can be highlighted. Of the 16 fires and their causes, five were labeled as unlisted or unclassified, six as suspicious or incendiary, two as discarded material, and three as an electrical failure or mechanical failure. For the material involved in the fire, eight reports noted trash, waste, and supplies; two reported not listed or not classified; one reported furniture; three reported electrical equipment; one reported duct work; and one reported shanties were the material involved in the fire.

Lastly, the location of the fires throughout the buildings was of interest. Of the 16 fires, four fires were concentrated above floor 100 or and six fires were located in the basement. The others (6 fires) were spread throughout the rest of the building.

G.4 ATTACHMENTS TO THIS FIRE HISTORY

Attachments G–A.1 through G–A.7 are included as a supplement to this report. The first three sections, G–A.1 through G–A.3 are explanations of the numeric codes used in the fire reports by the FDNY. Attachment G–A.1 is included to explain the codes for the fire reports produced prior to and including 1980, Attachment G–A.2 is included to explain the fire reports produced from 1981 to May 31, 1987, and Attachment G–A.3 is included to explain the fire reports produced from June 1, 1987, to the present. The report code explanations are divided into the same sections as the fire report and give short descriptions for the numbers used in the fire report under each section. For example, if the ignition factor for a fire occurring in 1990 was given a number code of 54, the reader can find that the cause of the fire was a “short circuit, ground fault.”

Attachments G–A.4 through G–A.7 include the actual fire reports produced by the FDNY on the significant fires highlighted in the sections above. The reader can use Attachments G–A.1 through G–A.3 (depending upon the date of the fire) to read the fire reports in more detail than what is provided in this fire history report.

G.5 CONCLUSIONS

From the information contained in FDNY fire reports and fire investigation records provided to NIST, 47 fires occurred in WTC building 1, 2, and 7 that were of sufficient size and duration to activate multiple sprinklers or were estimated by NIST to be capable of doing so, over the time period the buildings were occupied. This total does not include the major 1975 office fire in WTC 1 or the 1993 bombing.

The records indicate that in areas protected by automatic sprinklers, no fire activated more than 3 sprinklers. Three sprinklers would provide coverage for a floor area of approximately 63 m² (675 ft²). This area is much smaller than the 800 m² (9,000 ft²) damaged by the 1975 fire in an office space unprotected with automatic sprinklers.

Many of the fires that occurred were recorded as suspicious or unknown in cause, occurred during off-peak work hours, and involved materials such as trash or paper-based supplies. In cases where sprinklers

were activated, the FDNY records indicated that the sprinklers either extinguished the fire completely or aided in controlling the spread.

G.6 REFERENCES

Isner, M. S., and T. J. Klem. 1993a. Explosion and fire disrupt World Trade Center. *NFPA Journal*. National Fire Protection Association. 91-104.

Isner, M. S., and T. J. Klem. 1993b. *World Trade Center Explosion and Fire, New York, New York, February 26, 1993. Fire Investigation Report*. National Fire Protection Association. Quincy, MA.

PACO Group. 2002. *World Trade Center General Description of All Building Systems and the Capital Program*. August.

Powers, W. R. 1975. *One World Trade Center Fire New York, N.Y., February 13, 1975*. National Fire Protection Association. Boston, MA. 1-15.

Attachment G-A.1

Explanation of Numeric Codes Used on Fire and Emergency Reports -
Prior to 1980

CLASSIFICATION OF BUILDING
BY USECOMMERCIAL

01	Bank
02	Brewery
03	Coal Pocket
04	Department Store
05	Electric Power Plant
06	Factory: Multi occupancy
07	Factory: Single Occupancy
08	Foundry
09	Freight Depot
10	Garage: Non-Storage
11	" Storage
12	Gas Works
13	Lumber Yard
14	Motor Vehicle Repair Shop
15	Office Building
16	Oil Selling Station
17	Oil Storage Plant
18	Pier, Wharve, Dock, Bulkhead Building
19	Restaurant, Diner
20	Shed, Newsstand, Shanty
21	Shipyard, Drydock
22	Stable
23	Steam Generating plant
24	Store Building, Taxpayer
25	Warehouse, Storehouse
26	Store Building & Private Dwelling
39	Other Commercial

PUBLIC

40	Airport Building
41	Ayrtum
42	Bridge
43	Bus Terminal
44	Church, Synagogue
45	Dance Hall, Banquet Hall
46	Dispensary, Clinic
47	Ferry Terminal
	Government Building (Not otherwise classified);
48	City
49	Intersate
50	Federal
51	Foreign
52	State
53	Hospital, Infirmary
54	Nursing Home
55	Railroad Station
56	School; College, University
57	" Private High
58	" Public High
59	" Public Junior High
60	" Private Elementary
61	School: Public Elementary
62	" Children's Nursery
63	" Other
64	Television Studio
65	Theatre, Legitimate
66	Theatre, Motion Picture
67	Transit System - Station Structure
68	Tunnel
69	Other Public

RESIDENTIAL

80	Apartment Hotel "A"
81	Apartment House "A"
82	Boarding House, Rooming House "B"
83	Convent, Rectory, Monastery, etc.
84	Dormitory-School Club, Lodge
85	Hotel "B"
86	Lodging House "B"
87	Motel
88	Pvt. Dwelling: 1 Family
89	" Two Family
90	Tenement: New Law "A"
91	" Old Law "A"
92	Converted Dwelling "A"
99	Other Residential

BUILDING STATUS

1	Occupied
2	Partly Occupied, Good Condition
3	Partly Occupied, Deteriorating
4	Vacant
5	Under Demolition
6	Under Construction

DAMAGE (to Building or Contents)

0	None-No Appreciable
1	Light 0-15%
2	Medium 16%-49%
3	Heavy 50% & Greater

AREA FIRE ORIGIN -FLOOR

00	Outside Building
01	1st Floor
02	"
03	94th and Higher
04	Attic
05	Roof
06	Basement
07	Cellar
08	Sub-cellar

AREA FIRE ORIGIN-ROOM OR AREA

10	Area Not in Building
11	Attic
12	Awning
13	Balcony
14	Basement
15	Bathroom Toilet
16	Bedroom, Sleeping Area
17	Ceiling
18	Cellar
19	Chimney
20	Classroom Lecture Area
21	Closet
22	Cockloft
23	Court-Exterior
24	Court-Interior
25	Dining Room, Dining Area
26	Duct-Air Conditioning
27	Duct-Exhaust
28	Flooring
29	Furnace Room
30	Hallway-Private
31	Hallway-Public
32	Incinerator Closet or Room
33	Kitchen, Cooking Area

34	Living Room
35	Lobby
36	Machinery Room
37	Office Area
38	Operating Laboratory Area
39	Partition
40	Porch
41	Projection Booth
42	Recreation Area
43	Roof
44	Sales Showroom Display Area
45	Shaft-Duct, Pipe
46	Shaft-Dumbwaiter
47	Shaft-Elevator
48	Shaft-Exterior Light
49	Shaft-Interior Light
50	Shaft-Vent
51	Shipping Receiving Loading Area

52	Stage
53	Stairway
54	Storage Room Area
55	Vacant-Room, Apartment or area
56	Work Area Workroom
57	Other Areas, Not Classified (State area)

AREA FIRE ORIGIN-OCCUPANCY CLASSIFICATIONCOMMERCIAL

00	Factory:
	Chemicals
01	Clothing:
	Dresses
02	Undergarment
03	Other (State Type)
04	Dry Cleaning Laundry
05	Electrical Products
06	Food & Drink Products
07	Furniture
08	Furs, Fur Goods
	Hats:
09	Men's
10	Women's
11	Leather, Leather Products
12	Machine Shop Metal works
13	Paints
14	Paper Products
15	Petroleum Products
16	Plastics, Rubber
17	Printing & Allied Industries
18	Shoes
19	Textiles
20	Toy or Doll
21	Woodworking
22	Other Factories not classified (state type)
	Store:
23	Auto Accessories
24	Bakery
25	Butcher
26	Candy, Cigar, Stationery
27	Clothing
28	Department, large
29	Department, small (\$500)
30	Dry Cleaner & Tailor
31	Drug
32	Electrical Appliances
33	Fruit & Vegetables
34	Furniture
35	Grocery, Dairy, Delicatessen
36	Haberdashery
37	Ladies Accessories
38	Laundry
39	Paint Hardware

40 Restaurant Luncheonette
 41 Shoe
 42 Shoe Repair
 43 Super Market
 44 Tavern
 45 Other Stores not
 classified(state
 type)
 Garages:
 46 Non Storage
 47 Storage
 48 Oil Selling Station
 49 Motor Vehicle Re-
 pair Shop
 50 Office Building
 Warehouse:
 51 Film
 52 Paper, Rays, Fibre
 53 Other(state type)
 54 Freight Depot
 55 Pier
 56 Shipyard
 57 Lumber Yard
 58 Shed, Newstead, Shanty, etc.
 59 Other Commercial
 Building Occupancies,
 not classified(state
 type)

RESIDENTIAL

60 Apartment Hotel,
 Multiple Dwelling "A"
 61 Apartment House, Mul-
 tiple Dwelling "A"
 62 Boarding House, Rooming
 House Multiple
 Dwelling "A"
 63 Hotel, Multiple
 Dwelling "A"
 64 Lodging House, Mul-
 tiple Dwelling "B"
 65 Private Dwelling
 66 Rectory, Convent,
 Monastery
 67 Tenement House,
 New Law, Multi-
 ple Dwelling "A"
 68 Tenement House, Old
 Law, Multiple
 Dwelling "A"
 69 Other Residential,
 not classified
 (state type)

PUBLIC

70 Airport
 71 Cabaret, Banquet
 Hall
 72 Church
 73 Dance Hall
 74 Hospital
 75 Motion Picture
 Theatre
 76 N.Y. Transit
 System-Station
 77 Passenger Depot
 78 School
 79 Theatre
 80 T.V. Studio
 81 Other Public, not
 classified (state
 type)

MANNER EXTENSION

00 Confined to area
 of origin
 01 Cockloft
 02 Door or opening
 between rooms
 03 Floor
 04 Hall Stairway
 05 Partition
 06 Pipe Recess
 07 Shaft-Dumbwaiter
 08 Shaft-Elevator

09 Shaft-Air, Light,
 Chute, Duct, etc.
 10 Ceiling
 11 Window
 12 Other (state how)

CLASSIFICATION BY TYPE FIRE
OR EMERGENCYTRANSPORTATION FIRES

87 Ship, Vessel
 88 Motor Vehicle
 89 Other Transportation
 (state type).

NON-STRUCTURAL FIRES

86 ADV (Abandoned/
 Derelict Motor
 Vehicle)
 90 Bonfire
 91 Brush, Grass
 92 Demolition Wood,
 Building Site
 93 Dump, Land Fill
 94 Rubbish-Outside
 Building
 95 Manhole
 96 N.Y. Transit System-
 Yard Roadway, Ties,
 etc.
 97 Railroad-Yard, Road-
 way, Ties, etc.
 98 Tunnel, Bridge
 99 Other Non-Structural,
 not classified
 (state type)

EMERGENCY

02 Chimney
 03 Elevator, Escalator
 04 Explosives Escort
 05 First Aid - Assist
 Person(s)
 06 First Aid - Resucita-
 tion
 07 Marine
 08 Precarious Condition
 Signs, Trees, etc.
 09 Subway-Railroad
 10 Water Leak
 11 Bomb-Unexploded,
 Scare
 12 Collapse-Cave in
 13 Collision-Vehicular
 Incident
 14 Controlled Fire,
 Permitted
 15 Flood Condition-
 Broken Water Main
 16 Incinerator
 17 Leak-Fuel Oil, Gasoline
 etc.
 18 Leak-Illum, Gas, Flam,
 Vapor
 19 Lightning
 20 Oil Burner
 21 Person Locked in,
 Locked out
 22 Power - Electrical
 23 Pressure Rupture
 24 Refrigerant Leak
 25 Smoke Condition,
 Odor, Fumes
 26 Sprinkler
 27 Steam Discharge
 28 Other

This page intentionally left blank

Attachment G-A.2

Explanation of Numeric Codes Used on Fire and Emergency Reports -
From 1981 to May 31, 1987

Type of Report

- 1 Structural.
- 2 Transportation Fire.
- 3 Non-Structural Fire.
- 4 Emergency Response.
- 5 False Alarm.
- 6 Additional data (for BF 24A).

How Reported

- 1 Street Box Manual.
- 2 Telephone.
- 3 Verbal.
- 4 Class 3-Manual, PFA.
- 5 Class 3-Valve, PFA.
- 6 Class 3-Other Automatic, PFA.
- 7 Class 3-FRS.
- 8 Street Box-FRS.
- 9 Class 3-Manual, FONY.
- 10 Pre-recorded Alarm.

Initial Alarm

- 0 Special Call Other Than Engine Only—No Chief.
- 1 Box (Street or Class 3).
- 5 Special Call Engine Only—No Chief.
- 6 Special Call Chief Operated.
- 9 Still.

Highest Alarm

- 0 Initial Alarm.
- 1 More than the Initial Alarm & less than 3 Engines & 2 Ladder Co. at work.
- 2 2nd Alarm.
- 3 3rd Alarm.
- 4 4th Alarm.
- 5 5th Alarm.
- 6 Simultaneous.
- 7 Signal 7-5.

How Extinguished

- 0 Before Arrival.
- 1 Hand Extinguishers.
- 2 Sprinkler Heads (State Number).
- 3 Booster Stream.
- 4 Low Pressure Hydrant Stream.
- 5 One 1½" or larger hoseline from a pumping unit or a standpipe outlet, regardless of line termination (Controlling Nozzle, Hookups, Stang Multi Vessel, Ladder Pipe, T.L. from Nozzle, etc.).
- 6 Two 1½" or larger hoselines as above.
- 7 Three 1½" or larger hoselines as above.
- 8 Four or more 1½" or larger hoselines as above.
- 9 Other (State How).

Ignition Stage—Termination Stage

- 2 Smolder Stage, before any flame.
- 3 Flame Stage.
- 0 Undetermined or not reported.

EQUIPMENT INVOLVED IN IGNITION**Heating Systems**

- 11 Central heating unit.
- 12 Water heater.
- 13 Fixed, stationary local heating unit.
- 14 Radiator.
- 15 Portable local heating unit.
- 16 Chimney, gas vent flue.
- 17 Chimney connector, vent connector.
- 18 Heat transfer system.
- 19 Heating system not classified above.
- 20 Heating system, undetermined.

Cooking Equipment

- 21 Fixed, stationary surface unit.
- 22 Fixed, stationary oven.
- 23 Fixed, stationary food warming appliance.
- 24 Deep fat fryer.
- 25 Portable cooking, warming unit.
- 26 Open fry gril.
- 27 Grease hood, duct.
- 28 Cooking equipment not classified above.
- 29 Cooking equipment, undetermined.

Air Conditioning, Refrigeration Equipment

- 31 Central air conditioning, refrigeration equipment.
- 32 Water cooling device, tower.
- 33 Fixed, stationary local refrigeration unit.
- 34 Fixed, stationary local air conditioning unit.
- 35 Portable air conditioning, refrigeration unit.
- 39 Air conditioning, refrigeration equipment not classified above.
- 30 Air conditioning, refrigeration equipment, undetermined.

Electrical Distribution Equipment

- 41 Fixed wiring.
- 42 Transformer, associated equipment or disconnect equipment.
- 43 Meter, meter box.
- 44 Power switch gear, overcurrent protection devices.
- 45 Switch, receptacle, outlet.
- 46 Lighting fixture, lampholder, ballast, sign.
- 47 Cord, plug.
- 48 Lamp, light bulb.
- 49 Electrical distribution equipment, not classified above.
- 40 Electrical distribution equipment, undetermined.

Appliances, Equipment

- 51 Television, radio, phonograph.
- 52 Dryer.
- 53 Washing machine.
- 54 Floor care equipment.
- 55 Squeeze motor, generator.
- 56 Hand tools.
- 57 Portable appliance designed to produce controlled heat.
- 58 Portable appliance designed not to produce heat.
- 59 Appliances, equipment not classified in 51 through 58.
- 50 Appliances, equipment, undetermined.

Special Equipment

- 61 Electronic equipment.
- 62 Vending machine, drinking fountain.
- 63 Office machine.
- 64 Biomedical equipment device.
- 65 Squeeze pump, compressor.
- 66 Combustion engine.
- 67 Camera.
- 68 Printing press.
- 69 Special equipment, not classified above.
- 60 Special equipment, undetermined.

Processing equipment

- 71 Furnace, oven, kiln.
- 72 Casting, molding, forging equipment.
- 73 Heat treating equipment.
- 74 Working, shaping machine.
- 75 Coating machine.
- 76 Painting equipment.
- 77 Chemical process equipment.
- 78 Waste recovery equipment.
- 79 Processing equipment, not classified above.
- 70 Processing equipment, undetermined.

Service, Maintenance Equipment

- 81 Incinerator.
- 82 Boring, brake.
- 83 Rectifier, charger.
- 84 Tarpot, tar kettle.
- 85 Arc, oil lamp.
- 86 Elevator.
- 87 Torchbox.
- 89 Service, maintenance equipment, not classified above.
- 80 Service, maintenance equipment, undetermined.

Other Object, Exposure Fire

- 91 Separate, unexposed exposure.
- 92 Separate, detached exposure.
- 93 Separate, adjoining exposure.
- 94 Attached, protected exposure.

95 Attached, unprotected exposure.

- 96 Vehicle.
- 98 No equipment involved—
- 99 Other object, exposure fire not classified above.
- 80 Other object, exposure fire.
- 00 Equipment involved in ignition undetermined or not reported.

FORM OF HEAT OF IGNITION**Heat from Fuel-Fired, Fuel Powered Object**

- 11 Spark, ember, flame escaping from gas fueled equipment.
- 12 Heat from gas fueled equipment.
- 13 Spark, ember, flame escaping from liquid fueled equipment.
- 14 Heat from liquid fueled equipment.
- 15 Spark, ember, flame escaping from solid fueled equipment.
- 16 Heat from solid fueled equipment.
- 17 Spark, ember, flame escaping from equipment: fuel not known.
- 18 Heat from equipment: fuel not known.
- 19 Heat from fuel-fired, fuel-powered object not classified above.
- 10 Heat from fuel-fired, fuel-powered object, undetermined.

Heat from Electrical Equipment Arcing, Overloaded

- 21 Water caused short circuit arc.
- 22 Short circuit arc from mechanical damage.
- 23 Short circuit arc from defective, worn insulation.
- 24 Unspecified short circuit arc.
- 25 Arc from faulty contact, loose connection, broken conductor.
- 26 Arc, spark from operating equipment or switch.
- 27 Heat from overloaded equipment.
- 28 Fluorescent light ballast.
- 29 Heat from electrical equipment arcing overloaded, not classified above.
- 20 Heat from electrical equipment arcing, overloaded undetermined.

Heat from Smoking Material

- 31 Cigarette.
- 32 Cigar.
- 33 Pipe.
- 39 Heat from smoking material, not classified above.
- 30 Heat from smoking material, undetermined.

Heat from Open Flame, Spark

- 41 Cutting torch operation.
- 42 Welding torch operation.
- 43 Torch operation, other than cutting and welding.
- 44 Candle, taper.
- 45 Match.
- 46 Lighter.
- 47 Open fire.
- 48 Backfire from internal combustion engine.
- 49 Heat from open flame, spark, not classified above.
- 40 Heat from open flame, spark, undetermined.

Heat from Hot Object

- 51 Heat, spark from friction.
- 52 Molten, hot material.
- 53 Hot ember, ash.
- 54 Electric lamp.
- 55 Rekindle, reignition.
- 56 Heat from properly operating electrical equipment.
- 57 Heat from improperly operating electrical equipment.
- 59 Heat from hot object, not classified above.
- 50 Heat from hot object, undetermined.

Heat from Explosive, Fireworks

- 61 Explosive.
- 62 Blasting agent.
- 63 Fireworks.
- 64 Paper cap, party popper.
- 65 Model rocket, not amateur rocketry.
- 66 Incendiary device.
- 69 Heat from explosive, fireworks, not classified above.
- 60 Heat from explosive, fireworks, undetermined.

Heat from Natural Source

- 71 Sun's heat.
- 72 Spontaneous ignition chemical reaction.
- 73 Lightning discharge.
- 74 Static discharge.
- 75 Heat from natural source, not classified above.
- 76 Heat from natural source, undetermined.

Heat Spreading from Another Hostile Fire (Ex post facto)

- 81 Heat from direct flame, convection currents.
- 82 Reradiated heat.
- 83 Heat from flying brand, ember, spark.
- 84 Conducted heat.
- 85 Heat spreading from another hostile fire, not classified above.
- 86 Heat spreading from another hostile fire, undetermined.

Other Form of Heat of Ignition

- 87 Multiple forms of heat of ignition.
- 88 Other form of heat of ignition.
- 89 Form of heat of ignition undetermined.

TYPE OF MATERIAL IGNITED**Gas**

- 11 Natural gas.
- 12 LP city gas (LP and air mix).
- 13 Manufactured gas.
- 14 LP gas.
- 15 Acetylene gas.
- 16 Acetylene.
- 17 Specialty gas other than anesthetic.
- 18 Gas not classified above.
- 19 Gas.

Flammable, Combustible Liquid

- 21 Class IA flammable liquid.
- 22 Class IB flammable liquid.
- 23 Gasoline.
- 24 Class IC flammable liquid.
- 25 Class II combustible liquid.
- 26 Class IIIA combustible liquid.
- 27 Class IIIB combustible liquid.
- 28 Flammable, combustible liquid, not classified above.
- 29 Flammable, combustible liquid, undetermined.

Volatile Solid, Chemical

- 31 Fat, grease, food.
- 32 Grease (nonfood).
- 33 Polish.
- 34 Adhesive, resin, tar.
- 35 Applied paint, varnish.
- 36 Combustible metal.
- 37 Solid chemical (explosive type).
- 38 Redoxactive material.
- 39 Volatile solid, chemical, not classified above.
- 40 Volatile solid, chemical, undetermined.

Plastic

- 41 Polymethane.
- 42 Polystyrene.
- 43 Polyvinyl.
- 44 Polyacrylic.
- 45 Polyester.
- 46 Polyolefin.
- 47 Plastic, not classified above.
- 48 Plastic, undetermined.

Natural Product

- 51 Rubber.
- 52 Cork.
- 53 Leather.
- 54 Grass, leaves, hay, straw.
- 55 Grain, natural fiber.
- 56 Coal, coke, briquettes, peat.
- 57 Food starch.
- 58 Tobacco.
- 59 Natural product, not classified above.
- 60 Natural product, undetermined.

Wood, Paper

- 61 Growing wood.
- 62 Felled but unsawn wood.
- 63 Sawn wood.
- 64 Wood shavings.
- 65 Hardboard, plywood.
- 66 Fiberboard (low density material), wood pulp.
- 67 Paper, untreated, uncoated.
- 68 Cardboard.
- 69 Wood, paper, not classified above.
- 70 Wood, paper, undetermined.

Fabric, Textile, Fur

- 71 Man-made fabric, fiber, finished goods.
- 72 Cotton, rayon, cotton fabric, finished goods.
- 73 Wool, wool mixture fabric, finished goods.
- 74 Fur, silk, other fabric, finished goods.
- 75 Wig.
- 76 Human hair.
- 77 Fabric, textile, fur, not classified above.
- 78 Fabric, textile, fur, undetermined.

Material Compounded with Oil

- 81 Lubricant.
- 82 Oil, kerosene.
- 83 Treated and/or coated paper.
- 84 Waterproof canvas.
- 85 Dry rags.
- 86 Asphalt treated material.
- 87 Material compounded with oil, not classified above.
- 88 Material compounded with oil, undetermined.

Other Type of Material Ignited

- 89 Multiple types of material first ignited.
- 90 Type of material not applicable.
- 91 Type of material not classified above.
- 92 Type of material undetermined or not reported.

FORM OF MATERIAL IGNITED**Structural Component, Finish**

- 11 Exterior roof covering, surface, finish.
- 12 Exterior sidewall covering, surface, finish.
- 13 Exterior trim, appurtenances.
- 14 Floor covering, surface.
- 15 Interior wall covering, surface items permanently affixed to wall and door surface.
- 16 Ceiling covering, surface.
- 17 Structural member (framing).
- 18 Thermal, acoustical insulation within wall, partition, or floor/ceiling space.
- 19 Structural component, finish, not classified above.
- 20 Structural component, finish, undetermined.

Furniture

- 21 Upholstered sofa, chair, vehicle seats.
- 22 Upholstered chair, bench.
- 23 Cabinetry.
- 24 Ironing board.
- 25 Appliance housing or casing.
- 26 Furniture not classified above.
- 27 Furniture, undetermined.

Soft Goods, Wearing Apparel

- 31 Mattress, pillow.
- 32 Bedding, blanket, sheet, comforter.
- 33 Linen, other than bedding.
- 34 Wearing apparel not on a person.
- 35 Wearing apparel on a person.
- 36 Curtain, blind, drape, tapestry.
- 37 Goods not made up.
- 38 Luggage.
- 39 Soft goods, wearing apparel, not classified above.
- 40 Soft goods, wearing apparel, undetermined.

Adornment, Recreational Material

- 41 Christmas tree.
- 42 Decoration for special event.
- 43 Book.
- 44 Magazine, newspaper, writing paper.

- 45 Toy, game.
- 46 Awning, canopy.
- 47 Tarpaulin, tent.
- 48 Adornment, recreational material not classified above.
- 49 Adornment, recreational material, undetermined.

Suppliers, Stock

- 51 Bag, carton, bag.
- 52 Basket, barrel.
- 53 Pallet, skid (not in use).
- 54 Rope, cord, twine, yarn.
- 55 Packing, wrapping material.
- 56 Bulk storage.
- 57 Bulk storage.
- 58 Cleaning supplies.
- 59 Supplies, stock not classified above.
- 60 Supplies, stock, undetermined.

Power Transfer Equipment, Fuel

- 61 Electrical wire, cable insulation.
- 62 Transformer.
- 63 Conveyor belt, drive belt, V belt.
- 64 Tire.
- 65 Fuel.
- 66 Power transfer equipment, fuel, not classified above.
- 67 Power transfer equipment, fuel, undetermined.

General Form

- 71 Agricultural product.
- 72 Fence, pole.
- 73 Fertilizer.
- 74 Growing, living form.
- 75 Knitwear, brush, waste.
- 76 Cooking materials.
- 77 Sign.

Special Form

- 81 Dust, fiber, lint.
- 82 Pyrotechnics, explosives.
- 83 Atomized, vaporized liquid.
- 84 Glass.
- 85 Palletized material, material stored on pallets.
- 86 Gas or liquid in or from pipe or container.
- 87 Rolled material.
- 88 Adhesive.

Other Form of Material

- 89 Multiple form of material ignited.
- 90 Form of material not applicable.
- 91 Form of material not classified above.
- 92 Form of material undetermined or not reported.

IGNITION FACTOR**Incendiary**

- 11 Incendiary, not during civil disturbance.
- 12 Incendiary, during civil disturbance.

Suspicious

- 21 Suspicious, not during civil disturbance.
- 22 Suspicious, during civil disturbance.

Misuse of Heat of Ignition

- 31 Abandoned, discarded material.
- 32 Throwing.
- 33 Falling asleep.
- 34 Inadequate control of open fire.
- 35 Cutting, welding too close to.
- 36 Children with, child playing.
- 37 Unconscious, mental, physical impairment.
- 38 Misuse of heat of ignition not classified above.
- 39 Misuse of heat of ignition, undetermined.

Misuse of Material Ignited

- 41 Fuel spilled, released accidentally.
- 42 Improper fueling techniques.
- 43 Flammable liquid used to kindle fire.
- 44 Washing paint, cleaning, refinishing, painting.
- 45 Improper container.
- 46 Combustible too close to heat.
- 47 Improper storage.
- 48 Children with, child playing.
- 49 Misuse of material ignited not classified above.
- 50 Misuse of material ignited, undetermined.

Mechanical Failure, Malfunction

- 51 Part failure, leak, break.
- 52 Automatic control failure.
- 53 Manual control failure.
- 54 Short circuit, ground fault.
- 55 Other electrical failure.
- 56 Lack of maintenance, worn out.
- 57 Backfire.
- 59 Mechanical failure, malfunction not classified above.
- 50 Mechanical failure, malfunction, undetermined.

Design, Construction, Installation Deficiency

- 61 Design deficiency.
- 62 Construction deficiency.
- 63 Installed too close to combustibles.
- 64 Other installation deficiency.
- 65 Property too close to.
- 69 Design, construction, installation deficiency not classified above.
- 60 Design, construction, installation deficiency, undetermined.

Operational Deficiency

- 71 Collision, overturn, knockdown.
- 72 Accidentally turned on, not turned off.
- 73 Unattended.
- 74 Overloaded.
- 75 Spontaneous heating.
- 76 Improper startup, shutdown procedures.
- 79 Operational deficiency not classified above.
- 70 Operational deficiency, undetermined.

Natural Condition

- 81 High wind.
- 82 Earthquake.
- 83 High water, including floods.
- 84 Lightning.
- 89 Natural condition not classified above.
- 80 Natural condition, undetermined.

Other Ignition Factor

- 91 Animal.
- 92 Rekindled from a previous fire.
- 99 Other ignition factor not classified above.
- 00 Ignition factor undetermined or not reported.

Construction Class

- 0 No Building Involved.
- 1 Fireproof Structure.
- 2 Fire Protected Structure.
- 3 Non-fireproof Structure.
- 4 Wood Frame Structure.
- 5 Metal Structure.
- 6 Heavy Timber Structure.

Classification of Building By Use—Commercial

- 01 Bank.
- 02 Brewery.
- 03 Coal Pocket.
- 04 Department Store.
- 05 Electrical Power Plant.
- 06 Factory: Multi Occupancy.
- 07 Factory: Single Occupancy.
- 08 Foundry.
- 09 Freight Depot.
- 10 Garage: Non-Storage.
- 11 Garage: Storage.
- 12 Gas Works.
- 13 Lumber Yard.
- 14 Motor Vehicle Repair Shop.
- 15 Office Building.
- 16 Oil Selling Station.
- 17 Oil Storage Plant.
- 18 Pier, Wharve, Dock, Bulkhead Building.
- 19 Restaurant, diner.
- 20 Shed, Newsstand, Shanty.
- 21 Shipyard, Drydock.
- 22 Stable.
- 23 Steam Generating Plant.
- 24 Store Building, Taxpayer.
- 25 Warehouse, Storehouse.
- 26 Store Building & Private Dwelling.
- 39 Other Commercial.

Classification of Building By Use—Public

- 40 Airport Building.
- 41 Asylum.
- 42 Bridge.
- 43 Bus Terminal.
- 44 Church, Synagogue.
- 45 Dance Hall, Banquet Hall.
- 46 Dispensary, Clinic.
- 47 Ferry Terminal.
- Government Buildings—(Not otherwise classified):
- 48 City.
- 49 Interstate.
- 50 Federal.
- 51 Foreign.
- 52 State.
- 53 Hospital, Infirmary.
- 54 Nursing Home.
- 55 Railroad Station.
- 56 School: College, University.
- 57 School: Private High.
- 58 School: Public High.
- 59 School: Public Jr. High.
- 60 School: Private Elementary.
- 61 School: Public Elementary.
- 62 School: Children's Nursery.
- 63 School: Other.
- 64 Television Studio.
- 65 Theatre, Legitimate.
- 66 Theatre, Motion Picture.
- 67 Transit System—Station Structure.
- 68 Tunnel.
- 69 Other Public.

Residential

- 80 Apartment Hotel "A."
- 81 Apartment House "A."
- 82 Boarding House, Rooming House "B."
- 83 Convent, Rectory, Monastery, etc.
- 84 Dormitory—School, Club, Lodge.
- 85 Hotel "B."
- 86 Lodging House "B."
- 87 Motel.
- 88 Private Dwelling: One Family.
- 89 Private Dwelling: Two Family.
- 90 Tenement: New Law "A."
- 91 Tenement: Old Law "A."
- 92 Converted Dwelling "A."
- 99 Other Residential.

Building Status

- 1 Occupied.
- 2 Partly Occupied, Good Condition.
- 3 Partly Occupied, Deteriorating.
- 4 Vacant.
- 5 Under Demolition.
- 6 Under Construction.

Damage to Building or Contents

- 0 None.
- 1 1 to 15%.
- 2 16 to 49%.
- 3 50% or Greater.

Area Fire Origin—Floor

- 00 Outside Building
- 01 1st Floor.
- 10
- 94 94th and Higher.
- 95 Attic.
- 96 Roof.
- 97 Basement.
- 98 Cellar.
- 99 Subcellar.

Area Fire Origin—Room or Area

- 10 Area Not in Building.
- 11 Attic.
- 12 Awning.
- 13 Balcony.
- 14 Basement.

- 15 Bathroom Toilet.
- 16 Bedroom, Sleeping Area.
- 17 Ceiling.
- 18 Cellar.
- 19 Chimney.
- 20 Classroom Lecture Area.
- 21 Closet.
- 22 Cockloft.
- 23 Court—Exterior.
- 24 Court—Interior.
- 25 Dining Room, Dining Area.
- 26 Duct—Air Conditioning.
- 27 Duct—Exhaust.
- 28 Flooring.
- 29 Furnace Room.
- 30 Hallway—Private.
- 31 Hallway—Public.
- 32 Incinerator Closet or Room.
- 33 Kitchen, Cooking Area.
- 34 Living Room.
- 35 Lobby.
- 36 Machinery Room.
- 37 Office Area.
- 38 Operating Laboratory Area.
- 39 Partition.
- 40 Porch.
- 41 Projection Booth.
- 42 Recreation Area.
- 43 Roof.
- 44 Sales Showroom Display Area.
- 45 Shaft—Duct, Pipe.
- 46 Shaft—Dumbwaiter.
- 47 Shaft—Elevator.
- 48 Shaft—Exterior Light.
- 49 Shaft—Interior Light.
- 50 Shaft—Vent.
- 51 Shipping Receiving Loading Area.
- 52 Stage.
- 53 Stairway.
- 54 Storage Room Area.
- 55 Vacant—Room, Apartment or Area.
- 56 Work Area, Workroom.
- 57 Other Areas, Not Classified (state area).

Area Fire Origin—Occupancy Classification—Commercial**Factory:**

- 99 Chemicals.

Clothing:

- 01 Dresses.
- 02 Undergarment.
- 03 Other (state type).
- 04 Dry Cleaning Laundry.
- 05 Electrical Products.
- 06 Food & Drink Products.
- 07 Furniture.
- 08 Furs, Fur Goods.

Hats:

- 09 Men's.
- 10 Women's.
- 11 Leather, Leather Products.
- 12 Machine Shop Metal Works.
- 13 Paints.
- 14 Paper Products.
- 15 Petroleum Products.
- 16 Plastics, Rubber.
- 17 Printing & Allied Industries.
- 18 Shoes.
- 19 Textiles.
- 20 Toy or Doll.
- 21 Woodworking.
- 22 Other Factories Not Classified (state type).

Store:

- 23 Auto Accessories.
- 24 Bakery.
- 25 Butcher.

Area Fire Origin—Occupancy Classification—
(continued)**Stores:**

- 26 Candy, Cigar, Stationery.
- 27 Clothing.
- 28 Department, Large.
- 29 Department, Small (5&10).
- 30 Dry Cleaner & Tailor.
- 31 Drug.
- 32 Electrical Appliances.
- 33 Fruit & Vegetables.
- 34 Furniture.
- 35 Grocery, Dairy, Delicatessen.
- 36 Haberdashery.
- 37 Ladies Accessories.
- 38 Laundry.
- 39 Paint Hardware.
- 40 Restaurant Luncheonette.
- 41 Shoe.
- 42 Shoe Repair.
- 43 Super Market.
- 44 Tavern.
- 45 Other Stores Not Classified (state type).

Garages:

- 46 Non Storage.
- 47 Storage.
- 48 Oil Selling Station.
- 49 Motor Vehicle Repair Shop.
- 50 Office Building.

Warehouses:

- 51 Film.
- 52 Paper, Rags, Fibre.
- 53 Other (state type).
- 54 Freight Depot.
- 55 Pier.
- 56 Shipyard.
- 57 Lumber Yard.
- 58 Shed, Newsstand, Shanty, etc.
- 59 Other Commercial Building Occupancies, Not Classified (state type).

Residential

- 60 Apartment Hotel, Multiple Dwelling "A."
- 61 Apartment House, Multiple Dwelling "A."
- 62 Boarding House, Rooming House, Multiple Dwelling "B."
- 63 Hotel, Multiple Dwelling "B."
- 64 Lodging House, Multiple Dwelling "B."
- 65 Private Dwelling.
- 66 Rectory, Convent, Monastery, etc.
- 67 Tenement House, New Law, Multiple Dwelling "A."
- 68 Tenement House, Old Law, Multiple Dwelling "A."
- 69 Other Residential, Not Classified (state type).

Public

- 70 Airport.
- 71 Cabaret, Banquet Hall.
- 72 Church.
- 73 Dance Hall.
- 74 Hospital.
- 75 Motion Picture Theatre.
- 76 N.Y. Transit System—Station.
- 77 Passenger Depot.

- 78 School.
- 79 Theatre.
- 80 T.V. Studio.
- 81 Other Public, Not Classified (state type).

Manner Extension

- 00 Confined to area of origin.
- 01 Cockloft.
- 02 Door or Opening Between Rooms.
- 03 Floor.
- 04 Hall Stairway.
- 05 Partition.
- 06 Pipe Recess.
- 07 Shaft Dumbwaiter.
- 08 Shaft—Elevator.
- 09 Shaft—Aw, Light, Chute, Duct, etc.
- 10 Ceiling.
- 11 Window.
- 12 Other (state how).

Number of Occupancies

- 01 1 Occupancy.
- 02 2 Occupancies.
- 99 99 or more Occupancies.

Buildings

- 0 did not spread beyond building of origin.
- 1 1 structure or vehicle.
- 9 9 or more buildings or vehicles.

Note: Form BF 24A must be submitted for each building or vehicle listed in this coded space.

Smoke Detector

- 0 No detector present.
- 1 Ionization type, power disconnected or battery removed by occupant.
- 2 Ionization type, provided early warning.
- 3 Ionization type, failed to operate, battery powered.
- 4 Ionization type, failed to operate, line voltage power.
- 5 Photoelectric type, power disconnected or battery removed by occupant.
- 6 Photoelectric type, provided early warning.
- 7 Photoelectric type, failed to operate, battery powered.
- 8 Photoelectric type, failed to operate, line voltage power.
- 9 Not possible to determine if detector operated or not.

Classification by Type Fire or Emergency**Transportation Fires**

- 87 Ship, Vessel.
- 88 Motor Vehicle.
- 89 Other Transportation (state type).

Non Structural Fires

- 86 ADV (Abandoned/Derelect Motor Vehicle).
- 90 Bonfire.
- 91 Brush Grass.
- 92 Demolition Wood, Building Site.
- 93 Dump, Land Fill.
- 94 Rubbish—Outside Building.

- 95 Manhole.
- 96 N.Y. Transit System—Yard, Roadway, Ties, etc.
- 97 Railroad—Yard, Roadway, Ties, etc.
- 98 Tunnel, Bridge.
- 99 Other Non-Structural, Not Classified (state type).

Emergency

- 02 Chimney.
- 03 Elevator, Escalator.
- 04 Explosives Escort.
- 05 First Aid—Assist Person(s).
- 06 First Aid—Resuscitation.
- 07 Marine.
- 08 Precarious Condition—Signs, Trees, etc.
- 09 Subway—Railroad.
- 10 Water Leak.
- 11 Bomb—Unexploded, Scare.
- 12 Collapse—Cave In.
- 13 Collision—Vehicular Incident.
- 14 Controlled Fire, Permitted.
- 15 Flood Condition—Broken Water Main.
- 16 Incinerator.
- 17 Leak—Fuel Oil, Gasoline, etc..
- 18 Leak—Hum. Gas, Flam. Vapor.
- 19 Lightning.
- 20 Oil Burner.
- 21 Person Locked In, Locked Out.
- 22 Power—Electrical.
- 23 Pressure Rupture.
- 24 Refrigerant Leak.
- 25 Smoke Condition, Odor, Fumes.
- 26 Sprinkler.
- 27 Steam Discharge.
- 28 Defective Alarm Device (other than Sprinkler).
- 29 Smoke Detector.
- 30 Other.

Power for Equipment

- 01 123 volts A.C.
- 02 24 volts A.C.
- 11 16 volts D.C.
- 12 7-12 volts D.C.
- 15 115 volts A.C.
- 28 208 volts A.C.
- 30 220-230 volts A.C.
- 33 231-330 volts A.C.
- 34 331 or higher volts AC.
- 50 25 50 volts A.C.
- 61 Butane.
- 62 Coal, Coke, Charcoal, Peat.
- 63 Fuel Oil, No. 1 or No. 2.
- 64 Fuel Oil, No. 3 or No. 4.
- 65 Fuel Oil, No. 5 or No. 6.
- 66 Gasoline.
- 67 Kerosene.
- 68 LN gas (stored as liquid).
- 69 LP gas (stored as liquid).
- 70 Natural or illuminating gas (as a gas).
- 71 Paper.
- 72 Propane.
- 99 Other.

This page intentionally left blank

Attachment G-A.3

Explanation of Numeric Codes Used on Fire and Emergency Reports -
From June 1, 1987 to present

4 -
MO3-1 H1-5H266-5-025-115

14.1 TYPE OF REPORT

- Code No.
1 Structural
2 Transportation Fire
3 Non-Structural Fire
4 Emergency Response
5 False Alarm
6 Additional data (GF-24A)

14.2 HOW REPORTED

- Code No.
10 Telephone
20 Street — Manual
21 Class 3 — Manual
30 Class 3 — P.F.A.
31 Class 3 Valve, Sprinkler — P.F.A.
32 Class 3, Other Automatic — P.F.A.
40
50 Verbal
60 Pre-Recorded Telephone Alarm
70 Tie Line (Direct Line to Dispatcher — Pipeline Corp.)
80 Street Box — ERS
81 Class 3 — ERS
90 Radio Television Link
Note: 1. P.F.A. stands for Private Fire Alarm. These are received using the 3-Box-Terminator designation.

2. If the alarm was encountered while responding to or returning from another alarm, it is considered a verbal alarm.

3. A pre-recorded telephone alarm (P.P.T.A.) is used to designate those telephone alarms received from recording or pre-dialed machines, whether directly to 911, 7-digit telephone or an alarm service.

14.3 INITIAL ALARM

- Code No.
0 Special Call Other Than Engine Only — No Chief
1 Box (Street or Class 3)
5 Special Call Engine Only — No Chief
6 Special Call (Chief Operator)
9 Staff

14.4 HIGHEST ALARM

- Code No.
0 Initial Alarm
1 More than the Initial Alarm & Less than 3 Engines & 2 Ladder Cos. at work.
2 2nd Alarm
3 3rd Alarm
4 4th Alarm
5 5th Alarm
6 Simultaneous
7 Signal 7-5

14.5 BOROUGHS

- Code No.
1 Manhattan
2 Bronx
3 Staten Island
4 Brooklyn
5 Queens

14.6 HAZARDOUS MATERIALS

14.6.1 Class to be obtained from D.D.T. required labels or placard or from shipping papers or other documents

- Code No.
00 No Hazardous Materials Involved
11 Class A Explosives
12 Class B Explosives
13 Class C Explosives
15 Blasting Agents
21 Flammable Gases
22 Non-Flammable Gases
23 Poison Gases
24 Chlorine
25 Oxygen

FIRE RECORD CODE LIST

1

- 31 Flammable Liquids, flashpoint 100 degrees or less
32 Combustible Liquids, flashpoint greater than 100 degrees
41 Flammable Solids
42 Spontaneously Combustible Materials
43 Materials Dangerous when Wet
51 Oxidizers
52 Organic Peroxides
53 Poisons
54 Etiologic (Infectious) Substances
63 Inflammables
71 Radioactive I Materials
72 Radioactive II Materials
73 Radioactive III Materials
81 Corrosives
98 Multiple Classes (More than one hazardous material)
99 Other

14.6.2 Amount 3 Unit — The letter designating the unit of measurement shall follow the two digits indicating the amount. Example: 3000 gals. of gasoline would be correctly coded as 07G in the "Amount" field

- 000 No Hazardous Material Involved
01 Less Than 1 F Cubic feet, for gases only
02 1-5 G Gallon
03 10-40 M Multiple Units — Ext. a spill involves a liquid and a solid
P Pound
T Ton

05 100-499
06 500-999
07 1,000-4,999
08 5,000-9,999
09 10,000-49,999
10 50,000-99,999
11 100,000 and more

14.7 HEATING EQUIPMENT INVOLVED — TYPE OF FUEL USED

- Code No.
1 Kerosene
2 L.P.G.
3 Electric
4 Wood
5 Coal
6 Oil
7 Natural Gas
8 Gasoline
9 Other
0 No Heating Equipment Involved

14.8 HOW EXTINGUISHED

- Code No.
0 Before Arrival
1 Hand Extinguishers
2 Sprinkler Heads (State Number of heads that operated in Operations Section)
3 Booster Stream
4 Low Pressure Hydrant Stream
5 One 1½" or larger hose line from a pumping unit or a standpipe outlet, regardless of line termination (Controlling Nozzle, Decoupler, Stang, Multi Vessel, Ladder Pipe, T.L., Foam Nozzle, etc.)
6 Two 1½" or larger hose lines as above
7 Three 1½" or larger hose lines as above
8 Four or more 1½" or larger hose lines as above
9 Other (State How)

14.9 SPRINKLER PERFORMANCE — If sprinklers were present or a factor in this operation, record their performance.

1. Equipment Operated
2. Equipment in service, did not operate
3. Equipment present, fire too small to operate
4. Equipment operated, did not extinguish fire
5. No equipment present
9. Equipment present, not in service. (Record action taken in Operations Section)

14.10 STANDPIPE PERFORMANCE — If a standpipe system was present or used in this operation, record its performance.

1. Standpipe serviceable and used

2. Standpipe present but not used
3. No standpipe present
9. Equipment present, not in service. (Record action taken in Operations Section)

14.11 CONDITION ON ARRIVAL CODES

- 0 No indication of fire
1 Overheat
2 Smoldering
3 Open Flame
8 Out on Arrival

14.12 EQUIPMENT INVOLVED IN IGNITION

1. HEATING SYSTEMS

- 10 Solar panel.
11 Central heating unit, furnace
12 Water heater.
13 Woodstove, wall furnaces, fixed local heating unit
14 Indoor fireplace
15 Portable heating unit
16 Chimney, gas vent flue
17 Chimney vent connector
18 Heat transfer system, ducts, pipes.
19 Not classified above

2. COOKING EQUIPMENT

- 21 Fixed, stationary surface unit, stove
22 Fixed, stationary oven
23 Fixed, stationary food warming appliance
24 Deep fat fryer
25 Portable cooking, warming unit
26 Open faced grill
27 Griddle, brood, duct.
29 Not classified above

3. AIR CONDITIONING, REFRIGERATION EQUIPMENT

- 31 Central air conditioning, refrigeration equipment
32 Water Cooling device, tower
33 Cold boxes, freezers, refrigerators.
34 Fixed, stationary local air conditioning unit
35 Portable air conditioning, refrigeration unit, dehumidifier.
39 Not classified above

4. ELECTRICAL DISTRIBUTION EQUIPMENT

- 41 Fixed Wiring, power lines, junction boxes.
42 Transformer, overcurrent or disconnect equipment.
43 Meter, meter box.
44 Power Switch gear fused, circuit breakers.
45 Switch, receptacle outlet.
46 Lighting fixture, lamp-holder ballast, sign.
47 Cord, plug
48 Lamp, light bulb.
49 Not classified above

5. APPLIANCES EQUIPMENT

- 50 Dishwasher.
51 Television, radio, sound or picture.
52 Clothes dryer.
53 Washing machine.
54 Floor care equipment, vacuum.
55 Separate motor, generator.
56 Hand tools, soldering irons, drills
57 Controlled heat appliance, electrical blankets, steam irons, heat tapes.
58 Electrical razors, can openers.
59 Not classified above.

6. SPECIAL EQUIPMENT

- 61 Electronic equipment, radar, x-rays, computer, telephone, transmitter equipment.
62 Vending machine, drinking fountain
63 Office machines
64 Biomedical equipment, device.
65 Separate pump, compressor, sump pump.
66 Internal combustion engine.
67 Conveyer
68 Printing press.
69 Not classified above.

2

7. PROCESSING EQUIPMENT

- 71. Furnace, oven, kiln.
- 72. Casting, molding, forging.
- 73. Heat treating, quench tank.
- 74. Working, shaping, machine saws, grinders, sanders, etc.
- 75. Coating machine, asphalt saturating, rubber spreading machines.
- 76. Painting, dipping, spraying.
- 77. Chemical process, distilling.
- 78. Waste recovery.
- 79. Not classified above.

8. SERVICE, MAINTENANCE EQUIPMENT

- 81. Incinerator.
- 82. Reeling, brake.
- 83. Rectifier, charger, battery.
- 84. Tarpot, tar kettle.
- 85. Arc, oil lamp, gas mantles.
- 86. Elevator.
- 87. Torchets, Benson burners.
- 88. Not classified above.

9. OTHER OBJECTS, EXPOSURE FIRE

- 90. Vehicle, exhaust systems, vehicle parts.
- 91. No equipment involved.
- 92. Other object, Exposure Fire not classified above.

14.13 FORM OF HEAT IGNITION

- 1. **HEAT FROM FUEL-FIRED, FUEL-POWERED OBJECT**
The difference between subdivision 11 and subdivision 12 is whether a spark, ember or flame actually escaped from the equipment, or whether it was simply overheating of outside surface of the equipment (or its internal heat) causing the ignition of nearby combustibles.

- 11. Spark, ember, flame escaping from gas fueled equipment.
- 12. Heat from gas fueled equipment, pilot lights, normal flames.
- 13. Spark, ember, flame escaping from liquid fueled equipment.
- 14. Heat from liquid fueled equipment, pilot lights.
- 15. Spark, ember, flame escaping from solid fueled equipment.
- 16. Heat from solid fueled equipment.
- 17. Spark, ember, flame escaping from equipment, fuel not known.
- 18. Heat from equipment, fuel not known.
- 19. Not classified above.

2. HEAT FROM ELECTRICAL EQUIPMENT ARCING, OVERLOADED.

- 21. Water caused short circuit arc.
- 22. Short circuit arc from mechanical damage.
- 23. Short circuit arc from defective, worn insulation.
- 24. Unspecified short circuit arc.
- 25. Arc from faulty contact, loose connection, broken conductor.
- 26. Arc, spark from operating equipment or switch.
- 27. Heat from overloaded equipment, wires, motors.
- 28. Fluorescent light ballast.
- 29. Not classified above.

3. HEAT FROM SMOKING MATERIAL

- 31. Cigarette.
- 32. Cigar.
- 33. Pipe.
- 34. Not classified above.

4. HEAT FROM OPEN FLAME, SPARK

- 41. Cutting torch operation (separating metals).
- 42. Welding torch operation (joining metals).
- 43. Blow torches, plumbers torches, Bunsen Burners, soldering, paint stripping.
- 44. Candle, taper.
- 45. Match.
- 46. Lighter (flame type).
- 47. Campfires, bonfires, warming fires, rubbish fires.
- 48. Backfire from internal combustion engine.
- 49. Not classified above.

5. HEAT FROM HOT OBJECT

- 51. Heat, spark from friction, overheated tires.
- 52. Molten metal, hot forging and hot glass.
- 53. Hot ember, ash.
- 54. Electric lamp, light bulbs.
- 55. Rekindle, reignition.
- 56. Heat from properly operating electrical.
- 57. Heat from improperly operating electrical equipment.
- 58. Not classified above.

6. HEAT FROM EXPLOSIVES, FIREWORKS

- 61. Explosives, bombs, ammunition.
- 62. Flaming agent.
- 63. Fireworks, sparklers.
- 64. Paper cap, party popper.
- 65. Model rocket, not amateur rocketry.
- 66. Incendiary device.
- 67. Not classified above.

7. HEAT FROM NATURAL SOURCE

- 71. Sun's heat.
- 72. Spontaneous ignition, chemical reaction.
- 73. Lightning discharge.
- 74. Static discharge.
- 75. Not classified above.

8. HEAT SPREADING FROM ANOTHER HOSTILE FIRE (EXPOSURE)

- 81. Heat from direct flame, convection currents.
- 82. Radiated heat.
- 83. Heat from flying brand, ember, spark.
- 84. Conducted heat.
- 85. Not classified above.

9. OTHER FORM OF HEAT OF IGNITION

- 91. Multiple forms of heat of ignition.
- 92. Not classified above.

14.14 TYPE OF MATERIAL IGNITED

- 1. **GAS**
 - 11. Natural gas.
 - 12. LP-City Gas (LP and air mix).
 - 13. Manufactured gas.
 - 14. LP-Gas.
 - 15. Anesthetic gas.
 - 16. Acetylene.
 - 17. Specially gas other than anesthetic.
 - 18. Not classified above.

2. FLAMMABLE, COMBUSTIBLE LIQUID

- 21. Ethyl ether, pentane and ethylene oxide (Class 1A).
- 22. Acetone, ethyl alcohol, JP-4 jet fuel and methyl ethyl ketone, (Class 1B).
- 23. Gasoline.
- 24. Butyl alcohol, propyl alcohol styrene and turpentine, (Class 1C).
- 25. Kerosene, Fuel Oil 1, 2, 4, 5 and Diesel Fuel.
- 26. No. 6 fuel oil, cottonseed oil and cresset oil, (Class 1IA).
- 27. Cooking oil, transformer and lubricating oil, (Class 1IB).
- 28. Not classified above.

3. VOLATILE SOLID, CHEMICAL

- 31. Fat, grease (food).
- 32. Grease (nonfood), petroleum jellies.
- 33. Polish, paraffin, wax.
- 34. Creosote, pitch, adhesive, resin, tar, gelatin, rosin, asphalt.
- 35. Applied paint, varnish.
- 36. Combustible metal magnesium titanium and zirconium.
- 37. Solid chemical, explosives.
- 38. Radioactive material.
- 39. Not classified above.

4. PLASTIC

- 41. **RIGID PLASTICS**
Included are molded plastics such as appliance cases, floor tile, decorative kitchen laminates.
- 42. **RIGID FOAM PLASTICS**
Included are rigid thermal foam insulation for walls and refrigerators.

43. FLEXIBLE PLASTICS

- Included is electrical wire insulation.
- 44. **FLEXIBLE FOAM PLASTICS**
Included are mattresses, furniture interior foam and carpet pads.

45. FILM PLASTICS

- Included are polyethylene trash bags, photographic film and coated wallpaper.
- 46. Plastic not classified above.

5. NATURAL PRODUCTS

- 51. Rubber.
- 52. Cork.
- 53. Leather.
- 54. Grass, leaves, hay and straw.
- 55. Grain, leathers, felt, kapok, hemp, lute, cotton, before processing.
- 56. Coal, coke, briquettes, peat.
- 57. Food, starch, excluding fat and grease.
- 58. Tobacco.
- 59. Not classified above.

6. WOOD, PAPER

- 61. Growing wood, tree.
- 62. Felled but uncut wood.
- 63. Finished lumber, finished wood.
- 64. Wood shavings, sawdust excelsior.
- 65. Hardboard, plywood.
- 66. Fiberboard, wood pulp, press board.
- 67. Paper, untreated, uncoated.
- 68. Cardboard.
- 69. Not classified above.

7. FABRIC, TEXTILE, FUR

- 71. Man-made fabric, fiber, finished goods.
- 72. Cotton, rayon, cotton fabric.
- 73. Wool, wool mixture, fabric.
- 74. Fur, silk, other fabric.
- 75. Wig.
- 76. Human hair.
- 77. Not classified above.

8. MATERIAL COMPOUNDED WITH OIL

- 81. Linoleum.
- 82. Oil cloth.
- 83. Treated and/or coated paper, wax paper.
- 84. Waterproof canvas.
- 85. Oil rags.
- 86. Asphalt treated material.
- 87. Not classified above.

9. OTHER TYPE OF MATERIAL IGNITED

- 91. Multiple types of material first ignited.
- 92. Not classified above.

14.15 FORM OF MATERIAL IGNITED**1. STRUCTURAL COMPONENT, FINISH**

- 11. Exterior roof covering, surface, finish.
- 12. Exterior sidewall, covering surface, finish, eaves.
- 13. Doors, porches and platforms.
- 14. Tile, carpet, rug flooring and stairs.
- 15. Interior wall covering.
- 16. Ceiling covering surface.
- 17. Structural member, framing.
- 18. Thermal, acoustical insulation, within wall or ceiling.
- 19. Not classified above.

2. FURNITURE

- 21. Upholstered sofa, chair, vehicle seats.
- 22. Nonupholstered chair, bench.
- 23. Cabinetry, filing cabinets, pianos, dressers, desks, tables and bookcases.
- 24. Ironing board.
- 25. Appliance housing or casing.
- 26. Not classified above.

3. SOFT GOODS, WEARING APPAREL

- 31. Mattress, pillow.
- 32. Bedding, blanket, sheet, comforter, heating pad.
- 33. Linen, towels, tablecloths.
- 34. Wearing apparel not on a person.
- 35. Wearing apparel on a person.
- 36. Curtain, blind, drapery, tapestry.
- 37. Footwear, yard goods.
- 38. Luggage.
- 39. Not classified above.

4. ADORNMENT, RECREATIONAL MATERIAL

41. Christmas tree.
42. Decoration for special event.
43. Book.
44. Magazine, newspaper, writing paper, etc.
45. Toy, game.
46. Sewing, canopy.
47. Tarpaulin, tent.
49. Not classified above.

5. SUPPLIES, STOCK

51. Box, carton, bag.
52. Basket, barrel.
53. Pallet, skid.
54. Rope, cord, twine, yarn.
55. Packing, wrapping material.
56. Bulk storage.
57. Bulk storage.
58. Brooms, brushes, mops, cleaning cloths, cleaning supplies.
59. Not classified above.

6. POWER TRANSFER EQUIPMENT, FUEL

61. Electrical wire, cable insulation.
62. Transformer.
63. Conveyor belt, drive belt, v-belt.
64. Tire.
65. Fuel.
69. Not classified above.

7. GENERAL FORM

71. Agricultural product.
72. Fence, pole.
73. Fertilizer.
74. Forcals, brush and grass.
75. Film, creosote, rubbish, trash, waste.
76. Cooking materials.
77. Sign.

8. SPECIAL FORM

81. Dust, lint, dirt, sawdust.
82. Pyrotechnics, explosives.
83. Aerialized, vaporized liquid.
84. Chips.
85. Material stored on pallets.
86. Accelerants.
87. Solid material.
88. Adhesive.

9. OTHER FORM OF MATERIAL

97. Multiple form of material ignited.
99. Not classified above.

14.16 IGNITION FACTOR (CAUSE)**1. INCENDIARY**

11. Incendiary.
12. Incendiary, during civil disturbance.

2. SUSPICIOUS

21. Suspicious.
22. Suspicious, during civil disturbance.

3. MISUSE OF HEAT OF IGNITION

31. Abandoned, discarded material, cigarette, etc.
32. Thawing.
33. Falling asleep.
34. Inadequate control of open fire.
35. Cutting, welding too close to.
36. Children with matches, lighter, etc.
37. Unconscious, mental, physical impairment.
39. Not classified above.

4. MISUSE OF MATERIAL IGNITED

41. Fuel spilled, released accidentally.
42. Improper fueling technique.
43. Flammable liquid used to kindle fire.
44. Washing part, cleaning, refinishing, painting, etc.
45. Improper container.
46. Combustible too close to heat.
47. Improper storage.
49. Not classified above.

5. MECHANICAL FAILURE, MALFUNCTION

51. Part failure, leak, break.
52. Automatic control failure.
54. Short circuit, ground fault.
55. Other electrical failure.
56. Lack of maintenance, worn out, failure to clean.
57. Backfire.
59. Not classified above.

6. DESIGN, CONSTRUCTION, INSTALLATION DEFICIENCY

61. Design deficiency, catalytic converter failure.
62. Construction deficiency.
63. Installed too close to combustibles.
64. Other installation deficiency.
65. Property too close to. Included are exposure fires.
69. Not classified above.

7. OPERATIONAL DEFICIENCY

71. Collision, overturn, knockdown.
72. Accidentally turned on, not turned off.
73. Unattended.
74. Overloaded.
75. Spontaneous heating.
76. Improper startup, shutdown procedures.
79. Not classified above.

8. NATURAL CONDITION

81. High wind.
82. Earthquake.
83. High water, including floods.
84. Lightning.
89. Not classified above.

9. OTHER IGNITION FACTORS

91. Animal.
92. Rekindled from a previous fire.
99. Not classified above.
00. No fire.

14.17 JUVENILE INVOLVED IN IGNITION

0. Juvenile Not Involved in Ignition or No Information that a Juvenile was involved.
1. Juvenile Involved in Ignition.

14.18 CONSTRUCTION CLASS**Code No.**

0. No building involved.
1. Fireproof Structure.
2. Fire Protected Structure.
3. Non Fireproof Structure.
4. Wood Frame Structure.
5. Metal Structure.
6. Heavy Timber Structure.

14.19 CLASSIFICATION OF BUILDING BY USE**COMMERCIAL**

- 592 Bank.
- 723 Brewery.
- 895 Coal Storage.
- 561 Department Store.
- 615 Electrical Power Plant.
- 708 Factory: Multi Occupancy.
- 709 Factory: Single Occupancy.
- 771 Foundry.
- 894 Freight Depot.
- 882 Garage: Non-Storage.
- 889 Garage: Storage.
- 767 Gas Works, Natural Gas Plant.
- 851 Lumber Yard.
- 573 Motor Vehicle Repair Shop, Paint Shop.
- 591 Office Building, State, City, Federal or Commercial.
- 574 Oil Selling Station.
- 841 Oil Storage Plant.
- 898 Pier, Wharf, Dock, Bulkhead Building.
- 164 Restaurant, Diner.
- 925 Shop, Newstand, Shanty.
- 781 Shipyard, Drydock.
- 815 Stable.
- 614 Steam Generating Plant.

- 539 Storebuilding, Taxpayer.
- 831 Warehouse Storehouse.
- 410 Store Building & Private Dwelling.
- 580 Other Commercial.

PUBLIC

- 171 Airport Building.
- 361 Asylum.
- 921 Bridge.
- 173 Bus Terminal.
- 133 Church, Synagogue.
- 121 Dance Hall, Banquet Hall.
- 334 Dispensary, Clinic.
- 177 Ferry Terminal.
- 331 Hospital, Infirmary.
- 311 Nursing Home.
- 174 Railroad Station, Street Level.
- 175 Railroad Station, Below Grade.
- 176 Railroad Station, Above Grade.
- 241 School, College, University.
- 215 School: High School.
- 214 School: Junior High.
- 213 School: Elementary.
- 211 School: Children's Nursery.
- 210 School: Other.
- 185 Television Studio.
- 181 Theatre, Legitimate.
- 163 Theatre, Motion Picture.
- 170 Transit System—Station Structure.
- 922 Tunnel.
- 119 Other Public.

RESIDENTIAL

- 489 Apartment Hotel "A".
- 429 Apartment House "A".
- 439 Boarding House, Rooming House "B".
- 485 Convent, Rectory, Monastery, etc.
- 461 Dormitory—School, Club, Lodge.
- 449 Hotel "B".
- 430 Lodging House "B".
- 440 Motel.
- 411 Private Dwelling: One Family.
- 414 Private Dwelling: Two Family.
- 420 Tenement: New Law "A".
- 423 Tenement: Old Law "A".
- 492 Converted Dwelling "A".
- 490 Other Residential.

SPECIAL PROPERTIES

- 972 Airport Runway.
- 934 Cemetery.
- 951 Construction Site.
- 932 Dump, Landfill.
- 931 Open Land, Fields.
- 955 Parking Area, Lot.
- 983 Pipeline, Power Line Right-of-Way.
- 982 Public Street.
- 952 Railroad Switching Yard, marshalling yard.
- 936 Vacant Lots.
- 939 Outdoor Property Not Classified.

14.20 BUILDING STATUS CODE**Code Description**

- 1 Occupied: The building is normally fully occupied or is intended to be fully occupied. A few vacant areas, which are rentable, may exist.
 - 2 Partly Occupied: The building is in good condition and more than 25 percent of the areas are vacant.
 - 3 Partly Occupied, Deteriorating: The building has some vacant areas and these are expected to remain vacant until demolition or alteration because of the condition of the building or its surroundings.
 - 4 Vacant: The building is entirely vacant. (Even if squatters are present.)
 - 5 Under Demolition: The building is in the process of being torn down.
 - 6 Under Construction: The building is under construction and does not have any occupants.
 - 7 Under Construction: The building is partially occupied, whether under a temporary certificate of occupancy or not.
- Note: The status code applies to the building, not the fire area. Therefore, codes 1, 2 and 3 may be used whether the fire itself occurred in a vacant or occupied area, and code 1 may apply even if the fire occurred in a vacant area (for example, a fire in a vacant apartment being repaired for a new tenant). The occupied or vacant status of the fire area is now recorded on the "Area of Origin" Code. (See Paragraph 2.19.2.)

4

14.21 COMPLEX

11. **PUBLIC RECREATION COMPLEX**
Included are zoos, amusement parks and general recreation parks.
12. **STADIUM, EXHIBITION HALL COMPLEX**
Included ballparks, racetracks, sports gardens and arenas.
14. **CLUB COMPLEX**
Included are golf clubs, tennis clubs and country clubs.
20. **EDUCATIONAL COMPLEX**
Included are schools, colleges and universities.
33. **MEDICAL CARE COMPLEX**
Included are Hospitals, Medical Centers, Mental Institutions.
34. **PRISON COMPLEX**
40. **BUSINESS WITH RESIDENTIAL COMPLEX**
Included are apartments over stores.
41. **DWELLING COMPLEX (ONE AND TWO FAMILY)**
42. **APARTMENT COMPLEX**
44. **HOTEL COMPLEX**
Included are motels, inns and lodges.
47. **MOBILE HOME PARK COMPLEX**
53. **SHOPPING COMPLEX**
Included are department stores, malls, discount houses and shopping centers. Also included are groups of business and commercial establishments which may contain theaters and other places of assembly.
59. **OFFICE COMPLEX**
Included are non-military government office complexes.
61. **POWER PRODUCTION COMPLEX**
63. **MILITARY RESERVATION DEFENSE COMPANY**
65. **FARM COMPLEX**
70. **INDUSTRIAL PLANT, MANUFACTURING COMPLEX**
80. **WAREHOUSE, STORAGE COMPLEX**
91. **CONSTRUCTION COMPLEX**
Included are demolition operations.
93. **CAMPSITE COMPLEX**
94. **WATERFRONT COMPLEX**
Included are marinas.
95. **RAILROAD TRANSPORT COMPLEX**
96. **ROAD COMPLEX**
Included are highways, streets and all public ways.
97. **AIRPORT COMPLEX**
98. **NO COMPLEX**
If other properties meeting the definition for a complex as defined above are identified, they may be indicated by Complex Code 99.

AREA FIRE ORIGIN**14.22 FLOOR CODE NO.****00 OUTSIDE BUILDING**

- 01 1st Floor
- 10 to
- 94 94th and Higher
- 85 Attic
- 96 Roof
- 97 Basement
- 98 Cellar
- 99 Sub-Cellar

14.23 AREA FIRE ORIGIN—**OCCUPANCY CLASSIFICATION****00 NOT IN BUILDING****COMMERCIAL**

- Factory:
- 99 Chemicals
- 01 Dresses
- 02 Undergarment
- 03 Other (state type)
- 04 Dry Cleaning Laundry
- 05 Electrical Products
- 06 Food and Drink Products

- 07 Furniture
- 08 Furs, Fur Goods
- 09 Mens Hats
- 10 Womens Hats
- 11 Leather, Leather Products
- 12 Machine Shop Metal Works
- 13 Paints
- 14 Paper Products
- 15 Petroleum Products
- 16 Plastics, Rubber
- 17 Printing and Allied Industries
- 18 Shoes
- 19 Textiles
- 20 Toy or Doll
- 21 Woodworking
- 22 Other Features not classified (state type)

Store:

- 23 Auto Accessories
- 24 Bakery
- 25 Butcher
- 26 Candy, Confectionery
- 27 Clothing
- 28 Department, large
- 29 Department, small (5 & 10)
- 30 Dry Cleaner & Tailor
- 31 Drug
- 32 Electrical Appliance
- 33 Fruits and Vegetables
- 34 Furniture
- 35 Groceries, Dairy, Delicatessen
- 36 Haberdashery
- 37 Ladies Accessories
- 38 Laundry
- 39 Paint, Hardware
- 40 Restaurant Luncheonette
- 41 Shoe
- 42 Shoe Repair
- 43 Supermarket
- 44 Tavern
- 45 Other Stores not classified (state type)

Garage:

- 46 Non storage
- 47 Storage
- 48 Oil Filling Station
- 49 Motor Vehicle Repair Shop
- 50 Office Building

Warehouse:

- 51 Film
- 52 Paper, Bags, Fibre
- 53 Other (state type)
- 54 Freight Depot
- 55 Pier
- 56 Shipyard
- 57 Lumber yard
- 58 Shed, Newstand, Shanty, etc.
- 59 Other Commercial Building Occupancies, not classified (state type)

Residential:

- 60 Apartment, Hotel, Multiple Dwelling "A"
- 61 Apartment House, Multiple Dwelling "A"
- 62 Boarding House, Rooming House, Multiple Dwelling "B"
- 63 Hotel, Multiple Dwelling "B"
- 64 Lodging House, Multiple Dwelling "B"
- 65 Private Dwelling
- 66 Rectory, Convent, Monastery, etc.
- 67 Tenement House, New Law, Multiple Dwelling "A"
- 68 Tenement House, Old Law, Multiple Dwelling "A"
- 69 Other Residential, not classified (state type)

Public:

- 70 Airport
- 71 Cabaret, Banquet Hall
- 72 Church
- 73 Dance Hall
- 74 Hospital
- 75 Motion Picture Theatre
- 76 N.Y. Transit System Station
- 77 Passenger Depot
- 78 School
- 79 Theatre
- 80 TV Studio
- 81 Other Public, not classified (state type)

14.24 AREA OF FIRE ORIGIN**A. MEANS OF EGRESS**

- 01 Hallway, corridor, mall.
- 02 Exterior stairway.
- 03 Interior stairway.
- 04 Escalator.
- 05 Lobby, entrance way.
- 06 Not classified above.

1. ASSEMBLY AREA

- 11 Fixed seats (100 or more persons).
- 12 Without fixed seats (100 or more persons).
- 13 With or without fixed seats. (less than 100 persons)
- 14 Living room, family room, lounge area.
- 15 Sales, showroom area.
- 16 Library, art galleries, exhibit
- 17 Swimming pool area.
- 18 Not classified above.

2. FUNCTION AREAS

- 21 Bedrooms, patient rooms, cells, lockups.
- 22 Wards, dormitories, barracks.
- 23 Dining area, luncheon, cafeteria.
- 24 Kitchen, cooking area, cloakroom.
- 25 Laundry area.
- 26 Health clubs, massage parlors, barber, beauty.

3. FUN AREAS (continued)

- 31 Laboratory.
- 32 Printing or photographic room.
- 33 First aid, treatment room
- 34 Operating room.
- 35 Electronic, computer, telephone room, telephone booth.
- 36 Performance, stage area, indoor sports.
- 37 Projection room, stage light.
- 38 Process, manufacturing area.
- 39 Not classified above.

4. STORAGE AREAS

- 41 Tank, bin, product storage room.
- 42 Closet.
- 43 Supply room.
- 44 Records storage room, vault.
- 45 Shipping, receiving, loading mail room.
- 46 Trash or rubbish container, compactor.
- 47 Garage, carport, vehicle storage.
- 48 Not classified above.

5. SERVICE FACILITIES

- 51 Elevator, dumbwaiter.
- 52 Electrical, plumbing, ventilation shaft
- 53 Light shaft.
- 54 Laundry or mail chute.
- 55 Duct.
- 56 Display window.
- 57 Chimney, flue, stovepipe.
- 58 Conveyor.
- 59 Not classified above.

6. SERVICE, EQUIPMENT AREA

- 61 Machinery room.
- 62 Heating equipment, water heater area.
- 63 Switchgear area, transformer vault.
- 64 Incinerator room area.
- 65 Maintenance shop, workshop, paint shop, welding shop.
- 66 Test cell.
- 67 Enclosure with pressurized air.
- 68 Enclosure with enriched oxygen atmosphere.
- 69 Not classified above.

7. STRUCTURAL AREAS, NON-FUNCTIONAL

- 71 Crawlspace, cellar, substructural area.
- 72 Exterior balcony, open porch.
- 73 Floor and ceiling assembly concealed floor/ceiling space.
- 74 Roof and ceiling assembly, concealed roof/ceiling space.
- 75 Wall assembly, concealed wall space.
- 76 Exterior wall surface.
- 77 Exterior roof surface.
- 78 Awning, overhang.
- 79 Not classified above.

8. TRANSPORTATION, VEHICLE AREAS

- 81. Passenger area.
- 82. Trunk, load carrying area.
- 83. Engine, running gear, wheel area.
- 84. Fuel tank, fuel line.
- 85. Operating, control area, cab, cockpit.
- 86. Exterior exposed surface.
- 89. Not classified above.

9. OTHER AREAS OF ORIGIN

- 91. On or near railroad right of way, embankment.
- 92. On or near highway, public way, street.
- 93. Terrace, patio, courtyard.
- 94. Lawn, field, open area, vacant lot.
- 95. Wildland area, woods.
- 97. Multiple location.
- 98. Vacant room, apartment or area.
- 99. Not classified above.

14.25 MANNER OF EXTENSION**Code No.**

- 00 Confined to area of origin.
- 01 Cockloft.
- 02 Door or opening between rooms.
- 03 Floor.
- 04 Hall, Stairway.
- 05 Partition.
- 06 Pipe Recess.
- 07 Shaft-dumbwaiter.
- 08 Shaft-Elevator.
- 09 Shaft-air, Light, Chute, Duct, etc.
- 10 Ceiling.
- 11 Window.
- 12 Other (state type).

14.26 NUMBER OF OCCUPANCIES**Codes Description**

- 01 1 occupancy
- 02 2 occupancies
- •
- •
- 99 99 or more occupancies

14.27 BUILDINGS**Code: 0 to 9**

- 0— did not spread beyond building of origin
- 1—1 structure or vehicles
- •
- •

- 9—9 or more buildings or vehicles

NOTE: Form BF-24A must be submitted for each building or vehicle listed in this coded space.

14.28 DAMAGE CODES**14.28.1 Percentage Codes**

- 0 No appreciable damage
- 1 From 1 through 15%
- 2 From 16 through 49%
- 3 50% or greater

14.28.2 Extent of Damage Codes: To be used in the Damage Category Boxes "Flame, Smoke and Water".

- 1. Confined to object or origin.
- 2. Confined to part of room or area of origin.
- 3. Confined to room of origin.
- 4. Confined to fire-rated compartment of origin.
- 5. Confined to floor of origin.
- 6. Confined to structure of origin.
- 7. Extended beyond the structure of origin.
- 9. No damage of this type.

14.29 SMOKE AND HEAT DETECTOR CODES

- 14.29.1 Present
 - 1 Present
 - 0 Not Present

14.29.2 Type

- 1. Smoke
- 2. Heat

14.29.3 Power Source

- 1. Battery
- 2. A/C

14.29.4 Performance

- 1. In room of fire; operated
- 2. Not in room of fire; operated
- 3. In room of fire; did not operate
- 4. Not in room of fire; did not operate
- 5. In room; fire too small to operate
- 6. Did not operate; power source removed
- 9. Not classified

14.30 POWER FOR EQUIPMENT

- 01 1-23 volts A.C.
- 02 24 volts A.C.
- 11 1-6 volts D.C.
- 12 7-12 volts D.C.
- 15 115 volts A.C.
- 28 208 volts A.C.
- 30 220-230 volts A.C.
- 33 231-330 volts A.C.
- 34 331 or higher volts A.C.
- 50 25-50 volts A.C.
- 61 Butane
- 62 Coal, Coke, Charcoal, Peat
- 63 Fuel Oil, No. 1 or No. 2
- 64 Fuel Oil, No. 3 or No. 4
- 65 Fuel Oil, No. 5 or No. 6
- 66 Gasoline
- 67 Kerosene
- 68 LN gas (stored as liquid)
- 69 LP gas (stored as liquid)
- 70 Natural or illuminating gas (as a gas)
- 71 Paper
- 72 Propane
- 99 Other

14.31 CODE FOR TYPE OF ACTION TAKEN

- 1. Extinguishment
- 2. Rescue
- 3. Investigation
- 4. Remove Hazard
- 5. Standby
- 6. Salvage
- 7. First Aid
- 9. Cancelled Enroute

14.32 CLASSIFICATION BY TYPE FIRE OR EMERGENCY**TRANSPORTATION****Code No.**

- 87 Ship, Vessel
- 88 Motor Vehicle
- 89 Other Transportation (state type)

NON-STRUCTURAL FIRES**Code No.**

- 84 Explosion, no after fire
- 85 Outside Spill/Leak with Fire
- 86 ADV (Abandoned/Derelict Motor Vehicle)
- 90 Bonfire
- 91 Brush, Grass
- 92 Demolition Wood, Building Site
- 93 Dump, Land Fill
- 94 Rubbish—Outside Building
- 95 Manhole
- 96 N.Y. Transit System—Yard, Roadway, Ties, etc.
- 97 Railroad Yard, Roadway, Ties, etc.
- 98 Tunnel, Bridge
- 99 Other Non-Structural, not classified (state type)

EMERGENCY**Code No.**

- 03 Elevator, Escalator
- 04 Explosives Escort
- 05 First Aid—Assist Person(s)

- 06 First Aid—Resuscitation
- 07 Marine
- 08 Precarious Condition—Signs, Trees, etc.
- 09 Subway, Railroad
- 10 Water Leak
- 11 Bomb—Unexploded, Scare
- 12 Collapse—Cave In
- 13 Collision—Vehicular Incident
- 14 Controlled Fire, Permitted
- 15 Flood Condition—Broken Water Main
- 16 Incinerator
- 17 Leak—Fuel Oil, Gasoline, etc.
- 18 Leak—Illuminating Gas, Flammable Vapor
- 19 Lightning
- 20 Oil Burner
- 21 Person Locked In, Locked Out
- 22 Power Electrical
- 23 Pressure Rupture
- 24 Refrigerant Leak
- 25 Smoke Condition, Odor, Fumes
- 26 Sprinkler—Leak, Water Discharge, Damaged Head, etc.
- 27 Steam Discharge
- 28 Defective Alarm Device (other than Sprinkler)
- 29 Smoke Detector
- 30 Defective Alarm (Sprinkler)—Surge, Work on System, etc.
- 31 Other

14.33 MOBILE PROPERTY TYPE CODES

- 11 Automobile
- 12 Bus
- 13 Motorcycle, Snowmobile
- 14 Motorhome
- 15 Travel Trailer
- 17 Mobile Home
- 20 Freight, Road Transport
- 30 Rail Transport
- 40 Water Transport
- 50 Air Transport
- 60 Heavy Equipment
- 70 Special Vehicles, Containers
- 99 Other Mobile Property Types

Attachment G-A.4

Significant fire incidents occurring in WTC 1 (12)

Significant Fire	Incident Date	Fire Location	# Sprinklers Activated	# Standpipes Activated	Cause of Fire	Material Ignited
1	9/9/77	B-6 level storage room	2		None listed	Not listed
2	9/23/77	Dumpster on B-4 level	2		Not classified	Trash/waste
3	10/16/81	19th floor office area	-	2	Discarded material	Furniture
4	12/23/83	2 dumpsters on B-4 level	2	1	Suspicious	Trash/waste
5	1/27/85	Office space on mezzanine level (Floor 2)	2		Incendiary	Trash/waste
6	9/10/85	Garbage dumpster in service elevator lobby on floor 43	2	1	Suspicious	Trash/waste
7	11/1/85	Storage closet on B-4 level	3	1	Suspicious	Supplies/stock
8	6/7/86	Dumpster fire on floor 106, compactor room on floor 107	2	1	None listed	Trash/waste
9	9/30/91	Office on B-4 level	≥1	2	Discarded material	Trash/waste
10	11/19/91	Electrical closet on floor 93	0	2	Short circuit	Electrical wire or cable insulation
11	7/23/92	Level B-5 at the power distribution panel	0	2	Electrical failure	Electrical wire or cable insulation
12	11/10/99	Computer room on floor 104	3	≥1	None listed	Plastics, electronic equip

KEFUKI - SIKULUKAL FIRE

FOR FIRE RECORDS USE ONLY			TYPE REPORT		DATE AND TIME ALARM RECEIVED						DURATION OF INCIDENT		LOCATION				REPORT			
					MONTH	DAY	YEAR	CD. NO.	HOUR	MINUTE	HOURS	MINUTES	LOW REPEATED INITIAL ALARM	HIGHEST ALARM BROUGHT	ALARM	INCIDENT				
			1	09	09	77	1	2304	01	00	4	1	0	1	0070	5006	0113	0063	01	321

AIDED AND CASUALTIES						RESP.	EXTINGUISH- MENT	INVESTIGATION	STRUCTURE	AREA FIRE ORIGIN												
CIVILIANS																						
EVAQUATED	FIRST AID	INJURED	DIED	UNINFORMED INJURED	ENIG TO MARINE	ADDRESS CODE	NO OF UNIT FOR LOSS	TRANSIT NUMBER	LOSS EXTERIOR	CAUSE	FIRE MATERIAL	CONSTRUCT	USE	STATUS TO BE RECOVERED	REASON FOR COLLAPSE	FLOOR CODE	POOR OF AREA CODE	ORDNANCE	PANTRY PATTERNS			
00	00	00	00	00	03	2	0	02	00	0				1	15	1	0	1	99	54	50	00

ADDRESS	1	World Trade Center	Man.
	NUMBER	STREET	BOROUGH
BUILDING	110	200x200	
(Second Count)	STORIES		AREA

NAME OF OCCUPANT	ROOM/APT NO
Sgt. Daniels P.A. Police	
LEFT IN CHARGE	

10	10 12	21 12	31 12	41 12	51 12	61 12	71 12	81 12	91 12	101 12	111 12	121 12	131 12	141 12	151 12	161 12	171 12	181 12	191 12	201 12	211 12	221 12	231 12	241 12	251 12	261 12	271 12	281 12	291 12	301 12	311 12	321 12	331 12	341 12	351 12	361 12	371 12	381 12	391 12	401 12	411 12	421 12	431 12	441 12	451 12	461 12	471 12	481 12	491 12	501 12	511 12	521 12	531 12	541 12	551 12	561 12	571 12	581 12	591 12	601 12	611 12	621 12	631 12	641 12	651 12	661 12	671 12	681 12	691 12	701 12	711 12	721 12	731 12	741 12	751 12	761 12	771 12	781 12	791 12	801 12	811 12	821 12	831 12	841 12	851 12	861 12	871 12	881 12	891 12	901 12	911 12	921 12	931 12	941 12	951 12	961 12	971 12	981 12	991 12	1001 12	1011 12	1021 12	1031 12	1041 12	1051 12	1061 12	1071 12	1081 12	1091 12	1101 12	1111 12	1121 12	1131 12	1141 12	1151 12	1161 12	1171 12	1181 12	1191 12	1201 12	1211 12	1221 12	1231 12	1241 12	1251 12	1261 12	1271 12	1281 12	1291 12	1301 12	1311 12	1321 12	1331 12	1341 12	1351 12	1361 12	1371 12	1381 12	1391 12	1401 12	1411 12	1421 12	1431 12	1441 12	1451 12	1461 12	1471 12	1481 12	1491 12	1501 12	1511 12	1521 12	1531 12	1541 12	1551 12	1561 12	1571 12	1581 12	1591 12	1601 12	1611 12	1621 12	1631 12	1641 12	1651 12	1661 12	1671 12	1681 12	1691 12	1701 12	1711 12	1721 12	1731 12	1741 12	1751 12	1761 12	1771 12	1781 12	1791 12	1801 12	1811 12	1821 12	1831 12	1841 12	1851 12	1861 12	1871 12	1881 12	1891 12	1901 12	1911 12	1921 12	1931 12	1941 12	1951 12	1961 12	1971 12	1981 12	1991 12	2001 12	2011 12	2021 12	2031 12	2041 12	2051 12	2061 12	2071 12	2081 12	2091 12	2101 12	2111 12	2121 12	2131 12	2141 12	2151 12	2161 12	2171 12	2181 12	2191 12	2201 12	2211 12	2221 12	2231 12	2241 12	2251 12	2261 12	2271 12	2281 12	2291 12	2301 12	2311 12	2321 12	2331 12	2341 12	2351 12	2361 12	2371 12	2381 12	2391 12	2401 12	2411 12	2421 12	2431 12	2441 12	2451 12	2461 12	2471 12	2481 12	2491 12	2501 12	2511 12	2521 12	2531 12	2541 12	2551 12	2561 12	2571 12	2581 12	2591 12	2601 12	2611 12	2621 12	2631 12	2641 12	2651 12	2661 12	2671 12	2681 12	2691 12	2701 12	2711 12	2721 12	2731 12	2741 12	2751 12	2761 12	2771 12	2781 12	2791 12	2801 12	2811 12	2821 12	2831 12	2841 12	2851 12	2861 12	2871 12	2881 12	2891 12	2901 12	2911 12	2921 12	2931 12	2941 12	2951 12	2961 12	2971 12	2981 12	2991 12	3001 12	3011 12	3021 12	3031 12	3041 12	3051 12	3061 12	3071 12	3081 12	3091 12	3101 12	3111 12	3121 12	3131 12	3141 12	3151 12	3161 12	3171 12	3181 12	3191 12	3201 12	3211 12	3221 12
----	-------	-------	-------	-------	-------	-------	-------	-------	-------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------

OPERATIONS

Upon arrival at command post was told of fire in B 6 level storage room, operations as follows.

Ladder 1 made necessary investigation, located fire, vented, overhauled.

Ladder 3 checked for extension, vented overhauled.

Engine 6 stretched line from standpipe and stood fast.

Fire was extinguished by sprinkler system before arrival.

HN. 4 supervised operations on fire floor.

Fire Patrol 2 on the scene.

SC 1-14-68 1 D.C. 1 PAGE 1 OF 1
Rudy E. DiGeorgio 2306
 TIME OF ARRIVAL _____ TYPE FULL NAME _____ TIME OF ARRIVAL _____

FOR THE RECORDS USE ONLY		DATE AND TIME ALARM RECEIVED				DURATION OF INCIDENT		ALARM		LOCATION		REPORT	
TYPE	REPORT	MONTH	DAY	YEAR	CO. NO.	HOUR	MINUTE	HOURS	MINUTES	INITIAL ALARM	HIGHEST ALARM	BOROUGH	ALARM
1	09:23	77	1	2243	00	25	4	1	0	1	0070	5	006

AIDED AND CASUALTIES				EXTINGUISHMENT		INVESTIGATION		STRUCTURE		AREA FIRE ORIGIN	
CIVILIANS				RESP.		CAUSE		USE		FLOOR OR AREA CODE	
EVAQUATED	FIRST AID	INJURED	KILLED	UNIFORMED	INJURED	CAUSE	CAUSE	STATUS	STATUS	FLOOR OR AREA CODE	FLOOR OR AREA CODE
00	00	00	00	03	2	0	02	00	1	15	1

ADDRESS 1 World Trade Ctr. Man
 NUMBER STREET BOROUGH
 BUILDING 110 250 x250
 STORIES AREA
 (Second Card)
 NAME OF OCCUPANT PONYA B-4 (Lor)
 LEFT IN CHARGE Pal Lorensa(PONYA)

TYPE	NO.	SECT.	PTS.	TYPE	NO.	SECT.	PTS.	TYPE	NO.	SECT.	PTS.	TYPE	NO.	SECT.	PTS.
3	006	0	05	7	001	0	05								

OPERATIONS

Responded to 3-70-10(Mannual Alarm)

Upon arrival was informed of fire in Dumpster B-4 level 1 WTC. Ordered investigation and found fire therein, which had been extinguished prior to the arrival of this dept. Operations as follows:

E.6- Rolled up lengths stood fast.

L.1- Search. examination, ventilation of B-4 level, conditions as stated.

Michael R. Porgio 1 DC
 DIV. PAGE
Michael R. Porgio 2251
 TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

REPORT - STRUCTURAL FIRE

[illegible]

Responded to alarm box 8084. Upon arrival were informed by Port Authority personnel of a fire in the above location. Initial reports also indicated that the fire had penetrated the skin of the bldg. Signal 10-75 was transmitted. Port Authority personnel stretched initial hand line into fire location.

Eng. 10- Stretched standpipe line, extinguished main body of fire, washed down.

Eng. 6- Took handline from P.A. personnel, assisted in extinguishment.

Eng. 7- Relieved Eng. 10 on line, supplied standpipe.

Lad. 1- To fire floor, performed primary and secondary searches, vented, overhauled

Lad. 8- To 20th floor, performed primary and secondary searches on that and upper floors.

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		IGNITION				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION							
MONTH	DAY	YEAR	HOUR	MINUTE	BOROUGH	BOX NO.	BUILDING NO.	TERM STAGE	EQUIP INVOLVED	MAT FORM	MATERIAL TYPE	MATERIAL FORM	LOSS TYPE	USE	STATUS	RIGID DAMAGE	CONT'S DAMAGE	FLOOR CODE	RM/AREA CODE	OCCUPANCY	HANDLED BY	OCCUPANTS	
6	10	16	81	19	12	1	8084	00															
NUMBER (INCL. HYPER)		STREET NAME		TYPE		IF MOBILE PROPERTY																	
1		World Trade Center		1																			
YR		MAKE		MODEL		73 SERIAL NO		LICENSE		STATE													
1		1001		10																			
UNIT		PTS		195		201		207		213		219		225		231		236					

OPERATIONS

Lad.8 (cont.)- Forced door to Office room#2073

Res.1- Checked vent ducts and stairways on and above fire floor, secured passenger elevators serving fire floor.

Patrol#1- On scene, salvage work on 16th and 17th floors.

Patrol#2- On scene, salvage work on 18th floor.

Div.1- D.C. Rossi on scene, in charge of Department operations upon arrival.

B.C.	1	D.C.	1	PAGE
James J. McKenna	BN	John D. Rossi	DIV.	202
TYPE FULL NAME	TIME OF ARRIVAL	TYPE FULL NAME	TIME OF ARRIVAL	

REPORT - STRUCTURAL FIRE

BF-24 (1-80)-175M-008531 (B3)

INCIDENT LOCATION		DATE AND TIME		ALARM RECEIVED		DURATION		INCIDENT		BOX LOCATION		REPORT		COS. RESP.		
COMMUNITY	ADDRESS	MONTH	DAY	YEAR	HOUR	MINUTE	SECONDS	MINUTES	HOURS	MINUTES	BOX NUMBER	REPORT NUMBER	ENGINE NUMBER	ENGINE NUMBER	ENGINE NUMBER	
1	015 010	12	23	83	00	25	00	2	1	0	1	18093	0228	01	075	03

AIDED AND CASUALTIES		EXTINGUISHMENT		IGNITION		STRUCTURE		AREA		FIRE ORIGIN		FIRE EXTENSION		SPECIAL USE		
EVALUATED	FIRST AID	INJURED	KILLED	UNFURNISHED	COOL	SPRINKLER	STAMPED	TEAM STAGE	EQUIP INVOLVED	MATERIAL TYPE	CONSTRUCT	STATUS	BLDG DAMAGE	FLOOR CODE	MANNER OF	
00	00	00	00	2	02	01	3	98	40	99	75	21	1	15	1	1

NAME OF OCCUPANT		STREET NAME		TYPE		BUILDING		AREA	
NUMBER	UNIT	STREET NAME	TYPE	BUILDING	AREA	LEFT IN CHARGE	POWER	MODEL	SM
1	00	World Trade Center	1	130	200 X200	P.A. Police			

EQUIPMENT INVOLVED IN IGNITION		ROOM, APT. NO		YR		MAKE		MODEL		POWER	
UNIT	PTS	ITEM	ROOM	APT. NO	YR	MAKE	MODEL	POWER	SM	MODEL	POWER
5	010	10	7	001	10						

OPERATIONS

Responded to report of fire in B-4 Level, and heavy smoke condition. Found two dumpsters fully involved in separate locations on same floor. Sprinklers extinguished major portion of fire. Signal 10-43 code 1.

Engine Co. 10 - Stretched from standpipe, and extinguished remaining fire.

Ladder Co. 1 - Overhauled, checked for extension and vented.

BF-24 (11/80)

TYPE REPORT				DATE AND TIME				INCIDENT				REPORT				COS. RESP.											
COMMUNITY				ALARM RECEIVED				QUARTER				ALARM				LOCATION				BOX							
ADJ. NO.				HOUR				MINUTE				MONTH				YEAR				DAY				TIME			
ADJ. NO.				HOUR				MINUTE				MONTH				YEAR				DAY				TIME			
1	01	5	010	0137	01-27-85	2053	01:00	21	11	1	8084	0293	01	113	022												

AIDED AND CASUALTIES				EXTINGUISH				IGNITION				STRUCTURE				AREA FIRE ORIGIN				FIRE EXTENSION				SPECIAL USE			
CIVILIANS				MEAT				MATERIAL				MATERIAL				MATERIAL				MATERIAL				MATERIAL			
KILLED				WOUND				KILLED				WOUND				KILLED				WOUND				KILLED			
FIRST AID				WOUND				KILLED				WOUND				KILLED				WOUND				KILLED			
00	00	00	00	2	01	00	3	96	60	75	11	1	15	1	1	02	59	59	00	00	00	00					

STREET NAME				TYPE				BUILDING				AREA			
WORLD TRADE CENTER				1				110				200x200			
1															

NAME OF OCCUPANT				ROOM, APT. NO.				MODEL				POWER			
NEW YORK PORT AUTHORITY NY, NJ				130				110				200x200			
Sgt. Doubraski, PA Police				LEFT IN CHARGE											

On arrival, found two sprinkler heads containing fire in unoccupied office occupancy on mezzanine level. Units assigned as follows:

Eng. 6: Stretched line, stood fast.

Eng. 6: Stretched line, stood fast.
Lad. 1: Located fire, searched, extinguished remaining fire. Shut down sprinkler system.
Lad. 10: Checked for extension.

10-41 signal (code 1) transmitted.

John J. Spillane

abc _____ 1 BN DC _____ DIV. _____ PAGE 0F 0

John J. Spillane

2055 _____ TYPE FULL NAME _____ TIME OF ARRIVAL _____
TIME OF DEPARTURE _____

AUG 28 2003
JRE

8160198

INCIDENT LOCATION			DATE AND TIME			ALARM RECEIVED			INCIDENT			BOX LOCATION			REPORT			COS. RESP.		
COMMUNITY BOARD	ADMIN COMPANY	INCIDENT LOCATION	MONTH	DAY	YEAR	HOUR	MINUTE	MINUTES	HOW REPORTED	INITIAL ALARM	BOROUGH	BOX NUMBER	REPORT NUMBER	BATTALION	ENGINE	MAINE	ADDER	REPORT		
1	01	5010	09	10	85	16	05	01	40	4	1	2	1	8084	0119	01	578	7	6	

AIDED AND CASUALTIES			EXTINGUISHMENT			IGNITION			STRUCTURE			AREA FIRE ORIGIN			FIRE EXTENSION			SPECIAL USE									
EVACUATED	FIRST AID	INJURED	DEATH	UNINJURED	CODE	SPRINKLER	NO OPEN	STAMPED	TEAM STAGE	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	FACTORY	CONSTRUCT	USE	STATUS	BUILD DAMAGE	FLOOR CODE	RAMPAGE CODE	OCCUPANCY	MANNER OF	OCCUPANTS	WITHIN BLDG	NO BLDG	SMOKE DETECTORS	SPECIAL USE	
00	00	00	00	00	5	2	1	3	89	00	60	75	21	1	15	0	0	43	35	81	00	01	1	2			

STREET NAME			TYPE			BUILDING			AREA		
NUMBER	STREET NAME	TYPE	YR	MAKE	MODEL	POWER	YR	MAKE	MODEL	POWER	
1	World Trade Center	1	126	43	FL	99	200	x	200		

NAME OF OCCUPANT: Port Authority NY NJ

EQUIPMENT INVOLVED IN IGNITION: 43 FL

ROOM, APT NO: 99

LEFT IN CHARGE: Sgt. Ebin, PA Police Dept.

UNIT	PTS.	ITEM
5	010	10
5	006	02
7	010	10
7	008	03
7	001	10

OPERATIONS

Upon arrival at the Command Ctr of the World Trade Center, Batt. 1 was informed by the PA Police that, according to their reports, there was a sprinkler flow and smoke condition on the 43 floor. When Ladder 10 (1st due) reported a medium smoke condition on the 43 floor, Batt. 1 transmitted signal 10-76. The fire was located in a garbage dumpster in a service elevator lobby on the 43 F and was extinguished by 2 sprinkler heads with no extension.

Engine 10- Took rolled-ups to 42 floor. Stretched a 2 1/2 line from the standpipe in B stairwell to fire location. Line used for overhauling. Chauffeur manned the Standpipe phone at the CP and assisted in communications.

B.C. Kenneth T. McGowan 1 D.C. John Hodgkins 1

Kenneth T. McGowan 1611 John Hodgkins

TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL

PAGE 1 OF 2

FIRE RECORDS

TYPE REPORT				DATE AND TIME ALARM RECEIVED				BOX LOCATION		IGNITION				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION																	
MONTH	DAY	YEAR	MINUTE	BOROUGH	BOX NO.	BUILDING NO.	TEAM STAGE	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	CONSTRUCT	USE	STATUS	BLDG DAMAGE	CONT'S DMRG	FLOOR CODE	MAN/AREA CODE	OCCUPANCY	MANNER OF OCCUPANCY															
6	09	10	85	1605	1	8084																													
1				NUMBER (INCL. HYPER)				STREET NAME				TYPE				8160199				IF MOBILE PROPERTY															
1				World Trade Center																															
YR				MAKE				MODEL				73 SERIAL NO				LICENSE				STATE															
5				007 02																															
UNIT				PTS				201				207				213				219				225				231				236			

OPERATIONS

Engine 6- (teamed with E.10) Assisted E. 10 in Standpipe stretch.

Engine 7- Manned the Standpipe phone in Stairway B on 1st Fl., relayed messages to and from Command Center

Ladder 10- To 43 fl, stairway B, found fire, searched 43 fl (negative) made necessary examination and overhaul of fire area.

Ladder 1-to 44 fl, searched for fire, smoke extension, searched for troubled occupants (negative) Checked top ten fls (101-110) for smoke (Neg.)

Ladder 8- Made secondary search of 43 fl (negative). Searched fls 44 to 49. Searched affected service elevator cars #17 & 29.

Batt. 4- Set up operations post on 43 fl. Communicated with Command Center, supervised operations of units on 43 and 44 fls.

E.4, E.3 (HiRise Unit), L.15 & Res. Co 1 stood fast, took up.

Brooklyn Cos responding on supplemental Boxes 9031 & 9032 at 1617 hrs Batt 31, Batt 32, E. 205, E. 279, L.101, L.110 stood fast, took up.

F.C.U. - Established Field Hqtrs, Monitored Communications.

Sprinkler heads (2) replaced by P.A. personnel.

Signal 10-41, Code 1 transmitted, Evidence of separate, previous fire reported to FM McCaffrey.

Responded to Scene: AC Matthew Farrell, Manhattan Borough Commander

Signal	Time	By
10-84	1609	E.10
10-76	1615	Batt 1
P.W.H.	1627	Div 1
U.C.	1640	Div 1

P.C.	Signature	BN	O.C.	Signature	DIV.	PAGE
	Kenneth T. McGowan	1611		John Hodgens		2 OF 2
	TYPE FULL NAME	TIME OF ARRIVAL		TYPE FULL NAME	TIME OF ARRIVAL	

FIRE RECORDS

OPERATIONS

B.C. Joseph L. Barracato IN. DC 0408 0408
 () Joseph L. Barracato TIME OF ARRIVAL TIME OF ARRIVAL
 TYPE FULL NAME TYPE FULL NAME

REPORT - ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT			DATE AND TIME ALARM RECEIVED				BOX LOCATION		IGNITION				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION				
MONTH	DAY	YEAR	HOUR	MINUTE	SECOND	BOX NO.	BUILDING NO.	TERMINAL	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	USE	STATUS	DAMAGE	CONUS ONCE	FLOOR CODE	RM AREA CODE	OCCUPANCY	MANNER OF	OCCUPANCIES
6	11	01	85	04	05	1	8093														

NUMBER (INCL. HYPERM)	SWITCH	SWITCH (INCL.)	STREET NAME	TYPE	SWITCH (INCL.)
182			WTC		

IF MOBILE PROPERTY

VR	MAKE	MODEL	79 SERIAL NO	LICENSE	STATE

UNIT	PTS	195	201	207	213	219	225	231	236
189									

OPERATIONS

- E-10 stretched line into fire area from standpipe and extinguished all remaining in closet area
- E-7 stretched line from opposite side of fire and stood fast
- E-6 assisted E10 in stretching line and relieved on line and then washdown
- L-10 found fire and performed necessary VES and overhaul in area, made primary and secondary search, then up
- L-1 performed necessary VES and checked for possible extension in surrounding areas

Times: 10-84 0408
 10-75 0410
 All Hands 0425
 10-41-1 0425

B.C. Joseph L. barracato D.C. 0408 DIV. 2 PAGE 2 OF 2

Joseph L. barracato 0408
 TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

REPORT – STRUCTURAL FIRE

BF-24 (1/80) 175M 608551 (BJ)[illegible]

Received 1115 alarm for a heavy smoke condition on the 110th floor. While responding received 2nd. source and the box was filled out. Upon arrival found fire in garbage dumpster on the 106th floor. Sprinklers in operation and a heavy smoke condition on 106-110th floors. - Units operated V12: Transmitted 10/76.

[illegible]

REPORT — ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		IGNITION				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION					
MONTH	DAY	YEAR	HOUR	MINUTE	BOROUGH	BOX NO.	BUILDING NO.	TERM. STAGE	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	USE	STATUS	ROOM DAMAGE	FLOOR CODE	RM AREA CODE	OCCUPANCY	OCCUPANCIES		
6	06	07-86	09	49	1	8084	0	3	00	00	99	75	1	15	1	1	94	57	40	00	99

NUMBER (INCL. HYPHEN)	STREET NAME	TYPE	IF MOBILE PROPERTY
1	WTC		

MAKE	MODEL	SERIAL NO.	LICENSE	STATE

UNIT	PTS.	195	201	207	213	219	225	231	236
1	001	05	5	003	02				

- 2.7- Upon arrival reported to **OPERATIONS** 106th floor and stretched from standpipe to fire and extinguished same. Fire in dumpster assisted 1.10 in making search of area. Negative
- 1.6 Reported to 106th floor. Ordered to stand fast. Then up.
- 1.10 Reported to 106th floor. Ordered to stand fast. Then up.
- 1.10 Reported to 107th floor. Found fire in compactor room. Sprinkler in operation. Forced entry to sprinkler shut-off room. Shut same. Made necessary search and examination. Then up.
- 1.1 Reported to 107th floor. Assisted ladder 10 in search and examination. Negative search. Then up.
- R-1 searched floors above fire. Light smoke. Negative. Then up.
- 1.3/1.11-112 unit: ordered to 10-2
- Field Comm Unit: ordered to 10-2
- Batt. 4: Supervised operations on 106-110 floors. Units 1.7, 1.10, 1.1 and R-1. Then up.

B.C. _____ BN. _____ D.C. _____ DIV. _____

_____ TIME OF ARRIVAL _____ TYPE FULL NAME _____ TIME OF ARRIVAL _____

ADMINISTRATIVE COMPANY

PAGE
OF

[illegible]

[illegible]

REPORT - ADDITIONAL DATA																																																																																																																			
STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY																																																																																																																			
TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		INCIDENT NUMBER		BUILDING NO.		IGNITION		STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION		REASON FOR																																																																																															
MONTH	DAY	YEAR	HOUR	MINUTE	SECOND	BOX NUMBER	INCIDENT NUMBER	BUILDING NO.	CHIEF'S NAME	EQUIP. INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL QTY	CONSTRUCTION	USE	FLOOR NO.	OCCUPANCY	AREA CODE	MANAGER	OCCUPANCY	REASON FOR																																																																																														
6	11	1991	18	27	1	8024	056	00	3	411	22	43	61	1	59	1	9	84	52	09	04	0																																																																																													
<table border="1"> <thead> <tr> <th colspan="2">DAMAGE</th> <th colspan="2">DETECTORS</th> </tr> <tr> <th>SPR. PERFORMANCE</th> <th>IS DAMAGED</th> <th>FLAME</th> <th>SMOKE</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>1</td> <td>1</td> <td>0</td> </tr> </tbody> </table>																												DAMAGE		DETECTORS		SPR. PERFORMANCE	IS DAMAGED	FLAME	SMOKE	2	1	1	0																																																																												
DAMAGE		DETECTORS																																																																																																																	
SPR. PERFORMANCE	IS DAMAGED	FLAME	SMOKE																																																																																																																
2	1	1	0																																																																																																																
<table border="1"> <thead> <tr> <th colspan="2">STREET NAME</th> <th colspan="2">TYPE</th> </tr> </thead> <tbody> <tr> <td colspan="2">WORLD TRADE CENTER</td> <td colspan="2">TYPE</td> </tr> </tbody> </table>																												STREET NAME		TYPE		WORLD TRADE CENTER		TYPE																																																																																	
STREET NAME		TYPE																																																																																																																	
WORLD TRADE CENTER		TYPE																																																																																																																	
<table border="1"> <thead> <tr> <th colspan="2">AREA</th> <th colspan="2">WIDTH</th> <th colspan="2">LENGTH</th> </tr> </thead> <tbody> <tr> <td colspan="2">99</td> <td colspan="2">0250</td> <td colspan="2">0250</td> </tr> </tbody> </table>																												AREA		WIDTH		LENGTH		99		0250		0250																																																																													
AREA		WIDTH		LENGTH																																																																																																															
99		0250		0250																																																																																																															
<table border="1"> <thead> <tr> <th colspan="2">OCCUPANT (Driver)</th> <th colspan="2">ROOM/APT.</th> </tr> </thead> <tbody> <tr> <td colspan="2">World Trade Center</td> <td colspan="2">ROOM/APT.</td> </tr> </tbody> </table>																												OCCUPANT (Driver)		ROOM/APT.		World Trade Center		ROOM/APT.																																																																																	
OCCUPANT (Driver)		ROOM/APT.																																																																																																																	
World Trade Center		ROOM/APT.																																																																																																																	
<table border="1"> <thead> <tr> <th colspan="2">IF MOBILE PROPERTY</th> <th colspan="2">TYPE</th> <th colspan="2">YR.</th> <th colspan="2">MAKE</th> <th colspan="2">MODEL</th> <th colspan="2">VIN.</th> <th colspan="2">LICENSE</th> <th colspan="2">STATE</th> </tr> </thead> <tbody> <tr> <td colspan="2">5</td> <td colspan="2">205</td> <td colspan="2">02</td> <td colspan="2">5</td> <td colspan="2">279</td> <td colspan="2">02</td> <td colspan="2">5</td> <td colspan="2">055</td> <td colspan="2">02</td> </tr> <tr> <td colspan="2">7</td> <td colspan="2">010</td> <td colspan="2">30</td> <td colspan="2">7</td> <td colspan="2">001</td> <td colspan="2">30</td> <td colspan="2">7</td> <td colspan="2">015</td> <td colspan="2">30</td> </tr> <tr> <td colspan="2">7</td> <td colspan="2">008</td> <td colspan="2">20</td> <td colspan="2">7</td> <td colspan="2">110</td> <td colspan="2">10</td> <td colspan="2">7</td> <td colspan="2">131</td> <td colspan="2">10</td> </tr> <tr> <td colspan="2">7</td> <td colspan="2">006</td> <td colspan="2">30</td> <td colspan="2">7</td> <td colspan="2">020</td> <td colspan="2">10</td> <td colspan="2">7</td> <td colspan="2">003</td> <td colspan="2">02</td> </tr> </tbody> </table>																												IF MOBILE PROPERTY		TYPE		YR.		MAKE		MODEL		VIN.		LICENSE		STATE		5		205		02		5		279		02		5		055		02		7		010		30		7		001		30		7		015		30		7		008		20		7		110		10		7		131		10		7		006		30		7		020		10		7		003		02	
IF MOBILE PROPERTY		TYPE		YR.		MAKE		MODEL		VIN.		LICENSE		STATE																																																																																																					
5		205		02		5		279		02		5		055		02																																																																																																			
7		010		30		7		001		30		7		015		30																																																																																																			
7		008		20		7		110		10		7		131		10																																																																																																			
7		006		30		7		020		10		7		003		02																																																																																																			

OPERATIONS

STRATEGY: To attempt to contain the fire situation to electrical closets, and to prevent panic and hysteria in occupancies with large civilian populations, and establish parameters of fire and smoke condition as quickly as possible.

Action taken:

- On arrival at WTC command post, assumed command of fire situation,
- Communicated with Ladder Co. 10 who confirmed fire situation on floors 93, 94, 95 and possibly on 96,
- Ordered the transmission of signal 10-76 based on: potential for large volume of fire, height to fire area, time involved in units response, difficulty in effecting good voice communications in building,
- Ordered Manhattan Dispatcher to Alert 10-76 arriving units to assemble in Lobby Staging area, pending unit assignment,
- Ordered first alarm units to conduct diligent search.
- Ordered 1st alarm Engine companies to stretch from the "A" stairwell, but not to use water until confirmation of power off was received for electrical closets,

ONE	DIV.
Lawrence M. Byrnes	1830
TYPE FULL NAME	TIME ARRIVED

BF 244 (12/85)

REPORT - ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT				DATE AND TIME ALARM RECEIVED				BOX LOCATION		INCIDENT NUMBER		BUILDING NO.		IGNITION		STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION	
MONTH	DAY	YEAR	HOUR	MINUTE	BOROUGH	BOX NUMBER															
6	11	15	91	18	27	1	008	0562	00	3	41	25	43	61	1	591	1	93	81	52	09

NUMBER (INCL. HYPHEN)		STREET NAME		TYPE	
1	1	WORLD TRADE CENTER			

DAMAGE				DETECTORS			
NO. DAMAGED	FLAME	SMOKE	WATER	PREFAB	TYPE	POWER	PERFORMANCE
2	1	1	0	0	0	0	0

World Trade Center

AREA	
WIDTH	LENGTH
99	0250

OCCUPANT (Driver)				ROOMAPT.			

TYPE		YR.		MAKE		MODEL		V.I.N.		LICENSE		STATE	

OPERATIONS

- Confirmed with WTC personnel, engineering staff as to time frame for electrical power removal for effected floors,
- Denied WTC Police request to initiate general evacuation of floors "93 to roof level", based on unknowns of: a. smoke conditions, b. stair availability, c. numbers of people that may be involved,
- Upon notification by WTC Engineering staff of (2) elevators stuck at floor 88 and 101, Ladder Co. 6 assigned task of victim removal, as accompanied by WTC elevator mechanic,
- As Chief Officers arrived at Command Post they were issued WTC Handie Talkies and their assignments,
- Called for EMS response for reported burn victim (mechanic with facial burns and for possible needs,
- Primary search of upper floors proved to be time consuming due to large floor area and limited Handie Talkie capabilities, conducted by 1st alarm trucks,
- Rescue Company 1 assigned to follow up secondary search of floors with subsequent limited ladder operations,
- 10-76 Signal proved very effective, provided immediate response of Chief Officers to initiate various sector controls.

TYPE FULL NAME		TIME ARRIVED		TYPE FULL NAME		TIME ARRIVED	
50	Lawrence M. Byrnes	1830	85	oc.			

3

BF-24A (12/86)

REPORT - ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT				DATE AND TIME ALARM RECEIVED				BOX LOCATION		INCIDENT NUMBER		BUILDING NO.		IGNITION		STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION																																					
MONTH	DAY	YEAR	HOUR	MINUTE	BOROUGH	BOX NUMBER																																																			
6	11	1991	18	27	1	2084	0562	00	3	41	23	43	61	1	59	1	93	81	52	09	04																																				
<table border="1"> <thead> <tr> <th colspan="2">DAMAGE</th> <th colspan="2">DETECTORS</th> </tr> <tr> <th>SPK. PERFORMANCE</th> <th>% DAMAGED</th> <th>FLAME</th> <th>SMOKE</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>1</td> <td>1</td> <td>1</td> </tr> <tr> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> <tr> <td>0</td> <td>0</td> <td>0</td> <td>0</td> </tr> </tbody> </table>																						DAMAGE		DETECTORS		SPK. PERFORMANCE	% DAMAGED	FLAME	SMOKE	2	1	1	1	0	0	0	0	0	0	0	0																
DAMAGE		DETECTORS																																																							
SPK. PERFORMANCE	% DAMAGED	FLAME	SMOKE																																																						
2	1	1	1																																																						
0	0	0	0																																																						
0	0	0	0																																																						
<table border="1"> <thead> <tr> <th colspan="2">BORD.</th> <th colspan="2">NUMBER (INCL. HYPHEN)</th> <th colspan="2">SUITE</th> <th colspan="2">STREET NAME</th> <th colspan="2">TYPE</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>1</td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2">WORLD TRADE CENTER</td> <td colspan="2"></td> </tr> </tbody> </table>																						BORD.		NUMBER (INCL. HYPHEN)		SUITE		STREET NAME		TYPE		1	1					WORLD TRADE CENTER																			
BORD.		NUMBER (INCL. HYPHEN)		SUITE		STREET NAME		TYPE																																																	
1	1					WORLD TRADE CENTER																																																			
<table border="1"> <thead> <tr> <th colspan="2">B. BUILDING</th> <th colspan="2">STORIES</th> <th colspan="2">AREA</th> </tr> <tr> <th></th> <th></th> <th>WIDTH</th> <th>LENGTH</th> <th></th> <th></th> </tr> </thead> <tbody> <tr> <td>9</td> <td>9</td> <td>00</td> <td>0250</td> <td>0250</td> <td></td> </tr> </tbody> </table>																						B. BUILDING		STORIES		AREA				WIDTH	LENGTH			9	9	00	0250	0250																			
B. BUILDING		STORIES		AREA																																																					
		WIDTH	LENGTH																																																						
9	9	00	0250	0250																																																					
<table border="1"> <thead> <tr> <th colspan="2">IF MOBILE PROPERTY</th> <th colspan="2">TYPE</th> <th colspan="2">YR.</th> <th colspan="2">MAKE</th> <th colspan="2">MODEL</th> <th colspan="2">V.I.N.</th> <th colspan="2">LICENSE</th> <th colspan="2">STATE</th> </tr> </thead> <tbody> <tr> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> </tbody> </table>																						IF MOBILE PROPERTY		TYPE		YR.		MAKE		MODEL		V.I.N.		LICENSE		STATE																					
IF MOBILE PROPERTY		TYPE		YR.		MAKE		MODEL		V.I.N.		LICENSE		STATE																																											
<table border="1"> <thead> <tr> <th colspan="2">UNIT</th> <th colspan="2">PTS.</th> <th colspan="2">243</th> <th colspan="2">249</th> <th colspan="2">255</th> <th colspan="2">261</th> <th colspan="2">261</th> <th colspan="2">273</th> <th colspan="2">279</th> </tr> </thead> <tbody> <tr> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> <td colspan="2"></td> </tr> </tbody> </table>																						UNIT		PTS.		243		249		255		261		261		273		279																			
UNIT		PTS.		243		249		255		261		261		273		279																																									

OPERATIONS

Chief Officers at scene:

DAC. E. Butler,,,	CW Duty,
DC. H. MeyerS	Div. 1,
DC. V. Dunn	Div. 3,
E.C. L. Byrnes	Batt. ONE,
B.C. R. Ardisson	Batt. 2
B.C. Davison	Batt. 4,
B.C. Roche	Batt. 6,
B.C. Shelley	Batt. 31,
B.C. Wagner	Batt. 32,
B.C. Dawe	Batt. 7,
B.C. Cesark	Safety Battalion.

Personnel Present at Scene:

R. Schirer	Fire Comm. Liaison,
D.C. Basile	EMS Supervisor,
Lt. Valle	NYPD Pct. 1 supervisor,
Mr. T. Cancelliere	WTC Bldg Mgr.,
(2)	Representative of Salvation Army.

B.C.		ONE		DC.		DIV.	
TYPE FULL NAME	TIME ARRIVED	TYPE FULL NAME	TIME ARRIVED	TYPE FULL NAME	TIME ARRIVED	TYPE FULL NAME	TIME ARRIVED
Lawrence M. Byrnes	1830						

BF24A (12/85)

REPORT - ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		INCIDENT NUMBER		BUILDING NO.		EQUIP INVOLVED		IGNITION		STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION	
MONTH	DAY	YEAR	HOUR	MINUTE	BOROUGH	BOX NUMBER	INCIDENT NUMBER	BUILDING NO.	EQUIP INVOLVED	PLANT FORM	MATERIAL TYPE	MATERIAL FORM	CONSTRUCTION	STATUS	FLOOR CODE	OCCUPANCY	AREA CODE	MANNER	OCCUPANCY	REVISED REPORT	
6	11	1991	1827	1	1	8084	0562	0034	1	229	43	61	1	591	1	93	81	52	09	04	0

ADDRESS		STREET NAME		TYPE	
ROAD	NUMBER (INCL. HYPHEN)	STREET NAME	TYPE	SUPPLY	DIRECTION
1	1	WORLD TRADE CENTER			

DAMAGE		DETECTORS	
SPR. PERFORMANCE	% DAMAGED	FLAME	SMOKE
2	1	1	0
WATER	PRESENT	TYPE	POWER
0	0	0	0

World Trade Center

BUILDING		AREA	
STORIES	WIDTH	LENGTH	
99	0250	0050	

IF MOBILE PROPERTY		OCCUPANT (Driver)		ROOM/APT.	
TYPE	YR.	MAKE	MODEL	V.I.N.	LICENSE

UNIT		PTS.		243		248		255		261		261		273		279	

OPERATIONS

Time Sequences:

Signal

Box 8084

10-84

10-76

10-44

10-84

10-75

22-9084

10-84

UC/8084

Time

1827

1830

1833

1842

1845

1848

1858

1904

2008

By Order of:

Dispatcher,

Batt. 1,

Batt. 1,

Batt. 1,

Div. 1,

Div. 1,

Batt. 1,

Car. 6B, Chief Butler,

Car. 6B, via FCU.

Injuries:

[REDACTED], superficial burns,
[REDACTED], chest pains.

Unit Citations to be submitted for Ladder Co. 10 and Engine Co. 10.

ONE		DC		DIV.		PAC	
BC	BN.						
Lawrence M. Byrnes	1830					5	0
TYPE FULL NAME	TIME ARRIVED	TYPE FULL NAME	TIME ARRIVED				

3F-24A (12/85) REPORT - ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR

TYPE REPORT			DATE AND TIME ALARM RECEIVED			BOX LOCATION		MODIFY			BUILDING			IGNITION			STRUCTURE			AREA	
MONTH	DAY	YEAR	HOUR	MINUTE	SECOND	BOX NUMBER	LOCATION	MODIFY NUMBER	MODIFY DATE	MODIFY TIME	MODIFY TYPE	MODIFY DATE	MODIFY TIME	MODIFY TYPE	MODIFY DATE	MODIFY TIME	MODIFY TYPE	MODIFY DATE	MODIFY TIME	MODIFY TYPE	
6	12	1991	18	27		10084	0552	00	3	41	28	49	61	1	591	1	591	1	591	1	591

DAMAGE		DETECTORS	
TYPE	PERFORMANCE	TYPE	PERFORMANCE
21	1	1	0
0	0	0	0
0	0	0	0

World Trade Center

OCCUPANT (Driver)		ROOMMATE	
TYPE	NAME	TYPE	NAME
1	1	1	1

IF MOBILE PROPERTY

TYPE	YEAR	MAKE	MODEL	VIN
1	1	1	1	1

OPERATIONS

Unit Operations:

Eng. 10: Responded to the 93rd floor, stretched of 2 1/2" hose, hooked up to standpipe in assisted Lcd. 10 in search and size up 94th floors, used a fog nozzle to ext in electrical closets, assisted in evac civilians, connected to buildings stand

Eng. 6: Responded to the 95th floor, stretched 2 1/2" hose, stood fast, assisted in head of fire area, connected to and supplied siamese,

Eng. 7: Responded to the 93rd floor, stretched 2 1/2" hose from the "B" stairway, supplied ECC, connected to standpipe and supplied

Eng. 4: Responded to the 97th floor, hooked 2 1/2" hose, stood fast, assisted in

Following Engid/Companies reported to Lobby stood fast: Eng. 18, 205, 24, 18,

** E-10 also used dry chem on 93

AC ONE DC
RN
Laurence M. Dyrnes 1830
TYPE FULL NAME TIME ARRIVED

BF-24A (12/86)

REPORT - ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		BUILDING NO.		IGNITION		STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION		
MONTH	DAY	YEAR	HOURL	MINUTE	BOROUGH	BOX NUMBER	INCIDENT NUMBER	BUILDING NO.	CAUSE ON AREA	EQUIP. INVOLVED	WCT FLOOR	MATERIAL TYPE	MATERIAL FORM	CONSTRUCTION	USE	STATUS	REVISOR REPORT	
6	11	1991	1827	1	8084	0562	003	4123	43	61	1	591	1	93	81	52	09	04

NUMBER (INCL. HYPHEN)		STREET NAME		TYPE	
1	1	WORLD TRADE CENTER			

DAMAGE		DETECTORS	
SPR. PERFORMANCE	FLAME	SMOKE	WATER
2	1	1	0

World Trade Center

AREA	
WIDTH	LENGTH
99	0250

IF MOBILE PROPERTY		TYPE		VR.		MAKE		MODEL		V.I.N.		LICENSE		STATE	

UNIT		MTS.		243		248		255		261		261		273		273	

OPERATIONS

UNIT OPERATIONS cont:

- Lad. 10: Conducted primary search on floors 93, 94, 95, and 96, and 97. Unit split into 3 teams, located fire condition in electrical distribution closets, called for placement of hand lines, conducted opening up operations on 94th floor to check for fire extension, evacuated unknown member of civilians from floors 94 through 95 during initial operations,
- Lad. 1: Conducted primary search on 93rd floor, conducted secondary search on floors 94 to 101, proved to be negative, conducted survey on floors 81 through 92 for water damage to electrical closets due to hand-line use, negative.
- Lad. 15: Conducted primary and secondary searched of floors 93 to 97, negative results,
- Lad. 8: Conducted examination of floors 92 to 101 for possible fire extension from electrical closets, negative, conducted secondary search on floors 94 and 95,
- Lad. 110: Performed secondary search of floors 96 through 110, negative results,

O.C.		ONE		O.C.		DIV.	
Lawrence M. Byrnes		1930					
TYPE FULL NAME		TIME ARRIVED		TYPE FULL NAME		TIME ARRIVED	

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

OPERATIONS

Lad. 6: Conducted secondary search 66 floors 105 to 110, negative results, removed (2) civilians from stalled elevators on the 38th and 101st floors, no injuries to civilians, or damage to building,
Lad. 20: Conducted secondary search of floors 98,99, and 100 negative results,
Lad.131: Conducted search of floors 105 to 110, with negative results.

Division 1 operated at the Command Post as CIC.

TYPE FULL NAME

TIME ARRIVED

TYPE FULL NAME

TIME ARRIVED

G-51

BF-24A (12/86) **REPORT - ADDITIONAL DATA**

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		INDUSTRY		BUILDING		EQUIP INVOLVED		IGNITION		STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION	
MON	DAY	YEAR	HOUR	MINUTE	BOX	NUMBER	INDUSTRY	NUMBER	BUILDING	TYPE	NUMBER	TYPE	NUMBER	TYPE	NUMBER	TYPE	NUMBER	TYPE	NUMBER	TYPE	
6	07	23	92	2202	1	8093	0455	01	3	42	24	43	61	1	542	1	99	32	69	00	99

DAMAGE		DETECTORS	
SPR	PERFORMANCE	SMOKE	TYPE
0	0	0	0

STREET NAME		TYPE	
WORLD TRADE CENTER			

BUILDING		AREA	
STORIES	WIDTH	LENGTH	
99	0300	0400	

OCCUPANT (Driver)		ROOM/APT	
Port Authority NY/NJ			

IF MOBILE PROPERTY		MAKE		MODEL		VIN		LICENSE		STATE	
TYPE	YR	MAKE	MODEL	VIN	LICENSE	STATE					
7	010	20	7	001	20	7					
5	005	12	7	015	12	7					

OPERATIONS

Due to high electrical voltage (13000volts confirmed, no water was used in initially, pending confirmation of power off at the electrical distribution panel.

Due to large floor area of the 5th floor-sub-basement, responding units were split into teams viz: Ladder Co. 10 and Engine 10 using the K13 stair to approach the fire area, Ladder 1 to use 2nd stairway-K12, to access the 5th sub. basement level. These units were tasked with pin-pointing the fire area, an area of 200' x 400'.

A member of Ladder Co. 1 having found the fire situation in a very large power distribution panel, attempted to relay information to his officer. Prior to his transmission firefighter was struck by a shock blast generated by the involved panel. Ladder 1 firefighter knocked unconscious required a concerted effort to remove to a separate safe area.

Unit Operations.

Engine 10 - Operated on 5th sub level, stretched a 2 1/2" hand line from the standpipe, operated when power off confirmation received. Company

Engine 7 - Operated on fire floor with line off standpipe, operated under B.C. Demarest, Batt. 4, extinguished fire, used dry chemical extinguishers on fire.

By: Lawrence M. Byrnes 1 B.N. 2205

TYPE FULL NAME TIME ARRIVED TYPE FULL NAME TIME ARRIVED

3F-24A (12/86)

REPORT - ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT				DATE AND TIME ALARM RECEIVED				BOX LOCATION		INCIDENT NUMBER		BUILDING NO.		IGNITION		STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION		REVISED REPORT	
MONTH	DAY	YEAR	HOUR	MINUTE	BOROUGH	BOX NUMBER																	
6	07	23	92	22	02	1	8093	0455	01	3	42	24	43	61	1	642	1	99	32	63	00	09	0

ROAD OR RAIL		EQUIP INVOLVED		HEAT FORM		MATERIAL TYPE		MATERIAL CON		CONSTRUCTION		USE		STATUS		FLOOR CODE		OCCUPANCY		AREA CODE		MANNER		OCCUPANCY		REVISED REPORT	

ROAD		NUMBER (INCL. HYPHEN)		SUITE		FLOOR		STREET NAME		TYPE		SUITE		DIRECTION	
									WORLD TRADE CENTER						

SPR. PERFORMANCE		DAMAGE		DETECTORS	
% DAMAGED	FLAME	SMOKE	WATER	PRESSURE	POWER
0	0	0	0	0	0

OCCUPANT (Driver)		ROOM/APT.	
Post Authority NY/NJ	5th sub. base.		

IF MOBILE PROPERTY		TYPE		YR.		MAKE		MODEL		V.I.N.		L'ENSE		STATE	

UNIT		PTS.		243		249		255		261		267		273		279	

OPERATIONS

Operation cont:

Engine 6 - Assisted Eng 7 in stretch of and operation of a 2½" line into fire area, performed search of area, overhauled as necessary,

Engine 55 - Operated with and relieved Eng. 7 on hand line on fire floor, took up hose lines,

Engine 4 - Under supervision of BC. Turnee, B2, transported injured member of Lad. 1 to ambulance on the B1 level of the fire building, relieved Eng. 10 on a hand line, overhauled, took up hand line,

Engine 24 - Transported Air Cylinders fire area under supervision of BC. Jackson,

Engine 3 - Ordered to and did provide air cylinders to operating units of the B5 level.

Engin

Engine 5 - Operated as Command Post Company

Stood Fast - Eng 9 Sat 1, Engines 15, 28, 33, 34, 207/Maxi, 284/Sat.3,

BC <u>Lawrence M. Byrnes</u> 1 Lawrence M. Byrnes 2205 TYPE FULL NAME TIME ARRIVED	DC _____ DIV. _____ TYPE FULL NAME TIME ARRIVED
--	--

CNC 0 7%

BF-24A (12/86)

REPORT — ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		INCIDENT NUMBER		BUILDING NO.		IGNITION		STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION		
MONTH	DAY	YEAR	HOUR	MINUTE	BOROUGH	BOX NUMBER	INCIDENT NUMBER	BUILDING NO.	CHIEF ON SCENE	EQUIP. INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	CONSTRUCTION	USE	FLOOR CODE	OCCUPANCY	AREA CODE	MANNER	
6	07	23	92	22	02	18093	0455	01	342	24	43	61	1	992	1	99	32	63	00	99

ADDRESS		STREET NAME		TYPE	
BORO	NUMBER (INCL. HYPHEN)	SUPPLY	PREMISE	STREET NAME	TYPE
				WORLD TRADE CENTER	

SPK. PERFORMANCE		DAMAGE		DETECTORS	
% DAMAGED	FLAME	SMOKE	WATER	PRESENT	POWER
0	0	0	0	0	0

OCCUPANT (Driver)		ROOM/APT.	
NAME	ROOM/APT.	NAME	ROOM/APT.
Port Authority NY/NJ	5th sub base.		

IF MOBILE PROPERTY		TYPE		YR.		MAKE		MODEL		V.I.N.		LICENSE		STATE	

UNIT		PTS.		MAKE		MODEL		V.I.N.		LICENSE		STATE	

OPERATIONS

Operations cont:

Ladder 1- Operated at the B5 level, conducted search to pinpoint the fire area, conducted a primary search for possible employees trapped. FF. Amodio injured in explosion of 13000 volt distribution panel,

Ladder 10- Performed a search of the B5 level lto identify the fire area, and searched for possible trapped employees, gathered and used dry chemical extinguishers on the fire prior to power removal, overhauled as required,

Ladder 8- Performed a secondary search of the fire area, used dry chemical extinguishers, assisted in overhauling,

Ladder 6- Placed and used portable exhaust fans in stairwells to effatc ventilation , took up,

Ladder 15- Supplied spare SCBA cylinders to staging area,

Ladder 20- Supplied spare SCBA cylinders to staging area,

BC. Lawrence M. Byrnes 1 B.N. DC. 2205 DIV. 4

TYPE FULL NAME TIME ARRIVED TYPE FULL NAME TIME ARRIVED

BF-24A (12/89) **REPORT - ADDITIONAL DATA**
STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		INCIDENT NUMBER		BUILDING NO.		IGNITION		STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION		
MONTH	DAY	YEAR	HOUR	MINUTE	BOROUGH	BOX NUMBER	INCIDENT NUMBER	BUILDING NO.	END ON ARRIVAL	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	CONSTRUCTION	USE	FLOOR CODE	OCCUPANCY	AREA CODE	MANNER	
6	07	23	92	22	02	1	8093	0455	01	3	42	24	43	61	1	642	1	99	63	63

BORO		NUMBER (INCL. HYPHEN)		SUFFIX		STREET NAME		TYPE		SUFFIX DIRECTION	
1	1	1	1	1	1	1	1	1	1	1	1
WORLD TRADE CENTER											

SPK. PERFORMANCE		DAMAGE		DETECTORS	
% DAMAGED	FLAME	SMOKE	WATER	PRESENT	TYPE
0	0	0	0	0	0

Podit Authority NY/NJ 5th sub. base.

OCCUPANT (Driver)		ROOM/APT.	
1	1	1	1

IF MOBILE PROPERTY		TYPE		YR.		MAKE		MODEL		V.I.N.		LICENSE		STATE	
1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1

UNIT		PTS.		243		249		255		261		267		273		279	
1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1

OPERATIONS

Operation cont:

Rescue 1- Company split to perform several operations-

1. Assisted in administering first aid to Injured firefighter,
2. Conducted secondary search of fire area, negative,
3. Used Thermal Camera to check for possible fire extension,

Rescue 2- Assisted (2) civilian electricians (with SCBA's) to confirm power off in electrical panel, relayed confirmation of power off to Command Post. Assisted in hand line operation, assisted in VES of fire floor.

Chief Officers present:

DAC R. Palmer, CW Duty

DC. R. Manson Div. 1,

B.C. L. Byrnes Batt. 1,

B.C. W. Demarest Batt. 4,

B.C. R. Turner, Batt. 2,

B.C. JACKSON Batt. 33,

B.C. Costa Batt. 7,

B.C. Miccio Batt. 6,

B.C. Nardone Batt. 9,

B.C. ROSS Batt. 31.

BC. Lawrence M. Byrnes

1

BN.

DC.

DIV.

PAI

CAC 328

TYPE FULL NAME

TIME ARRIVED

TYPE FULL NAME

TIME ARRIVED

REPORT - ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT		DATE AND TIME		BOX LOCATION		INCIDENT		IGNITION		STRUCTURE		AREA OF ORIGIN		EXTENSION	
MONTH	DAY	YEAR	TIME	BOX	NUMBER	BUILDING	NUMBER	CAUSE	TYPE	FLOOR	AREA	ORIGIN	EXTENSION	REMARKS	
6	7	22	22	1	8098	10455	01	13	42	24	42	1	54	1	99

DAMAGE		DETECTORS	
SPK	PERFORMANCE	TYPE	PERFORMANCE
0	0	0	0

STREET NAME		TYPE	
STREET	NUMBER	TYPE	NUMBER
WORLD TRADE CENTER	1	TYPE	NUMBER

BUILDING		AREA	
STORIES	WIDTH	LENGTH	STORY
99	0200	0400	0

OCCUPANT (Driver)		ROOM/APT.	
NAME	NUMBER	ROOM/APT.	NUMBER
Port Authority NY/NJ	1	ROOM/APT.	NUMBER

IF MOBILE PROPERTY		MAKE		MODEL		VIN		LICENSE		STATE		
TYPE	YEAR	MAKE	MODEL	VIN	LICENSE	STATE	TYPE	YEAR	MAKE	MODEL	VIN	
UNIT	YEAR	MAKE	MODEL	VIN	LICENSE	STATE	UNIT	YEAR	MAKE	MODEL	VIN	
237	UNIT	YEAR	MAKE	MODEL	VIN	LICENSE	STATE	UNIT	YEAR	MAKE	MODEL	VIN

OPERATIONS

Operations cont:

Greater alarms transmitted due to magnitude of fire area involved, potential for smoke and heat problems, numbers of employees in building need to supply and relieve operating personnel.

Injuries: FF. Amodio, Lad. 1, concussion, removed to Beckman Hosp.,
 FF. Cancel, Lad 10, granted ML.,
 FF. Hanson, Lad. 10, granted ML.,
 FF. Selletti, Lad. 10, Granted ML.

Note: Staff and employees of the New York Port Authority provided excellent guidance and assistance. Help provided included mechanical, ventilation, electrical distribution disciplines which made for a much easier fire ground operation.

EC	Lawrence M. Byrnes	1	DC	PAG
TYPE FULL NAME		TIME ARRIVED	TYPE FULL NAME	
2005		2005		6

REPORT -- STRUCTURAL FIRE

BF-24 (12) 510-1027 N

TYPE REPORT				DATE AND TIME				INCIDENT				BOX				REPORT				COMPANIES				HAZ				SPECIAL							
COMMUNITY BOARD				ALARM RECEIVED				DURATION				LOCATION				NUMBER				PLANT				RESPONDING				MAT				USE			
1016010111				09230101				0130101				7118084				01030648				0185030201				630400				0000							
1				1				1				1				1				1				1				1							

AIDED AND CASUALTIES				EXTIN.				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS											
EVAQUATED				UNINJURED				KILLED				CODE				SFX. PER.				COND. ON ARRIVAL				EQUIP INVOLVED				HEAT FORM				MATERIAL TYPE							
0000				0100				0021				112				6129				4361				0159				159				9481				2700			
0000				0100				0021				112				6129				4361				0159				159				9481				2700			

BF-24

BOND				NUMBER				INCL. HYPHEN				SUFFIX				STREET NAME				TYPE				STORIES				AREA				DEFECTIVE DETECTOR							
111				111				111				111				111				111				111				111				111				111			
111				111				111				111				111				111				111				111				111				111			
111				111				111				111				111				111				111				111				111				111			

PORT AUTHORITY

NAME OF OCCUPANT 211

ROOM/APT.

YR.

MAKE

LEFT IN CHARGE MIKE HURLY

SERIAL NUMBER

POWER

FSD

BADGE NO.

EQUIPMENT INVOLVED IN IGNITION

UNIT	PTS	ITEM
W	5	0101050060270010500705
R	1	0101050060270010500705

OPERATIONS

Upon arrival at box 8084 found fire on the 104th floor which was knocked down by three sprinkler heads. Initially a 10-76 was transmitted until the source of the smoke condition was found. B-1 then operated with 3 Engines and 2 Trucks and all other units returned to Quarters. Units operated as follows:

L-10 Gained access to building, found smoke condition on 103rd and 104th floors, found fire in computer room on the 104th floor, performed search and overhauling.

E-10 Took hydrant, stretched line to the siamese, stretched line from standpipe, completed extinguishment.

L-1 Assisted L-10, performed search of areas above and adjacent to the fire.

E-6 Took hydrant, assisted E-10 in stretch off the standpipe.

B.C.	B.N.	O.C.	DIV.	PAGE
John Akerman	23.07	01	1	1 OF 2

ADMINISTRATIVE COMPANY

TIME OF ARRIVAL

TIME OF ARRIVAL

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

OPERATIONS

F.M. Kregler #361 responded on BFL's own knowledge of prior suspicious activity. Job #11201.

G-58

Attachment G-A.5

Significant fire incidents occurring in WTC 2 (3)

Significant Fire	Incident Date	Fire Location	# Sprinklers Activated	# Standpipes Activated	Cause of Fire	Material Ignited
1	5/19/75	Floor 32	-	3	Incendiary	Trash/waste
2	4/12/77	Duct work over grill in restaurant on floor 107	2		None listed	Duct work
3	3/22/93	Fan motor room on floor 108	2		Mechanical failure	Not classified

FIRE RECORDS USE ONLY				DATE AND TIME ALARM RECEIVED				DURATION OF ALARM				LOCATION				INCIDENT				REPORT			
MO.	DAY	YEAR	CDNO.	HOUR	MINUTE	SECONDS	HOURS	MINUTES	SECONDS	MO.	DAY	YEAR	CDNO.	MO.	DAY	YEAR	CDNO.	MO.	DAY	YEAR	CDNO.		
1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1		
05	05	00	21	09	47	00	03	21	15	11	11	11	33	31	50	00							

ADDRESS 2 World Trade Center Map N.Y. S. Banking 32nd
 BUILDING 110 STORIES 200 AREA 200
 (Second Card)

5	028	0	30	5	007	0	30	5	027	0	30	5	010	0	25	5	009	0	12	5	055	0	15
5	024	0	12	5	017	0	12	6	001	0	05	7	010	0	30	7	001	0	20	7	008	0	20

TYPE NO. SECT. FIS 104

Upon arrival was informed by Port Authority Police of smoke condition on 32 floor and occupants reported trapped on 31 and 32 floors. Established command post and ordered Engine 6 (28) and Engine 7 to proceed to fire area and operate in separate stairways. Ladders 10 and 12 to transmit immediate report of fire conditions and to make search for occupants and perform necessary duties. Battalion 4 to supervise operations in fire area. Division 1 assumed command upon arrival. Ordered one additional engine and ladder units. Then transmitted 2nd alarm upon receipt of report from fire area of "heavy fire and smoke condition". Battalion 1 with Engine 10 and Ladder 8 ordered to operate in third stairway. Additional units put to work as required and to relieve operating units. Fire area involved core area throughout and was confined to same.

Four minor fires in previous two hours were suspected arson and were each reported via dispatcher to fire marshal and same ordered to respond.

E.6(28) Stretched line to 32fl via stairway B. Operated to extinguish major body of fire. Then relieved by E.7. EWS

E.7- Assisted E.6 in stretching and advancing line. Then stretched 2nd line to 32nd fl via stairway and operated to extinguish fire.

E. L. Allen *J. O. Smith*

Charles J. Votruba

2140

Roger Rodriguez

TYPE FULL NAME

TIME OF ARRIVAL

270' TYPE FULL NAME: 1100 1700 TIME OF ARRIVAL

SECRET

ADMINISTRATIVE COLLEGE

INCIDENT	LOCATION	DATE AND TIME	ALARM RECEIVED
E.27- Stretched line to 32nd fl. Operated to extinguish remaining fire. assisted in search. Overhauled fire area.	32nd fl.		
L.10- Forced door to 32nd fl- stairway "C". Operated house hose line to assist in making search. Then operated on 32nd fl. continuing search. Made examinations. Then assisted in overhauling. Then relieved by L.1	32nd fl.		
L.1- Made search of floors 33, 34, and 35. Then made examination at 33rd fl for extension off fire.	33rd fl.		
E.10 (Spec. called)- Ordered to stand fast at 31st fl. Then relieved on hose lines 32nd fl. to assist in overhauling. Then took up lines of E.6 & 7.	31st fl.		
L.6- (Spec. called)- Assisted in making secondary search of office occupancies 32nd fl. Then relieved L.10 overhauling fire.	32nd fl.		
Batt.4- Supervised units initially operating on the 32nd fl.	32nd fl.		
Batt.1- Ordered to assist in supervision in fire area. Then relieved Batt.4 and supervised secondary search, examination and overhauling.	32nd fl.		
K.9- Ordered to stand fast. Then made search of 44th fl.	44th fl.		
E.55- Relieved operating units on the 32nd fl. where necessary.	32nd fl.		
E.24- Made examination 20th, 40th and 60th fls. (2 WTC)	20th, 40th, 60th fls.		
E.17- Made search examination 20, 40th, 60th fls (1 WTC)	20, 40th, 60th fls.		
L.15- Made search of perimeter office occupancies 32nd fl. Then made search and examination of 44th fl. Then made final examination of 31st fl core area.	32nd fl, 44th fl, 31st fl		
Batt.32 Supervised examination in #1 WTC. Then supervised examination in #2 WTC 44th and 60th fls.	#1 WTC, #2 WTC 44th and 60th fls.		
Mar.1- Stretched line to gate and ordered to stand fast.	gate		
Res.1- Administered oxygen to Fr. O'Neill E.7. Then made examination for fire extension around perimeter of fire area and involved 31st fl.	31st fl.		
Superpumper System- Superpumper and Sat.12 ordered to return to qtrs.	qtrs.		
Sat.1 ordered to stand fast at hook up site then	hook up site		
PCU. Established Field Hdqts. Monitored HT circuits. Transmitted Progress reports. Maintained control band.	Field Hdqts.		
MSU- Serviced Units, Exchanged 30 cylinders.	Units		

(3000) Time of Special Calls: 2150 hrs.

2nd alarm: 2154 hrs.

under control: 2257 hrs.

Chief Officers Operating:

BC Votruba, Batt. 1 BC Bagley, Bn

REPORT - STRUCTURAL FIRE																				
FOR FIRE RECORDS USE ONLY		DATE AND TIME ALARM RECEIVED					DURATION OF INCIDENT		LOCATION			REPORT								
		MONTH	DAY	YEAR	CO. NO.	HOUR	MINUTE	HOURS	MINUTES	HOW REPORTED	INITIAL ALARM			HIGHEST ALARM	BOROUGH	ALARM	INCIDENT			
		1	06	12	77	1	1315	00	30	1	1	0	1	0070	5	006	0113	0056	01	999

AIDED AND CASUALTIES					RESP.	EXTINGUISHMENT	INVESTIGATION	STRUCTURE	AREA FIRE ORIGIN
CIVILIANS									
EVAQUATED	INJURED	DIED	PROPERTY DAMAGE	LOST TO BUSINESS					
00	00	00	00	00	00	00	00	00	00

ADDRESS		Man	
NUMBER	STREET	BOROUGH	ROOM/APT. NO.
2	World Trade Center	Man	
110		400 ± 400	
BUILDING		LEFT IN CHARGE	

COMPANY		Mr. Sarnelli FSD	
TYPE	NO. SECT. PIS.	NAME OF OCCUPANT	ROOM/APT. NO.
7	001 0	Mr. Sarnelli FSD	

OPERATIONS

On arrival found fire to be extinguished prior to arrival ;

Fire was located in duct work over grills in in restaurant on 107 th floor, Bn. 1 notified dispatcher to notify board of Health of possible food contamination from heat smoke and gases in restaurant.

E. 6 Took rolled ups to 107 floor, stretched line and stood fast.

L. 1 Made necessary search and investigation.

F.P. 2 on scene replaced two sprinkler heads.

60 William M. Feehan 1

ABC William M. Feehan 1318

TYPE FULL NAME DATE OF ARRIVAL TYPE FULL NAME

AIDED AND CASUALTIES				EXTIN- GUISHMENT		IGNITION		STRUCTURE		FIRE ORIGIN		FIRE EXTENSION		DAMAGE		DETECTORS												
EVACUATED	INJURED	KILLED	UNIDENTIFIED	CODE	EQUIP INVOLVED	FUEL FORM	MATERIAL TYPE	MATERIAL FORM	FACTORY	ALTERNATE CONSTRUCTION	STATUS	COMPL EX	FLOOR CODE	OCCUPANCY	AREA OF ORIGIN		MAINTENANCE	NO BLANKS	% DAMAGES	FLAME	SMOKE	WATER	PRESENT	TYPE	POWER	PERFORMANCE	FOR INVESTIGATION	
															CAUSE	ORIGIN												
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
00	00	00	00																									

B-F-24

192		NAME OF OCCUPANT		211		ROOM/APT.		ACS108		LEFT IN CHARGE		FEELY		POWER		BADGE NO.	
193		EQUIPMENT INVOLVED IN IGNITION		212		MAKE		MODEL		SERIAL NUMBER		244		264			
194		UNIT		PTS		ITEM		272		278		284		290		295	
195		W		5		010		05		7		001		05		5	
196		R		5		010		05		5		006		05		7	
197		I		5		010		05		5		007		05		05	

Upon arrival at Box 8087 found smoke condition on the 108th floor caused by a overheated bearing in a fan motor room ACS-108-4. Smoke Det. caused 2 sprinkler heads to go off. Units operated VIZ: E10-Hooked up to standpipe on the 108th fl. Goodfast, then up. L10-Made necessary search and examination, found cause of smoke condition, checked for extension found neg. Then up. E6-Assisted L10 in search, then up.

B.C. Golden Symon
GO: dia Symon

B.C.	B.N.	DIV.	PAGE
Goidan Symon	0844		OF 2
Foster Symon			/
TYPE FULL NAME		TIME OF ARRIVAL	
WHITE - FIRE RECORD	YELLOW-BATTALION	PINK-REFERRAL	GOLD-ADMINISTRATIVE COMPANY

F-24A (12/86) 15942-60153-1020-N

REPORT — ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		INCIDENT NUMBER	BUILDING NO	IGNITION				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION																																						
MONTH	DAY	YEAR	HOUR	MINUTE	BOX	NUMBER	COND ON ARRIVAL			EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	CONSTRUCTION	USE	STATUS	FLOOR CODE	OCCUPANCY	AREA CODE	MANNER	OCCUPANCY	REVISED REPORT																																		
6	03	22	93	0839	1	8087	0058	00																																																
<table border="1"> <thead> <tr> <th colspan="2">ADDRESS</th> <th colspan="2">STREET NAME</th> <th colspan="2">TYPE</th> <th colspan="2">SUFFIX DIRECTION</th> </tr> </thead> <tbody> <tr> <td>2</td> <td></td> <td></td> <td>WTC</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>																					ADDRESS		STREET NAME		TYPE		SUFFIX DIRECTION		2			WTC																								
ADDRESS		STREET NAME		TYPE		SUFFIX DIRECTION																																																		
2			WTC																																																					
<table border="1"> <thead> <tr> <th colspan="2">SPK PERFORMANCE</th> <th colspan="2">DAMAGE</th> <th colspan="2">DETECTORS</th> </tr> </thead> <tbody> <tr> <td>% DAMAGED</td> <td>FLAME</td> <td>SMOKE</td> <td>WATER</td> <td>PRESENT</td> <td>TYPE</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td>POWER</td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td>PERFORMANCE</td> </tr> </tbody> </table>																					SPK PERFORMANCE		DAMAGE		DETECTORS		% DAMAGED	FLAME	SMOKE	WATER	PRESENT	TYPE						POWER						PERFORMANCE												
SPK PERFORMANCE		DAMAGE		DETECTORS																																																				
% DAMAGED	FLAME	SMOKE	WATER	PRESENT	TYPE																																																			
					POWER																																																			
					PERFORMANCE																																																			
<table border="1"> <thead> <tr> <th colspan="2">OCCUPANT (Driver)</th> <th colspan="2">ROOM/APT.</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>																					OCCUPANT (Driver)		ROOM/APT.																																	
OCCUPANT (Driver)		ROOM/APT.																																																						
<table border="1"> <thead> <tr> <th colspan="2">IF MOBILE PROPERTY</th> <th colspan="2">TYPE</th> <th colspan="2">YR</th> <th colspan="2">MAKE</th> <th colspan="2">MODEL</th> <th colspan="2">VIN</th> <th colspan="2">LICENSE</th> <th colspan="2">STATE DM</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>																					IF MOBILE PROPERTY		TYPE		YR		MAKE		MODEL		VIN		LICENSE		STATE DM																					
IF MOBILE PROPERTY		TYPE		YR		MAKE		MODEL		VIN		LICENSE		STATE DM																																										
<table border="1"> <thead> <tr> <th colspan="2">UNIT</th> <th colspan="2">PTS</th> <th colspan="2">243</th> <th colspan="2">249</th> <th colspan="2">255</th> <th colspan="2">261</th> <th colspan="2">261</th> <th colspan="2">273</th> <th colspan="2">279</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>																					UNIT		PTS		243		249		255		261		261		273		279																			
UNIT		PTS		243		249		255		261		261		273		279																																								

OPERATIONS

E7-Assisted E10 in stretching line, then up.
 L1-Assisted L10 in search, then up.

1
 B.C. Gordon Symon 1st B.N. 0844 OC DIV.
 TYPE FULL NAME TIME ARRIVED TYPE FULL NAME TIME ARRIVED
 PAGE 2 OF 2

Attachment G-A.6.1

Additional fire incidents involving the deployment of standpipe lines in WTC 1 and WTC 2 –

- Fires involving the use of one standpipe line and the activation of one sprinkler (4 in total)

REPORT—STRUCTURAL FIRE

[illegible]

Responded to alarm box 8087. Upon arrival found light fire, medium smoke conditions in storage room (office records) at above address and location. Transmitted signal 10-75. Fire had activated 1 sprinkler head. Fire was confined to and extinguished in said room.

Eng. 10- Stretched standpipe line, extinguished fire, washed down.

Eng. 6- Relieved Eng. 10 on line.

Lad. 1- Searched, found fire, shut down sprinkler system, reactivated system, checked for extension, overhauled.

[illegible]

Upon arrival found alarm for fire in dumpster on 106 th floor. sprinkler head controlled fire.

ing. 10 supplied standpipe system, stretched handline & extinguished fire.

Ing. 6 supplied standpipe system & assisted Ing. 10.

7 Wide search & examination of floors 98-105.

10. Make necessary search, examination or overhaul of fire arm.

1 Made necessary search & examination of 106 & 107 floors.

BC	<i>Kenneth P Markgraf</i>	1st	D.C.		DIV.		PAGE		OF	
	Kenneth P. Markgraf	0415	BN.							
	TYPE FULL NAME	TIME OF ARRIVAL								
	TYPE FULL NAME	TIME OF ARRIVAL								

TYPE REPORT				INCIDENT LOCATION				DATE AND TIME				ALARM RECEIVED				INCIDENT DURATION				BOX LOCATION				REPORT NUMBER				COMPANIES REQUESTING				RECEIVED			
COMMITTEE BOARD				ADDRESS				YEAR				MINUTE				HOURS				MINUTES				MINUTES				MINUTES				MINUTES			
1				01-15-10				06-11-87				18				01-15-10				10				10				10				10			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00				00-00-00			
00-00-00				00-																															

BF-24 (12/86) !
1530 NC26-N

42 Lb

NYPA	ROOMMATT	5 th. Floor	LEFT IN CHARGE	Sgt. Bleeker	NYPA Sgt.	1	294	BAGGE NO.
NAME OF OCCUPANT	NO	NAME	MODEL	SCRAM NUMBER	POWER			

NAME OF OCCUPANT	211	ROOM/APT	5 th. Floor		LEFT IN CHARGE	Sgt. Blocker NYPA Sgt.		294
EQUIPMENT INVOLVED IN IGNITION		VR		NAME	MODEL	SERIAL NUMBER	POWER	
UNIT	P/S	ITEM	212	244				
5	010	10	5	007	02	5	004	05
781A	10	7	001	10				
010	254	250	255					

Chief officers & Officials on Scene

D.C. Hassett	MSFC
H.C. Casey	Battalion
B.C. Demerest	Battalion
FM Corbett	#224
FSD Faggio	NYPA
Sgt. Bleeker	NYPA PD.

Signal	Time	By order of
8084	2104	Disp.
10-76 8084	2110	En. 1
75 8084	2126	Div. 1
U.C.	2128	Div. 1
10-41-1	2133	Div. 1

DC	John B. Casey	BN.	2109	TIME OF ARRIVAL
	TYPE-FULL NAME			
				WHITE-FIRE RECORD
				YELLOW-BATTALION

DC	Bruce Hassett	BN.	2121	TIME OF ARRIVAL
	TYPE-FULL NAME			
				PINK-REFERRAL
				ROYAL ADMINISTRATIVE COMPANY

PAGE 1 OF 2

This page intentionally left blank

Attachment G-A.6.2

Additional fire incidents involving the deployment of standpipe lines in WTC 1 and WTC 2 –

- Fires involving the use of one standpipe line (27 in total)

DATE AND TIME ALARM RECEIVED										LOCATION									
ALARM / INCIDENT										REPORT									
DATE	TIME	ALARM	INCIDENT	REPORT	REPORT	REPORT	REPORT	REPORT	REPORT	REPORT	REPORT	REPORT	REPORT	REPORT	REPORT				
05	24	73	0310	01	20	2	1	1	1	0067	7	010	0033	0068	01	365			

DEATH AND CASUALTIES										EXTINGUISHMENT										INVESTIGATION										STRUCTURE										AREA FIRE ORIGIN									
CIVILIANS										EXTINGUISHMENT										INVESTIGATION										STRUCTURE										AREA FIRE ORIGIN									
NAME	AGE	SEX	RACE	RELIGION	EDUCATION	EMPLOYMENT	RESIDENCE	DATE OF BIRTH	DATE OF DEATH	CAUSE OF DEATH	DATE OF BIRTH	DATE OF DEATH	CAUSE OF DEATH	DATE OF BIRTH	DATE OF DEATH	CAUSE OF DEATH	DATE OF BIRTH	DATE OF DEATH	CAUSE OF DEATH	DATE OF BIRTH	DATE OF DEATH	CAUSE OF DEATH	DATE OF BIRTH	DATE OF DEATH	CAUSE OF DEATH	DATE OF BIRTH	DATE OF DEATH	CAUSE OF DEATH																					
00	00	00	00	00	05	2	6	00	01	0	64			1	15	1	1	0	09	47	50	00																											

ADDRESS 1 World Trade Center Man,
NUMBER STREET BOROUGH

World Trade Center
NAME OF OCCUPANT ROOM NO.

BUILDING 110 570 x 970
STORIES AREA
 (Below Grade)

Mickey Seetock -
Superv. Engr.

PA - Lt. Newman #21

5	006	0	10	5	007	0	02	5	027	0	02	5	010	0	02	7	010	0	10	7	001	0	10
TIME NO. SEC. MIN.																							

OPERATIONS

On arrival found fire in elevator car (J3) - B2 level, -J-4 area - Heavy smoke condition in adjacent areas, B-2 level. Light smoke cond. in Concourse, on 19th, 36th & 76th floors and various other floors. Fire was confined and extinguished with 1 house line and one F.D. hand line from standpipe. Areas involved with smoke were searched, occupant assisted where required. Operations as follows:

- E6 - stretch line from standpipe J-4 area, ext. fire in elev. & shaft.
- E7 - assist E6 in stretching handline.
- E10 - made search upper floors - 77th to 79th (light smoke cond.)
- E27 - made search upper floors - 36th fl. & vic.
- L10(L18) - report to CP - search & examination of concourse area.
- L1 - forced elev. door B-2 level, examine car, overhaul.
- B2 - supervise operations of E6 & L1 opening elev. car door & ext. fire B-2 ~~118~~ level (284)

Frank L. Picariello 0312 John J. Hart
TYPE FULL NAME TIME OF ARRIVAL

DATE & TIME ALARM RECEIVED				LOCATION OF NOTIFICATION				LOCATION OF ALARM / INCIDENT				REPORT		
MONTH	DAY	YEAR	HOURS	MINUTES	SECONDS	ALARM / INCIDENT	REPORT	REPORT	REPORT	REPORT	REPORT	REPORT		
06	15	73	2015	00	45	21	01	0067	7	010	0033	0104	02	325

AIDED AND CASUALTIES				RESP.		EXTINGUISHMENT		INVESTIGATION		STRUCTURE		AREA FIRE ORIGIN	
CIVILIANS	CHILD	ADULT	UNIDENTIFIED	DEATH	INJURY	CAUSE	CAUSE	CAUSE	CAUSE	CAUSE	CAUSE	CAUSE	CAUSE
00	00	00	00	01	05	2	9	00	01	1	64	1	15

ADDRESS	1 World Trade Center	Manhattan	Unoccupied	6518
NUMBER	STREET	BOROUGH	NAME OF OCCUPANT	ROOM
BUILDING	110	200x200	Security Guards	
STORIES	AREA	LEFT IN CHARGE		

5	006	0	10	7	010	0	10						

OPERATIONS

Upon arrival found fire in rubbish in room 6518 On the 65th. floor, fire confined and extinguished. Fire was in an unoccupied office of Bldg E.6: Stretched line off standpipe extinguished. fire, had taken rolled ups to 65th. floor.

L.10: Overhauled, made necessary examination, ventilated.

On Scene: Fire Patrol #2.

Injured Member: Fr. 1st. Vincent Segretto #9050 Lad. 10, twist right knee
Dr. Schwartz notified. No time lost.

Louis Pike	2	John J. Hart	1
TYPE FULL NAME	EN.	TYPE FULL NAME	PAGE
2017		2017	
TIME OF ARRIVAL		TIME OF ARRIVAL	

FIRE RECORD

REPORT - STRUCTURAL FIRE																	
FIRE RECORDS USE ONLY		DATE AND TIME ALARM RECEIVED					DURATION OF INCIDENT		LOCATION			REPORT					
TYPE REPORT	MONTH	DAY	YEAR	CO. NO.	HOUR	MINUTE	HOURS	MINUTES	HOW REPORTED	INITIAL ALARM	HIGHEST ALARM	BOROUGH	ALARM NUMBER	INCIDENT ADMIN. COMPANY	REPORT NUMBER	REPORT NUMBER	REPORT NUMBER
1	10	30	75	1	0308	0025	4	10	15	0070	7	010	0033	0181	01	445	
AIDED AND CASUALTIES				RESP.		EXTINGUISH- MENT		INVEST- IGATION		STRUCTURE		AREA FIRE ORIGIN					
CIVILIANS																	
EVACUATED	FIRST AID	INJURED	KILLED	UNIFORMED	END SO.	LADDERS	CODE	STAND BY	CAUSE	STATUS	USE	ROOM OF	AREA CODE	EXTENSION			
00	00	00	00	00	00	03	26	00	01	15	00	02	30	50			

ADDRESS	# 2 World Trade Center	Manhattan
BUILDING	110	250x250
(Second Card)	STORIES	AREA

Port of N.Y. Authority
NAME OF OCCUPANT
Fire Safety Director
LEFT IN CHARGE

COMPANIES	5006	05	7010	05
-----------	------	----	------	----

OPERATIONS

Responded to Class 3-70-4

Upon arrival found fire in planter on 32 floor there confined and ~~extinguished~~ extinguished as follows.

E.6 - Carry in rolled up ladders, hook up to S/P outlet, stretch line and operate on and extinguish fire and necessary wash down.

L.10 - Make necessary examination of 32 and 33 floors and overhaul burnt debris on 32 floor.

1st D.C. PAGE

Fergus J. McDermott #2 DIV. ☐ OF ☐

TYPE FULL NAME TIME OF ARRIVAL

FOR FIRE RECORDS USE ONLY		DATE AND TIME ALARM RECEIVED				DURATION OF INCIDENT		HOW REPORTED			LOCATION			REPORT			
TYPE	REPORT	MONTH	DAY	YEAR	CO. NO.	HOUR	MINUTE	HOURS	MINUTES	INITIAL ALARM	HIGHEST ALARM	BOX NUMBER	ADMIN. COMPANY	ROOM NUMBER	REPORT NUMBER	FLIGHT NUMBER	BAGGE NUMBER
1	03	09	76	1	1603	00	30	4	1	0	1	0070	5 006	0010	0124	04	280

AIDED AND CASUALTIES				RESP.	EXTINGUISHMENT	INVESTIGATION	STRUCTURE	AREA FIRE ORIGIN													
EVAKUATED	FIRST AID	INJURED	KILLED	UNIFORMED INJURED	ENG. TO MARINE	LADDERS	CODE	NO. SPRINKLERS OPEN	STANDPIPE LINE USED	EXTINGUISHING AGENT	CAUSE	FIRE MARSHAL	CONSTRUCT	USE	STATUS	STATUS TO LIGHT	STATUS TO LIGHT	FLOOR CODE	ROOM OR AREA CODE	OCCUPANCY	MANNER OF EXTENSION
00	00	00	00	00	03	2	6	00	01	1	64		1	15	1	1	0	20	10	50	00

ADDRESS 1 World Trade Center Mm.
 BUILDING 110 204 x 204
 (Second Card) STORIES AREA

Various
 NAME OF OCCUPANT Lt. John Elliott PAPD
 ROOM/APT. NO.
 LEFT IN CHARGE

COMPANY	TYPE	NO.	SECT.	PIS	NO.	SECT.	PIS	NO.	SECT.	PIS	NO.	SECT.	PIS	NO.	SECT.	PIS
5	055	0	10	7	008	0	05									

OPERATIONS

On arrival found light fire condition in rubbish piled against wall in main concourse which had caused scorching to said wall.

E 55 Stretched line from standpipe outlet and extinguished fire. washed down.

L 8 Examined for extension and overhauled.

Stanley Hirschfeld
 Stanley Hirschfeld 1608
 TYPE FULL NAME TIME OF ARRIVAL
 DIV PAGE
 1 1
 TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

FOR FIRE RECORDS USE ONLY				DATE AND TIME ALARM RECEIVED				DURATION OF INCIDENT				LOCATION				REPORT							
TYPE REPORT				MONTH DAY YEAR				HOURS MINUTES				HOW REPORTED				ALARM INCIDENT							
				CO. NO. HOUR MINUTE				HOURS MINUTES				INITIAL ALARM HIGHEST ALARM				BATTALION							
				CO. NO. HOUR MINUTE				HOURS MINUTES				INITIAL ALARM HIGHEST ALARM				BATTALION							
1				06 24 77				1 2205 01 55				+ 0 7 1 0070 5 006 0113				0158 01 531							
AIDED AND CASUALTIES				RESP				EXTINGUISHMENT				INVESTIGATION				STRUCTURE							
CIVILIANS				FIRE				FIRE				FIRE				FIRE							
EVACUATED				FIRE				FIRE				FIRE				FIRE							
00 03 07				00 00 03				+ 0 00 01 1 62				1 15 1 1 0 46 31 50 00											
ADDRESS 1 World Trade Ctr				Man				Port of N.Y. Authority hallw				46th											
BUILDING 110 250 x250				Richard Hintzen (Fire Safety D)				NAME OF OCCUPANT				ROOM/APT. NO											
(Second Carol)				AREA				TEST IN CHARGE															
5 006 0 20				5 007 0 12				5 024 0 12				1 001 0 10				7 001 0 20				7 008 0 20			
7 015 0 10																							

OPERATIONS

Responded to 3-70-2 (Manual Alarm)

While responding Batt.1 notified via dept. radio of special call additional Ladder Co(L.15) due to report of fire 46th fl. Upon arrival was informed of fire 46th fl public hallway near freight elevator. Ordered investigation and found fire therein, which had been extinguished prior to the arrival of this dept. Evacuation instituted by Port Authority personnel prior to arrival of Fire Dept. units. Report of smoke detector operational of the 103rd fl. Fire located between freight elevators 49 & 17.

E.6- Rolled up lengths to the 44th fl. Connected to standpipe therein and stretched to fire floor(46th) Washed down fire area for overhauling purposes.

E.7- Assisted in stretch, then ordered to search, examination of 53rd to 58th fls. Also Checked 45th fl. report of smoke condition.

E.24- Reported to secondary command post(55th-56th). Then ordered to check smoke condition report 70th fl. Then requested in search, examination of 53rd to 56th fls. Also checked out smoke detector 103rd fl.

James J. McKenna 1 DE 1 PAGE
 James J. McKenna 2208 Matthew J. Farrell 1 DIV. 1 2
 TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

BF-24A (6/76)

REPORT — Additional Data**Structural Fire, Transportation Fire, Non-Structural Fire or Emergency**

FOR FIRE RECORDS USE ONLY		DATE AND TIME ALARM RECEIVED				ALARM	
TYPE REPORT	MONTH	DAY	YEAR	CD. NO.	HOUR	MINUTE	BOX NUMBER
1	06	24	77	2	2205	1	0070

COMPANY	TYPE	NO.	SECT.	FIS.
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				

OPERATIONS

- L.1- Initially to the fire floor (46th) operated for overhauling search & examinations ventilation of same. Then search, examination & ventilation of the 107th to 46th fl. Stairway "B".
- L.8- Initially to secondary command post. (West St). Then ordered to check 78th to 60th fls search & examination. Also assisted in overhauling fire floor (46th)
- L.15- Special called to report to West St. Then through lobby to secondary command post. Enroute found (2) civilian cleaning personnel (female) had been removed to lobby suffering smoke inhalation. Performed first Aid on injured civilians. Then relieved by Res. 1 with resuscitator. Then ~~xxx~~ ordered to search 47th to 52nd fls as (2) injured civilians reported to have worked on the 48th & 50th fls.
- Res.1- Relieved L.15 and administered first aid (Inhalation) to injured civilians. Then ordered Officer & remainder of members went to investigate report of smoke & people on the 55th fl. Then ~~down~~ down to 46th fl. Search, examination of floors enroute.
- Batt.1- Initially in command, then ordered to ~~set up~~ set up additional command in lobby, as first aid station. Two public ambulances standing by with (4) resuscitators. Directed search operations of E.7, L.15, Res. 1. Ordered smoke purge 45th to 107 when fire was out.
- Batt.2- Ordered to supervise units on the fire floor & report conditions therein. Supervised in part operation of E.6, L.1
- Batt.32 - Ordered to supervise operations of units above fire floor.
- Div.1- In overhauled command of operations at command post B.1 level.

James J. McKenna IN. D.C. _____ PAGE 4
 James J. McKenna 2208 Matthew J. Farrell 2 of 3
 TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL

REPORT -- Additional Data

Structural Fire, Transportation Fire, Non-Structural Fire or Emergency

FOR FIRE RECORDS USE ONLY		DATE AND TIME ALARM RECEIVED				ALARM	
TYPE REPORT	MONTH	DAY	YEAR	CD. NO.	HOUR	MINUTE	BOX NUMBER
1	06	24	77	2	2205	1	0070

COMPANY	TYPE	NO.	SECT.	PIS.
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				

OPERATIONS

Act. Asst Chief Munk on the scene to supervised overall operations.

Remarks: L. 1 checked all elevator ~~cars~~ cars before leaving scene.
 Ordered 10-41 Code 1 due to report from Port Authority police of labor trouble with Maintenance personnel (Temco)
 Dept. Photographer ordered to scene to take pictures of fire area.

Alarm was turned in by Mr. Nick Cappola, Temco Maintenance
 (2) Beekman Ambulances on the scene under Mr. B. John

Injured Civilians:

Name	Address	Injury	Treated
[REDACTED]	[REDACTED]	Smoke inhal.	Beekman & Released
[REDACTED]	[REDACTED]	Smoke inhal.	" " "
[REDACTED]	[REDACTED]	Smoke Inhal.	Received O2 not removed to Hos

Note : All of the above are employees of the Temco Co.

Sgt. Steve Fox Bd# 264	Burn to Fingers Rt Hand.
Ptl A. Hallicker	Burn to Rt Wrist
Ptl Meyers	Smoke inhal
Ptl. Carcalc	Smoke Inhal.

Note: Police members of Port Authority Police Dept. All injured treated at Beekman Hospital & released.

by James J. McKenna BN. D.C. Matthew J. Farrell dv. PAGE ☐ of ☐
 James J. McKenna TIME OF ARRIVAL 2208 Matthew J. Farrell TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

REPORT - 10000

[illegible]

G-81

REPORT - STRUCTURAL FIRE															
FOR FIRE RECORDS USE ONLY		DATE AND TIME ALARM RECEIVED					DURATION OF INCIDENT		LOCATION			REPORT			
TYPE REPORT	MONTH	DAY	YEAR	CD NO.	HOUR	MINUTE	MINUTES	HOW REPORTED	INITIAL ALARM	HIGHEST ALARM	BOROUGH	FOX NUMBER	ADMIN. COMPANY	BLOCK NUMBER	REPORT NUMBER
1	08	08	77	1	11	05	00	20	4	1	1	0070	6	00600113	0070 04 999
AIDED AND CASUALTIES					RESP.	EXTINGUISHMENT	INVESTIGATION	STRUCTURE	AREA FIRE ORIGIN						
CIVILIANS															
EVALUATED	INJURED	FILED	UNINFORMED	INJURED	INJURED	INJURED	INJURED	INJURED	INJURED	INJURED	INJURED	INJURED	INJURED	INJURED	INJURED
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00
ADDRESS 1 World Trade Center Man. BUILDING 110 200 E 200 (Second Card) STORIES AREA															
Various NAME OF OCCUPANT Sgt. Brown, 109 P.A.P.D. LEFT IN CHARGE															
C O M P A N I E S 5 006 D 05 7 001 D 05															
TYPE NO. SECT. FIS.															

OPERATIONS

On arrival found fire in accumulated rubbish in elevator lobby of 35th floor which had caused scorching of the walls and ceiling. Port Authority personnel had extinguished fire with hand extinguishers and standpipe hose. Fire termed suspicious by P.A.P.D.

E 6 Responded with rolled-up lengths, hooked-up to standpipe and stood fast.

L 1 Searched, examined for extension and overhauled.

ABC *James Hallinan* 4 DC
 James Hallinan 1110
 TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL
 DIV PAGE
 1 OF 1

ADMINISTRATIVE COMPANY

AIDED AND CASUALTIES					RESP.	EXTINGUISH- MENT	INVEST- IGATION	STRUCTURE	AREA FIRE ORIGIN													
CIVILIANS																						
EVACUATED	FIRST AID	INJURED	KILLED	UNFIREKILLED INJURED	ENG. TO MARINE	LADDERS CODE	NO SPRINK- LERS OTHER STANDPIPE LINES USED	EXPLOSIVE CONTAIN.	CAUSE	FIRE MARSHAL	CONSTRUCT.	USE	STATUS DAMAGE TO BUILDING CONJUNCT TO FLOOR CODE	FLOOR CODE	AREA OF FIRE CODE	OCCUPANCY	MANNER OF EXTINCTION					
00	00	00	00	00	03	2	5	00	01	1	62			1	15	1	1	0	58	21	50	00

LEFT IN CHARGE

OPERATIONS

L-1 Made examination of walls and ceiling and ventilated as necessary.

1

G-83

FOR FIRE RECORDS USE ONLY		DATE AND TIME ALARM RECEIVED				DURATION OF INCIDENT		HOW REPORTED		HIGHEST ALARM		LOCATION		REPORT					
TYPE REPORT		MONTH	DAY	YEAR	CD. NO.	HOUR	MINUTE	HOURS	MINUTES	INITIAL ALARM	HIGHEST ALARM	BOROUGH	BOX NUMBER	ADMIN. COMPANY	BLOCK NUMBER	REPORT NUMBER	FILING BATTALION	BATCH NUMBER	
1		02	13	78	1	2018	00	45	4	1	0	1	8089	5	006	0113	0071	01	531

AIDED AND CASUALTIES				RESP.	EXTINGUISHMENT	INVESTIGATION	STRUCTURE	AREA FIRE ORIGIN													
CIVILIANS																					
EVAQUATED	FIRST AID	INJURED	KILLED	UNIFORMED INJURED	ENG. CO. MACHINE	LADDERS CODE	NO SPRINKLERS OPEN	STANDPIPE LINES USED	CAUSE	FIRE MARSHAL	CONSTRUCT	USE	STATUS	DAMAGE TO LOG	DAMAGE TO FLOOR	ROOM OR AREA CODE	OCCUPANCY	NUMBER OF EXTENSION			
00	00	00	00	00	03	2	5	00	01	1	62		1	15	1	1	0	94	15	50	00

ADDRESS 2 World Trade Ctr Man Port of N.Y. Authority 107
 NUMBER STREET BOROUGH NAME OF OCCUPANT ROOM/APT. NO.
 BUILDING 110 200 x200 Sgt. Wescott POLYA Police
 (Second Cord) STORIES AREA LEFT IN CHARGE

10	16122	26129	35136	42143	49150	56
5	006	0110	7	001	0	10

COMPANIES
 TYPE NO. SECT. PTS. 104 70171 77110 16122 26129 35

OPERATIONS

Responded to manual alarm box 8089-

Upon arrival was informed of fire 107th fl. Ordered investigation and found fire in rubbish & maint. materials therein. Batt. 1 ordered additional Battalion Chief to respond on report of definite fire. Batt.4 responded.

R.6- Rolled up lengths to the fire floor extinguished remaining fire

L.1- Search, examination of fire floor & floor above. Opened walls for examination. Overhauled burned materials.

Bn.4- Ordered to supervise operations on the fire floor.

Div. 1- Responded to scene, and assumed command.

Note: Batt.1 transmitted 10-41 Code 2 & requested F.M. to respond.

B.C. James J. McKenna 2020 Matthew J. Farrell PAGE
 DIV. 1 OF 1
 TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

FOR FIRE RECORDS USE ONLY		DATE AND TIME ALARM RECEIVED				DURATION OF INCIDENT		LOCATION				REPORT			
TYPE REPORT	MONTH	DAY	YEAR	CO. NO.	HOUR	MINUTE	HOURS	MINUTES	HOW REPORTED	INITIAL ALARM	HIGHEST ALARM	BOROUGH	ALARM	INCIDENT	REPORT
1	01	18	79	1	2353	00 45	4	1	0	1	8047	5	006	0113	0164

AIDED AND CASUALTIES				RESP.	EXTINGUISHMENT	INVESTIGATION	STRUCTURE	AREA FIRE ORIGIN	
CIVILIANS									
EVAQUATED	FIRST AID	INJURED	KILLED	UNIFORMED INJURED	ENG. SO. MACHINE	LADDER CODE	NO. STINK. LINES OPEN	STANDPIPE LINES USED	FLOOR NUMBER
00	00	00	00	00	03	2	5	00	01

ADDRESS 2 World Trade Center Man.
 NUMBER 110 STREET 150x150 BOROUGH
 BUILDING 110 AREA
 (Second Card) STORIES

N.Y. State
 NAME OF OCCUPANT Don Bailly P.A. Police ROOM/APT. NO.
 LEFT IN CHARGE

COMPANIES		TYPE NO. SECT. PTS.		TYPE NO. SECT. PTS.		TYPE NO. SECT. PTS.		TYPE NO. SECT. PTS.	
5	006	0	10	5	007	0	10	7	001
0	10	7	008	0	10				

OPERATIONS

Upon arrival was told of fire on the 6th floor, operations as follows.
 Ladder 1 made necessary investigation, located the fire, vented, overhauled and searched.
 Ladder 8 searched and vented floor above, overhauled.
 Engine 6 stretched a line from standpipe and extinguished the fire.
 Engine 6 washed down.
 Batt. 2 on the scene.
 Div. 1 on the scene.

Joseph A. Hingerton 2355 1 01
 TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL
 DIV. PAGE 1 OF 1

ADMINISTRATIVE COMPANY

OF 4-11-67

TYPE REPORT		INCIDENT LOCATION		DATE AND TIME		ALARM RECEIVED		INCIDENT DURATION		BOX LOCATION		REPORT		COS. RESP.							
COMMUNITY BOARD	ADMIN. COMPANY	BLOCK NUMBER	MONTH	DAY	YEAR	HOUR	MINUTE	MINUTES	HOURS	HIGHEST ALARM	BOX NUMBER	REPORT NUMBER	REPORT DATE	ENGINE NUMBER	LADDER						
1	01	5	006	0113	04	19	80	1406	02	30	1	1	2	1	1	8086	0156	01	531	07	3

AIDED AND CASUALTIES		EXTINGUISHMENT		IGNITION		STRUCTURE		AREA FIRE ORIGIN		FIRE EXTENSION		SPECIAL USE														
EVAQUATED	FIRST AID	KILLED	INJURED	UNINJURED	CODE	SPRINKLER	STANDARD	STAGE	EQUIP. INVOLVED	HEAT FORM	MATERIAL TYPE	CONSTRUCT.	STATUS	BROS. DAMAGE	FLOOR CODE	AREA CODE	OCCUPANCY	MANNER OF	OCCUPANTS	WITHIN BLDG.	NO. BROS.	SMOKE DETECTORS	1	2	3	
500	00	00	00	5	00	01	3	98	30	40	50	31	15	1	1	1106	54	59	00	01	0	2				

STREET NAME		BUILDING		AREA	
NUMBER	TYPE	STREET	NUMBER	AREA	LEFT IN CHARGE
1	WORLD TRADE	110	212	212 x 212	Mr. John Barrett, F.B.D.

NAME OF OCCUPANT		ROOM, APT. NO.	
NAME	ROOM, APT. NO.	MAKE	MODEL
Port Authority N.Y. & N.J.	126	130	130

EQUIPMENT INVOLVED IN IGNITION		YR.		MAKE		MODEL		SIN /		POWER				
UNIT	PTS.	YR.	MAKE	MODEL	SIN /	POWER	UNIT	PTS.	YR.	MAKE	MODEL			
5	006	20	5	007	08	5	010	02	7	001	20	7	008	20

OPERATIONS

Upon arrival Batt. 1 received report of activated smoke detector in return air duct 106 floor Tower #1.

Batt. 1 subsequently received reports of heavy smoke on floor 106, light smoke on floor 109, heavy odor of smoke in stairways "A" and "B" leaving only stairway "C" as a clear exit

B.C. James J. McKenna B.N. 1409 DIV. 1 OF 5 PAGE
 TYPE FULL NAME TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

24A (1/80)

REPORT - ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT				DATE AND TIME ALARM RECEIVED				BOX LOCATION		IGNITION				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION	
MONTH	DAY	YEAR	TIME	BOX NO.	BUILDING NO.	FLOOR	STAGE	MATERIAL TYPE	MATERIAL FORM	MATERIAL TYPE	MATERIAL FORM	USE	STATUS	ROOM	CONT'S	FLOOR CODE	RAJANA CODE	OCCUPANCY	
6	04	19	80	1405	11	8085	01	3	98	30	40	50	1	15	1	1	106	54	59

NUMBER		STREET NAME		IF MOBILE PROPERTY	
VEHICLE	TYPE	STREET NAME	STREET NAME	ITEM	STATE
1	1	WORLD TRADE	CENTRE		

UNIT	PTS.	195	201	207	213	219	225	231	237
5	006	20	5	007	15	5	010	12	7
001	20	7	008	20					

OPERATIONS

from the 107th. floor restaurant. There is an open access stair from 106, opening into 107th. floor restaurant dining area.

At this point fire had not been located. On basis of above, Batt. 1 ordered approx. 300 persons evacuated from the " Windows on the world restaurant " on the 107th. floor via stairway " C " which was clear of smoke. Later stairway " B " was clear of smoke and was made available for evacuation.

On Arrival of D.C. Rossi, Div. 1 Batt. 1 advised Him of above and recommended a 2nd. alarm be transmitted, as fire had not been located. Restaurant was being evacuated and all units were now assigned to work. D.C. Rossi transmitted a 2nd. alarm and requested 2 additional Batt. ch. Operations of Cos. are as follows:

Eng. 6 Masks, rolledups, responded to fire floor via freight elevator to 104 fl. via stairway to 106 fl. Mat Lad. 1 who had located fire on 106 fl. Hooked 4 lengths of 2 1/2 hose to standpipe, operated on fire.

B.C. James J. McKenna BN. 1409 D.C. DIV. 1 PAGE 3 OF 4

James J. McKenna 1409

TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL

(1) White Copy: Fire Records (2) Canary Copy: Battalion (3) Pink Copy: Administrative Company (4) Colored Copy: Battalion

[illegible]

OPERATIONS

Operations of Cos. continued:

Lad. 1 to 106 floor to investigate activated smoke alarm, searched, and located fire, checked floor above for extension, and overhauled.

Eng. 7 Responded to 109 fl. to investigate a sprinkler alarm, found no sprinkler flow, and light smoke condition.

Lad. 8 Responded to 109 fl. with Eng. 7.

Eng. 7, and Lad. 8 then reported to 108, 107, and 106fls. made search and assisted in evacuation of Restaurant.

Eng. 10, Responded to 106 fl. to assist and relieve Eng. 6 on the line.
2nd. alarm units reported to comand post, stood fast then orded to take
up by DAC Glassee.

Rescue 1 responded on 2nd. alarm, reported to 107 fl. assisted in evacuation of restaurant, then to 106 fl. to assist Lad. 1, then ordered to take up.

James J. McKenna		1409		3 OF 5	
TYPE FULL NAME		TIME OF ARRIVAL		TYPE FULL NAME	

(1) White Copy: Fire Records (2) Canary Copy: Barratien (3) Pink Copy: Administrative Company (4) Goldenrod Copy: Referral

SEP-24A (1/80)

REPORT - ADDITIONAL DATA

STRUCTURAL FIRE TRANSPORTATION FIRE NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT				DATE AND TIME ALARM RECEIVED				BOX LOCATION				IGNITION				STRUCTURE				AREA OF ORIGIN				FIRE EXTENSION	
MONTH	DAY	YEAR	TIME	ROOM	FLOOR	BOX NO.	SECTION NO.	STAGE	GROUP INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	USE	STATUS	BACK DAMPER	CURTAIN DAMPER	FLYING CODE	RAMPAGE CODE	OCCUPANCY	MARKER OF	OCCUPANCIES				
6	04	19	30	14	05	1	8085	01	3	28	30	40	50	1	15	1	1	1	06	54	59	00	01		

NUMBER	TYPE	MAKE	MODEL	YEAR	IF MOBILE PROPERTY
1	WORLD TRADE				

UNIT	MAKE	MODEL	YEAR	IF MOBILE PROPERTY
1				

OPERATIONS

Operations of Cos. continued:

Chief Officers on scene:

DAC Glasse, City wide command Chief.

D.C. Rossi Dept. chief 1st. Div.

B.C. James J. McKenna Chief 1st. Batt.

B.C. Louis Pike Chief 2nd. Batt.

B.C. John T. Carroll Chief 4th. Batt.

B.C. Edward J. Miller Chief 6th. Batt.

Field Comm. unit, Lieut. Soranno on scene.

Fire Patrol #2 on scene.

W.T.C. fire safety director Mr. John Barrett on scene.

P.A. Patrolmen Cemonuk, and Oorbeek on Duty at Command Post.

Building Mechanical System failures noted:

#1 Sprinkler alarm received for unsprinklerd 109 Fl.

#2 Return air duct smoke detectors did not shut fans down.

#3 Heat fused link shut damper in purge system.

#4 107 floor standpipe phone unreliable due to feed back from radios.

S.C. James J. McKenna B.N. D.C. DIV. 15

James J. McKenna 1409

TYPE FULL NAME TIME OF ARRIVAL TYPE FULL NAME TIME OF ARRIVAL

(1) White Copy: Fire Records (2) Copy: Station (3) Pink Copy: Administrative Company (4) Green Copy: Referral

REPORT - ADDITIONAL DATA																																
STRUCTURAL FIRE TRANSPORTATION FIRE NON STRUCTURAL FIRE OR EMERGENCY																																
DATE AND TIME		BOX		LOCATION		IGNITION		STRUCTURE		AREA OF ORIGIN		FIRE																				
REPORT	ALARM RECEIVED	LOCATION	LOCATION	LOCATION	LOCATION	LOCATION	LOCATION	LOCATION	LOCATION	LOCATION	LOCATION	LOCATION	LOCATION																			
6-14-19-20-1406	1805	01	2	3	4	5	6	7	8	9	10	11	12																			
<table border="1"> <tr> <th>NUMBER</th> <th>STREET NAME</th> <th>IF MOBILE PROPERTY</th> </tr> <tr> <td>1</td> <td>WORLD TRADE</td> <td></td> </tr> </table>															NUMBER	STREET NAME	IF MOBILE PROPERTY	1	WORLD TRADE													
NUMBER	STREET NAME	IF MOBILE PROPERTY																														
1	WORLD TRADE																															
<table border="1"> <tr> <th>MAKE</th> <th>MODEL</th> <th>SERIAL NO.</th> <th>LICENSE</th> <th>STATE</th> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>															MAKE	MODEL	SERIAL NO.	LICENSE	STATE													
MAKE	MODEL	SERIAL NO.	LICENSE	STATE																												
<table border="1"> <tr> <th>UNIT</th> <th>190</th> <th>201</th> <th>207</th> <th>213</th> <th>219</th> <th>225</th> <th>231</th> <th>236</th> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>															UNIT	190	201	207	213	219	225	231	236									
UNIT	190	201	207	213	219	225	231	236																								
OPERATIONS																																
<p>High Rise Report prepared and forwarded to Div. of Fire Prevention.</p> <p>Follow up on Mechanical and Electrical malfunctions being made with Port Authority.</p> <p>See copy of High Rise report for details.</p>																																
<p>B.C. <i>James J. McKenna</i> D.C. <i>1409</i></p> <p>JAMES J. McKenna 1409</p>																																
<table border="1"> <tr> <th>TYPE FULL NAME</th> <th>TIME OF ARRIVAL</th> <th>TYPE FULL NAME</th> <th>TIME OF ARRIVAL</th> </tr> <tr> <td></td> <td></td> <td></td> <td></td> </tr> </table>															TYPE FULL NAME	TIME OF ARRIVAL	TYPE FULL NAME	TIME OF ARRIVAL														
TYPE FULL NAME	TIME OF ARRIVAL	TYPE FULL NAME	TIME OF ARRIVAL																													
<p>(1) White Copy: Fac Records (2) Canvas Copy: Battalion (3) Pink Copy: Administrative Company (4) Goldenrod Copy: Release</p>																																

BF-24 (1/80)

КЕРУКИ - СИМУЛЯТОР ЛИНЕ

TYPE REPORT				INCIDENT LOCATION				DATE AND TIME ALARM RECEIVED				INCIDENT DURATION				BOX LOCATION				REPORT				COS. RESP.																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																											
COMMUNITY BOARD				ADMIT. COMPANY				MONTH				DAY				YEAR				HOUR				MINUTE				MINUTES				HIGHEST ALARM				BOOTH				DOY. NUMBER				REPORT NUMBER				FILING NUMBER				BATTALION				BADGE NUMBER				ENG. SQ. NUMBER				LADDER																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																			
1	01	5	006	0113	11	04	'80	0123	00	15	6	1	0	1	8093	0026	01	531	03	12																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																															
EVACUATED				FIRST AND INJURED				KILLED				UNFATAL				CODE				SPRINKLER				STANDARD				YEAR STAGE				EQUIP. INVOLVED				NEAT FORM				MATERIAL TYPE				MATERIAL FORM				CONSTRUCT				USE				STATUS				BLOS. DAMAGE				FLOOR CODE				RM AREA CODE				OCCUPANCY				MANNER OF				OCCUPANTS				NO. BLOS.				SMOK. DETECTORS				SPECIAL USE																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
46				56				61				66				71				76				81				86				91				96				101				106				111				116				121				126				131				136				141				146				151				156				161				166				171				176				181				186				191				196				201				206				211				216				221				226				231				236				241				246				251				256				261				266				271				276				281				286				291				296				301				306				311				316				321				326				331				336				341				346				351				356				361				366				371				376				381				386				391				396				401				406				411				416				421				426				431				436				441				446				451				456				461				466				471				476				481				486				491				496				501				506				511				516				521				526				531				536				541				546				551				556				561				566				571				576				581				586				591				596				601				606				611				616				621				626				631				636				641				646				651				656				661				666				671				676				681				686				691				696				701				706				711				716				721				726				731				736				741				746				751				756				761				766				771				776				781				786				791				796				801				806				811				816				821				826				831				836				841				846				851				856				861				866				871				876				881				886				891				896				901				906				911				916				921				926				931				936				941				946				951				956				961				966				971				976				981				986				991				996				1001				1006				1011				1016				1021				1026				1031				1036				1041				1046				1051				1056				1061				1066				1071				1076				1081				1086				1091				1096				1101				1106				1111				1116				1121				1126				1131				1136				1141				1146				1151				1156				1161				1166				1171				1176				1181				1186				1191				1196				1201				1206				1211				1216				1221				1226				1231				1236				1241				1246				1251				1256				1261				1266				1271				1276				1281				1286				1291				1296				1301				1306				1311				1316				1321				1326				1331				1336				1341				1346				1351			

OPERATIONS

Responded to alarm box 8093. Upon arrival found cause to be for a rubbish fire at the above location. Eng. 10- Stretched standpipe line, extinguished fire, washed down. Lad. 1- Searched, found fire, vented, checked for extension, overhauled.

B.C. James G. McKenna 1 D.C. 8N 0126 James J. McKenna

TYPE FULL NAME TIME OF ARRIVAL

TYPE FULL NAME TIME OF ARRIVAL

PAGE 1 OF 1

PAGE OF

REPORT — STRUCTURAL FIRE

BF-24 (11/00)

TYPE REPORT		INCIDENT LOCATION		DATE AND TIME ALARM RECEIVED		INCIDENT DURATION		BOX LOCATION		REPORT		COS. RESP.								
ADMIN. COMPANY	INCIDENT NUMBER	MONTH	DAY	YEAR	HOUR	MINUTE	MINUTES	HIGHEST ALARM	BOX NUMBER	REPORT NUMBER	FILE NUMBER	ENGINE NAME	LOOKUP							
1	01	5	006	0113	04	47	81	0918	01	30	7	1	2	1	8084	0145	01	196	09	13

AIDED AND CASUALTIES		EXTINGUISHMENT		IGNITION		STRUCTURE		AREA FIRE ORIGIN		FIRE EXTENSION		SPECIAL USE								
CIVILIANS	UNFURNISHED	SPRINKLER	STAMPED	EQUIP. INVOLVED	MATERIAL TYPE	FACTOR	USE	STATUS	CONT. DAMAGE	FLOOR CODE	MANAGER	OCCUPANCY	NO. BLOBS	SMOKE DETECTORS	1	2	3			
99	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00

STREET NAME		TYPE		BUILDING		AREA		LEFT IN CHARGE	
NUMBER	STREET NAME	TYPE	BUILDING	AREA	LEFT IN CHARGE	AREA	LEFT IN CHARGE	AREA	LEFT IN CHARGE
1	World Trade Center	104	106	104	106	104	106	104	106

Port Authority N.Y., N.J.

Bill Sarnelli P.S.D.

EQUIPMENT INVOLVED IN IGNITION		HVAC Unit												
UNIT	PTS	ITEM	MAKE											
5	010	10	5	006	10	5	007	10	7	001	10	7	015	10

OPERATIONS														
UNIT	PTS	ITEM	MAKE											
5	010	10	5	006	10	5	007	10	7	001	10	7	015	10

YR MAKE MODEL S/N POWER

188 194 200 206 212 217

Upon arrival at box 8084, was informed by PA police of fire in MER room on the 7th floor with smoke condition on 7 thru 11 floors, transmitted 2nd alarm.

Eng. 10 Masks, rolledups, responded to 7th floor, hooked up to standpipe, extinguished fire in air condition unit in MER room.

Eng. 6 Masks, rolledups, responded to 7th floor, stood fast.

Eng. 7 Masks, rolledups, responded to 7th floor, stood fast.

Lad. 1 Masks, responded to 7th floor, V.S.O. air condition unit, checked for extension in AO duct.

Lad. 15 Masks, Vented and searched floors 8 thru 13, checked for extension in AO duct.

Lad. 6 Masks, under direction of BG Moffet, Rm. 4 searched floors 13 thru 18.

B.C. _____ BN. _____ D.C. _____ DIV. _____ PAGE 1 of 1

TIME OF ARRIVAL _____ TYPE FULL NAME _____

ADMINISTRATIVE COMPANY

REPORT — Additional Data

Structural Fire, Transportation Fire, Non-Structural Fire or Emergency

FOR FIRE RECORDS USE ONLY				DATE AND TIME ALARM RECEIVED				ALARM	
TYPE REPORT				MONTH				DAY	
YEAR				CD. NO.				BOX NUMBER	
HOUR				MINUTE				BOROUGH	
1				04				17	
8				2				0918	
8				8084					

COMPANY	NO.	SECT.	PTS.
1	1	1	1
2	2	2	2
3	3	3	3
4	4	4	4
5	5	5	5
6	6	6	6
7	7	7	7
8	8	8	8
9	9	9	9
10	10	10	10
11	11	11	11
12	12	12	12
13	13	13	13
14	14	14	14
15	15	15	15
16	16	16	16
17	17	17	17
18	18	18	18
19	19	19	19
20	20	20	20
21	21	21	21
22	22	22	22
23	23	23	23
24	24	24	24
25	25	25	25
26	26	26	26
27	27	27	27
28	28	28	28
29	29	29	29
30	30	30	30
31	31	31	31
32	32	32	32
33	33	33	33
34	34	34	34
35	35	35	35
36	36	36	36
37	37	37	37
38	38	38	38
39	39	39	39
40	40	40	40
41	41	41	41
42	42	42	42
43	43	43	43
44	44	44	44
45	45	45	45
46	46	46	46
47	47	47	47
48	48	48	48
49	49	49	49
50	50	50	50
51	51	51	51
52	52	52	52
53	53	53	53
54	54	54	54
55	55	55	55
56	56	56	56
57	57	57	57
58	58	58	58
59	59	59	59
60	60	60	60
61	61	61	61
62	62	62	62
63	63	63	63
64	64	64	64
65	65	65	65
66	66	66	66
67	67	67	67
68	68	68	68
69	69	69	69
70	70	70	70
71	71	71	71
72	72	72	72
73	73	73	73
74	74	74	74
75	75	75	75
76	76	76	76
77	77	77	77
78	78	78	78
79	79	79	79
80	80	80	80
81	81	81	81
82	82	82	82
83	83	83	83
84	84	84	84
85	85	85	85
86	86	86	86
87	87	87	87
88	88	88	88
89	89	89	89
90	90	90	90
91	91	91	91
92	92	92	92
93	93	93	93
94	94	94	94
95	95	95	95
96	96	96	96
97	97	97	97
98	98	98	98
99	99	99	99
100	100	100	100

OPERATIONS
continued

Rescue 1 Masks, searched floors 18 thru 23.

2nd. alarm units:

Engs. 24, 15, 55, 9, 241, and Marine 1 were ordered to stand fast at there assigned locations.

Div. 1, D.C. DeCaprio responded and supervised operations

Chiefs Gormley, Bishop, and Farrell also on scene.

P.A. personell reported evacuation of aprox, 1,500 persons from floors 9 thru 23.

F.C. unit on scene

F.P. 2 on scene.

TIMES

Box	0918
2-2	0928
U/C	0959



Peter Costello

0920

Angelo DeCaprio

PAGE	2	OF	2
------	---	----	---

TYPE FULL NAME

TIME OF ARRIVAL

TYPE FULL NAME

TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

ADMINISTRATIVE COMPANY

REPORT - STRUCTURAL FIRE

BF 24 (11/80)

TYPE REPORT		INCIDENT LOCATION		DATE AND TIME		ALARM RECEIVED		INCIDENT DURATION		BOX LOCATION		REPORT		CDS. RESP.							
COMMUNITY BOARD	ADMIN COMPANY	BLOCK NUMBER	MONTH	DAY	YEAR	HOUR	MINUTE	HOURS	MINUTES	HIGH RISE ALARM	BOX NUMBER	REPORT NUMBER	ENGINE NUMBER	LADDER							
1	01	5	010	0113	11	10	02	20	58	00	25	17	1	0	1	8087	0086	01	150	03	2

AUXILIARY AND CASUALTIES		EXTINGUISHMENT		IGNITION		STRUCTURE		AREA		FIRE ORIGIN		FIRE EXTENSION		SPECIAL USE												
EVACUATED	FIRST AID	INJURED	DEATH	SPRINKLER	SPRINKLER NO. OPEN	SPRINKLER LINES USED	TEAM STAGE	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	CONSTRUCT	STATUS	LOG DAMAGE	FLOOR COOK	ROOM COOK	APRIL COOK	OCCUPANCY	MANNER OF OCCUPANCY	NO. OCCUPANTS	NO. RUGS	SMOKE DETECTORS	1	2	3		
00	00	00	00	5	00	01	3	98	40	60	75	31	1	15	1	0	99	14	47	00	00	0	0	0	0	0

PORT AUTHORITY		STREET NAME		TYPE		BUILDING		AREA	
NUMBER	STREET	STREET NAME	TYPE	ROOM, APT. NO.	MAKE	MODEL	POWER	151	165
2	World Trade Center	126	130	99	200 X 200	117	167	151	165

EQUIPMENT INVOLVED IN IGNITION		OPERATIONS	
UNIT	PTS	ITEM	TIME
5	010	057	001
0	057	001	05
0	057	001	05

Responded to smoke condition at 11th B-2 level. Building personnel reported heavy smoke condition. found fire in open shaft.

Engine 10- stroked line from standpipe, and extinguished fire.
Ladder 1- searched , vented checked for extension, overhauled.

B.C. Joseph L. Barrasato 1st D.C. 20:59 DIV. 1 OF 1
Joseph L. Barrasato TYPE FULL NAME TIME OF ARRIVAL

ADMINISTRATIVE COMPANY

REPORT — STRUCTURAL FIRE

BF-24 (1/80) 175M 608551 (83)

TYPE REPORT		INCIDENT LOCATION		DATE AND TIME		ALARM RECEIVED		INCIDENT DURATION		BOX LOCATION		REPORT		COS. RESP.				
COMMUNITY	ADMIN.	BLOCK	COMPANY	MONTH	DAY	YEAR	HOUR	MINUTE	MINUTES	HOW REPORTED	BOX NUMBER	REPORT NUMBER	ENGINE NUMBER	ENGINE	RESP.			
1	01	05	010	01	04	84	16	25	00	20	1	0	1	8084	01	572	03	2

AIDED AND CASUALTIES		EXTINGUISHMENT		IGNITION		STRUCTURE		AREA FIRE ORIGIN		FIRE EXTENSION		SPECIAL USE	
EVALUATED	FIRST AID	INJURED	KILLED	UNIFORMED	CODE	SPRINKLER	STANDPIPE	TRIM STAGE	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	CONSTRUCT	STATUS
00	00	00	00	00	01	3	00	40	60	75	00	1	15

EQUIPMENT INVOLVED IN IGNITION		STREET NAME		BUILDING		AREA	
UNIT	PTS	ITEM	NUMBER	STREET NAME	BUILDING	AREA	LEFT IN CHARGE
5	010	05	7	010	05	200x200	PSD Noroia

OPERATIONS		TYPE FULL NAME		TIME OF ARRIVAL	
UNIT	PTS	ITEM	NUMBER	STREET NAME	BUILDING
5	010	05	7	010	05

ADMINISTRATIVE COMPANY

OPERATIONS

Upon arrival at box was informed of fire in service elevator room on the 15th floor. Engine 10 extinguished fire. Ladder 10 checked for extension and overhauled. one sprinkler head was released.

BC Kenneth P. Markgraf BN 1628 DC 1 DIV. 101 PAGE 1 OF 1

TYPE FULL NAME TIME OF ARRIVAL

REPORT — STRUCTURAL FIRE

BF 741160) 175M 000551 (63)

TYPE REPORT		INCIDENT LOCATION		DATE AND TIME		ALARM RECEIVED		INCIDENT DURATION		BOX LOCATION		REPORT		CIS. RESP.		
QUANTITY	GRADE	ADMIN. COMPANY	BLOCK NUMBER	MONTH	DAY	YEAR	HOUR	MINUTE	MINUTES	HIGHEST ALARM	BOX NUMBER	BOX LOCATION	REPORT	ENGINE NUMBER	LADDER	
1	01	5	010	0113	12-28-84	1435	00:25	6	1	1	1	0007	0269	01	150	01

A DED AND CASUALTIES		EXTINGUISHMENT		IGNITION		STRUCTURE		AREA FIRE ORIGIN		FIRE EXTENSION		SPECIAL USE	
EVAQUATED	INJURED	KILLED	UNINJURED	CODE	SPRINKLER	SPRINKLER	SPRINKLER	SPRINKLER	SPRINKLER	SPRINKLER	SPRINKLER	SPRINKLER	SPRINKLER
00	00	00	00	00	00	00	00	00	00	00	00	00	00

STREET NAME		TYPE		BUILDING		AREA	
NUMBER	STREET NAME	TYPE	STREET NAME	BUILDING	AREA	STREET NAME	AREA
2	WORLD TRADE CENTER	1	1	110	200' x 200'	110	200' x 200'

NAME OF OCCUPANT		ROOM, APT NO.		EQUIPMENT INVOLVED IN IGNITION		YR		MAKE		MODEL		S/N		POWER	
NAME OF OCCUPANT	ROOM, APT NO.	EQUIPMENT INVOLVED IN IGNITION	YR	MAKE	MODEL	S/N	POWER								
IRV SMALL, Fire Safety Director	110	200' x 200'	110	200' x 200'	110	200' x 200'	110								

OPERATIONS

Upon arrival found fire in the freight elevator lobby, 23rd floor.
 Units operated as follows:
 Engine 10 stretched line from the standpipe and operated line.
 Ladder 10 V.B.S. performed necessary overhaul, used can on the fire.

COBIL 10-41-CODE 1 Transmitted.

B.C. Joseph P. DiNardo BN 1440 D.C. hrs DIV 1 OF 1

JO. EPH L. BARRACATO TYPE FULL NAME TIME OF ARRIVAL

REPORT - STRUCTURAL FIRE

BF-24 (1/80) 173M 606551 (83)

TYPE REPORT		INCIDENT LOCATION		DATE AND TIME ALARM RECEIVED		INCIDENT DURATION		BOX LOCATION		REPORT		COS. RESP.	
COMMUNITY	BRAND	COMPANY	BLOCK	MONTH	DAY	YEAR	MINUTE	HOURS	MINUTES	INITIAL ALARM	BOMBING	REPORT NUMBER	REPORT
1	01	01	01	01	01	01	01	01	01	01	01	01	01
AIDED AND CASUALTIES		EXTINGUISHMENT		IGNITION		STRUCTURE		FIRE EXTENSION		SPECIAL USE			
EVAQUATED	FIRST AID	INJURED	KILLED	UNINJURED	CODE	SPRINKLER	STANDARD	STAGE	EQUIP INVOLVED	HEAT FORM	MATERIAL TYPE	CONSTRUCT	USE
STATUS		DAMAGE		FLOOR CODE		OCCUPANCY		NO. BLOCS		SMOK DETECTORS		SPECIAL USE	
STATUS		DAMAGE		FLOOR CODE		OCCUPANCY		NO. BLOCS		SMOK DETECTORS		SPECIAL USE	
STATUS		DAMAGE		FLOOR CODE		OCCUPANCY		NO. BLOCS		SMOK DETECTORS		SPECIAL USE	

NAME OF OCCUPANT		ROOM, APT NO.		YR		MAKE		MODEL		SIN		POWER	
UNIT	PTS.	ITEM	194	200	212	217	217	217	217	217	217	217	217
5	040	05	7	010	05	7	015	05	7	015	05	7	015
OPERATIONS		STREET NAME		TYPE		BUILDING		AREA		LEFT IN CHARGE			
OPERATIONS		STREET NAME		TYPE		BUILDING		AREA		LEFT IN CHARGE			

Upon arrival, advised by FSD that there was a dumpster fire in the hall on the 38th floor, extinguished prior to FD arrival. Once informed that all fire had been extinguished permission was granted to building personnel to clear floor area of smoke by use of HVAC system. A 10-41-1 was transmitted from this box. Operations as follows: B4 set up lobby command post, monitored hard wire communications E 10 donned masks, stretched line from stamplie and completed operations on fire floor. L 10 " " " made search of 38th floor, overhauled as needed. L 15 " " " made search of 39th, 40th, 41st floors, all found satisfactory. All other 10-76 units stood fast at staging area. 10-41-1 transmitted.

BC: *Arthur V. Meadows* 4 BN. DC. 1423
 TYPE FULL NAME: *Arthur V Meadows* TIME OF ARRIVAL: 1423
 TYPE FULL NAME: *Thomas Kilker* TIME OF ARRIVAL: 1423
 PAGE 1 OF 1

[illegible]

Responded to EES alarm, report of smoke in building. As units were responding informed by dispatcher of numerous reports of smoke from 30 to 55th floor. After searching found cause of smoke to be coming from NER fl room on 55th floor. Fire was caused by welding operation resultant heat caused insulating to ignite inside of fan room. Units operated viz.

Engine Co. 10 - Stretched line from standpipe on 55th floor and extinguished fire.
Ladder Co. 10 - Searched, overhauled, checked for extension.
Ladder Co. 1 - Searched, checked for extension.
Ladder Co. 2 - Searched, warned command post.

Engine Co. 8 - Seaford & Market St.
Carpenter - Quetzona
ON b.c. 1st
17:51
ACTUAL NAME
TIME OF ARRIVAL

PAGE 1 OF 1

G-101

B-24

INCIDENT LOCATION				DATE AND TIME				INCIDENT DURATION				REPORT				COMPARISON			
INCIDENT LOCATION				DATE AND TIME				INCIDENT DURATION				REPORT				COMPARISON			
AREA	STREET	BOX	LOCATION	YEAR	MONTH	DAY	MINUTE	HOURS	MINUTES	SECONDS	REPORT	COMPARISON	REPORT	COMPARISON					
101	5010	04	28	88	04	28	00	00	00	00	00	00	00	00					
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00					

AIDED AND CASUALTIES				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION/DAMAGES				DETECTOR			
AIDED AND CASUALTIES				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION/DAMAGES				DETECTOR			
ENCL	FIRED	INJURED	DEATH	CAUSE	TYPE	LOCATION	STATUS	USE	CONSTRUCTION	REASON	ORIGIN	EXTENSION	DAMAGES	DETECTOR									
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00									
00	00	00	00	00	00	00	00	00	00	00	00	00	00	00									

STREET NAME				FLOOR				EQUIPMENT INVOLVED IN IGNITION				EQUIPMENT INVOLVED IN EXTINCTION				EQUIPMENT INVOLVED IN DAMAGE			
STREET NAME				FLOOR				EQUIPMENT INVOLVED IN IGNITION				EQUIPMENT INVOLVED IN EXTINCTION				EQUIPMENT INVOLVED IN DAMAGE			
STREET	NUMBER	FLOOR	TYPE	EQUIPMENT	TYPE	LOCATION	EQUIPMENT	TYPE	LOCATION	EQUIPMENT	TYPE	LOCATION							
World Trade Center	110	11	11	11	11	11	11	11	11	11	11	11							
World Trade Center	110	11	11	11	11	11	11	11	11	11	11	11							

OPERATIONS

responded to WTC Complex and upon arrival found fire in 11WC, 27 level in locker room at 11th floor. Fire confined to lockers Nos. 131-132-133-151-152-153-154. Co's operated via stretched 2 1/2" line to fire and extinguished all fire, washed down, and then stood fast. 10 assisted E7 in stretching line and then stood fast. 10 found fire, performed necessary VES, forced entry into locker, and secondary searches in fire room negative, overhauled, and then up. 15 checked 21. above for attention (negative), also checked adjacent rooms, negative, and then up.

Joseph L. Baradato

TYPE REPORT				DATE AND TIME				INCIDENT				BOX				REPORT				COMPANIES				HAZ				SPECIAL															
ADDITIONAL LOCATION				ALARM RECEIVED				DURATION				LOCATION				HIGHEST ALARM				REPORT NUMBER				FLOOR CODE				ACCOMPLISH				RESPONDING				MATERIAL				USER			
1 01 5 010 12 17 89 1313				01:00 81 1 7 1 8084				1 7 1 8084				1 7 1 8084				1 7 1 8084				1 7 1 8084				1 7 1 8084				1 7 1 8084				1 7 1 8084				1 7 1 8084				1 7 1 8084			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE				DETECTORS			
FACED				MILITARY				CIVILIANS				AIDED AND CASUALTIES				EXTIN				IGNITION				STRUCTURE				FIRE ORIGIN				FIRE EXTENSION				DAMAGE							

REPORT - ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

DATE AND TIME ALARM RECEIVED				BOX LOCATION		IGNITION SOURCE				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION			
TYPE	MONTH	DAY	YEAR	HOUR	MINUTE	BOX NUMBER	BOX LETTER	FLOOR	WALL	CEILING	DOOR	WIND	WIND DIRECTION	FLOOR CODE	AREA CODE	MANAGER	REMOVED REPORT
6	12	67	89	13	13	1	8054	0230									

NUMBER - (INCL. HYDRANT)				STREET NAME				TYPE	
1	1	1	1	WTC					

DAMAGE				DETECTORS			
SMOKE	FLAME	WATER	WIND	SMOKE	FLAME	WATER	WIND

OCCUPANT (Driver)				ROOM/APT.			

IF MOBILE PROPERTY				GUIDING			
TYPE	YR.	MAKE	MODEL	AREA	WIDTH	LENGTH	STATE

UNIT	PTS.	243	245	255	261	263	273	274
7	008	10						

OPERATIONS

L-8- search floors 9-40 results negative and then up.
 B-6- established operations post on 6th floor., then went to 7th floor MER and directed operation of units. Supervised E10, E6, E4 and L15.
 B-4- supervised operations of L15, L10, an L8 on floors above fire units conducted primary and secondary search of floors above, results negative.
 Times 10-76 1314 - E10

Under control 1340 - Div 1
 Injured Civilians -

- smoke inhalation
 taken to St. Vincents Hospital

- smoke inhalation
 taken to Beekman

BMS Chief Cerro directed operations for BMS
 PA operations Commander on scene Capt. Stinner.

cc Charles Callahan

Charles Callahan

TYPE FULL NAME

1317

TIME ARRIVED

cc Robert J. Blume

Robert J. Blume

TYPE FULL NAME

1330

TIME ARRIVED

PAGE

2 of

24A (12/05) BFD-2000-1000-000

REPORT — ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT		DATE AND TIME ALARM RECEIVED				BOX LOCATION		INCIDENT NUMBER	BUILDING #2				IGNITION				STRUCTURE		AREA OF ORIGIN		FIRE EXTENSION	
MONTH	DAY	YEAR	HOUR	MINUTE	BOROUGH	BOX NUMBER	LOAD IN JARIN		LOUSE INVOLVED	HEAT FORM	MATERIAL TYPE	NATURAL FIRM	CONSTRUCTION	USE	STATUS	FLOOR CODE	COORINACY	AREA CODE	MANAGER	OCCUPANCY	RECEIVED REPORT	
6	08	11	94	1317	1	8087	0254	00														

NUMBER (INCL INP/FIN)		STREET NAME		TYPE	
1	2	WTC			

DAMAGE		DETECTORS	
SPK PERFORMANCE	FLAME	SMOKE	WATER
PRESENT	TYPE	POWER	PERFORMANCE

OCCUPANT (Driver)		ROOMAPT.	

IF MOBILE PROPERTY		TYPE		YR		MAKE		MODEL		VIN		LICENSE		STATE DM										
5	224	02	5	024	07	5	028	02	5	003	02	7	010	20	7	001	20	7	015	20	7	008	20	
7	101	10	7	003	07	7	005	07	7	018	07	1	001	20										

OPERATIONS

E3-Stood fast at the Lobby Command Post, then up.
 E55-Stood fast at Lobby Command post, then up.
 L10-Pererated on the 107th floor, opened various walls and doors, finding no fire or extention, then up.
 L15-Assisted R1 in opening up a wall exposing fire in shaft, made necessary search and exam from 94 thru 99th floor (Termination point of shaft) Negative.
 L8-Made necessary search and exam of floors 100 thru 106, found negative.
 L5-Stood fast at the Lobby Command Post, then up.
 L18-Stood fast at the Lobby Command Post, then up.
 L101-Searsh 75, 91 and 92nd floor, found negative, then up.
 L1-Made necessary search and exam of floors 104 thru 106, then up.
 E224-Stood fast at the Lobby Command Post, then up.
 R1-Used Thermal-Imaging camera and located fire in shaft on the 94th floor.
 Batt4-Supervised operation on the fire floor, then up.
 Batt8-Supervised operations on 107 and 74 floors, then up.
 Batt2-Stood fast, then up.
 FCU-Monitored handi-talkie circuit, progress reports, then up.

DC. Lawrence M. Byrnes 01 B.N. DC. David Corcoran 1 DIV. PAGE 2 OF 2
 Lawrence M Byrnes 13:21 David Corcoran 13:25
 TYPE FULL NAME TIME ARRIVED TYPE FULL NAME TIME ARRIVED

REPORT -- STRUCTURAL FIRE

BF-24 (12/1/01) 510 0026 N

INCIDENT LOCATION		DATE AND TIME		ALARM RECEIVED		INCIDENT DURATION		BOX LOCATION		REPORT		COMPANIES RESPONDING		HAZ MAT		SPECIAL USE	
INCIDENT LOCATION	ALARM RECEIVED	DATE	TIME	MINUTES	HOURS	MINUTES	HOURS	BOX NUMBER	BOX LOCATION	REPORT NUMBER	REPORT NUMBER	CLASS	HAZ MAT	SPECIAL USE	HAZ MAT	SPECIAL USE	RECEIVED REPORT
00:00:00	00:00:00	08/29/99	07:47	01:00	08:11	17	08:04	0320	0128	01	021	0302	00	00	00	00	00

AIDED AND CASUALTIES		EXTINGUISHMENT		IGNITION		STRUCTURE		FIRE ORIGIN		FIRE EXTENSION		DAMAGE		DETECTORS	
EVACUATED	CIVILIANS	UNDEAD	UNDEAD	COOL	COOL	COOL	COOL	COOL	COOL	COOL	COOL	COOL	COOL	COOL	COOL
00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00	00:00:00

BF-24

BUILDING		STREET NAME		TYPE		AREA		DEFECTIVE DETECTOR	
NUMBER	INCL. HYDRA	STREET NAME	TYPE	STREET NAME	TYPE	STREET NAME	TYPE	STREET NAME	TYPE
116	116	WORLD TRADE CENTER	126	WORLD TRADE CENTER	126	WORLD TRADE CENTER	126	WORLD TRADE CENTER	126

PORT AUTHORITY		EQUIPMENT INVOLVED IN IGNITION		EQUIPMENT INVOLVED IN IGNITION		EQUIPMENT INVOLVED IN IGNITION	
NAME OF OCCUPANT	211	ROOM/FLR	MAKE	MODEL	POWER	MODEL	POWER
NAME OF OCCUPANT	211	ROOM/FLR	MAKE	MODEL	POWER	MODEL	POWER

UNIT		PTS		ITEM		ITEM	
UNIT	PTS	UNIT	PTS	UNIT	PTS	UNIT	PTS
7	0	10	5	0	10	5	0

OPERATIONS

Upon arrival at box 8364 found rubbish fire in utility shaft at the B-1 level which dropped down to the B-4 level. Units operated as follows:

L-10 Gained access to the B-1 level, performed search, found fire in shaft, performed overhauling.

B-10 Took hydrant, stretched line to stairwell, stretched line from standpipe to utility shaft, extinguished fire at the B-1 level.

L-1 Assisted L-10, performed search of areas above and adjacent to fire, found fire in the shaft at the B-4 level, gained access for stream operation, performed overhauling.

E-7 Took hydrant, assisted E-10 in stretching line on the B-4 level, stretched line from standpipe on B-4 level and extinguished fire that had dropped down from fire on B-1 level.

B.C.		B.N.		D.C.		D.V.	
NAME	NAME	NAME	NAME	NAME	NAME	NAME	NAME
William Dehm	William Dehm	William Dehm	William Dehm	William Dehm	William Dehm	William Dehm	William Dehm

ADMINISTRATIVE COMPANY

TIME OF ARRIVAL

TIME OF ARRIVAL

E-24A (12/85) 15742-86-531-4028-4

REPORT -- ADDITIONAL DATA

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

TYPE REPORT				DATE AND TIME ALARM RECEIVED				BOX LOCATION				INCIDENT NUMBER				IGNITION				STRUCTURE				AREA OF ORIGIN				FIRE EXTENSION																																																							
MONTH	DAY	YEAR	TIME	BOX	NUMBER	INCIDENT	NUMBER	BUILDING NO.	COND. ON ARRIVAL	EQUIP. INVOLVED	HEAT FORM	MATERIAL TYPE	MATERIAL FORM	CONSTRUCTION	USE	STATUS	FLOOR CODE	OCCUPANCY	AREA CODE	MANNER	OCCUPANCY	REVISED REPORT																																																													
6	08	25	99	07	47	18	084	0128	00																																																																										
<table border="1"> <thead> <tr> <th colspan="4">ADDRESS</th> <th colspan="4">STREET NAME</th> <th colspan="4">TYPE</th> </tr> <tr> <th>BORO</th> <th>NUMBER (INCL HYPHEN)</th> <th>SUFFIX</th> <th>PREFIX/DIRECT</th> <th colspan="4">STREET NAME</th> <th colspan="4">TYPE</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>1</td> <td></td> <td></td> <td colspan="4">WORLD TRADE CENTER</td> <td colspan="4"></td> </tr> </tbody> </table>																								ADDRESS				STREET NAME				TYPE				BORO	NUMBER (INCL HYPHEN)	SUFFIX	PREFIX/DIRECT	STREET NAME				TYPE				1	1			WORLD TRADE CENTER																															
ADDRESS				STREET NAME				TYPE																																																																											
BORO	NUMBER (INCL HYPHEN)	SUFFIX	PREFIX/DIRECT	STREET NAME				TYPE																																																																											
1	1			WORLD TRADE CENTER																																																																															
<table border="1"> <thead> <tr> <th colspan="4">SPR. PERFORMANCE</th> <th colspan="4">DAMAGE</th> <th colspan="4">DETECTORS</th> </tr> <tr> <th>% DAMAGED</th> <th>FLAME</th> <th>SMOKE</th> <th>WATER</th> <th>PRESENT</th> <th>TYPE</th> <th>POWER</th> <th>PERFORMANCE</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>												SPR. PERFORMANCE				DAMAGE				DETECTORS				% DAMAGED	FLAME	SMOKE	WATER	PRESENT	TYPE	POWER	PERFORMANCE									<table border="1"> <thead> <tr> <th colspan="4">BUILDING</th> </tr> <tr> <th>STORIES</th> <th>WIDTH</th> <th>LENGTH</th> <th>AREA</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>												BUILDING				STORIES	WIDTH	LENGTH	AREA																								
SPR. PERFORMANCE				DAMAGE				DETECTORS																																																																											
% DAMAGED	FLAME	SMOKE	WATER	PRESENT	TYPE	POWER	PERFORMANCE																																																																												
BUILDING																																																																																			
STORIES	WIDTH	LENGTH	AREA																																																																																
<table border="1"> <thead> <tr> <th colspan="4">OCCUPANT (Driver)</th> <th colspan="4">ROOM/APT.</th> </tr> </thead> <tbody> <tr> <td colspan="4"></td> <td colspan="4"></td> </tr> </tbody> </table>												OCCUPANT (Driver)				ROOM/APT.																																																																			
OCCUPANT (Driver)				ROOM/APT.																																																																															
<table border="1"> <thead> <tr> <th colspan="4">IF MOBILE PROPERTY</th> <th colspan="4">TYPE</th> <th colspan="4">YEAR</th> <th colspan="4">MAKE</th> <th colspan="4">MODEL</th> <th colspan="4">V.I.N.</th> <th colspan="4">LICENSE</th> <th colspan="4">STATE DM</th> </tr> </thead> <tbody> <tr> <td colspan="4"></td> <td colspan="4"></td> <td colspan="4"></td> <td colspan="4"></td> <td colspan="4"></td> <td colspan="4"></td> <td colspan="4"></td> </tr> </tbody> </table>																								IF MOBILE PROPERTY				TYPE				YEAR				MAKE				MODEL				V.I.N.				LICENSE				STATE DM																															
IF MOBILE PROPERTY				TYPE				YEAR				MAKE				MODEL				V.I.N.				LICENSE				STATE DM																																																							

OPERATIONS

E-6 Took hydrant, assisted E-7 in stretch.

B.C. William Oehm 01
B.N.
William Oehm 07:51
TYPE FULL NAME TIME ARRIVED

D.C. _____ DIV. _____
N/A 00:00
TYPE FULL NAME TIME ARRIVED

PAGE 2 OF 2

Attachment G-A.7

Significant fires occurring in WTC 7 (1)

Significant Fire	Incident Date	Fire Location	# sprinklers activated	# standpipes activated	Cause of fire	Material Ignited
1	5/20/88	Construction shanties on floor 3	Multiple, # not listed	1	Suspicious	Shanties

STRUCTURAL FIRE, TRANSPORTATION FIRE, NON-STRUCTURAL FIRE OR EMERGENCY

OPERATIONS

L5-Assisted L10 Made primary and secondary search of 5-10,11,12.Then up.
 L1-Made search and examination of the 4th floor.Then assisted L8 in the
 examination of upper floors.Then up.
 Batt 4-Supervised L7C and L10 on fire floor.
 Batt 2-Supervised E4 and E6 and L1 on floors above fire.
 PCU- SOP
 MSU- SOP
 E3- Stood fast.
 Batt 6- Stood fast.

B.C.

$$\frac{n-1}{n}$$

DC

DIV

PAI

Adolph S. Quatrone
TYPE FULL NAME

0043
TIME ARRIVED

TYPE FULL NAME

TIME ARRIVED

1.

This page intentionally left blank

Attachment G-B

PACO 2002 Report: World Trade Center General Description of All Building Systems and the Capital Program. Extracted page.

Miscellaneous Life Safety Improvements and Sprinklerization Program

12. Miscellaneous Life Safety Improvements and Sprinklerization Program

12.1 Description of the Program

The initial base building provided for Fire Standpipe (FSP) protection in the Towers and Plaza Buildings and no sprinkler system installation (except in the sub-grade Levels). In response to the enactment of Local Law 5 and other NYC Building Code Local Law enactments related to the fire protection of high rise office towers built after 1973 the Port Authority voluntarily retrofitted the WTC complex to comply with the new NYC Building Code Requirements supplemented by PA imposed life safety requirements unique to the WTC. These requirements provided tenants the option of achieving fire protection compliance by a compartmentalization or a sprinklerization option. The Scope of miscellaneous life safety and sprinkler system upgrades/improvements, other than certain fire alarm, concourse circulation and blast recovery improvements discussed elsewhere, included but was not limited to:

12.2 Scope of Fire Life Safety Improvements

Architectural Modifications - On all floors:

- Upgraded core wall construction to provide for a 2 hour rated fire separation from one side of a tower floor to the opposite side (Where core wall were already 2 hour rated, such as in elevator shafts, upgraded where not previously required).
- Installed a double acting set of rated HM fire doors in the core corridors where the above 2 hour rated fire separation crossed the corridor (This enabled one half of a typical tower floor to serve as a horizontal fire refuge for the other.) Doors included special magnetic hold open hardware and closures linked to smoke detectors in floor return air ducts.
- Restored all ceilings in corridors and lobbies affected by fire protection Installations.
- Provided slab-to-slab 1hour fire rated walls to enable a maximum of 10,000 gross square foot compartmentalization on each side of the 2 hour rated fire separations.

Sprinkler System Installation

- The entire WTC complex was fully sprinklered. The Sprinkler System was installed in three basic phases. Phase 1: Sub-grade areas for the Initial building construction; Phase 2: Sprinkler riser/main installation throughout 1 & 2 WTC including the sprinklerization of corridors, storage rooms, lobbies and certain tenant/PA spaces in 1976 in compliance with Local Law 5 to provide tenants with a compartmentation or sprinkler fire protection option; Phase 3: The full sprinklerization of the entire complex for all remaining places from 1983 to the 2001 (including 1993 blast recovery and ongoing up-grades/improvements and replacements).
- The Tower sprinkler systems were fed in the various zones from the gravity feed fire reserve tanks located on the 20th, 41st, 75th and 110th Floors through a 4" vertical sprinkler riser located in the Janitor Closet on each floor of each building in the WTC complex.

EXP 013001

CONFIDENTIAL

CONFIDENTIAL

REV 55 000000

TABLE OF CONTENTS

List of Figures	H-iii
List of Tables	H-v

Appendix H

Interim Report on Evolution of WTC Fires, Smoke, and Damage Based on

Image Analysis..... H-1

H.1 Collection and Analysis of Visual Material.....	H-1
H.1.1 Sources	H-2
H.1.2 Procedures	H-2
H.1.3 Contents.....	H-3
H.2 Databasing and Cataloging	H-3
H.2.1 Digital Storage.....	H-3
H.2.2 Digitizing Techniques	H-4
H.2.3 Searchable Database.....	H-4
H.3 Timing of Photographs and Video Clips.....	H-8
H.3.1 Digital Timestamps	H-8
H.3.2 Reference Time	H-15
H.3.3 Timing Techniques.....	H-15
H.3.4 Absolute Time Accuracy	H-16
H.4 Analysis of Visual Images	H-16
H.4.1 Window Numbering	H-16
H.4.2 Fire Properties	H-18
H.4.3 Window-by-Window Assessment.....	H-18
H.5 Initial Damage Patterns on WTC 1 and WTC 2 Due to the Plane Strikes.....	H-22
H.5.1 WTC 1	H-22
H.5.2 WTC 2.....	H-25
H.6 Fire Behaviors in the Two Towers.....	H-32
H.6.1 WTC 1	H-35
H.6.2 WTC 2	H-36
H.7 Evidence for Collapsed Floors in WTC 2.....	H-37
H.7.1 Hanging Objects	H-37
H.7.2 Molten Material	H-38

H.8 Progress on Collection of Images and Analysis for WTC 7	H-39
H.9 Summary with Key Findings	H-40
H.10References	H-43

LIST OF FIGURES

Figure H-1.	An example of the VideoList data entry sheet for video assets.	H-5
Figure H-2.	An example of the first page of the Cumulus data entry sheet for photographic assets..	H-12
Figure H-3.	An example of a Cumulus asset screen display for the video database	H-12
Figure H-4.	An example of the PhotoTiming sheet for calculating times for photographs containing Exif meta data.....	H-13
Figure H-5.	An example of the VideoList sheet for calculating clip times for video assets.	H-14
Figure H-6.	Photograph taken at 9:26:20 a.m. on September 11, 2001, showing the east face of WTC 2.....	H-17
Figure H-7.	This photograph is cropped from the image shown in Figure H-6. It was taken on September 11 and shows the east face of WTC 2 at the northeast corner from floor 77 to floor 82.....	H-18
Figure H-8.	The key used to describe observations with regard to fire, smoke, and window breakage in Excel data files for individual windows in the two towers.....	H-19
Figure H-9.	A portion of the Excel spreadsheet describing fires on the east face of WTC 1 around 9:42 a.m.....	H-20
Figure H-10.	A representation of fires for floors 91 to 100 on the east face of WTC 1 around 9:42 a.m.....	H-21
Figure H-11.	A single frame from a time-dependent visualization generated by Smokeview	H-21
Figure H-12.	A drawing of the damage to the steel façade of WTC 1	H-23
Figure H-13.	The condition of windows is shown for the four faces of WTC 1 around 8:47 a.m. shortly after it was struck by American Airlines Flight 11	H-24
Figure H-14.	Photograph showing a full panel section lying in Cedar Street near its intersection with West Street	H-26
Figure H-15.	Series of sequential cropped frames taken from a video shot on September 11, 2001, showing the plane approaching WTC 2	H-27
Figure H-16.	Plots of pixel locations for the nose and tail of the plane that struck WTC 2 as a function of time	H-28
Figure H-17.	Frames from a composite video	H-29
Figure H-18.	The time when null points are observed in the difference video following the plane strike on WTC 2 are plotted versus the null point number	H-30
Figure H-19.	A drawing of the damage to the steel facade of WTC 2	H-31
Figure H-20.	The condition of windows is shown for the four faces of WTC 2 around 9:03 a.m. shortly after it was struck by United Airlines Flight 175	H-33
Figure H-21.	An enhanced photograph of the north face of WTC 2 taken at 9:58 a.m. shows the east side of the north face.....	H-34

Figure H-22. Images of the east face of WTC 2 taken shortly after the plane struck and shortly before the tower collapse	H-38
--	------

LIST OF TABLES

Table H-1.	Attributes for photographic assets.....	H-6
Table H-2.	Attributes for video assets.....	H-9
Table H-3.	Times for major events of September 11, 2001.	H-15

This page intentionally left blank.

Appendix H

INTERIM REPORT ON EVOLUTION OF WTC FIRES, SMOKE, AND DAMAGE BASED ON IMAGE ANALYSIS

H.1 COLLECTION AND ANALYSIS OF VISUAL MATERIAL

Photographic and video images of damage and fires in the World Trade Center (WTC) towers and WTC 7 are critical for guiding the investigation led by the National Institute of Standards and Technology (NIST). The conditions of the towers immediately following the plane strikes, the rates of fire development and spread through the buildings, and indications as to the floors on which the structural collapses may have begun and their causes are examples of issues that are being addressed using imagery. Observations discussed below demonstrate the importance of such visual evidence.

This appendix is designed to provide an update on NIST efforts to collect and analyze visual material available for the WTC disaster. This effort is part of Project 5, Reconstruction of Thermal and Tenability Environment, and this is the focus of the material presented. It is important to recognize that the effort is coordinated with the other projects that form the NIST-led WTC Investigation, and the visual material is being used as the basis for additional analysis in these projects.

The amount of visual material recorded on September 11, 2001, was extraordinary. The terrorist attacks occurred in an area that is the national home base of several news organizations, has several major newspapers, and is the center of the fashion industry. As a result, there were likely hundreds of professional photographers and videographers equipped with excellent equipment and the knowledge to use it in the immediate area. New York City is also a major tourist destination, and visitors often carry cameras to record their visits.

The WTC towers (WTC 1 and WTC 2) were immense, and they dominated the New York City skyline. When WTC 1 was struck by American Airlines Flight 11 around 8:46 a.m., the approach of the plane was captured by at least two videographers who were coincidentally filming nearby. Other photographers and videographers in the vicinity began recording within a few seconds of the impact. As fires grew in the tower, smoke pouring from the building formed a plume that could be seen for miles in all directions in the clear air of September 11, 2001. People in Manhattan, Brooklyn, Queens, and New Jersey began to turn their cameras toward the WTC complex. The major news organizations began coverage almost immediately and began moving professionals into position to cover the event. Numerous other videographers and photographers, both professional and amateur, started moving toward the WTC in order to create their own visual records.

At the time United Airlines Flight 175 struck WTC 2, around 9:03 a.m., the approach and collision of the aircraft were recorded by numerous cameras from a variety of directions. Many people continued to record images until WTC 2 collapsed, around 9:59 a.m. Following this collapse, the amount of visual material decreased markedly as people rushed to escape the area and the huge dust clouds generated by the collapse obscured the site. This situation was only exacerbated by the collapse of WTC 1, around

10:28 a.m. The visual record between the period following the collapse of WTC 1 and the collapse of WTC 7, around 5:21 p.m., is much less complete, but there is still a substantial amount of material.

Even as the disaster unfolded, it was clear that a large amount of visual material was being recorded that was being used to inform the public, demonstrate the immensity of the disaster, and to chronicle the associated human suffering. It is now clear that the imagery of September 11, 2001, is the most extensive ever recorded of such a single tragic event. The resulting visual record offers an unparalleled opportunity to contribute to the technical understanding of the tragedy of September 11. Even though it was clear that an extensive visual record of the events of September 11 existed, approaches for obtaining access to photographs and videos and cataloging the material had to be developed. These critical aspects of the task have required a great deal of time and effort.

H.1.1 Sources

Potential sources of visual material have been identified in a number of ways. Recordings of newscasts from September 11, 2001, and afterwards, documentaries and other remembrances, provided information directly, but also pointed toward other potential sources of material. The major photo clearinghouses, such as AP, Reuters, and Corbis, have World Wide Web sites that were reviewed for material related to September 11. Several members of the media suggested sources. Several collections of visual material have been assembled for charitable or historical purposes. Collections from the *Here is New York City* exhibition and the *September 11 Digital Archive* were reviewed. Many photographs and videos began appearing on the Web as early as September 11. These could often be identified by Web searches, and in many cases contact information was provided. Public appeals for visual material were made during Investigation news conferences and updates. News accounts of these events led many to contact NIST using the toll-free number or the Investigation Web site. Frequently, a new source would provide information about other potential sources.

NIST hired a visual media consultant, Mr. Valentine Junker, to act as its representative in the New York City area. In addition to interacting with a number of individuals, his efforts were particularly valuable in interfacing with the major television networks and local New York City stations as well as the major photographic news services.

H.1.2 Procedures

The identification of sources was only the first step in the collection process. It was then necessary to contact the source, request the material, and make arrangements for its transfer. Special considerations such as copyright and privacy issues often needed to be addressed. Once an agreement was reached, arrangements were made to review and transfer copies of the material to NIST.

In the collection process, emphasis has been placed on obtaining material in a form that is as close as possible to the original in order to maintain as much spatial and timing information as possible. In the case of digital photographs and videos this implies a direct digital copy. For film or slide photographs, it would be a high-resolution digitized version of the original media, and for analog video, a direct copy from the original source. While it was not always possible to maintain this standard, the majority of material ultimately collected was handled in this manner.

H.1.3 Contents

Significant progress has been made in collecting visual material related to September 11, 2001. Thus far, in excess of 150 hours of video have been assembled. At the time of preparation of this update, video footage has been provided by NBC, CBS, ABC, CNN and local New York City stations WABC, WCBS, WNBC, WPIX, WNYW and New York City One. In many cases, the videos provided not only include material broadcast (known as air checks), but also material that was recorded but not broadcast (known as outtakes). Additionally, videotapes recorded by more than 20 individuals have been received.

Photographs have been provided by a number of sources dominated by commercial photo services, the New York City Police Department (NYPD), the New York City Fire Department (FDNY), and individuals. Well in excess of 6,000 photographs, representing more than 185 photographers, have been received. Professional news organizations that have provided material include AP, Corbis, Reuters, the *New York City Times*, the *Daily News*, and the *Star Ledger*. As for the videos, many of these organizations have provided access to unpublished photographs. The majority of photographs have come from individual photographers, both professional and amateur.

It is difficult to estimate the actual amount of relevant visual material recorded on September 11, 2001, and thus to estimate how complete the collection efforts have been. There is certainly material that has not been identified and collected. However, NIST believes that the extraordinarily large collection of video material that it possesses is sufficient for the Investigation.

H.2 DATABASING AND CATALOGING

It would be impossible to effectively use the vast amount of visual material collected for the Investigation without some means of organizing and cataloging the material.

H.2.1 Digital Storage

Very early in the task, the decision was made to save all material in digital format on large digital data storage devices. This approach has several advantages. Because the material is in digital form, it can be assessed quickly. It is not necessary to search for a particular photographic collection or videotape, and no special equipment is required to display it. Because most material is received in other forms, the digital storage is in effect a backup system for the original. Additional redundancy is provided by backing up the entire digital storage system at regular intervals. Because videos are saved digitally, they can be analyzed using a variety of commercially available editing software.

Various storage solutions were considered. An approach was finally adopted in which a central server along with two 325 gigabyte and one 160 gigabyte external hard drives were connected with eight personal computers equipped with 70 gigabyte hard drives. The personal computers not only provide additional disk storage, but also serve as workstations for data entry and analysis. All of the systems are connected by high-speed ethernet to form a single network configured such that the entire system becomes, in effect, a single mass storage device. The total amount of storage available is roughly 1.4 terabytes.

Due to security concerns related to the sensitive nature of some of the visual material and copyright issues, the computer network has been set up with its own dedicated connections and is isolated from the internet backbone of NIST. Policies have been adopted that require all viewing and analysis of the material to be done in secured rooms using secured networks.

H.2.2 Digitizing Techniques

When new visual material is received at NIST, it is stored digitally on the dedicated system. If the material is already in digital form this simply means copying and saving it on the system. Analog material must be first digitized in some manner. For instance, a photograph might be scanned and digitized, or a video might be converted to a digital video format (typically mini-DV) and then copied to a hard disk.

Each arriving video is logged into VideoList, a Microsoft Access database written specifically for this application. There it is assigned a unique identification number. Pertinent information concerning the tape is recorded, including its duration, the network and broadcast date if applicable, its physical format (e.g., VHS, Hi-8, or mini-DV), where the tape is stored, whether the tape is an original or a copy, its source, whether it has been digitized, whether it contains embedded timecode, and general notes on its content. Figure H-1 shows an example of the entry sheet for the VideoList database. Videos to be stored digitally are copied onto mini-DV media, and each copy is also logged into the database. VideoList also contains a calculator for assisting in the calculation of clip timing that is described in H.3.1. Selected video material is then transferred to hard disk for storage. Video material is often found to have natural breaks, such as when the camera is turned off and on (e.g., by an individual videographer) or when multiple cameras are used (e.g., during a newscast). It is advantageous to treat each of these breaks as the end of an individual video. This is accomplished by a process known as "clipping." By using Adobe Premiere software and a personal computer to control the video player, it is possible to identify and note such breaks in a "clip file." The clip file can also contain notes related to the material. Once a clip file has been generated for an entire tape, the software goes through and automatically generates multiple data files containing the video material. The material is stored in "avi" format, which maintains all of the digital information. The maximum video file size that can be handled by this system is 1 gigabyte. This corresponds to slightly more than 4 1/2 min of avi video. Longer continuous video segments are broken into lengths having roughly this period. Breaking longer videos up in this manner also makes them easier to search and catalog.

H.2.3 Searchable Database

As noted earlier, a vast amount of visual material has been collected and saved digitally as part of the investigation. Without some organization, it would be impossible to use this material effectively. A commercial database program written specially for organizing visual material, Cumulus, was chosen for this purpose. This software is designed to collect individual "assets" in specified catalogs and to allow the assets to be characterized with a variety of attributes. It is possible to generate specific attributes and include these in specially designed forms for data entry. Once a catalog has been assembled, it is possible to search for assets having a specific attribute or combinations of attributes. Quite sophisticated searches can be created. It is also possible to order assets based on a particular attribute. As an example, when dates and times are assigned, the assets can be ordered in chronological order.

Videos

Video title: Scott Myers - 9/11 video - East faces

Network: None

Broadcast_date:

Duration (min): 60

Subject: WTC - 9/11

Notes: 12 John Street
East faces
Captures 2nd plane strike - subtraction of images shows pressure wave movement of WTC2
View of burning floors somewhat blocked by building

Tape ID	Tape name	Copy	Format	Duration	Location	Source	Derived from	Batch	Clips	Timecode
32	Scott Myers - 9/11 video - East faces	3	mini-DV	60	Pitts	copy	60	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
51	WTC 9/11/01 Scott Myers	4	mini-DV	60	Pitts	copy	60	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
60	WTC 9/11 @ Scott Myers	1	mini-DV	60	Pitts	Myers	0	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
77	WTC 9/11/01 Scott Myers	2	Hi8	60	Pitts	copy	60	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
*InNumber		1		n			n	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Batch:

Record: 148 of 209

Notes:

Taskbar: Start | [Icons] | R:\Databases | C:\Documents... | ScottMyersScre... | frmMain : Form | Videos | 11:23 AM

Figure H-1. An example of the VideoList data entry sheet for video assets.

Two separate catalogs, one for photographs and one for video clips, have been created for visual materials collected as part of the Investigation. Each catalog has a similar set of attributes that is used to characterize the assets that are included. These attributes were chosen based on the needs of this task dealing with fire conditions within WTC 1, 2, and 7 and by consultation with members of other project teams. Tables H-1 and Table H-2 list the attributes used for photographic and video catalogs, respectively. A description of each attribute is provided along with details on how information concerning the attribute is input into the worksheet. Figure H-2 shows an example of the first screen for the photographic data entry form.

Cumulus allows thumbnails of entire catalogs or selected subsets to be displayed. This makes it possible to review large numbers of photographs and video clips quickly and to decide which are most likely to be useful for a particular purpose. A variety of asset characteristics can also be shown simultaneously. Typically, the asset name and the time the asset was recorded are displayed. Figure H-3 shows an example of thumbnails taken from the video database.

Table H-1. Attributes for photographic assets.

Attribute	Definition	Entry Choice
Asset Reference	Location of photograph in file system	Set by Cumulus
Categories	List of categories under which the photograph is listed, typically the photographer's name or source	Set by Cumulus
Record Name	File name of photograph	Set by Cumulus
Photographer	Photographer's name	Text
Received from	Where photograph was obtained ("Other" may refer to a third party, for example)	Photographer WWW Other
Original Source	How photograph was added to the collection	Digital Copy of Original Digital Copy from Program Digitized Slide or Negative Digitized Photograph Uploaded from Web
Use Limited	Photographer has requested that use of the photograph be limited	Checkbox
Copyright	A copyright exists	Checkbox
Copyright Agreement	Usage agreement with NIST	Text
Shot From	Location of photographer	Text
Date Recorded	Date and time of shot	Date and time
Time Uncertainty (s)	Number of seconds uncertainty in the time assigned	Integer
View Direction	Location of photographer with respect to the WTC	North Northeast East Southeast South Southwest West Northwest
WTC Faces WTC 1 North Face WTC 1 East Face WTC 1 South Face WTC 1 West Face WTC 2 North Face WTC 2 East Face WTC 2 South Face WTC 2 West Face WTC 7 North Face WTC 7 East Face WTC 7 South Face WTC 7 West Face	Building face(s) visible in the photograph	Checkbox for each choice

Attribute	Definition	Entry Choice
Distance Near Medium Far	Clarity of the photograph Near = Can make out details in windows Medium = Can count windows Far = Unable to count windows	Checkbox for each choice
Building WTC 1 WTC 2 WTC 7 Other Building	Building(s) visible in photograph	Checkbox for each choice
1st Plane Strike	Photograph shows the plane strike on WTC 1	Checkbox
2nd Plane Strike	Photograph shows the plane strike on WTC 2	Checkbox
WTC 1 Collapse	Photograph shows the collapse of WTC 1	Checkbox
WTC 2 Collapse	Photograph shows the collapse of WTC 2	Checkbox
WTC 7 Collapse	Photograph shows the collapse of WTC 7	Checkbox
Street	Street scene, or a street is visible in the photograph	Checkbox
Debris Aircraft Debris Collapse Debris Debris Inside Building Street Debris	Debris is visible in the photograph Type of debris: Aircraft = Can be identified as plane debris (e.g., tires, engines) Collapse = Resulting from collapse Inside Building = Visible through windows or openings Street = On street	Checkbox for each choice
Fireball	Initial fireball from plane strike is visible	Checkbox
Thermal	The thermal is a tall region of the smoke plume that results from the lift caused by the hot gases of the initial fireball	Checkbox
Plume	Smoke plume generated by the fires within the towers and blown downwind. This marker is checked if the smoke plume in the photograph extends farther than a single tower width.	Checkbox
Flames Visible	Flames are visible in the photograph	Checkbox
People Inside Falling Outside	The photograph includes people Inside = People inside the buildings, at the windows or climbing down Outside = People on the street	Checkbox for each choice
Falling building component	The photograph shows a building component falling (e.g., aluminum cladding)	Checkbox
Streamers Falling	The photograph shows a streamer, an object that emits smoke as it falls and leaves a trail	Checkbox
Dripping	Molten material dripping from WTC 2 is visible	Checkbox
Hanging Floor	A sagging or hanging object suggesting a floor is visible within the windows	Checkbox

Attribute	Definition	Entry Choice
Building Core	Photograph shows the core of WTC 1 or WTC 2 — both remained standing briefly during collapse before falling	Checkbox
FDNY FDNY Apparatus FDNY Personnel	FDNY personnel or vehicles are visible, including EMTs, fire trucks, and ambulances	Checkbox for each choice
NYPD NYPD Apparatus NYPD Personnel	NYPD personnel or vehicles are visible, also includes FBI and other police officials	Checkbox for each choice
Impact Aircraft	Photograph shows aircraft approaching WTC 1 or WTC 2 before or during the strike	Checkbox
Other Aircraft	Aircraft other than the impact aircraft are included in the photograph, such as helicopters or fighter jets	Checkbox
Good for Analysis	Mark photograph for possible window-by-window analysis	Checkbox
Analyzed	The photograph has been used for window-by-window analysis	Checkbox
Notes	Notes, including a description of how the photograph was timed	Checkbox

Not all collected visual material is incorporated into the two catalogs. Photographs and videos judged not to contain information directly relevant to the Investigation are not included. Even so, the number of photographs and clips included in the catalogs is huge. At the time of writing, the photographic catalog includes 6,759 assets and the video catalog includes 6,911 assets.

H.3 TIMING OF PHOTOGRAPHS AND VIDEO CLIPS

Since one of the major goals of this task is the development of time lines for fire growth and spread in WTC 1, 2, and 7, it is important to assign times of known accuracy to assets included in the two catalogs. This task is complicated by the absence of accurate times for the majority of visual materials collected.

H.3.1 Digital Timestamps

Modern photographic and video digital cameras often record camera clock times as part of their output. For photographs, this information is usually stored as an integral part of the image in a header known as an Exif file. Similarly, digital video cameras often embed a variety of information, including the camera clock time, as part of what is known as meta data. Software is available for reading these clock times from Exif and other meta data media file formats. While a great help, these times usually still require some adjustment because people do not generally set their camera clocks accurately. In some cases, camera clocks were off by days or even years. Even so, the relative times over the short time period of the events of September 11, 2001, are quite accurate.

Table H-2. Attributes for video assets.


Attribute	Definition	Entry Choice
Asset Reference	Location of video clip in the file system	Set by Cumulus
Categories	List of categories under which the video clip is listed, typically the photographer's name or source	Set by Cumulus
Record Name	File name of video clip	Set by Cumulus
Photographer	Photographer's name	Text
Content	<p>Content of video clip</p> <p>WTC 9/11 Footage = Events before collapse of WTC 7</p> <p>Street Scene (no timing)</p> <p>Debris field = Ground Zero after WTC 7 collapse</p> <p>Construction = Construction of WTC towers from documentary</p> <p>Normal Operation = Normal operation of building, usually from documentary</p> <p>Animation = Animation of 9/11 events from documentary</p> <p>Still(s) = Photographs contained within documentary</p> <p>Interview = Clip only shows interview</p>	<p>WTC 9/11 Footage</p> <p>Street scene (no timing)</p> <p>Debris field</p> <p>Construction</p> <p>Normal operation</p> <p>Animation</p> <p>Still(s)</p> <p>Interview</p>
Use Limited	Videographer has requested that use of the videotape be limited	Checkbox
Copyright	A copyright exists	Checkbox
Copyright Agreement	Usage agreement arrangements with NIST	Text
Shot From	Location of videographer	Text
Date Recorded	Date and time of beginning of video clip	Date and time
End Recording	Date and time of end of video clip	Date and time
Duration	Number of minutes:seconds contained in clip	Real number
Time Uncertainty (s)	Number of seconds uncertainty in the time recorded / end recording	Integer
View Direction	Location of videographer with respect to the WTC	<p>North</p> <p>Northeast</p> <p>East</p> <p>Southeast</p> <p>South</p> <p>Southwest</p> <p>West</p> <p>Northwest</p>

Attribute	Definition	Entry Choice
WTC Faces WTC 1 North Face WTC 1 East Face WTC 1 South Face WTC 1 West Face WTC 2 North Face WTC 2 East Face WTC 2 South Face WTC 2 West Face WTC 7 North Face WTC 7 East Face WTC 7 South Face WTC 7 West Face	Building face(s) visible in the video clip	Checkbox for each choice
Distance Near Medium Far	Clarity of the video clip Near = Can make out details in windows Medium = Can count windows Far = Unable to count windows	Checkbox for each choice
Building WTC 1 WTC 2 WTC 7 Other Building	Building(s) visible in video clip	Checkbox for each choice
1st Plane Strike	Clip shows the plane strike on WTC 1	Checkbox
2nd Plane Strike	Clip shows the plane strike on WTC 2	Checkbox
WTC 1 Collapse	Clip shows the collapse of WTC 1	Checkbox
WTC 2 Collapse	Clip shows the collapse of WTC 2	Checkbox
WTC 7 Collapse	Clip shows the collapse of WTC 7	Checkbox
Street	Street scene, or a street is visible in the video clip	Checkbox
Debris Aircraft Debris Collapse Debris Debris Inside Building Street Debris	Debris is visible in the video clip Type of debris: Aircraft = Can be identified as plane debris (e.g., tires, engines) Collapse = Resulting from collapse Inside Building = Visible through windows Street = On street	Checkbox for each choice
Fireball	Initial fireball from plane strike is visible	Checkbox
Thermal	The thermal is a tall region of the smoke plume that results from the lift caused by the hot gases of the initial fireball	Checkbox
Plume	Smoke plume generated by the fires within the towers and blown downwind. This marker is checked if the smoke plume in the video clip extends farther than a single tower width.	Checkbox
Flames Visible	Flames are visible in the video clip	Checkbox

Attribute	Definition	Entry Choice
People Inside Falling Outside	The video clip includes people Inside = People inside the buildings, at the windows, or climbing down Outside = People on the street	Checkbox for each choice
Falling building component	The video clip shows a building component falling (e.g., aluminum cladding)	Checkbox
Streamers Falling	The video clip shows a streamer, an object that emits smoke as it falls and leaves a trail	Checkbox
Dripping	Molten material dripping from WTC 2 is visible	Checkbox
Hanging Floor	A sagging object suggesting a floor is visible within the windows	Checkbox
Building Core	Video clip shows the core of WTC 1 or WTC 2 – both remained standing briefly during collapse before falling	Checkbox
FDNY FDNY Apparatus FDNY Personnel	FDNY personnel or vehicles are visible, including EMTs, fire trucks, and ambulances	Checkbox for each choice
NYPD NYPD Apparatus NYPD Personnel	NYPD personnel or vehicles are visible, also includes FBI and other police officials	Checkbox for each choice
Aircraft Impact Aircraft Other Aircraft	Aircraft are visible in the video clip Impact: Shows aircraft approaching WTC 1 or WTC 2 before or during the strike Other: Helicopters or fighter jets	Checkbox for each choice
Major Change Major Fire Change Major Smoke Change Windows Opened	One of the following events takes place in the video clip: Major Fire Change: Fire flares up, dies down, or spreads to a new region Major Smoke Change: Smoke bursts, dies down, or spreads to a new region Windows Opened: Window breaks open, either due to fire or to people	Checkbox for each choice
Good for Analysis	Mark video clip for possible window-by-window analysis	Checkbox
Analyzed	The video clip has been used for window-by-window analysis	Checkbox
Notes	Notes, including a description of how the video clip was timed	Text

Information for Asset "MarkStetler_WTC9_1113.TIF" of "dbWTC"

Asset Edit Help

Field Name	Field Content
Categories	Roll 1
Record Name	MarkStetler_WTC9_1113.TIF
Thumbnail	
Photographer	Mark Stetler
Received From	Photographer
Original Source	Digital Copy of Original
Use Limited	<input checked="" type="checkbox"/>
Copyright?	<input checked="" type="checkbox"/>
Copyright Agree...	
Shot From	80 Nassau St
Date Recorded	9/11/2001 9:10:44 AM
Time Uncertainty (s)	2
View Direction	east
WTC 1 Faces	<input type="checkbox"/> WTC 1 North F... <input checked="" type="checkbox"/> WTC 1 East Face <input type="checkbox"/> WTC 1 South F... <input type="checkbox"/> WTC 1 West Fa...
WTC 2 Faces	<input type="checkbox"/> WTC 2 North F...

Start [Icons] 3:13 PM

Figure H-2. An example of the first page of the Cumulus data entry sheet for photographic assets. Thumbnail © 2001 Mark Stetler.

Cumulus - [WTCVideo]

File Edit View Catalog Category Collection Asset Special Window Help

Myers_clip1.avi Myers_clip2.avi Myers_clip3.avi

Myers_clip4.avi Myers_clip5.avi Myers_clip6.avi

9/11/2001 8:47:01 AM 9/11/2001 8:48:35 AM 9/11/2001 8:49:39 AM
 9/11/2001 8:49:31 AM 9/11/2001 8:49:54 AM 9/11/2001 8:53:38 AM

9/11/2001 8:53:29 AM 9/11/2001 8:57:29 AM 9/11/2001 9:01:29 AM
 9/11/2001 8:57:39 AM 9/11/2001 9:01:39 AM 9/11/2001 9:05:39 AM

127 of 146 Categories (1 Selected) 11 of 6278 Records

Figure H-3. An example of a Cumulus asset screen display for the video database. Thumbnails are shown along with the time and dates when the recording started and ended. Thumbnails © 2001 Scott Meyers.

Occasionally analog photo and video cameras imprint a time stamp on their outputs that can provide relative times similar to Exif or meta data, but generally there is no time information available, and such material must be timed in some other way. Some of the approaches used are described later in this section.

Photograph Tools

In order to make the best use of the information embedded in digital photographs, software was required to retrieve the Exif file information and software to adjust the recorded clock times. The commercial software package CatDV is able to retrieve meta data embedded in a variety of media formats, including digital photographs and mini-DVs. The Access database PhotoTiming was written for the purpose of determining the actual times for a set of photographs given the Exif time for each and an accurate time reference. For a set of photographs sharing a common clock from the same digital camera, an accurate time for a single photograph is sufficient to set the times for the entire set. Figure H-4 shows a PhotoTiming data sheet for a selected photographer. A file generated by CatDV containing the Exif data for each photograph, if available, is read into PhotoTiming. The equivalent Exif and actual times are entered into the appropriate fields at the upper right of the data sheet. Selection of the Calculate Photo Times button fills the Actual Time column with the appropriate value for each Exif time. In this example, the Exif time was found to be off by 62 s.

The screenshot shows the PhotoTiming application window. At the top is a menu bar (File, Edit, View, Insert, Format, Records, Tools, Window, Help) and a toolbar. Below the menu bar is a text area with 'MS Sans Serif' font and size '8'. The main window contains a form titled 'Photographs'. The form has several fields and buttons:

- Photographer Name:** Nicolas Cianca
- EXIF Reference Time:** Sep 11, 2001 9:25:42 AM
- is equivalent to:**
- Actual Time:** Sep 11, 2001 9:24:00 AM
- Buttons:** Calculate Photo Times, Report Photo Times
- Table:** A table with columns: Photo Source, Photo Name, EXIF Time, and Actual Time. It lists five photos from Nicolas Cianca, all with EXIF times from Sep 11, 2001 17:26:13 to 17:29:16. The Actual Time column shows calculated times from 9/11/2001 5:24:31 PM to 5:27:34 PM.
- Buttons:** Check All Photos, Uncheck All Photos
- Record:** 70 of 115

The status bar at the bottom shows 'Form View' and a taskbar with various icons and the time '6:02 PM'.

Figure H-4. An example of the PhotoTiming sheet for calculating times for photographs containing Exif meta data.

Video Tools

In addition to containing the video database described in Section H.2.3, VideoList also assists with timing the clips from a videotape. This function is similar to that in the PhotoTiming tool. For a broadcast video that was filmed in real time, the timing of every clip in the video, except for replays, can be set from knowing the time at a single point. An example is shown in Figure H-5. A clip file generated in Adobe Premiere for a specified video is read into VideoList. The mini-DV time of an event in the video whose timing is known, such as the moment of the second plane strike, is identified. Both times are entered into the fields at the upper right of the data sheet. Clips to be timed (excluding replays) are identified by a check mark, and the requested calculation results in the actual times in and out for each clip as shown in Figure H-5. This tool is also useful in calculating timings for continuous video segments broken into multiple clips.

Video Clips

Tape Name: Scott Myers -- 9/11 video - East faces

Tape ID: 32 Tape Length (min): 60

DV Reference Time: Hour: Min: Sec: Frame: Calculate Clip Times

is equivalent to Actual Time: Hour: Min: Sec: Frame: Report Clip Times

Click on button to select clip for time calculation

Clip Name	DV Time In	DV Time Out	Actual Time In	Actual Time Out	Duration	Notes
Myers_clip1	00:00:03:00	00:01:33:12			00:01:30:13	East faces of 1 and 2 From street Medium distant vie
Myers_clip2	00:01:33:13	00:01:52:02			00:00:18:20	East faces of 1 and 2 From street Medium view Betr
<input checked="" type="checkbox"/> Myers_clip3	00:01:52:03	00:05:52:00	08:49:38:11	08:53:38:08	00:03:59:28	Start of continuous track. East faces of 1 and 2 From
<input checked="" type="checkbox"/> Myers_clip4	00:05:42:00	00:09:52:00	08:53:28:08	08:57:38:08	00:04:10:01	2nd in continuous track. East faces of 1 and 2 From
<input checked="" type="checkbox"/> Myers_clip5	00:09:42:00	00:13:52:00	08:57:28:08	09:01:38:08	00:04:10:01	3rd in continuous track. East faces of 1 and 2 From s
<input checked="" type="checkbox"/> Myers_clip6	00:13:42:00	00:17:52:00	09:01:28:08	09:05:38:08	00:04:10:01	4th in continuous tracking. East faces of 1 and 2 fron
Myers_plane_strike	00:15:07:10	00:15:21:16			00:00:14:07	Plane strike East faces of 1 and 2 From street Medi
<input checked="" type="checkbox"/> Myers_clip7	00:17:42:00	00:21:52:00	09:05:28:08	09:09:38:08	00:04:10:01	5th in continuous track. East faces of 1 and 2 From s

Check All Clips Uncheck All Clips

Record: 111 of 172

Figure H-5. An example of the VideoList sheet for calculating clip times for video assets.

For each mini-DV video that contains meta data, CatDV is used to extract the clock times for the In and Out point for each clip. These values enable the timing of every clip in the video from a single reference time.

H.3.2 Reference Time

Faced with the timing considerations above, a timing scheme was developed in which all of the times in the databases are placed on a relative time scale tied to a single well-defined event. Due to the large number of different views available, the moment the second plane struck WTC 2 was chosen to be this time. This event was defined to have occurred at 9:02:54 a.m. based on times for major events included in the earlier Federal Emergency Management Agency (FEMA) report (McAllister 2002) describing the events of September 11, 2001.

H.3.3 Timing Techniques

Once the reference time was chosen, it was possible to place times on videos that showed the second plane strike. By matching other photographs and videos to these initially assigned videos, the assignments were extended to visual materials that did not include the primary event. By such a bootstrap process, it was possible to place photographs and videos extending over the entire period of the event on a single time line. Sets of photographs containing Exif times and video clips that either contained meta data or were continuous over relatively long periods were particularly useful for this purpose because a single time assignment would allow the entire series to be timed. Sets of photographs recorded on film or analog videos that were frequently turned on and off caused the most difficulty in timing, and individual matches were required for each photo or video clip.

Matching visual images and assigning times has turned out to be a demanding task requiring unique approaches. A variety of characteristics have been employed to match times in different photographs and videos. These include distinct shadows cast on the buildings by the smoke plumes, the appearance and locations of smoke and fire plumes, the occurrence of well-defined events such as a falling object or the sudden appearance of smoke, and a variety of other unlikely clues such as a clock being recorded in an image.

To assist in the timing process, relative times for the five major events of September 11, 2001: first plane strike, second plane strike, collapse of WTC 2, collapse of WTC 1, and collapse of WTC 7 have been determined with 1 second accuracy. These times are summarized in Table H-3. Note that the building collapse times are defined to be when the entire building is first observed to start to collapse. In the case of WTC 7, a penthouse on the roof sank into the building before the main collapse started.

Table H-3. Times for major events of September 11, 2001.

Event	Relative Time from Visual Analysis	Adjusted Time from Television Broadcasts	Time Reported in the FEMA Study
First plane strike	8:46:25 a.m.	8:46:30 a.m.	8:46:26 a.m.
Second plane strike	9:02:54 a.m.	9:02:59 a.m.	9:02:54 a.m.
Collapse of WTC 2	9:58:54 a.m.	9:58:59 a.m.	9:59:04 a.m.
Collapse of WTC 1	10:28:20 a.m.	10:28:25 a.m.	10:28:31 a.m.
Collapse of WTC 7	5:20:47 p.m.	5:20:52 p.m.	5:20:33 p.m.

It is not only important to assign relative times for photographs and videos, but also to estimate how accurately they are known. For this reason, timing uncertainties are estimated for each determination and are included in the databases.

The bootstrap timing process was initially quite difficult. However, team members' timing skills improved with practice at the same time as more visual material became available and the number of timed assets increased. At the present time, 3,032 of the 6,759 catalogued photographs and 2,673 of the 6,911 video clips in the databases are timed with assigned relative accuracies of 3 seconds or better.

H.3.4 Absolute Time Accuracy

Many of the news broadcasts on September 11, 2001, included small clocks, known in the industry as "bugs," imprinted on the screen. As such broadcasts were timed, it became apparent that there were small differences between times for the second plane strike based on these bugs and the time used as the basis for the database. Checks with several broadcasters indicated that the bugs should be quite close to the actual time because their clocks are regularly updated from highly accurate sources such as geopositioning satellites or the precise atomic-clock-based timing signals provided by NIST as a public service. Careful checks showed small time differences between different video recordings, but these were generally less than 1 second. These small discrepancies are likely due to variations in transmission times resulting from the different pathways that the video signals take to the sites where they are recorded. Based on four such video recordings, the time of the second plane impact is estimated as 9:02:59 a.m., or 5 seconds later than the time assumed in developing the database. The estimated uncertainty is 1 second. Table H-3 compares times for the major events taken from the database, adjusted to television time, and reported in the FEMA report (McAllister 2002). Possible explanations for the observed differences are still under investigation. Because times based on the television broadcasts appear to be accurate (i.e., those in column 3 of Table H-3), 5 seconds will be added to times included in the databases when precise times are reported for the Investigation.

H.4 ANALYSIS OF VISUAL IMAGES

Once the two visual databases became available, it was possible to use the images to begin characterizing the events of September 11, 2001. Some of the images are quite close up and can be used to learn specific details concerning the towers. As an example, Fig. H-6 shows an image of the east face of WTC 2 recorded at 9:26:20 a.m., and Fig. H-7 shows an enlarged portion of the same photograph. The photograph has been enhanced using Adobe Photoshop, and lettering has been added to indicate the floors and the numbering system used to identify specific windows in the tower. The amount of detail available is evident. For instance, large piles of debris are present on the north side of the tower on floors 80 and 81, and locations with fires visible or with windows missing are easily identified.

H.4.1 Window Numbering

The system used to describe window locations in the two towers and WTC 7 requires some elaboration. It is based on the outer-wall column numbering system used in plans for the buildings. First, consider the towers. In these structures individual windows were placed between two exterior columns. In order to refer to a particular window the designation for the column to the right as viewed from the outside is assigned to that window. These columns are numbered from 1 to 59 from right to left across a tower face, and windows are numbered from 1 to 58. Faces for the towers are also assigned numbers as follows; WTC 1—north: 1, east: 2, south: 3, and west: 4, and WTC 2—west: 1, north: 2, east: 3, and south: 4. By combining the floor number, the face number and a column number, a specific window on one of the




Figure H-6. Photograph taken at 9:26:20 a.m. on September 11, 2001, showing the east face of WTC 2. It has been enhanced, and lettering indicating floors and columns has been added.

towers can be identified. As an example, for WTC 1, the number 94-214 refers to the fourteenth window from the right on the east face of floor 94.

The window numbering system is somewhat different for WTC 7. It is also based on the outside column numbers, but in this building the numbering of columns was continuous around the structure and ranged from 1 to 57. Column 1 was located at the northwest corner of the building, and the numbering proceeded counter clockwise around the building faces with columns 15, 28, and 42 located at the southwest, southeast, and northeast corners, respectively. Note that the total number of perimeter columns is actually 58. An extra column, numbered 14A, was included on the west face between columns 14 and 15. Unlike the towers, the number of windows to the right of a given column varied from one to five depending on location. In some cases, the windows are located in front of the column. Individual windows to the right of a column are assigned letters increasing from left to right as seen from the outside. As an example, 12-45c refers to a window on the north face of WTC 7 that is the third window to the right of column 45 on floor 12.



Figure H-7. This photograph is cropped from the image shown in Figure H-6. It was taken on September 11 and shows the east face of WTC 2 at the northeast corner from floor 77 to floor 82. Note the large piles of debris evident on floor 80 and floor 81.

H.4.2 Fire Properties

Photographs and video images have been used to characterize a number of properties relevant to fire growth and spread in the towers as a function of time. Specific properties addressed include whether or not fire and smoke are present and whether windows are still in place. When smoke and/or fire are present, additional details concerning their appearances are documented. A numbered coding system is used to describe these characteristics. The key for this numbering system is shown in Fig. H-8.

H.4.3 Window-by-Window Assessment

The key in Fig. H-8 is used as the basis for a window-by-window assessment of the towers. The results are coded in three separate data sheets using Microsoft Excel. The floor and window locations are identified using the numbering system described in the last section. Separate files containing the three data sheets are generated for each face of a tower and time analyzed. Figure H-9 shows a portion of such a data sheet describing fires (i.e., sheet one) on the east face of WTC 1 around 9:42 a.m.

KEY FOR ANALYSIS

Sheet #1: Fire Visible

- | | |
|---|---------------------|
| 0 | No fire |
| 1 | Spot fire |
| 2 | Fire visible inside |
| 3 | External flaming |
| 9 | Not visible |

Sheet #2: Smoke

- | | |
|---|------------------|
| 0 | No smoke evident |
| 1 | “Light smoke” |
| 2 | “Heavy smoke” |
| 9 | Not visible |

Sheet #3: Windows

- | | |
|---|-----------------|
| 0 | Window open |
| 1 | Window in place |
| 9 | Not visible |

Figure H-8. The key used to describe observations with regard to fire, smoke, and window breakage in Excel data files for individual windows in the two towers.

	A	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ
1		238	237	236	235	234	233	232	231	230	229	228	227	226	225
2	110	9	9	9	9	9	9	9	9	9	9	9	9	9	9
3	109	9	9	9	9	9	9	9	9	9	9	9	9	9	9
4	108	9	9	9	9	9	9	9	9	9	9	9	9	9	9
5	107	9	9	9	9	9	9	9	9	9	9	9	9	9	9
6	106	9	9	9	9	9	9	9	9	9	9	9	9	9	9
7	105	9	9	9	9	9	9	9	9	9	9	9	9	9	9
8	104	9	9	9	9	9	9	9	9	9	9	9	9	9	9
9	103	9	9	9	9	9	9	9	9	9	9	9	9	9	9
10	102	9	9	9	9	9	9	9	9	9	9	9	9	9	9
11	101	9	9	9	9	9	9	9	9	9	9	9	9	9	9
12	100	9	9	9	9	9	9	9	9	9	9	9	9	9	9
13	99	9	9	9	9	9	9	9	9	9	9	9	9	9	9
14	98	9	9	9	9	9	9	9	0	0	0	0	0	9	9
15	97	9	9	9	0	0	0	2	2	2	0	0	0	0	0
16	96	3	3	3	3	2	2	2	2	2	0	0	0	0	0
17	95	2	2	2	0	0	0	0	0	0	0	0	0	0	0
18	94	0	0	0	0	1	0	0	0	0	0	0	0	1	0
19	93	0	0	0	0	0	0	0	0	0	0	0	0	0	0
20	92	2	2	2	2	2	2	2	2	2	2	2	2	2	2
21	91	0	0	0	0	0	0	0	0	0	0	0	0	0	0
22	90	0	0	0	0	0	0	0	0	0	0	0	0	0	0
23	89	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Figure H-9. A portion of the Excel spreadsheet describing fires on the east face of WTC 1 around 9:42 a.m. is shown. The numbers at the left refer to floors, and those at the top are the window numbers.

While the data sheets capture the desired behaviors, it is very difficult to use them to track changes without visualizing the results in some way. Two approaches have been developed for this purpose. The first employs a Web-based system that generates color-coded maps of the results contained in the data sheets. Figure H-10 shows such a map for the fire data included in the data sheet shown in Fig. H-9. The second approach uses the program Smokeview (Forney and McGrattan 2003; Forney, Madrzykowski, and McGrattan 2003) to generate a time-dependent visualization of the results. Smokeview was developed at NIST in order to display the results of fire dynamics calculations. In the current application, it is used to visualize the properties of interest on a three-dimensional representation of a tower façade as a function of time. Because Smokeview allows the point of view to be varied at will, this approach is a powerful means for investigating the temporal behavior of the fires on different faces of the tower. Figure H-11 shows a frame taken from a visualization in which results from the fire and windows data sheets for WTC 2 have been combined.




Figure H-10. A representation of fires for floors 91 to 100 on the east face of WTC 1 around 9:42 a.m. is shown. Results are taken from the Excel spreadsheet shown in Figure H-13. The color coding is based on the key shown. The color assignments are: 0-No fire, 1-Spot fire, 2-Fire visible inside, 3-External Flaming, and 9-Can't see.



Figure H-11. A single frame from a time-dependent visualization generated by Smokeview is reproduced here. The frame is a three-dimensional representation of the condition of windows and fires on WTC 2 from the time the second tower was struck at 9:02:59 a.m. until it collapsed at 9:58:59 a.m. The color assignments are: – window in place, – missing window, – external flaming, – fire inside, and – spot fire.

H.5 INITIAL DAMAGE PATTERNS ON WTC 1 AND WTC 2 DUE TO THE PLANE STRIKES

Close-up photographs and videos have been used to characterize the initial damage to the façades of the towers struck by the two planes along with precise determinations of the locations of the plane strikes. For WTC 2, analysis of videos has also been employed to estimate the speed of the airplane that struck the tower and to show that the tower swung back and forth for several minutes after it was struck. The period of the swinging has also been determined.

H.5.1 WTC 1

Damage Resulting from Plane Strike

A detailed drawing of the damage to the steel façade of WTC 1 was included in the FEMA *World Trade Center Building Performance Study* (McAllister 2002). A careful inspection using photographs and videos in the database confirmed the accuracy of this analysis. Figure H-12 shows a drawing that represents this damage. It is similar to that included in the FEMA report, but it incorporates several minor changes that better reflect the geometry of the north face of WTC 1 in the vicinity of the plane strike.

It was observed that the wing tips and the end of the vertical stabilizer at the plane's tail section damaged the aluminum column covers on the steel façade without cutting through the steel below or completely removing the covers. By inspection it was possible to map out locations on columns where the wingtips and the vertical stabilizer struck the tower. These locations were then transferred to the representation of the damaged steel façade shown in Fig. H-12 and are represented by dashed lines, with wings to the right and left and the vertical stabilizer in the center. The good agreement between the damage pattern and the wing tip locations is evident. It is reported in the FEMA report (McAllister 2002) and widely in the media that American Airlines Flight 11 struck floors 94 to 98 of WTC 1. The dotted horizontal lines on the left side of Fig. H-12 indicate the locations of concrete floors. It can be seen that while the tip of the left wing of the aircraft struck very close to the base of floor 94, the wing end marked column 153 at the very top of floor 93. It is evident from the figure that the right wing actually struck well up on floor 99 on column 109. The impacted floors therefore range from floor 93 to floor 99.

Fireballs and Missing Windows

Additional insights into the initial damage inflicted on the towers by the plane strikes can be obtained by considering locations where fireballs are observed immediately following the plane strikes as well as locations where windows are missing. Videos and photographs recorded during and immediately following the plane strike on WTC 1 show that significant fireballs formed at the plane strike location on the north face, as well as near the center of the east face and on the western side of the south face. Figure H-13 compares window damage for the four sides of WTC 1 immediately after the plane strike. The floors shown extend from 91 to 100. The missing windows on the north face are consistent with the plane strike location and strike angle. The plane struck very close to the center of the face. Interestingly, the damage on the east and west faces appears to be asymmetric with a much higher number of windows missing on the east face than on the west. This observation is consistent with the formation of a fireball on the east side of the tower and not on the west side. Areas obscured by smoke are also much larger on




Figure H-12. A drawing of the damage to the steel façade of WTC 1. The dark dotted lines show locations where the airplane wings and vertical stabilizer marked the aluminum cladding on columns.

the east side suggesting that more fire is present on this face as well. An asymmetry is also apparent on the south face where only a single window is missing on the east side while numerous windows are missing and significant smoke is present on the west side. Taken together, these observations suggest that debris and fuel from the airplane as well as any building materials and contents tended to pass straight across the building on the west side, while material on the east side was somehow reflected and more heavily damaged the east face.




Figure H-13. The condition of windows is shown for the four faces of WTC 1 around 8:47 a.m. shortly after it was struck by American Airlines Flight 11. The colors represent ■ - window open, ■ - window in place, and ■ - not visible.

Panel Section in Street

A photograph supplied by the NYPD provided additional details with regard to the initial damage suffered by WTC 1. Figure H-14 shows a full three-story three-column-wide steel panel section lying on the corner of Cedar Street near its intersection with West Street. This location is to the south of and roughly 210 m from the south face of WTC 1. The photograph was taken prior to the collapse of either tower. Closer inspection shows that there is an aircraft wheel embedded in one of the windows. The most likely source location for this panel section has been identified as being near the center of the south face of WTC 1 (i.e., columns 329 to 331) and extending from the middle of floor 93 to the middle of floor 96. This conclusion remains tentative since, as indicated in Fig. H-13, the area is obscured by smoke in all of the close-up photographs of the area in NIST's possession. If the location is identified correctly, the wheel is stuck in window 95-329.

H.5.2 WTC 2

Calculation of Plane Speed

One of the videographers who provided material to the Investigation filmed from the top of his apartment building located to the east of the WTC complex. His camera was located on a tripod so that the images are very steady. One of the events he captured was United Airlines Flight 175 as it approached WTC 2. Figure H-15 is a series of cropped frames captured from this video that show the plane approaching the building.

The images included in Fig. H-15 have been used to determine the speed of the plane as it approached the tower. This is done by identifying the locations of the nose and tail of the airplane relative to a fixed point defined to be the point on the frame where the plane passes out of sight behind the corner of the building. The plane is very nearly level relative to this point, so it is appropriate to simply count the number of picture elements, pixels, between this location and the two measurement points on the aircraft.

This analysis, which presumes that the aircraft at this time travels in a straight path such that the nose and tail pass through the same point in space, has the advantage of being independent of the orientation of the flight path with respect to the line of sight of the observer.

Figure H-16 shows the locations of the two points as a function of time. Using linear least squares curve fits, the exact relative times when the nose and tail pass the reference location are estimated. The difference between these two times is the period required for the entire length of the aircraft to pass the reference location. The result is 0.1939 s. Since the length of the plane is known to be 155.0 ft, the speed can be determined simply by dividing this length by the passage time to give $155.0 \text{ ft}/0.1939 \text{ s} = 799 \text{ ft/s} = 545 \text{ mph}$. An uncertainty estimate based solely on the uncertainty in the determined time difference yields a value of $\pm 18 \text{ mph}$ with 95 percent confidence.



Figure H-14. Photograph showing a full panel section lying in Cedar Street near its intersection with West Street. An aircraft wheel can be seen imbedded in one of the windows. The building behind the panel is Saint Nicholas Greek Orthodox Church and the lower section of WTC 2 can be seen across Liberty Street.

Note that the airplane speed and uncertainties are slightly different than listed in an earlier report (NIST 2003) due to a correction of the plane length to reflect the actual distance between the nose and the end of the body at the rear stabilizer and a math error in the uncertainty calculator. Uncertainties associated with aircraft motion that are not aligned with the aircraft body are judged to be less than the uncertainties in plane passage time.

Observation of WTC 2 Sway Following the Plane Strike

Close examination of the video revealed a perceptible movement of WTC 2 after it was struck by the aircraft. The building rocked back and forth much as a pendulum for at least 4 minutes. Image



© 2001 Scott Myers

Figure H-15. Series of sequential cropped frames taken from a video shot on September 11, 2001, showing the plane approaching WTC 2. The frames, ordered from left to right and top to bottom, are separated by 33.3 ms.




Figure H-16. Plots of pixel locations for the nose and tail of the plane that struck WTC 2 as a function of time taken from the images shown in Fig. H-15. Straight lines are the results of linear least squares curve fits to the data. Extrapolation of the lines to pixel 0 allows the time for the passage of the plane to be calculated.

analysis was used to enhance this motion and estimate the period required for the building to sway through one complete cycle. This was accomplished by creating a new video in which a single frame just prior to the plane strike was subtracted from subsequent frames. In this way, small differences between images can be identified. If the image is unchanged from the initial frame, the result should be a black image, but any changes in location or color will appear in the difference video. When this approach was applied to the video, a region of windows was observed on the building that seemed to appear and disappear. Figure H-17 shows several frames of a composite video formed by overlaying half frames of the original video and the difference video. In the initial frame (time = 0.0 seconds), the plane has not yet appeared and the difference frame is black. In the next frame (time = 10.7 seconds), the plane is approaching the building. The plane is evident in the difference frame since it represents a change in the frame. WTC 2 is still dark except near the top where changes due to smoke movement are apparent. In the third frame (time = 11.3 seconds), the plane has struck the building and dramatic changes in the appearance of the building façade in the difference frame occur. Careful inspection shows what appear to be curved lines running across the face of WTC 2. These curves result from an interaction between the straight lines formed by the windows on the tower and the straight lines of picture elements that make up the detector in the digital video camera. This well-known behavior is called the moiré effect. The moiré effect also provides a sensitive approach for determining the displacement of the building. Such an analysis is in progress and will be reported at a later time.




Figure H-17. Frames from a composite video are shown. The half frames on the left are taken from a video showing the plane strike on WTC 2, while the half frames on the right are generated by subtracting a frame recorded prior to the plane strike from all subsequent frames in the original video. Times refer to the period since the start of the difference video.

Following the plane strike, areas of the tower face above the strike floors become hidden by smoke, and it is difficult to see the moiré patterns in the difference frames. However, the area of the tower below the strike floors to the left of the building in the foreground continues to show a distinct difference pattern because it is not obscured by smoke. This pattern is apparent in the fifth frame (time = 30.9 seconds). On the other hand, frames 4 and 6 (times = 28.0 seconds and 33.5 seconds, respectively) have been chosen because they are near null points, and the area appears dark in the difference frame because the location of the building is essentially unchanged from its position before the plane struck. When the video is

played, the moiré patterns in this area of the tower face alternately appear and disappear in the difference video.

Because the absence of color is easiest to identify, it is straightforward to determine times when the null points occur in the difference image. Figure H-18 shows a plot of time versus null point number obtained from the difference video. The points fall on a straight line having a slope of 5.647 seconds \pm 0.008 seconds (95 percent confidence interval). Because the building passes through a null point twice during a single full oscillation, the period required for a single oscillation is 11.3 seconds.




Figure H-18. The time when null points are observed in the difference video following the plane strike on WTC 2 are plotted versus the null point number. The points fall on a very good straight line having a slope of 5.647 seconds \pm 0.008 seconds.

The measured oscillation period is consistent with measurements that are available from WTC 1 that yielded periods of 10.9 seconds in the east-west direction (averaged over a 9-year period that ended in 1993) and 11.6 seconds in the north-south direction (averaged over a 14-year period that also ended in 1993). The cores of the two towers were oriented perpendicular to each other so the motion monitored here should be comparable to the east-west direction of WTC 1.

Damage Resulting from the Plane Strike

The results of an analysis of the damage to the steel façade of the south face of WTC 2 are provided in Fig. H-19. Much of the steel damage pattern is revealed, but it should be noted, as indicated, that a portion of this face on the east side of the plane strike location was constantly obscured by smoke, and the detailed pattern could not be discerned. The FEMA report (McAllister 2002) also includes a figure describing the damage to the steel façade inflicted by United Airlines Flight 175. The pattern in Fig. H-19 differs somewhat from that provided in this earlier study. Some inconsistencies in façade dimensions have also been corrected in the current version.




Figure H-19. A drawing of the damage to the steel façade of WTC 2. The dark dotted lines show locations where the airplane wings and tail marked the aluminum cladding on the columns. The area shaded in gray was hidden by smoke and could not be observed.

As was true for WTC 1, in areas of the façade struck by the wing tips and the upper portion of the vertical stabilizer the aluminum covering was marked, but the aluminum covers were not removed and the steel was not cut through. Measurements for the location of the left wing tip were mapped out as shown in Fig. H-19. As already noted, the area at the end of the right wing was obscured by heavy smoke. However, there were brief periods when the location of the last column struck by the wing tip could be observed. This location is indicated on column 404 of floor 95 in Fig. H-19. The center of the plane strike is clearly located towards the east side of the face. The left wing mark extends to the bottom of the spandrel located below floor 78. The actual location of the concrete floor is well above this point, which means the lowest point struck lies on floor 77. Thus, the plane strike location on WTC 2 extends from floor 77 to floor 85. This can be contrasted to the FEMA study (McAllister 2002) and most media sources that report the floors struck extended from floor 78 to floor 84.

Fireballs and Missing Windows

Intense fireballs were observed on the south, east, and north faces of WTC 2 following the plane strike. Figure H-20 compares missing windows on floor 77 to floor 86 for the four faces of WTC 2 shortly after the plane struck at 9:02:59 a.m.

The distribution of missing windows on the south face traces roughly the outline of the plane strike, with missing windows increasing in height from left to right. Recall that a portion of the east side of this face could not be observed due to smoke obscuration. The analysis indicates that a very large number of windows were removed on the east face by the collision and subsequent fireball. This is particularly true on floor 80 to floor 82. Photographs and videos show that extensive areas of the aluminum covering the façade and holding windows were removed, exposing the steel panels, as a result of the plane strike and fireballs. This damage is much more extensive than observed on the east face of WTC 1, consistent with the plane strike occurring closer to this face. In contrast to the extensive damage on the east face of the tower, no missing windows were found on the west face.

A large number of windows are also missing on the north face of WTC 2. A substantial area of the aluminum façade was also removed during the plane strike and subsequent fireball. The missing windows on this face almost appear to be a mirror image of the south face with damage towards the center being on lower floors than on the eastern edge. This suggests that a great deal of debris passed through the entire length of the building. This hypothesis is supported by close up images that show large piles of debris on the east side of the north face on floor 80 and floor 81, and on floor 79 near the center of the face. Figure H-21 includes a photograph showing these debris piles. Recall that piles of debris were also evident on floor 80 and floor 81 on the north side of the east face (see Fig. H-7).

H.6 FIRE BEHAVIORS IN THE TWO TOWERS

Analysis of the fire spread in the towers is ongoing as this update is being prepared, but sufficient information is available to allow some of the fire characteristics to be described.




Figure H-20. The condition of windows is shown for the four faces of WTC 2 around 9:03 a.m. shortly after it was struck by United Airlines Flight 175. The colors represent ■ - window open, ■ - window in place, and ■ - not visible.




Figure H-21. An enhanced photograph of the north face of WTC 2 taken at 9:58 a.m. shows the east side of the north face. Piles of debris are evident on floor 80 and floor 81 on the northeast corner and on floor 79 to the right of column 230. The "cold" area extends over floor 80 to floor 82 from roughly column 229 to 240. There is a break in column 253 on floor 81, and the adjacent column, 254, is bent. Floors 80, 81, and 82 appear to be partially collapsed. It appears as if the collapsed floor 83 in the northeast corner has broken into sections.

H.6.1 WTC 1

It has already been mentioned that substantial fireballs formed on the north, east, and south faces immediately following the plane strike. A brief period of intense burning from openings on these faces was observed after the fireballs dissipated, but in a short period (on the order of 60 seconds) the fires seemed to “damp down” and very little flame and only light smoke was evident from the outside. This period of light burning lasted several minutes before fires began to reappear.

Rapid early fire growth was observed on the east side of the north face on floor 96 and floor 97, the center of the east face on floor 94 and floor 97, and the western side of the south face on floor 96. Even though relatively little initial damage was sustained by the west face, heavy smoke followed shortly by flame appeared around window 97-437 at 8:55 a.m. After this time, a very rapid fire spread was observed across the west face on this floor. Within a couple of minutes, over half of the windows were emitting smoke, and flames were visible in many. Even though floor 92 was not directly struck by the airplane, fire appeared on the east side of the tower on this floor shortly after 9:00 a.m.

Following the initial development of large fires, fire spread continued until WTC 1 collapsed around 10:28 a.m. At times the fires displayed the systematic, relatively slow spread expected for fire growth in a typical building. For instance, after the initial rapid growth phase, fires on floors 92, 94, 96, and 97 on the east face began to move deliberately toward the south. As they spread, the fires would burn intensely at a given location for a while before dying down. As a result, these fires developed the appearance of a wave moving slowly across the building.

There were also certain times and locations during which fire appeared to spread quite rapidly. Some of these episodes were clearly connected with rapid fire growth and likely flashover in rooms. During the first half hour, significant fires were observed toward the centers of floors 92, 94, 96, and 97 on the east face that were spreading towards the north. Each of these fires eventually reached a certain point where further fire spread was inhibited for many minutes. A review of building plans showed that walls of offices or meeting rooms were presented at the locations where fire spread was inhibited.

Apparently, these walls served as effective fire breaks that protected against further fire spread. However, for each of these floors fire and smoke eventually appeared at one of the windows beyond the walls, and after one of these windows was broken fire growth was extremely rapid and robust across the remaining windows. These observations are consistent with the occurrence of flashover within an enclosed space.

At other times, unusually rapid fire growth apparently occurred in areas that are believed to have been relatively open and not constrained by walls. One of these episodes occurred around 9:54 a.m. on the north face. Fire suddenly appeared on floor 96, a location to the west of the damage inflicted by the airplane. Within a very short period of time, fire could be seen in roughly 10 windows covering a distance of more than 30 ft.

Another example of very rapid fire growth appeared to take place on floor 98. In the early period of the fire, this floor did not appear to be heavily involved, and this remained true for quite a while. However, after 9:30 a.m., fire began to appear on this floor and by 10:00 a.m., fires were observed over significant lengths on all four faces of the tower.

One of the more unusual fire spread episodes in WTC 1 occurred just after the collapse of WTC 2 around 9:59 a.m. Within a couple of minutes, a large intense fire suddenly appeared on the south side of the west face on floor 104 in an area well above any other apparent fire. This unusual jump in fire location is difficult to explain, but is likely associated with vertical shafts located in the core of the tower.

For most of the time following the plane strike, no fire was observed on any of the floors on the south face over lengths extending from the eastern edge of the tower to near the center of the face. Fires were not observed in this region of the building until around 10:00 a.m. By the time this tower collapsed roughly 25 minutes later, intense fires extending over significant lengths of the originally uninvolved area were burning on floor 94 to floor 98 in this area.

A final example of rapid fire spread and growth in WTC 1 was described previously in the *May 2003 Progress Report* for the Investigation (NIST 2003). In this case, a line of smoke appeared suddenly over a significant length of floor 92 on the north face of WTC 1 at 10:18:48 a.m., or roughly 9 minutes before the collapse of the tower. Puffs of smoke were observed simultaneously on the north face from floors 94, 95, and 97. More isolated puffs were seen at the same time from floor 92 and floor 95 on the west face and from floor 92 on the south face. Very shortly (seconds) after the appearance of the smoke, a localized fire on floor 95 to the west of the plane strike location grew very rapidly and flames erupted from windows. Following the smoke release, a large fire began to spread rapidly across the western side of floor 92 on the north face. Previous to the appearance of the smoke, only small fires were evident on this floor. By the time the tower collapsed, this fire had spread across most of the floor and had reached the western wall. This fire was responsible for the large burst of flame from the north face observed when this tower collapsed.

H.6.2 WTC 2

The fire behavior observed in WTC 2 was qualitatively different than occurred in WTC 1. Intense fireballs were created by the released jet fuel on the south, east, and north faces immediately after the airplane struck the building. As observed for WTC 1, the fireballs were followed by a brief period (on the order of a minute) of intense flaming from windows over a large area of the building. Most of these flames then “damped down” as observed in WTC 1, but two regions of intense burning remained. One of these areas was located on floor 81 and floor 82 at the northeast corner of the tower. Flames were evident from windows on either side of the corner as well as the corner itself, which had become exposed by removal of the corner facing during the plane strike. This area is in the vicinity of large piles of debris formed during the plane strike. The second fire was located primarily on floor 79 just to the left of the center (roughly from windows 79-231 to 79-238) of the north face. This is in the area of the second debris pile described earlier. Both of these fires died slowly with time when compared to fires at other locations in WTC 1 and WTC 2. Both were still burning lightly when the tower fell 56 minutes after the plane strike.

A curious aspect of the fire behavior is the existence of an area of the building façade between these two fire locations on the north face where very little fire and/or smoke was observed before the tower collapsed. This area is roughly rectangular in shape, covering floor 80 to floor 82 and extending across windows 249 to 239. Infrared images recorded shortly following the plane strike showed that this region was quite cool relative to other sections close to the fires. This area will be referred to as the “cold spot.” Spreading fires seemed to move around this cold spot.

In general, the fires in WTC 2 appeared to be less active than those observed in WTC 1. The fires covered a smaller area of the façade and did not spread as quickly. This is true even when the shorter time between the plane strike and collapse for WTC 2 (1 hour 42 minutes for WTC 1 and 56 minutes for WTC 2) is taken into account. Nevertheless, there was significant fire spread, and instances of rapid fire growth similar to those seen in WTC 1 did take place.

Around 9:29 a.m., large flames and heavy smoke erupted from an area on the north face just to the right of the cold spot (around window 83-236) on floor 83. Four minutes and forty-one seconds later, flames suddenly appeared at a separate location on the same floor further to the right near window 83-226. Another area of fire formed just to the right of the cold spot on floor 82 around 9:54 a.m. or 5 minutes before the collapse. The fires on floor 79 of the north face also spread towards the west, approaching the western edge of the tower just prior to the collapse.

Initial fire growth on the east face was on floor 82. Around 9:12 a.m., flames could be seen in nearly half of the windows on this floor, and heavy smoke was pouring from additional windows. Only limited fire was evident on lower floors at this time. The fires on floor 82 grew smaller after this time, and most were no longer visible when the tower collapsed. Around 9:35 a.m., heavy flames and smoke appeared over large areas of floor 79 and floor 80. These fires abruptly died down 45 seconds later, before growing back slowly during the remainder of the time before the tower collapsed.


In the early period following the plane strike, fire growth on the south face was seen primarily on floor 81 with active fires present on both sides of the airplane strike location. Smaller isolated fires were present on other floors around the area damaged by the airplane. These fires were relatively quiet and stationary until just prior to the collapse. At 9:56 a.m., there was a sudden release of smoke along much of floor 80 extending from the area of the plane strike to near the western edge. During the next 2 minutes, an intense fire developed covering approximately windows 81-441 to 81-454.

No smoke or fire was observed near the floors struck by the airplane on the west face of WTC 2. Some smoke was apparent at windows higher on the face. This was most likely coming from windows broken by occupants located on these floors.


H.7 EVIDENCE FOR COLLAPSED FLOORS IN WTC 2

H.7.1 Hanging Objects

In the *May 2003 Investigation Progress Report* (NIST 2003), a photograph was shown in which there appeared to be a floor draped across a number of windows extending roughly from 310 to 342 across the east face of floor 82 of WTC 2. Figure H-22 compares an image taken shortly after the plane strike at 9:03 a.m. and one taken at 9:55 a.m. shortly before the tower collapsed. At the earlier time, the hanging object is already present, but is seen through the windows draped much higher on the floor 82. An interpretation consistent with these observations is that floor 83 along the east side of WTC 2 was partially collapsed over a significant fraction of its length by the passage of the plane through the building. At the later time the floor has sagged further. By reviewing a number of photographs and videos, it has been determined that the change in floor position occurred between 9:34 a.m. and 9:38 a.m.



9:03:41 a.m.



9:55:04 a.m.

Figure H-22. Images of the east face of WTC 2 taken shortly after the plane struck and shortly before the tower collapse are shown. An object that is most likely a floor can be seen through windows on floor 82 as indicated by the arrows. The object has dropped lower between the times the two photographs were taken.

Very similar objects, albeit of shorter length, are seen hanging in windows in images taken from the north. These objects are apparent in Fig. H-21 hanging below floors 81, 82, and 83. As seen through windows on floor 82 (corresponding to the floor 83), the floor appears to have split into at least two sections.

H.7.2 Molten Material

It has been reported in the FEMA report (McAllister 2002) as well as in the media that what appeared to be molten metal was observed pouring from the north face near the northeast corner. This is the area where the sustained fires were seen. Video records and photographs indicate that the material first

appeared at 9:51:52 a.m. and continued to pour intermittently from the building until the time of collapse. Some of the material can be seen falling in Fig. H-21. Close-up video and photographs of the area where the material is pouring from have been examined and show that it is falling from near the top of window 80-256. The most likely explanation for this observation is that the material had originally pooled on the floor above, that is, floor 81, and that it was allowed to pour out of the building when this floor either pulled away from the outer spandrel or sank down to the point where the window was exposed. The fact that the material appears intermittently over a several minute period suggests that the floor was giving way bit by bit.

The composition of the flowing material can only be the subject of speculation, but its behavior is consistent with it being molten aluminum. Visual evidence suggests that significant wreckage from the plane passed through the building and came to rest in the northeast corner of the tower in the vicinity of the location where the material is observed. Much of the structure of the Boeing 767 is formed from two aluminum alloys that have been identified as 2024 and 7075 and closely related alloys. These alloys do not melt at a single temperature, but melt over a temperature range from the lower end of the range to the upper as the fraction of liquid increases. The Aluminum Association handbook (Aluminum Association 2003) lists the melting point ranges for the alloys as roughly 500 °C to 638 °C and 475 °C to 635 °C for alloys 2024 and 7075, respectively. These temperatures are well below those characteristic of fully developed fires (ca. 1,000 °C), and any aluminum present is likely to be at least partially melted by the intense fires in the area.

H.8 PROGRESS ON COLLECTION OF IMAGES AND ANALYSIS FOR WTC 7

Visual material is also required to characterize the initial damage to, fire spread in, and collapse behavior of WTC 7. Considerable useful material has been collected, but the visual record for times between the collapses of WTC 1 and WTC 7 is much less complete than those for the two towers. The reasons for this are easy to understand. Following the collapses of the towers, most people were focused on escape or rescue. A large dust cloud was formed by the collapses, and fires developed that generated large amounts of smoke. Both tended to obscure views of WTC 7, particularly from the south due to the northwesterly wind direction on September 11, 2001.

Both photographs and videos have been included in the database that show fires and damage to the east, north, and west faces of WTC 7. Some of this material has been timed, but in general the record is insufficient to allow generation of a complete time line of fire behavior for the relevant period. Numerous images show the upper portion of WTC 7 from the south, but the actual face of the building is generally obscured by smoke. No clear images of the lower portion of the south face have been obtained despite a careful search and repeated appeals for the public's help. This is particularly unfortunate since most of the damage caused by the collapses of the towers, and particularly WTC 1, should have occurred on this face.

There is considerable interest in images showing the collapse of WTC 7. Currently, there are at least four videos in the database that include the collapse, primarily from northerly directions, as well as several photographs. While not ideal, these are providing adequate information for characterizing the collapse sequence, and some progress along these lines has been made.

An effort has begun to map out the same information concerning fires, smoke, and windows as in the towers using visual material in the database. This effort will continue with a goal of mapping out as much of the fire time line as possible based on the material in the database.

H.9 SUMMARY WITH KEY FINDINGS

This section provides a brief summary of progress on the collection and analysis of visual data along with key findings.

The approaches used to identify and obtain visual material related to the WTC disaster are described along with the approaches employed by NIST to archive and catalog the material. Material is either saved in its original digital format or digitized and saved, and a commercial software package has been used to provide data entry, a searchable database, and ready access to assets for review. The large numbers of attributes used to characterize the photographs and videos are included.

Separate databases are provided for photographic and video materials. A major effort has focused on assigning accurate times to the material, and the approaches used are summarized. In excess of 6,700 photographs and 6,900 video clips have been included in the databases and 45 percent and 39 percent, respectively, of these have assigned times accurate to 3 seconds or better.

Major events timed to an accuracy of 1 second are:

- First plane strike on WTC 1: 8:46:30 a.m.
- Second plane strike on WTC 2: 9:02:59 a.m.
- Collapse of WTC 2: 9:58:59 a.m.
- Collapse of WTC 1: 10:28:25 a.m.
- Collapse of WTC 7: 5:20:52 p.m.

An approach has been developed to characterize the observed fire behaviors at the periphery of the buildings on a window-by-window basis by determining whether windows are open or closed and whether smoke and/or fire are observed. If smoke is present, it is characterized as “light” or “heavy”, and fires are characterized as “spot” (a small local fire), “fire inside,” and “external flaming.” The observations are coded in separate electronic spreadsheets for each building, façade, and time.

Two approaches are used to visualize the fire-related parameters. The first is a Web-based application that displays single sides of the towers at a single time. The second is a time-dependent three-dimensional representation based on Smokeview (Forney and McGrattan 2003; Forney, Madrzykowski, McGrattan, and Sheppard 2003).

Photographs and videos have been used to characterize several aspects related to the plane strikes on the towers and the distribution of damage on the external faces. For WTC 1, locations where the ends of the wings and vertical stabilizer of the tail section struck the north face and the damage to the steel façade are mapped. The behavior of fireballs generated by the release of fuel as a result of the collision of the

aircraft with the tower and initial tower damage as reflected in broken windows is used to characterize the distribution of damage to the facades of the tower. In addition, it has been shown that an exterior panel section from the south face was dislodged and landed on the ground. It contained an aircraft wheel that passed through the tower.

The following conclusions are reached concerning the immediate effects of the plane strike on WTC 1:

- The airplane struck columns on the north face ranging from 109 to 152 and covering floor 93 to floor 99.
- Damage and initial fire growth were greater on the east face of the tower than on the west. Significant damage and early fire growth occurred on the west side of the south face, but not on the east side.
- A three-story panel section was knocked from the south side of the tower and had an aircraft wheel lodged in window 95-329.

Visual evidence related to the plane strike on the south face of WTC 2 is more extensive than for WTC 1. This has allowed additional analyses beyond the mapping of damage on the plane strike face and façade damage to the remaining faces. The following conclusions have been reached concerning the immediate effects of the plane strike on WTC 2:

- The aircraft struck the tower with a measured speed of 545 miles per hour \pm 18 miles per hour.
- The collision of the aircraft caused a measurable sway of the tower that lasted more than 4 minutes. The period of oscillation was 11.3 seconds.
- The airplane struck columns on the south face ranging from 404 to 443 and covering floor 77 to floor 85.
- Large areas of the façade were removed and/or damaged along the east face of the tower and on the eastern side of the north face. No façade damage or window breakage was evident on the west face.
- Debris piles are observed in the northeast corner of the tower primarily on floors 80 and 81. Debris is also evident towards the center of the north face on the floor 79.
- Column 253 on the north face is broken on the floor 81 and the column 254 is severely distorted.

Detailed maps for fire behavior are currently being made. This update characterizes general fire behaviors for the two towers and notes some particularly interesting observations. For WTC 1, the following observations are highlighted.

- Extensive fires observed immediately following the plane strikes and which are most likely associated with released jet fuel damped down after roughly 60 seconds.

- In the period following the plane strikes fires tended to reappear over a period of many minutes. Initial fire growth was principally observed on floor 96 and floor 97 on the north face, floor 94 and floor 97 on the east face, floor 96 on the south face, and floor 97 on the west face.
- Observed fire spread rates were quite variable. Examples of both relatively slow and very rapid apparent fire spread are described.
- Interior walls at several locations were inferred to protect areas of the towers for a period of many minutes, though they were typically eventually breached by nearby fires.
- Following the collapse of WTC 2, a large fire appeared and grew rapidly on the west face at floor 104.
- There was an extensive area of the façade on the eastern side of the south face for which no fire was observed until at least 1 hour following the plane strike. When fires finally did appear in this area their growth was rapid over multiple floors.
- A large amount of smoke was suddenly released from floor 92 on the north face at 10:18:40 a.m. Smoke was expelled simultaneously from other floors and faces. Immediately after the smoke release rapid fire growth was observed at an isolated location on floor 95 and across much of the west side of the north face on floor 92.

Observed fire behaviors for WTC 2 were somewhat different than for WTC 1. This is true even when the differences in times between plane strikes and collapses (1 hour and 42 minutes for WTC 1 and 56 minutes for WTC 2) are considered. The following observations concerning fire behavior in WTC 2 are emphasized:

- Extensive fires observed immediately following the plane strikes and most likely associated with released jet fuel damped down after roughly 60 seconds.
- Two regions of intense fire remained following the initial fire period due to jet fuel burning. These fires were located on floor 81 and floor 82 in the northeast corner and towards the center of the north face on floor 79. These fires burned for longer periods than observed elsewhere in WTC 1 and WTC 2. They are located in regions of the tower where debris piles are observed.
- No large fires were observed in a multi-floor region on the north face located between the two fire areas described in the last bullet.
- Initial fire growth in areas away from the sustained fires was along the east face of floor 82. Large fires did not appear on lower floors of this face until later and were sporadic in space and time.
- Prior to the tower collapse, fire spread primarily from east to west was observed on floors 79, 82, and 83 of the north face.

- A sudden release of smoke from windows on the west side of the south face on floor 80 occurred at 9:56:37 a.m. This was followed very shortly by the appearance of heavy fire.

A number of photographs and videos show what appears to be floor 83 hanging across window openings over a large fraction of floor 82 on the east face of WTC 2. This object is observed very shortly after the plane strike and is found to drop lower prior to the tower collapse. On the north face, shorter lengths of what appear to be floors 81, 82, and 83 are seen hanging through the windows below.

Starting around 9:52 a.m., a molten material began to pour from the top of window 80-256 on the north face of WTC 2. The material appears intermittently until the tower collapses at 9:58:59 a.m. The observation of piles of debris in this area combined with the melting point behaviors of the primary aluminum alloys used in the Boeing 767 suggest that the material is molten aluminum derived from aircraft debris located on floor 81.

The visual record for the period following the collapses of the two towers is much less complete than prior to this time. In addition to the general chaos caused by the collapses, significant dust and smoke from fires started by the collapses obscured the site. As a result, it has not been possible to identify clear visual images showing the damage to the south face of WTC 7 caused by the collapses of WTC 1 and WTC 2. The number of videos and photographs showing fires on the east, north, and west faces of WTC 7 is limited and sporadic. The images that are available are being used to generate an approximate time line for fire growth and spread.

H.10 REFERENCES

- Forney, G. P., and K. B. McGrattan. 2003. *User's Guide for Smokeview Version 3.1: A Tool for Visualizing Fire Dynamics Simulation Data*. NISTIR 6980. National Institute of Standards and Technology. Gaithersburg, MD.
- Forney, G. P., D. Madrzykowski, K. B. McGrattan, and L. Sheppard. 2003. Understanding fire and smoke flow through modeling and visualization, *IEEE Computer Graphics and Applications*, vol. 23, p. 6-13.
- McAllister, T., ed. 2002. *World Trade Center Building Performance Study: Data Collection, Preliminary Observations, and Recommendations*. FEMA 403. Federal Emergency Management Agency. Washington, DC, May.
- NIST (National Institute of Standards and Technology). 2003. *May 2003 Progress Report on the Federal Building and Fire Safety Investigation of the World Trade Center Disaster*. NIST Special Publication 1000-3. U.S. Department of Commerce, Washington, DC, May.
- The Aluminum Association. 2003. *Aluminum Standards and Data - 2003*. The Aluminum Association, Inc., Washington, DC.

This page intentionally left blank.

TABLE OF CONTENTS

List of Figures	I-ii
List of Tables	I-iv

Appendix I

Interim Report on Assessment of Sprayed Fireproofing in the WTC Towers—

Methodology.....	I-1
I.1 Introduction.....	I-1
I.2 Sensitivity of Thermal Response to Fireproofing Geometry	I-1
I.3 In-Place Conditions of Fireproofing before Impact	I-7
I.3.1 History of WTC Fireproofing.....	I-7
I.3.2 Specified Thickness of Fireproofing	I-8
I.3.3 As-Applied Thickness and Variability	I-9
I.3.4 Equivalent Thickness.....	I-20
I.3.5 Thickness of SFRM for Use in Analyses	I-23
I.4 Thermal Properties.....	I-25
I.4.1 Thermal Conductivity Measurements	I-25
I.4.2 Specific Heat Measurements	I-26
I.4.3 Density Measurements	I-27
I.5 Response to Impact.....	I-27
I.5.1 Mechanical Properties of SFRM	I-28
I.6 Summary	I-31

LIST OF FIGURES

Figure I-1. Model used to study effects of fireproofing thickness and variability of thickness on steel temperature	I-3
Figure I-2. Temperature distribution after 1 h of exposure to gas temperature of 1,100 °C (1,373 K).	I-3
Figure I-3. Variation of steel temperature (at a point 6 in. from end of plate) with time for different average thicknesses of fireproofing.....	I-4
Figure I-4. Example of “gap” in fireproofing on diagonal member of a bridging floor truss.....	I-5
Figure I-5. Effects of gap in fireproofing.....	I-6
Figure I-6. Example of plot matrix from sensitivity study of the effects of missing fireproofing and variability of fireproofing thickness on steel temperature.....	I-7
Figure I-7. Dotplot of average thickness from floor trusses for floors 23 and 24, histogram of average thickness, normal probability plot of average thickness, histogram of natural logarithm of average thickness, and probability plot of natural logarithm of average thickness.	I-12
Figure I-8. Example of measurement procedure used to estimate fireproofing thickness from photographs.....	I-14
Figure I-9. Normal probability plot of estimated fireproofing thickness based on photographs, and normal probability plot of natural logarithms of thickness.	I-16
Figure I-10. Dotplot of individual thickness measurements on floor trusses from Port Authority Construction Audit Reports, histogram of thickness measurements, normal probability plot of thickness measurements, histogram of natural logarithms of thickness measurements, and normal probability plot of natural logarithm of thickness measurements.	I-18
Figure I-11. Fireproofing thickness on floor trusses in upgraded portions of WTC towers	I-19
Figure I-12. Individual and average thickness for core columns, normal probability plot of individual measurements on columns, individual and average thickness for core beams, and normal probability plot of individual measurements on beams.	I-20
Figure I-13. Randomly generated thickness profiles with average thickness of 0.75 in. and standard deviation of 0.3 in., cumulative element size, and deformation of 1 in. bar compared with deformation for uniform thickness of fireproofing.	I-22
Figure I-14. Randomly generated thickness profiles with average thickness of 2.5 in. and standard deviation of 0.6 in., normal probability plots of thickness values, and deformation of 1 in. bar compared with deformation for uniform thickness of fireproofing.	I-24
Figure I-15. Preliminary test results: thermal conductivity as a function of temperature, and specific heat as a function of temperature.....	I-26
Figure I-16. Pull-off test of SFRM applied to steel plate.....	I-29

Figure I-17. Derivation of acceleration to dislodge SFRM from planar substrate.....	I-29
Figure I-18. Derivation of acceleration to dislodge SFRM surrounding a round bar.	I-30

LIST OF TABLES

Table I-1.	Specified passive fire protection.....	I-9
Table I-2.	Average fireproofing thickness from six measurements taken in 1994 on each of 16 random floor trusses on floors 23 and 24 of WTC 1.....	I-11

Appendix I

INTERIM REPORT ON ASSESSMENT OF SPRAYED FIREPROOFING IN THE WTC TOWERS—METHODOLOGY

I.1 INTRODUCTION

The structural steel in the World Trade Center (WTC) towers was “fireproofed” with sprayed fire resistive materials (SFRMs). These materials are packaged as dry ingredients, and water is added by a pressurized system as the materials are sprayed onto the steel. The water mixes with the cementitious materials and provides “stickiness” that allows the SFRM to adhere weakly to the steel. With time, the cementitious materials harden, and excess water evaporates. When dry, SFRMs provide an insulation barrier to reduce the vulnerability of the steel to excessive temperature rise during a fire.

Analysis of the effects of the fires on the structural capacity of the damaged WTC towers as a function of time requires knowledge about the condition of fireproofing on the various structural components, namely, the exterior columns, the spandrel beams, the floor trusses, and the core columns. Because of the method of application, sprayed fireproofing will have variable thickness, especially when applied to long, thin elements such as the diagonals and chords of the floor trusses. In addition, fireproofing was dislodged during the impact, either from direct impact by debris or from vibrations of the members. The thermal properties of the fireproofing also need to be known as a function of temperature.

The thermal-structural analysis of the WTC towers focused on two objectives: (1) analysis of the undamaged buildings exposed to postulated fires, and (2) analysis of damaged buildings exposed to the fires that occurred after impact. In order to reduce the uncertainties in the calculated thermal histories of various structural elements, the condition of the sprayed fireproofing as it existed on September 11, 2001, needs to be estimated as accurately as possible. In addition, reasonable estimates of the extent of fireproofing dislodged by the aircraft are needed. This appendix discusses the approach that will be used for this purpose.

To gain an understanding of the effect of fireproofing thickness and its variability on the steel temperature during exposure to fire, a simple finite-element model was used for a sensitivity study. The information gained from that study is reviewed first. A brief summary of the construction history of the sprayed fireproofing in WTC 1 and WTC 2 is presented. This is followed by a quantitative assessment of in-place thickness and its variability based on available data. The rationale for the thickness of fireproofing to be used in the structural fire endurance analyses is presented. The tests conducted to determine the thermal properties of fireproofing materials similar to those used in the WTC towers are reviewed. The approach used to gain an understanding of the inherent fragility of sprayed fireproofing is discussed, and the scheme for estimating the extent of damage during impact is summarized.

I.2 SENSITIVITY OF THERMAL RESPONSE TO FIREPROOFING GEOMETRY

The fireproofing thickness has a great effect on the thermal response of the structural elements for a given fire condition. While others have considered the effect of thickness of fireproofing, the effect of the

variation of thickness along the length of a member is not well known. A sensitivity study using finite element modeling of heat transfer was conducted to investigate the sensitivity of steel temperature to the variability in fireproofing thickness.

The simplified model that was used is shown in Fig. I-1. A 1 in. thick, 60 in. long steel plate (cyan color) was coated with fireproofing material (purple color) and subjected to the uniform radiative flux arising from a 1,100 °C fire. As shown in Fig. I-1 (b), the fireproofing is modeled with a layer of finite elements (0.125 in. thick and 0.6 in. long) having the thermal properties of fireproofing (purple). A parametric study was conducted with average thickness of fireproofing varying from 0 in. to 2 in. in increments of 1/4 in. The effect of variability in thickness was modeled by imposing a normal probability distribution on the fireproofing thickness along the length of the steel plate. The assumed standard deviation varied from 0 in. (uniform thickness) to 1 in. A psuedo-random number generator was employed to determine the thickness at each cross section based on the assumed average thickness and standard deviation. The layer representing fireproofing was taken to be twice the average thickness, and the thickness of fireproofing at any cross section was modeled by assigning a low heat capacity and a high thermal conductivity to those elements that do not provide fireproofing. Figure I-1 (c) shows an example of variable thickness fireproofing; in this case, the average thickness is 1 in. and the standard deviation is 3/8 in.

When the model in Fig. I-1 is exposed to the thermal flux representing an 1,100 °C fire, the surface of the insulation heats up quickly to the gas temperature ($1,100 + 273 = 1,373$ K). Numerical simulation was performed over a 2-h period, and the steel temperature at five locations was recorded at 30 min, 60 min, 90 min, and 120 min of exposure. The temperature recording locations are 6 in. from each end and at 12 in. intervals, which are shown as numbers 1 to 5 in Fig. I-1 (a). The initial temperature of the model is 300 K.

Figure I-2 shows temperature contours (in K) through the fireproofing and steel at 60 min after initial exposure for the model shown in Fig. I-1 (a). The fireproofing surface temperature is close to the gas temperature of 1,373 K, while the steel temperature is 311 K. If the fireproofing were of uniform thickness, the isotherms would be a series of lines parallel to the plate. It is seen that, when the thickness of fireproofing is variable, the isotherms follow the shape of the fireproofing surface contour. Thus, the temperature history at any point in the steel depends on the local thickness of the fireproofing.

Figure I-3 shows the steel temperature at the far sensor #1 (6 in. from the end) as a function of time for various insulation thicknesses ranging from 0 in. to 2 in. (the thickness is indicated by the numbers on the curves). For the case in Fig. I-3 (a), the fireproofing is of uniform thickness, and for the cases in Fig. I-3 (b), the thickness varies with a standard deviation of 1 in. The time to reach a temperature of 600 °C is used as a measure of relative performance. It is seen that the presence of high variability in thickness has a detrimental effect of the protection provided by the fireproofing. For example, for a uniform thickness of 0.5 in., it takes about 60 min for the steel at point #1 to reach 600 °C; but when the standard deviation of the thickness is 1 in., the average thickness has to be 1.75 for the same level of thermal protection.




Figure I-1. Model used to study effects of fireproofing thickness and variability of thickness on steel temperature: (a) physical model used in analyses (points 1 to 5 are locations where temperatures are monitored), (b) finite element mesh used to represent physical model, and (c) finite element model to represent variable thickness of fireproofing (purple) (the elements in red represent material of high thermal conductivity).




Figure I-2. Temperature distribution after 1 h of exposure to gas temperature of 1,100 °C (1,373 K).




Figure I-3. Variation of steel temperature (at a point 6 in. from end of plate) with time for different average thicknesses of fireproofing (shown as numbers on the curves): (a) uniform thickness, and (b) variable thickness with a standard deviation of 1 in.

In addition to the effect of variation in thickness, it is important to understand the effect of missing fireproofing over a portion of a member. As an example, Fig. I-4 shows missing fireproofing from a diagonal of a bridging truss of the WTC towers floor system. Figure I-5 (a) shows an example of a numerical model with missing fireproofing. In this case, there is 12 in. of missing fireproofing on the steel plate, which is otherwise protected by 2 in. of uniform thickness fireproofing. Figure I-5 (b) shows the temperature contours (isotherms) at time 50 min. For comparison, Fig. I-5 (c) shows isotherms at the same time in a plate with no gap in the fireproofing. As expected, the bare steel at the missing fireproofing is at the gas temperature, but more importantly the “gap” in fireproofing leads to a “leakage” of heat into the interior steel.




Figure I-4. Example of “gap” in fireproofing on diagonal member of a bridging floor truss.

The combined effects of variation in thickness of the fireproofing and length of missing fireproofing were examined by a factorial study with the following factors:

- Average thickness of fireproofing varying from 0 in. to 2.0 in. in 1/4 in. increments;
- Standard deviation of fireproofing thickness of 0 in., 0.25 in., 0.5 in., 0.75 in. and 1.0 in.; and
- Length of missing fireproofing varying from 0 in. to 30 in., in 6 in. increments.




Figure I-5. Effects of gap in fireproofing: (a) model of plate with fireproofing having 2 in. uniform thickness and 12 in. gap, (b) isotherms (K) at time = 50 min with 12 in. gap, and (c) isotherms without gap.

The results of the sensitivity study can be summarized in a series of plot matrices, which show the time histories of the steel temperature for different combinations of gap length and variability in fireproofing thickness. For example, Fig. I-6 shows the plot matrix for the temperature history at point #2 (18 in. from the end of the plate). Each plot contains a series of curves representing different average thickness of fireproofing, as in Fig. I-3. Each column of plots represents a constant value of thickness variability (standard deviation), and each row represents a constant gap length. The plot in the upper left corner represents the case of uniform thickness of fireproofing and no gap, which is the same plot as in Fig. I-3(a). (Note that for the case of uniform thickness and no gap, the steel temperature at any point in a cross section is the same along the length of the plate, as shown in Fig. I-5(c).) For gaps of 24 in. and 30 in., the temperature at point #2 rises rapidly because there is no fireproofing on the plate at that location. This explains the shapes of the curves in the two lower rows. In going from left to right in one of the top four rows it is seen that as variability of thickness increases, the time histories shift upward, thereby reducing the time to reach 600°C. This is the same observation as shown in Fig. I-3. Moving from the top to the bottom in any column shows the effects of increasing gap length. The effect of gap length depends, of course, on where the steel temperature is measured. At a point within the portion of steel that is bare, the temperature rises quickly. At points within the steel that are surrounded with fireproofing, the gap provides a path for heat flow, as shown in Fig. I-5 (b). As a result, points in the steel within the vicinity of the missing fireproofing will experience higher temperatures, as indicated by the rising trend of the curves in going downward from the top of a column in Fig. I-6. The National

Institute of Standards and Technology (NIST) does not have sufficient information to determine the frequency of occurrence of these gaps or their typical locations. Therefore, gaps in fireproofing will not be considered in the thermal modeling.




Figure I-6. Example of plot matrix from sensitivity study of the effects of missing fireproofing and variability of fireproofing thickness on steel temperature. Each graph is a temperature history of the steel at point #2 (see Fig. I-5) for different thicknesses of fireproofing.

I.3 IN-PLACE CONDITIONS OF FIREPROOFING BEFORE IMPACT

I.3.1 History of WTC Fireproofing

In Appendix 4 of the *May 2003 Progress Report* (NIST SP 1000-3), the history of the sprayed fireproofing, as reconstructed from available documentation, was reviewed. Basically, the following significant activities took place:

- 1969: Decision made to use 1/2 in. of CAFCO BLAZE-SHIELD Type D (asbestos fibers) sprayed fireproofing.

- 1970: Use of CAFCO BLAZE-SHIELD Type D was discontinued at the 38th floor of WTC 1; remaining fireproofing to use CAFCO BLAZE-SHIELD Type DC/F (mineral wool fibers).
- 1994: Thickness measurements of fireproofing on trusses of floors 23 and 24 of WTC 1.
- 1995: Port Authority performed study to establish sprayed fireproofing thickness for tenant alterations.
- 1999: Port Authority established guidelines for fireproofing repairs, replacement, and upgrades.
- Late 1990s: Floor truss fire protection upgraded to 1 1/2 in. during tenant alterations using CAFCO BLAZE-SHIELD Type II. In-place measurements of thickness, density, and bond strength recorded.

I.3.2 Specified Thickness of Fireproofing

WTC project specifications for spray-applied fireproofing do not provide required material thickness or hourly ratings. However, a letter dated October 30, 1969, from Robert J. Linn (manager, Project Planning, WTC) to Mr. Louis DiBono (Mario & DiBono Plastering Co., Inc.) states, in part:

...Tower "A" columns that are less than 14WF228 will require 2 3/16" thick of 'Cafco [B]laze-Shield Type D' spray-on Fireproofing. All Tower columns equal to or greater than 14WF228 will require 1 3/16" of fireproofing...

All Tower beams, spandrels and bar joists requiring spray-on fireproofing are to have a 1/2" covering of "Cafco."

No reference is made in this letter to the required thickness of fireproofing of core box columns or exterior built-up columns.

Alcoa was the supplier of the aluminum cladding on the exterior columns (Contract WTC 400.00), and the following "Note 11" was included among the "General Notes" of their drawings:

11. Exterior column and spandrel fireproofing—CAFCO BLAZE SHIELD Type D Fireproofing. Interior column and spandrel fireproofing—Vermiculite plaster aggregate fireproofing with finished plaster coat on exposed areas of columns. (3 hr on spandrels, 4 hr on columns)

Rating	Fireproofing Thickness	
	Cafco	Vermiculite Aggregate
4 hr (heavy column)	1 3/16"	7/8"
3 hr (spandrels)	1/2"	1/2"

In 1995, the Port Authority performed a study to establish the requirements for applying spray-on fireproofing to the floor trusses in the case of new construction (alterations conducted when tenants vacated the space) in the towers. The study estimated the fireproofing requirements for the floor trusses of the towers based on “the fireproofing requirements for Design No. G805 contained in the Fire Resistance Directory” of Underwriters’ Laboratories. The study concluded that 1 1/2 in. of spray-on mineral fiber fireproofing, “when applied directly to the chords and web members,” was sufficient to achieve the required 2 h rating for the floor trusses. In the years between 1995 and 2001, fireproofing was upgraded in a number of the floors affected by the fires on September 11, 2001.

The specified fire protection is summarized in Table I-1.

Table I-1. Specified passive fire protection.

Structural Component	Member Size	Location	Material	Thickness (in.)
Floor trusses	All	NA	CAFCO DC/F	1/2
Interior columns ^a	< 14WF228	NA	CAFCO DC/F	2 3/16
	≥ 14WF228	NA	CAFCO DC/F	1 3/16
Exterior columns	“heavy”	Exterior faces	CAFCO DC/F	1 3/16
	“heavy”	Interior faces	Vermiculite aggregate	7/8
Spandrel beams	All	Exterior face	CAFCO DC/F	1/2
	All	Interior face	Vermiculite aggregate	1/2

a. No thicknesses specified for core beams and box columns.

Key: NA, not applicable.

In a letter dated July 25, 1966, from Emery Roth and Sons to the Port of New York Authority, it is stated “Since the deck is non-structural it will not be fire proofed.” Photographs show that in some areas the underside of the metal deck was indeed not fireproofed, while in other areas fireproofing appears to be present but of undetermined thickness and possibly resulting from overspray. Photographs reveal that the dampers and damper saddles were not fireproofed. Additionally, it is unclear whether the bridging trusses were required to be fireproofed in all areas. Subsequent to the design and construction of the WTC towers, some information has been found that further describes the elements of the structural systems that were indeed fireproofed.

I.3.3 As-Applied Thickness and Variability

The actual thickness of a spray-applied fire protection material generally exceeds the specified thickness by some amount. Since both towers collapsed on September 11, 2001, and most of the fireproofing was either dislodged or abraded (or scraped) off in the collapse, no examples remain of the “as installed” condition of the fireproofing. To make an estimate of the as-applied thickness and variability in thickness, several sources of information have been employed, including measurements taken by the Port Authority, condition surveys and anecdotal information, and photographs and video clips showing the condition of the fireproofing in selected areas. Each of the structural components or systems is considered here separately.

Steel Truss-Supported Floor System

Qualitative information on the “as installed” fireproofing thickness for the floor system first appears in Sample Area Data Sheets from 1990, in which comments on the state of the in-place fireproofing were recorded. As an example, the data sheet for floor 29 of WTC 1 states the following for the South West quadrant of the floor:

Fluffy spray-on fireproofing coating the support beams, joists, and deck above the ceiling. The thickness of the material on the beams and joists was consistently about 1/2" Regarding the deck it ranged from very sparse [sic] in areas to 1/4" other areas.

Similar statements were recorded for the remaining quadrants of the floor.

Information regarding quantitative inspection of existing fireproofing appears in documentation from 1994. That year, the Port Authority performed a series of thickness measurements of the existing fireproofing on floors 23 and 24 of WTC 1. Six measurements were taken from “both flanges and web” of each of 16 randomly chosen trusses on each floor at those locations where the fireproofing was not damaged or absent.

The averages of six measurements per joist that were recorded on the two floors are presented in Table I-2. Measured average thickness varied between 0.52 in. and 1.17 in. For the 32 measurements (16 on each floor), the overall average was 0.74 in. and the standard deviation of these averages was 0.16 in. Four of the 32 floor trusses, had an average thicknesses between 0.52 in. and 0.56 in. These measurements suggest that the minimum average thickness exceeded 1/2 in.

This same report stated that, on floor 23,

... truss members located adjacent to the outside walls (within 3 ft) are devoid of fireproofing material. Visual inspection on floor 24 was not possible, as this area still has a lowered ceiling in place.

The data in Table I-2 can be examined further to understand the variability of the fireproofing thickness in the non-upgraded locations. Figure I-7 (a) shows the average thicknesses measured on the floor trusses of floors 23 and 24. The values appear to be similar for the two locations in terms of overall average thicknesses and the variation in average thickness. A formal analysis of variance indeed indicated no statistically significant differences between the overall mean thicknesses for the two floors. Thus, the two groups of data can be combined into one. A question to be answered is whether the values of average thickness follow a normal distribution. To answer this question, histograms and normal probability plots are used. Figure I-7 (b) shows a histogram of the average thicknesses, and it appears to be non-symmetrical and skewed to the right, which is characteristic of a lognormal distribution.¹ Figure I-7(c) is the normal probability plot of the average thicknesses for the combined data. If the points fall approximately on a straight line, it indicates that the data are normally distributed. It is seen that there are systematic deviations of the data from the best-fit line. To examine whether the data are represented better by a lognormal distribution, the average thicknesses, in Table I-2 were transformed by taking their

¹ In a lognormal distribution, the natural logarithms of the values of a variate have a normal distribution.

natural logarithm. Figure I-7 (d) is a histogram of the natural logarithms of thickness, and Fig. I-7(e) is the corresponding normal probability plot. It is seen that the data are less dispersed about the straighter line, and the correlation coefficient has increased from 0.97 to 0.99. Thus, there is some indication that the distribution of fireproofing thickness is lognormal in the non-upgraded floor trusses.

Table I-2. Average fireproofing thickness from six measurements taken in 1994 on each of 16 random floor trusses on floors 23 and 24 of WTC 1.

Fireproofing Thickness (in.)	
Floor 23	Floor 24
0.60	0.76
0.53	0.60
0.70	0.90
0.76	0.72
0.88	0.64
0.89	0.80
0.83	0.68
1.17	0.65
0.88	0.67
0.71	0.77
0.82	0.96
0.52	0.66
0.69	0.65
0.52	1.11
0.64	0.95
0.52	0.56

Source: Data provided by Port Authority of New York and New Jersey.

A lognormal distribution for the average thickness of the fireproofing on the non-upgraded floor trusses is explained as follows. It is expected that the thickness of fireproofing will be highly variable due to the difficulty in spraying the material on the relatively thin members. If the overall thickness is low and the variability is high, a normal distribution would require a fraction of the surfaces to have negative values of fireproofing. If the thickness distribution is lognormal, the thickness cannot be zero, and there is a low likelihood of having thickness close to zero. If the underlying distribution of fireproofing thickness is lognormal, the average thickness overestimates the thickness expected to be exceeded with 50 percent probability, and the median is the appropriate statistic for the 50 percentile value.




Figure I-7. (a) Dotplot of average thickness from floor trusses for floors 23 and 24, (b) histogram of average thickness, (c) normal probability plot of average thickness, (d) histogram of natural logarithm of average thickness, and (e) probability plot of natural logarithm of average thickness.

As stated, the standard deviation of the average thicknesses in Table I-2 is 0.16 in. Since each of the averages is based on six individual measurements, the variability in average thickness is less than the variability of the fireproofing thickness on a given element. If it is assumed that the true average thicknesses of fireproofing at the truss locations represented in Table I-2 are the same, it is possible to estimate the variability of individual measurements from the following well-known relationship:

$$S_{\overline{X}} = \frac{S}{\sqrt{n}} \quad (I.1)$$

where:

$S_{\overline{X}}$ = standard deviation of the average thicknesses

S = standard deviation of the individual thickness measurements

n = number of measurements to obtain the average thickness

Thus, an estimate of the standard deviation of the individual measurements is $0.16\sqrt{6} \approx 0.4$ in. Since it is unlikely that there is no difference in average fireproofing thickness at different cross sections, the standard deviation of 0.4 in. is an upper limit for the variability of fireproofing thicknesses in the non-upgraded floor trusses on the basis of the information provide in Table I-2.

Analysis of Photographs

Additional data regarding the thickness of fireproofing has been gathered by evaluating photographic evidence. Although photographic evidence of the state of the fireproofing is limited, two groups of photographs have been located and used for estimating fireproofing thickness.

The first group of photographs was provided to NIST by Morse Zehnter Associates and includes images of floor trusses from WTC 1 (floors 12, 22, 23, and 27) and WTC 2 (floor 26). From this group, only photographs from floors 22, 23, and 27 of WTC 1 were analyzed. Photographs provided by Morse Zehnter Associates were taken in the mid-1990s and illustrate the fireproofing conditions prior to the upgrade carried out by the Port Authority. Thus, fireproofing thickness on the photographed trusses should be at least 1/2 in. as specified by the Port Authority on October 1969.

The second group of photographs, taken in 1998, was provided by Gilsanz Murray Steficek (consulting engineers). This group illustrates the state of fireproofing after the upgrade program that was initiated in 1995. The photographs were of trusses for floor 31 and below in WTC 1.

Selection of which photographed trusses were used to estimate thickness of fireproofing was based on clarity of fireproofing edges and whether a feature of known dimensions was present. Thus, only photographs where reference measurements could be performed were used. The general approach to the analysis involved the estimation of distances based on the computed reference length per pixel. The procedure is summarized as follows:

- A feature of known dimension (based on construction drawings) that could be used as reference was located in the photograph. For example, the dimension of the bare vertical leg of a damper saddle was a dimension that could be obtained from shop drawings.

- In the photograph, the length of the reference dimension was measured in pixels.
- The scaling factor of length per pixel was computed by dividing the known dimension in inches by the number of pixels. For example, if the vertical leg of the damper saddle was measured as 48.2 pixels in the photograph, and it is known that the actual size of the leg was 3.13 in., the scaling factor would be $3.13 \text{ in.} / 48.2 \text{ pixels} = 0.065 \text{ in./pixel}$.
- Only truss webs or struts (diagonal bar at end of truss) located near and in the same plane as the reference object were selected for analysis. This selection was made to minimize error due to perspective.
- It was assumed that the fireproofing on web bars was applied evenly around the perimeter of the bar. Based on this assumption, a “virtual” centerline along the length of the bar was drawn in the photograph.
- Lines were drawn perpendicular to the “virtual” centerline. The number of pixels along the lines from the “virtual” centerline to the edge of the fireproofing was determined from the cursor positions indicated by the software. Measurements were made at regularly spaced intervals to avoid bias. Figure I-8 is an example of a series of measurements made on a strut.




Figure I-8. Example of measurement procedure used to estimate fireproofing thickness from photographs.

- Each measurement in pixels was multiplied by the scaling factor (in./pixel) to estimate the bar radius plus fireproofing thickness.

- The radius of the bar was subtracted to provide the estimate of the fireproofing thickness.

It was observed that the estimated thickness of fireproofing in the non-upgraded floors tended to be larger for the webs of the main trusses. Hence estimates of fireproofing thickness were divided into three groups:

- Webs of main trusses,
- Webs of bridging trusses, and
- Diagonal strut at the exterior wall end of the truss.

No estimates of fireproofing thickness on top and bottom chords were possible using photographs. For the upgraded floors in WTC 1 that were included in the second group of photographs, only estimates of the thickness on the web bars of the main trusses were made. Figure I-9 (a) shows normal probability plots of the fireproofing thickness estimated from the photographs. It is seen that the points for the “upgraded” main trusses follow a generally linear trend, which indicates that the estimated thicknesses for the upgraded main trusses are approximately normally distributed. The estimated thicknesses from the non-upgraded floors, however, do not follow linear trends on the normal probability plot. Figure I-9 (b) shows normal probability plots of the natural logarithms of the thicknesses. The transformed values for the non-upgraded fireproofing now follow generally linear trends, which means that a lognormal distribution is more appropriate for the non-upgraded floors. This reinforces the observation noted in the previous section. Thus there is strong evidence that the original fireproofing thickness on the floor trusses follows a log normal distribution.

The average, standard deviation, and coefficient of variation were computed for the total number of measurements in each of these groups. The results are summarized as follows:

- Main trusses before upgrade: Average thickness 0.6 in., standard deviation = 0.3 in., and coefficient of variation = 0.5.
- Bridging trusses before upgrade: Average thickness 0.4 in., standard deviation = 0.25 in., and coefficient of variation = 0.6.
- Diagonal struts before upgrade: Average thickness 0.4 in., standard deviation = 0.2 in., and coefficient of variation = 0.5.
- Main trusses after upgrade: Average thickness 1.7 in., standard deviation = 0.4 in., and coefficient of variation = 0.2.

Port Authority Data on Upgraded Fireproofing on Trusses

As discussed in the *May 2003 Progress Report* (NIST SP 1000-3), the Port Authority provided information on fireproofing thickness from tenant alteration Construction Audit Reports prepared in 1997 to 1999. Those reports included average thicknesses of fireproofing at the “bottom of truss.” In 2004, the Port Authority provided NIST reports of the individual measurements for many of the average thicknesses in the Construction Audit Reports. With the individual measurements, it is possible to investigate the




Figure I-9. (a) Normal probability plot of estimated fireproofing thickness based on photographs, and (b) normal probability plot of natural logarithms of thickness.

variation of thickness at a cross section of a truss member and the variation in average thickness from truss to truss. To permit such analyses, only those data having the same number of individual measurements at each cross section were used. This resulted in 18 data sets for WTC 1 (including floors 93, 95, 98, 99, and 100) and 14 data sets for WTC 2 (including floors 77, 78, 88, 89, and 92).

An analysis of the individual measurements was carried out to determine the underlying distribution for the measured thicknesses. Figure I-10 (a) is a dotplot of the individual measurements in WTC 1 (144 measurements) and in WTC 2 (112 measurements). It is observed that the central values and ranges

are similar for the two towers, and the two groups of measurements were combined into one group. Figure I-10 (b) is the histogram of the individual measurements, and Fig. I-10 (c) is the corresponding normal probability plot. A straight line fit to the normal probability plot shows a tendency of the points to deviate from the line. Figure I-10 (d) is a histogram of the natural logarithms of the individual thickness values, and Fig. I-10 (e) is the corresponding lognormal probability plot. A comparison of the probability plots shows that natural logarithms fall closer to a straight line. Thus, it appears that the thickness of the upgraded fireproofing on the floor trusses is described by a lognormal distribution. This contradicts the observation based on analysis of photographs from lower floors discussed in the previous section. The overall average thickness of the 256 individual measurements is 2.5 in. with a standard deviation of 0.6 in. Thus, the average thickness on the upgraded upper floors appears to be greater than that estimated from photographs taken on upgraded lower floors.

The overall standard deviation of 0.6 in. includes two contributions: (1) the variation of thickness at the cross section (within-truss variability), and (2) the variation of average thickness between trusses (between-truss variability). Figure I-11 shows these two components of the thickness variability for the two towers. Figures I-11 (a) and (c) show the within-truss variability, and Figs. I-11 (b) and (d) show the variation of average thickness of each truss. From analysis of variance, it was found that the within-truss standard deviation is 0.4 in., and the between-truss standard deviation is also 0.4 in. The within-truss standard deviation of 0.4 in. is similar to the standard deviation of the estimated individual thickness obtained from analysis of the photographs of upgraded main trusses.

Column Fireproofing Thickness

NIST requested that the Port Authority provide available information on the thickness of fireproofing for the exterior and interior columns of the WTC towers. Specifically, the request included the following:

- The fireproofing material used and the thickness on the various plates comprising the exterior columns and spandrels.
- The fireproofing material used and the thickness on core columns.
- Confirmation that the wide flange column sections were protected with CAFCO BLAZESHIELD Type DC/F with specified thickness of 2 3/16 in. for sections smaller than 14WF228 and 1 3/16 in. for 14WF228 and larger.
- Information on in-place fireproofing thickness.

The Port Authority replied that, due to inaccessibility of exterior columns and core columns, there were no recent records of fireproofing thickness for these elements. The only available measurements of fireproofing thickness were for beams and columns accessible within elevator shafts. The most complete data set included measurements on beams and columns taken within shaft 14/15 in WTC 1. These measurements were taken in April 1999 and included measurements from floor 1 to floor 45. The thicknesses were recorded to the nearest 1/8 in., with a few thicknesses recorded to the nearest 1/16 in. The columns included 10 to 18 replicate measurements, and the beams included 11 to 16 replicate measurements.




Figure I-10. (a) Dotplot of individual thickness measurements on floor trusses from Port Authority Construction Audit Reports, (b) histogram of thickness measurements, (c) normal probability plot of thickness measurements, (d) histogram of natural logarithms of thickness measurements, and (e) normal probability plot of natural logarithm of thickness measurements.




Figure I-11. Fireproofing thickness on floor trusses in upgraded portions of WTC towers: (a) individual measurements in WTC 1, (b) average thickness in WTC 1, (c) individual measurements in WTC 2, and (d) average thickness in WTC 2.

Figure I-12 (a) shows the individual and average fireproofing thickness on the core columns. Analysis of variance indicated no statistically significant differences among the average values and all data were pooled together. The average thickness for the columns is 0.82 in., the standard deviation is 0.20, and the coefficient of variation is 0.24. The information from the Port Authority indicated that the “minimum thickness required” for the columns was 0.5 in. Figure I-12 (b) is the normal probability plot of the individual thickness measurements. Because most of the thicknesses were reported to the nearest 1/8 in., the points are staggered instead of uniformly distributed. The plot, however, shows that the points follow a linear trend, and it appears that the thickness of the fireproofing on the core columns could be described by a normal distribution. Figures I-12 (c) and (d) shows the corresponding plots for the thickness of fireproofing on the beams. The average thickness for the beams is 0.97 in., the standard deviation is 0.21 in. and the coefficient of variation is 0.21. The information from the Port Authority indicated that the “minimum thickness required” for the beams was 0.75 in.




Figure I-12. (a) Individual and average thickness for core columns, (b) normal probability plot of individual measurements on columns, (c) individual and average thickness for core beams, and (d) normal probability plot of individual measurements on beams.

As might be expected, the variation in thickness of fireproofing for the beams and columns is lower than the variation observed in the floor trusses. The planar surfaces of the beams and columns result in more uniform application of the sprayed fireproofing than for the slender truss members. This results in reduced differences in the average thickness of fireproofing on different members and less variability within a member.

I.3.4 Equivalent Thickness

The sensitivity study summarized in Section I.2 indicated that variation in the thickness of fireproofing reduced the “effective thickness” of the fireproofing. It would be impractical to attempt to account for the variation in fireproofing thickness in the thermal modeling by introducing variable thickness fireproofing in the finite-element models. As an alternative, it was decided to attempt to determine the “equivalent uniform thickness” of fireproofing that would result in the same thermo-mechanical response of a

member as variable thickness fireproofing. An approach similar to the methodology described in Section I.2 was used to model a 1 in. diameter by 60 in. long bar with fireproofing and subjected to the heat flux arising from a 1,100 °C fire. The bar was subdivided into 0.6 in. long elements, so that there were 100 elements along the length of the bar. The thermal history of the bar was calculated, and that history was used to calculate the length change of the unrestrained bar under a tensile stress of 12,500 psi. The bar was assumed to be similar to the steel used in the floor trusses, and the temperature dependence of the coefficient of thermal expansion and the modulus of elasticity were based on NIST measurements.

The fireproofing thickness in the models was based on the measurements summarized in the previous section for the web bars of main trusses in the original condition and after the upgrade. Specifically, the following target values were investigated:

- Original: average thickness = 0.75 in., standard deviation = 0.3 in., lognormal distribution.
- Upgrade: average thickness = 2.5 in., standard deviation = 0.6 in., lognormal distribution.

The variation of fireproofing thickness along the length of the bar was established by using a psuedo random number generator to select values from a lognormal distribution with central value and dispersion consistent with the above average values and standard deviation. Three sets of random data were generated for each condition.

When the randomly selected thicknesses of each element were applied to the bar, it resulted in sudden changes in fireproofing thickness along the length of the bar. This resulted in a “rough” surface texture as shown by the dotted thickness profile in Fig. I-13 (a). It was felt that this rough texture (see also Fig. I-1 (c)) might not be representative of actual conditions, so an alternative approach was to use 5-point averaging to reduce the roughness of the fireproofing profile. The solid line in Fig. I-13 (b) shows such a “smooth” profile. The two profiles in Fig. I-13 (a) have approximately the same average value and standard deviation and have similar cumulative distribution of fireproofing thickness as shown in Fig. I-13 (b).

As stated, the calculated thermal histories of the bar elements were used to calculate the unrestrained length change of the bar due to thermal expansion and an applied stress of 12,500 psi. Work is currently underway to examine the performance of the bar under fully restrained conditions in which the induced stress history is computed. For comparison, the deformation of the bar with different but uniform thickness of fireproofing was calculated. The “equivalent thickness” was taken as the uniform thickness that resulted in similar deformation as under the variable thickness conditions. Figure I-13 (c) shows the results of these calculations for the original fireproofing. The three continuous curves are the deformation-time relationships for uniform thickness of 0.4 in., 0.5 in., and 0.6 in. The solid symbols represent the results for three cases with “rough” texture, and the open symbols are for the “smooth” texture. The following values summarize the six variable thickness profiles:

- Rough 1: average = 0.79 in., standard deviation = 0.29 in.
- Rough 2: average = 0.77 in., standard deviation = 0.27 in.
- Rough 3: average = 0.79 in., standard deviation = 0.31 in.




Figure I-13. (a) Randomly generated thickness profiles with average thickness of 0.75 in. and standard deviation of 0.3 in., (b) cumulative element size, and (c) deformation of 1 in. bar compared with deformation for uniform thickness of fireproofing.

- Smooth 1: average = 0.79 in., standard deviation = 0.28 in.
- Smooth 2: average = 0.78 in., standard deviation = 0.31 in.
- Smooth 3: average = 0.78 in., standard deviation = 0.32 in.

Figure I-13 (c) shows that the “rough” texture reduces the effectiveness of the fireproofing by a small amount compared with the “smooth” texture. As noted above, it is believed that the “smooth” texture is more representative of the actual conditions. On the basis of these analyses, it is concluded that fireproofing with an average thickness of 0.75 in. and a standard deviation of 0.3 in. provides equivalent protection to 0.6 in. of uniform thickness.

The results for the upgraded fireproofing are shown in Fig. I-14. Only the “smooth” texture was used, and the values for the three cases are as follows:

- Case 1: average = 2.50 in., standard deviation = 0.71 in.
- Case 2: average = 2.43 in., standard deviation = 0.51 in.
- Case 3: average = 2.55 in., standard deviation = 0.63 in.

Figure I-14 (a) shows the three profiles, and Fig. I-14 (b) shows the normal probability plots of thickness values. Because the three randomly generated profiles do not have the same averages and dispersions, the responses show more scatter than in Fig. I-13 (c). On the basis of these analyses, it is concluded that an average thickness of fireproofing of 2.5 in. with a standard deviation of 0.6 in. is equivalent to 2.2 in. of uniform thickness.

I.3.5 Thickness of SFRM for Use in Analyses

Analyses of available data on fireproofing thickness and thermal modeling revealed the following:

- From measurements of fireproofing thickness, the average values exceeded the specified thickness.
- Fireproofing thickness was variable, and the distribution of thickness in the floor trusses appears to be described best by a lognormal distribution.
- The standard deviation of fireproofing thickness on the trusses varied between about 0.3 in. to 0.6 in.
- The standard deviation of fireproofing on columns and beams from the core tended to be lower, with a value of 0.2 in. for the available data.
- No information is available on the fireproofing thickness on the exterior columns and spandrel beams.
- Variation in thickness reduces the effectiveness of fireproofing, and the equivalent uniform thickness is less than the average thickness.




Figure I-14. (a) Randomly generated thickness profiles with average thickness of 2.5 in. and standard deviation of 0.6 in., (b) normal probability plots of thickness values, and (c) deformation of 1 in. bar compared with deformation for uniform thickness of fireproofing.

Based on the above findings, the following uniform thickness for the undamaged fireproofing will be used in calculating thermal response under various fire scenarios:

- Original fireproofing on floor trusses: 0.6 in.
- Upgraded fireproofing on floor trusses: 2.2 in.
- Fireproofing on other elements: the specified thickness.

The choice of specified thickness for those members lacking data is justified by offsetting factors as follows: (1) measured average thicknesses exceed specified values, and (2) variation in thickness reduces the effectiveness of fireproofing.

I.4 THERMAL PROPERTIES

Based on the information provided by the manufacturers, three SFRMs have been identified in WTC 1, 2, and 7: (1) CAFCO BLAZE-SHIELD Type DC/F, (2) CAFCO BLAZE-SHIELD Type II, and (3) Monokote MK-5. Of the three SFRMs, only CAFCO BLAZE-SHIELD Type II is currently sold in the U.S., and CAFCO BLAZE-SHIELD Type DC/F is sold in Canada.

CAFCO BLAZE-SHIELD Type DC/F is manufactured by Isolatek International (Stanhope, New Jersey) and was used in the interior columns, floor systems, and the exterior faces of the exterior columns of WTC 1 and WTC 2. CAFCO BLAZE-SHIELD Type II, also from Isolatek, was used in subsequent retrofit of WTC 1 floor systems. CAFCO BLAZE-SHIELD Type DC/F and Type II are portland cement-based products. Monokote MK-5 a gypsum-based SFRM, was manufactured by W.R. Grace and Co. (Cambridge, Massachusetts) and used in WTC 7. W.R. Grace stopped the production of Monokote MK-5 in the 1980s. In addition to these three SFRMs, vermiculite plasters, manufactured by W.R. Grace until the 1970s, were used on the interior faces of the exterior columns of WTC 1 and WTC 2.

To provide thermophysical property data for the modeling effort in fire-structure interaction, the thermal conductivity, specific heat and density of each SFRM were determined as a function of temperature up to 1200 °C. Tests were performed by Anter Laboratories, Inc. in Pittsburgh, PA through an open-bid contract. Anter Laboratories is an ISO 9002 certified company.

Samples of CAFCO BLAZE-SHIELD Type DC/F and Type II were prepared by Isolatek, Inc. in Stanhope, New Jersey, and sample of Monokote MK-5 were prepared by W.R. Grace and Co. in Cambridge, Massachusetts according to their respective application manuals. Since Monokote MK-5 is no longer on the market, it was specially manufactured by W.R. Grace according to the original MK-5 formulation. The samples were made from the same batch of raw material, shipped to NIST for examination and documentation, and sent to Anter Laboratories for testing. The sample is 9 in. long, 4.5 in. wide, and 3 in. thick. Three samples of each material were sent for testing. Two of them were used for the thermal conductivity measurements, and the third was used to prepare specimens for the other measurements involved.

I.4.1 Thermal Conductivity Measurements

The thermal conductivity measurements were performed according to ASTM C 1113 Test Method for Thermal Conductivity of Refractories by Hot Wire (Platinum Resistance Thermometer Technique). This test method is based on heating two specimens with a platinum wire placed between them. The thin platinum wire serves not only as a heater, but also as a temperature sensor, since the variation of its electrical resistance during the test is converted into variation of temperature. Thermal conductivity is calculated based on the rate of temperature increase of the wire and power input. It was reported that substantial shrinkage during the measurements occurred for the three materials. The two MK-5 specimens shrunk, exposing the platinum wire positioned between them. For this reason, no thermal conductivity measurement could be performed for this material at 1,200 °C. Figure I-15 (a) shows preliminary results for thermal conductivity as a function of temperature. The results show similar trends of increased thermal conductivity with increasing temperature; however, the Monokote MK-5 specimens had a different behavior than CAFCO BLAZE-SHIELD Type DC/F and Type II at temperatures above 500 °C.




Figure I-15. Preliminary test results: (a) thermal conductivity as a function of temperature, and (b) specific heat as a function of temperature.

I.4.2 Specific Heat Measurements

For the specific heat capacity measurements, the same instrument (Unitherm Model QL-3141) was used with a slight modification. A thermocouple was added to the system and mounted on the specimen, parallel with the platinum wire at a known distance from the thermocouple. The test was performed in a similar manner as the thermal conductivity measurements, but from the thermocouple output the thermal diffusivity of the material was derived. Knowing the thermal conductivity, the thermal diffusivity, and the density calculated from the thermal expansion results and the thermogravimetric analysis, the specific heat of the material was calculated. Figure I-15 (b) shows preliminary results for specific heat as a function of temperature. It is seen that the materials had similar increasing trends with temperature, but the actual values differed.

1.4.3 Density Measurements

Densities of the samples were not measured directly (except at room temperature) but were calculated from TGA (thermal gravimetric analysis) and thermal expansion measurements. The TGA tests were performed according to ASTM Test Method E1131 using an Orton Model ST-736 TGA instrument. The thermal expansion tests were performed according to ASTM Test Method E228 using a Unitherm Model 1161 instrument. Since the materials were not isotropic, separate tests were performed for the X and Z orientations. It was assumed that the X and Y directions had the same thermal expansion. The Z direction was defined as the direction perpendicular to the fibrous strands in the specimens. The specimens were tested from room temperature to 1,200 °C at a heating rate of 2 °C/min. All of the specimens shrank during the tests and, in all cases, lost contact with the pushrod before reaching the maximum test temperature.

From the thermal expansion test results, the change in volume for each material was calculated at each temperature of interest. The density values were calculated from the results of the TGA and thermal expansion.

1.5 RESPONSE TO IMPACT

In order to estimate the extent of damage or loss of SFRM due to aircraft impact, the detailed finite element analysis of aircraft impact into the WTC towers, conducted within the framework of Project 2 of the investigation, will provide the following information:

Debris Field—A database and graphics of the major fragments of the aircraft and destroyed structural components of the towers, including their mass, approximate size, speed, and trajectory will be developed in the global analysis of aircraft impact into WTC 1 and WTC 2. The trajectory of each fragment will consist of the initial point of entry, point of exit or resting place. This debris field database will be used to estimate which areas within the impacted floors would likely have lost their fireproofing due to direct impact by debris.

Deformations and Accelerations—Estimates of accelerations and deformations, including localized effects, as a function of time on steel members in each of the two towers will be developed in the global analysis of the aircraft impact. Accelerations will be determined at representative locations on the floor truss systems and columns in the impact-affected zones of both towers (floors 93 to 98 of WTC 1 and floors 78 to 83 of WTC 2). These accelerations will be compared with the threshold values estimated from the adhesion and cohesion properties of SFRM developed in the experimental and analytical study presented below to estimate the likely extent of damage to the fireproofing on the columns and floor systems.

Preliminary results from the subassembly impact analysis of an aircraft engine into a strip of the towers with a width and height of single exterior panel (three exterior columns width and three floor height) extending all the way through the core indicate that the accelerations on the lower chords of floor trusses will need further analysis to account for high frequency vibrations and the short-duration sharp peaks in the computed acceleration time-histories and their effects on damage to SFRM. One possible approach is to low-pass filter the acceleration records to remove these high-frequency vibrations. Another approach is to develop “shock spectra” for a number of steel members with fireproofing configurations using finite

element analysis to determine, for a given frequency, the acceleration amplitude that is needed to dislodge the fireproofing based on its adhesive and cohesive strength. The shock spectra will then be compared with spectra of the calculated acceleration time-histories to estimate the extent of damage to the fireproofing.

I.5.1 Mechanical Properties of SFRM

The purpose of these tests is to develop a rational basis for estimating the extent of loss of SFRM as a result of impact loads on protected members. Tests will (1) determine the mechanical properties of CAFCO BLAZE-SHIELD Type DC/F, and (2) verify models for estimating loss of fireproofing when a protected member is subjected to impact-induced vibration. The mechanical properties to be measured are:

- SFRM cohesive strength, and
- SFRM adhesive strength to steel substrates with and without primer.

The adhesive and cohesive strengths will be measured for static loads, as described below for Phase I tests. The tests will be done on 1/4 in. thick steel plate specimens, with and without primer (Tnemec Series 10 red primer), and for nominal SFRM thickness of 3/4 in. and 1 1/2 in. Specimens are fabricated and testing will be done during June and July, 2004.

From the measured strength properties, estimates will be made of the local accelerations required to damage or dislodge the SFRM, as described below. These estimates will be verified by impact tests of plates and bars covered with SFRM and instrumented with accelerometers, as described in the Phase II tests.

Phase I—Tensile Pull-off Test to Measure Adhesive Bond Strength and Cohesive Strength

Specimen—Steel plates (8 by 16 by 1/4 in.) with CAFCO BLAZE-SHIELD Type DC/F and nominal thickness of 3/4 in. and 1 1/2 in.

Pull-Off Test Procedure (see Fig. I-16)

- Using a fine-tooth saw, cut into SFRM applied to plate to obtain 2 3/4 in. square test specimens to ensure that the area resisting the applied load is well defined.
- Affix aluminum plates with two-component adhesive.
- Allow adhesive to cure.
- Measure force required to pull off the plate.
- Record load and note failure mode (cohesive, adhesive, mixed).




Figure I-16. Pull-off test of SFRM applied to steel plate.

If all failures are adhesive, the cohesive strength will be determined by bonding the SFRM block to a steel plate with adhesive and repeating the test.

Phase II—Verification of Models to Predict Dislodgement of SFRM

Impact tests of plate and bar specimens will be done to determine the impact loads needed to produce different levels of accelerations. Plates and bars with SFRM will be subjected to different levels of impact until the SFRM is dislodged. Two simplified models will be used to estimate the relationships between material strengths and impact required to dislodge the SFRM. Model predictions will be compared with test results.

CASE 1: Planar Element

The simplified model considers the substrate and SFRM as rigid bodies. The SFRM would dislodge when the inertial force exceeds the smaller of the adhesive bond strength or cohesive strength.

Figure I-17, shows the free body of the fireproofing being acted upon by its inertial force and the adhesive force. The acceleration to dislodge the SFRM is:

$$a = \frac{f_b}{\rho t} \quad (I.1)$$




Figure I-17. Derivation of acceleration to dislodge SFRM from planar substrate.

where:

f_b = bond or adhesive strength

t = thickness of SFRM

ρ = density of SFRM

For example, for an SFRM with cohesive and adhesive strength of 150 psf, a density of 15 pcf, and an applied thickness $t = 1$ in., we would find that $a = 119g$, where g is the gravitational acceleration. This shows that acceleration on the order of 100g would be required to dislodge this SFRM from a planar surface.

CASE 2: Encased Round Element

Again, a rigid body model is used. In this case, the SFRM would mobilize its cohesive tensile strength, f_t , and adhesive bond strength, f_b . Figure I-18 shows the derivation for the relationship between material strengths and acceleration to dislodge the SFRM from a round bar. The required acceleration is as follows:

$$a = \frac{4f_t(d_o + (\alpha - 1)d_i)}{(d_o^2 - d_i^2)\rho\pi} \quad (I.2)$$

where:

f_t = cohesive tensile strength of SFRM

d_o = outside diameter of SFRM

Inertial Force Equilibrium

$$\text{Mass} = m = \pi \frac{(d_o^2 - d_i^2)}{4} \rho$$

$$F = f_t(d_o - d_i) + f_b d_i$$

$$\text{Let } f_b = \alpha f_t$$

$$F = f_t(d_o + (\alpha - 1)d_i) = \pi \frac{(d_o^2 - d_i^2)}{4} \rho a$$

$$a = \frac{4f_t(d_o + (\alpha - 1)d_i)}{(d_o^2 - d_i^2)\rho\pi}$$




Figure I-18. Derivation of acceleration to dislodge SFRM surrounding a round bar.

d_i = steel bar diameter

α = Ratio of bond strength to cohesive strength of SFRM

ρ = Density of SFRM

For example, if the steel bar has a diameter of $d_i = 1$ in., the SFRM has an outside diameter of $d_o = 2$ in., a density $\rho = 15$ pcf, a cohesive tensile strength of $f_t = 300$ psf, and a bond strength to cohesive strength ratio of $\alpha = 0.5$, we would find that an acceleration of $a = 152g$ is required to dislodge the SFRM from the bar.

I.6 SUMMARY

This appendix has focused on conditions of the fireproofing (or SFRM) in the WTC towers before and after aircraft impact. Results of simplified finite-element simulations of heat transfer under fire conditions have shown that variability in thickness of fireproofing reduces the effectiveness of the fireproofing so that protection is less than implied by the average thickness of the fireproofing. As a result, the NIST-led investigation sought available information on the in-place condition of the SFRM used in the WTC towers. Limited information was provided by the Port Authority in the form of thickness measurements taken at various times during the 1990s. Additional information was obtained from photographs of floor trusses provided to NIST. Analysis of the data indicated that fireproofing thickness was variable, as would be expected for application to floor truss members with small cross sections. Based on analyses of the available data, the following values were taken to be representative of the SFRM thickness on the floor trusses:

- Original SFRM: Average thickness of 0.75 in. with a standard deviation of 0.3 in. (coefficient of variation = 0.40)
- Upgraded SFRM: Average thickness of 2.5 in. with a standard deviation of 0.6 in. (coefficient of variation = 0.24)

Based on finite-element simulations of a 1 in. round bar covered with SFRM having lognormal distributions for thickness that are consistent with the above values, it is concluded that the original fireproofing on the floor trusses is equivalent to a uniform thickness of 0.6 in. and the upgraded fireproofing is equivalent to a uniform thickness of 2.2 in.

No information is available on in-place conditions of the fireproofing on the exterior columns and spandrel beams, and little information is available on the conditions of fireproofing on core beams and columns. In subsequent thermal analyses, the fireproofing on these elements will be taken to have uniform thicknesses equal to the specified values. This assumption is believed to be justified by the offsetting factors of measured average thicknesses tending to be greater than specified thicknesses and the reduced effectiveness of a given average thickness of fireproofing due to thickness variability.

Another objective of this appendix is to review the methodology that will be used to estimate how much of the SFRM may have dislodged as result of aircraft impact. Simple static models have been developed for an order of magnitude estimate of the acceleration that would be required to dislodge the SFRM. Based on these models and assumed, but representative, values of density and strength (adhesive and

cohesive), it is estimated that acceleration on the order of 100g to 150g (where g is the acceleration due to gravity) would be needed dislodge the fireproofing. Additional analytical studies will be conducted to account for dynamic effects, and tests will be performed to verify these predictions.

